



LIMITED ASBESTOS SURVEY REPORT

**RENOVATIONS TO ACCOMMODATE
COLLOCATION OF SIX (6) METROPOLITAN POLICE DEPARTMENT
UNITS AT 2850 NEW YORK AVENUE, NE
WASHINGTON, DISTRICT OF COLUMBIA**

**STV Project Number 3015141
May 27, 2011**

Prepared by:

STV Incorporated
225 Park Avenue South
New York, NY 10003
Phone: (212) 777-4400
Fax: (212) 529-5237

Prepared for:

Government of the District of Columbia
Department of Real Estate Services
Construction Division
2000 14th Street NW, Suite 800
Washington, DC 20009



225 Park Avenue South
New York, NY 10003
Phone: (212) 777-4400
Fax: 212-529-5237

May 27, 2011

Mr. Michael Gaffney
Government of the District of Columbia
Department of Real Estate Services (DRES)
Construction Division
2000 14th Street NW, Suite 800
Washington, Dc 20009

**Re: Limited Asbestos Survey Report
District of Columbia, Department of Real Estate Services (DRES)
Construction Division
Renovations to Accommodate Collocation of Six (6) Metropolitan Police
Department Units at 2850 New York Avenue NE Facility**

STV Project Number 3015141

Dear Mr. Gaffney:

STV Incorporated (STV) is pleased to submit the enclosed Limited Asbestos Survey Report for Renovations to Accommodate Collocation of Six (6) Metropolitan Police Department Units at 2850 New York Avenue NE Facility.

STV appreciates the opportunity to be of service to the Department of Real Estate Services on this project and looks forward to working with you on future assignments. In the meantime, if you have questions or comments regarding the information in this report or if we can be of further assistance, please do not hesitate to contact the undersigned in the STV Incorporated New York, New York, office at (212) 505-4930.

Sincerely,
STV Incorporated

A handwritten signature in cursive script, appearing to read 'Douglas Glorie'.

Douglas Glorie
Senior Project Manager

cc: D. Hessemer, S. Sottung

TABLE OF CONTENTS

LETTER OF TRANSMITTAL..... i

EXECUTIVE SUMMARY iii

1.0 BACKGROUND 1

2.0 DESCRIPTION OF FACILITY..... 2

3.0 SAMPLING AND ANALYTICAL PROTOCOL..... 3

 3.1 Survey Procedures - General 3

 3.2 Sampling Protocol..... 4

 3.2.1 Choosing Sample Locations4

 3.2.2 Sampling Methods4

 3.3 Analytical Protocol 4

4.0 FINDINGS 6

 4.1 Surfacing Material 6

 4.2 Thermal System Insulation 6

 4.3 Miscellaneous Materials 6

 4.4 Inaccessible Suspect ACM 7

 4.5 Review of Previous Surveys 7

6.0 FINDINGS AND CONCLUSIONS..... 8

 6.1 Summary of Asbestos Containing Materials Findings 8

7.0 ASSUMPTIONS AND LIMITATIONS 8

APPENDICES

Appendix A: Inspector Certification, Company License and Laboratory Certifications

Appendix B: Bulk Material Sampling Analytical Results

Appendix C: Previous Survey Report

Appendix D: D-1 Summary of Limited Asbestos Survey Results
 D-2 Summary of Asbestos-Containing Materials

Appendix E: Sample Location Plans

Appendix F: Photo Log

EXECUTIVE SUMMARY

On May 12, 2011, STV Incorporated (STV) conducted a limited asbestos survey of 2850 New York Avenue NE Facility, Washington, D.C., hereinafter referred to as the site. The purpose of the survey was to identify, locate, sample, and assess the condition of accessible building materials not previously sampled that were suspected of containing asbestos that may be impacted by Renovations to Accommodate Collocation of Six (6) Metropolitan Police Department Units at 2850 New York Avenue NE Facility.

The analytical results of the samples collected during the limited asbestos survey of 2850 New York Avenue NE Facility, indicated that none of the building materials sampled by STV on May 12, 2011 contain asbestos greater than one percent (>1%) in content. The prior report indicates that the following building materials were confirmed or assumed to contain asbestos greater than one percent (>1%) in content:

1. Expansion Joint Caulk (Prior Report)
2. Remnant Black Floor Tile Mastic (Prior Report)
3. Exterior Metal Fire Door Insulation (Prior Report)
4. Roofing Materials (Prior Report)

A summary of limited asbestos containing material (ACM) survey results are included in Table D-1 (in Appendix D). A summary of positive ACM identified during the survey and prior report, including their location and quantity, is included in Table D-2 (in Appendix D).

Asbestos containing materials must be properly removed by a licensed contractor prior to construction activities. Contractors and employees working in this building should be made aware of the possibility that concealed ACM may be found during renovation/demolition. They should be advised not to disturb known or suspect ACM without owner approval. Any concealed building materials discovered during maintenance or renovation activities, which are suspected to contain asbestos, should be sampled and analyzed to confirm the presence of asbestos prior to disturbing.

1.0 BACKGROUND

On May 12, 2011, STV Incorporated (STV) conducted a limited asbestos survey of 2850 New York Avenue NE Facility, Washington, D.C., hereinafter referred to as the site. The purpose of the survey was to identify, locate, sample, and assess the condition of accessible building materials that were suspected of containing asbestos that may be impacted by Renovations to Accommodate Collocation of Six (6) Metropolitan Police Department Units and were not previously sampled. The survey was performed by STV representatives, Mr. Douglas Glorie, (Asbestos Inspector Certificate Number 94-09065) and Mr. Robert Fields (Asbestos Inspector Certificate Number 10-10983). Copies of the inspectors' certifications are presented in **Appendix A**.

2.0 DESCRIPTION OF FACILITY

The existing two-story building is rectangular in configuration and is approximately 100,000 gross square feet (gsf) on the first floor contained in a building footprint of approximately 678 feet long x 146 feet wide. The second floor, located on the west side of the building is approximately 17,000 sf with a mezzanine on the east side of approximately 11,000 sf. The building is approximately 25 feet in height, with the second floor and mezzanine approximately 10'- 4" above the first floor. Loading bays are located on the south and east sides of the first floor with docks approximately 4 feet high, some with dock levelers. The existing building was utilized for warehouse functions and more specifically by the Times as a printing facility.

3.0 SAMPLING AND ANALYTICAL PROTOCOL

3.1 Survey Procedures - General

The site was inspected for the presence of suspect asbestos containing building materials that may contain more than one percent asbestos. The survey included the interior and exterior of the building and was conducted without destructive sampling procedures. Asbestos containing materials (ACM) are divided into three main categories: Surfacing Materials, Thermal System Insulation, and Miscellaneous Materials. All of the suspect materials identified were described and categorized into homogeneous areas (HAs). An HA consists of all identified material found in various locations in a building that are identical in color, appearance, pattern, texture, and date of installation. The HA can be described only within a single building (i.e., red floor tile in different buildings on the same campus, even if installed on the same day, compose different HAs).

The asbestos survey was conducted in accordance with the Asbestos Hazard Emergency Response Act (AHERA) guidelines. The number of samples collected was dependant upon the homogeneous area category and the amount of material present, using a minimum number of samples, which met the sampling criteria found in 29 CFR 1926.1101 as follows:

| AHERA GUIDELINES FOR DETERMINING THE NUMBER OF SAMPLES TO TAKE | | |
|--|-----------------------------|---|
| HA CATEGORY | HA SIZE | SAMPLES REQUIRED |
| Surfacing Materials | <1,000 SF | 3 |
| | 1,000-5,000 SF | 5 |
| | >5,000 SF | 7 or more |
| Thermal System Insulation | < 6 SF or LF of patched | 1 |
| | < 6 SF or LF of non-patched | Per AHERA, these materials must be sampled "in a manner sufficient to determine whether or not they contain asbestos", typically 3 samples based upon inspector judgment. |
| | > 6 SF or LF | Per AHERA, these materials must be sampled "in a manner sufficient to determine whether or not they contain asbestos", typically 3 samples based upon inspector judgment. |
| Miscellaneous Materials | No Stipulation | Per AHERA, these materials must be sampled "in a manner sufficient to determine whether or not they contain asbestos", typically 3 samples based upon inspector judgment. |

SF = Square feet
LF = Linear feet

3.2 Sampling Protocol

3.2.1 Choosing Sample Locations

Samples of suspect miscellaneous materials were collected in a randomly distributed manner sufficient to determine whether the materials were asbestos containing. No samples were collected from any HA where the inspector determined that the material was non-ACM (such as thermal system insulation that was obviously fibrous glass, foam glass, or rubber).

3.2.2 Sampling Methods

Samples were obtained with tools designed to penetrate a material without creating excessive dust. A utility knife, chisel, and hammer were utilized, rather than scratching a sample from the surface of suspected materials, in an effort to obtain a sample that was representative of all layers of the material. The area was pre-wetted to reduce fiber generation during the sampling process. Where practical, a small, broken piece of the material was found and used as a sample.

STV sampling procedures incorporate the use of plastic whirl-pak bags labeled in a unique numbering sequence to store the bulk samples. Information about bulk samples, including the sample number and material description, were noted on the chain-of-custody sheets as each sample was collected. Analytical results and laboratory chain-of-custody sheets are included in **Appendix B**.

3.3 Analytical Protocol

Bulk samples of suspect building materials were collected at the site and laboratory analysis for asbestos was conducted by AmeriSci New York located at 117 East 30th Street, New York, New York (NVLAP Laboratory Code 200546-0) utilizing Polarized Light Microscopy (PLM) methodology. The laboratory is accredited for PLM analysis by both the American Industrial Hygiene Association (AIHA) and the National Voluntary Laboratory Accreditation Program (NVLAP).

Bulk samples of suspect ACM were analyzed using PLM coupled with dispersion staining, as described in 40 CFR Part 763 and the National Emissions Standard for Hazardous Air Pollutants (NESHAP). NESHAP is the standard industry protocol for the determination of asbestos in building materials. A suspect material is immersed in a solution of known refractive index and subjected to illumination by polarized light. The color displays that result are compared to a standardized atlas whereby the specific variety of asbestos is determined. It should also be recognized that PLM is primarily a qualitative identification method whereby asbestos percentage, if any, is estimated. While United States Environmental Protection Agency (USEPA) regulations governing ACM consider materials containing greater than 1 percent as

Limited Asbestos Survey Report
DRES/MPD
2850 New York Avenue NE Facility

asbestos, accurately quantifying asbestos content below 5 percent has been shown to be unreliable.

The New York State Department of Health has revised the PLM Stratified Point Counting Method. The new method, “Polarized Light Microscopy Methods for Identifying and Quantifying Asbestos in Bulk Samples” can be found as item 198.1 in the Environmental Laboratory Approval program (ELAP) Certification manual. The method specifies a procedure of analysis for bulk samples that fall into the category of “Non-friable Organically Bound” (NOB). This category includes any sample in a flexible to rigid asphalt or vinyl matrix (floor tiles, mastic, roofing shingles, roofing felt, etc.). Additional materials that may fall into this category are textured paints and stucco, pipe valve and joint packing, and a variety of other applications. These samples must be “ashed” in a muffle furnace at 480-degrees Celsius (to remove organic matrix), treated with acid (to remove any mineral carbonate), and filtered through a 0.4-micron filter before being analyzed by PLM. The sample must be weighed between each of these steps to track the percent loss of organic matrix. All samples were analyzed by PLM only.

4.0 FINDINGS

The analytical results of the samples collected during the limited asbestos survey conducted May 12, 2011, of 2850 New York Avenue NE Facility, Washington, D.C., and review of the prior report indicate that the following building materials that may be impacted by the proposed renovations were confirmed or assumed to contain asbestos greater than one percent (>1%) in content:

1. Expansion Joint Caulk (Prior Report)
2. Remnant Black Floor Tile Mastic (Prior Report)
3. Exterior Metal Fire Door Insulation (Prior Report)
4. Roofing Materials (Prior Report)

According to the Occupational Safety and Health Administration (OSHA) and USEPA regulations, any material that contains more than one percent of any type of asbestos is considered an ACM. The following narrative lists the types of suspect materials sampled during the survey. Similar materials with unique patterns or colors (e.g., ceiling tiles, floor tiles) have been assigned unique HAs. An Asbestos-Containing Materials Summary Table is presented in **Appendix D**.

4.1 Surfacing Material

Surfacing materials are defined by 29 CFR 1910.1101 as “sprayed, troweled-on or otherwise applied to surfaces (such as plaster on ceilings and walls or other materials on surfaces for acoustical, fireproofing and other purposes)”. No suspect surfacing materials impacted by the proposed renovations were observed, other than those identified in the prior report.

4.2 Thermal System Insulation

Thermal system insulation is defined as insulation material applied to pipes, fittings, boilers, breeching, tanks, ducts or other structural components to prevent heat loss or gain. Suspect thermal system insulation impacted by the proposed scope of work, and not previously reported, included the following:

1. Paper Covering over Fiberglass Duct Insulation
2. Paper Covering over Fiberglass Pipe Insulation

4.3 Miscellaneous Materials

Miscellaneous materials are defined by 40 CFR 763.83 as building materials on “structural components, structural members or fixtures, such as floor and ceiling tiles, and does not include surfacing or thermal system insulation.” Suspect miscellaneous materials impacted by the proposed renovations, and not previously reported, included the following:

1. CMU Mortar
2. Brick Mortar
3. 6"x6" Brown Ceramic Tile Grout
4. Yellow Mastic associated with Brown Ceramic Tile Cove Base
5. Expansion Joint – Floor
6. Expansion Joint – Wall
7. Black Vibration Cloth
8. Brown Wallpaper
9. Gray Linoleum
10. Brown Mastic associated with Gray Linoleum
11. Gray with Silver Flecks Flooring Material
12. Black Expansion Joint under Gray Expansion Joint Caulk

4.4 Inaccessible Suspect ACM

During the survey, samples were collected if they were readily accessible and could be collected using non-destructive methods. The following portions of the building were not accessible:

1. 1st and 2nd floor offices located in the southwest corner of the building (not in scope of work)
2. Roofing System

Additional ACM may be present in inaccessible or concealed spaces. These spaces include, but are not limited to, pipe chases, spaces between wall/ceiling cavities, interior or mechanical components such as boiler cavities, interior ducts, etc. If future maintenance, renovation, and/or demolition activities make these areas accessible, STV recommends that a thorough assessment of these spaces be conducted at that time to identify and confirm the presence of additional ACM.

4.5 Review of Previous Surveys

STV was provided with the following prior report which included an asbestos survey:

1. "Space Program, District of Columbia, Department of Real Estate Services, Metropolitan Police Department" (MPD Space Program report) prepared by Atelier Architects, Inc. dated July 23, 2010.

For Asbestos-Containing Materials (ACM), the MPD Space Program report states "Areas behind solid walls and ceilings were inaccessible and could not be visually surveyed for the presence of ACM". The report also excluded the 1st and 2nd floor offices located in the southwest corner of the building. (Note: During the site visit on May 12, 2011, STV was informed by the client that 1st and 2nd floor offices located in the southwest corner of the building are not included in the scope of work.) The prior report identified the following ACM:

1. Expansion Joint Caulk
2. Remnant Black Floor Tile Mastic

3. Exterior Metal Fire Door Insulation
4. Roofing Materials (Prior Report)

6.0 FINDINGS AND CONCLUSIONS

6.1 Summary of Asbestos Containing Materials Findings

The analytical results of the samples collected during the limited asbestos survey conducted May 12, 2011, of 2850 New York Avenue NE Facility, Washington, D.C., indicate that the following building materials were confirmed or assumed to contain asbestos greater than one percent (>1%) in content:

1. Expansion Joint Caulk (Prior Report)
2. Remnant Black Floor Tile Mastic (Prior Report)
3. Exterior Metal Fire Door Insulation (Prior Report)
4. Roofing Materials (Prior Report)

A summary of limited ACM survey results are included in Table D-1 (in Appendix D). A summary of positive ACM identified during the survey, including their location and quantity, is included in Table D-2 (in Appendix D).

6.1.1 Asbestos Containing Materials Recommendations

Asbestos containing materials must be properly removed by a licensed contractor prior to construction activities. Contractors and employees working in this building should be made aware of the possibility that concealed ACM may be found during renovation/demolition. They should be advised not to disturb known or suspect ACM without owner approval. Any concealed building materials discovered during maintenance or renovation activities, which are suspected to contain asbestos, should be sampled and analyzed to confirm the presence or absence of asbestos prior to disturbing.

7.0 ASSUMPTIONS AND LIMITATIONS

The results, findings, conclusions, and recommendations expressed in the report are based only on conditions that were noted on May 12, 2011 during STV's limited ACM survey of 2850 New York Avenue NE Facility, Washington, D.C.

Any conditions or materials that could not be visually identified on the surface were not inspected and may differ from those conditions or materials noted. It was not within the scope of the survey to remove surface materials to investigate portions of the structure or materials that lay beneath the surface. STV selection of sample locations and frequency of sampling was based on STV observations and the assumption that like materials in the same area are homogeneous in content.

Limited Asbestos Survey Report
DRES/MPD
2850 New York Avenue NE Facility

The report is designed to aid the building owner, architect, construction manager, general contractors, and potential asbestos abatement contractors in locating ACM. Under no circumstances is the report to be utilized as a bidding document or as a project specification document.

The Scope of services performed in execution of this evaluation may not be appropriate to satisfy the needs of other users, and use or re-use of this document or the findings, conclusions, or recommendations is at the risk of said user. Although every attempt has been made to identify suspect asbestos-containing materials in the areas identified, the non-destructive survey technique used is inherently limited in the sense that only full demolition procedures will reveal all building materials of a structure. Additionally, the passage of time may result in a change in the environmental characteristics at this site. The report does not warrant against future operations or conditions that could affect the recommendations made. The results, findings, conclusions and recommendations expressed in this report are based only on conditions that were observed during STV's survey of the site on May 12, 2011.


A P P E N D I X A

Inspector Certifications, Company License and Laboratory Certifications

STATE OF NEW YORK - DEPARTMENT OF LABOR
ASBESTOS CERTIFICATE



DOUGLAS J. GLORIE
CLASS (EXPIRES)
D/DISP (04/12) I/PO (04/12)



CERT# 04-00065
DMV# 154909473

MUST BE CARRIED ON ASBESTOS PROJECTS



EYES BRO
HAIR BRO
HGT 5' 10"

IF FOUND RETURN TO:
NYS DOL - L&C UNIT
ROOM 161A BUILDING 12
STATE OFFICE CAMPUS
ALBANY NY 12240

STATE OF NEW YORK - DEPARTMENT OF LABOR
ASBESTOS CERTIFICATE



ROBERT E. FIELDS
CLASS EXPIRES
C/TEC(08/11) D/RSP(08/11)
H/PM(08/11) P/PT(08/11)
DEPARTMENT OF LABOR

CERT# 10-10983
DMV# 744418592

MUST BE CARRIED ON ASBESTOS PROJECTS



EYES BRO
HAIR BRO
HGT 6' 00"

IF FOUND RETURN TO:
NYSOL - L&C UNIT
ROOM 161A BUILDING 12
STATE OFFICE CAMPUS
ALBANY NY 12240



May 26, 2009

Laboratory ID: 102843

Tonya Williams - Kassim
AmeriSci New York
117 East 30th Street
New York, NY 10016

Dear Ms. Williams - Kassim:

Congratulations! The AIHA Laboratory Accreditation Programs (AIHA-LAP), LLC's Analytical Accreditation Board (AAB) has approved AmeriSci New York as an accredited Industrial Hygiene laboratory.

Enclosed, please find the IHLAP accreditation certificate, scope of accreditation document and a copy of the current AIHA-LAP, LLC license agreement (if your completed agreement is not on file at AIHA-LAP, LLC). The accreditation logo has been designed for use by all AIHA-LAP, LLC accredited laboratories. If your laboratory chooses to use the logo in its advertising the laboratory's accreditation, you must complete and return the AIHA-LAP, LLC license agreement to a Laboratory Accreditation Specialist. Once submitted, an electronic copy of the accreditation logo will be sent to you. Please inform us if your laboratory does not wish to use the logo in advertising.

Laboratory accreditation shall be maintained by continued compliance with IHLAP requirements (*see Policy Modules 2B and 6B*), which includes proficient participation in the IHPAT programs for all Fields of Testing (FoTs) for which the laboratory is accredited. An accredited laboratory that wishes to expand into a new FoT must submit an updated accreditation application to AIHA-LAP, LLC for review by the AAB.

Any changes in ownership, laboratory location, personnel, FoTs/Methods, or significant procedural changes shall be reported to AIHA-LAP, LLC in writing within twenty (20) business days of the change.

The accreditation certificate is the property of AIHA-LAP, LLC and must be returned to us should your laboratory withdraw or be removed from the IHLAP.

Again, congratulations. If you have any questions, please contact Heather I. Thompson, Laboratory Accreditation Specialist, at (703) 846-0716.

Sincerely,

A handwritten signature in cursive script that reads "Cheryl O. Morton".

Cheryl O. Morton
Director, Laboratory Quality Assurance Programs

Enclosure



AIHA Laboratory Accreditation Programs, LLC

acknowledges that

AmeriSci New York

117 East 30th Street, New York, NY 10016

Laboratory ID: 102843

has fulfilled the requirements of the AIHA Laboratory Accreditation Programs (AIHA-LAP), LLC thereby, conforming to the ISO/IEC 17025:2005 international standard, *General Requirements for the Competence of Testing and Calibration Laboratories*. The above named laboratory, along with all premises from which key activities are performed, as listed above, have been accredited by AIHA-LAP, LLC in the following:

ACCREDITATION PROGRAMS

- INDUSTRIAL HYGIENE
 - ENVIRONMENTAL LEAD
 - ENVIRONMENTAL MICROBIOLOGY
 - FOOD
- Accreditation Expires: 06/01/2011
 - Accreditation Expires:
 - Accreditation Expires:
 - Accreditation Expires:

Specific Field(s) of Testing (FoT)/Method(s) within each Accreditation Program for which the above named laboratory maintains accreditation is outlined on the attached **Scope of Accreditation**. Continued accreditation is contingent upon successful on-going compliance with AIHA-LAP, LLC requirements. This certificate is not valid without the attached **Scope of Accreditation**. Please review the AIHA-LAP, LLC website (www.aihaaccreditedlabs.org) for the most current status of the scope of accreditation.

Pamela A. Kostle

Pamela A. Kostle, CIH
Chairperson, Analytical Accreditation Board

Date Issued: 06/01/2009



AIHA Laboratory Accreditation Programs, LLC SCOPE OF ACCREDITATION

AmeriSci New York
117 East 30th Street, New York, NY 10016

Laboratory ID: **102843**
Issue Date: 06/01/2009

The laboratory is approved for those specific field(s) of testing/methods listed in the table below. Clients are urged to verify the laboratory's current accreditation status for the particular field(s) of testing/Methods, since these can change due to proficiency status, suspension and/or revocation. A complete listing of currently accredited Industrial Hygiene laboratories is available on the AIHA-LAP, LLC website at: <http://www.aihaaccreditedlabs.org>

Industrial Hygiene Laboratory Accreditation Program (IHLAP)

Initial Accreditation Date: 04/01/2001

| IHLAP Category | Field of Testing (FoT) | Method | Method Description <i>(for internal methods only)</i> |
|----------------------|----------------------------------|------------------|--|
| Core Program Testing | Polarized Light Microscopy (PLM) | EPA 600/R-93/116 | |
| | Phase Contrast Microscopy (PCM) | NIOSH 7400 | |

The laboratory participates in the following AIHA-LAP, LLC-approved proficiency testing programs:

| | |
|--|---|
| <input type="checkbox"/> Metals | <input type="checkbox"/> Organic Solvents |
| <input type="checkbox"/> Silica | <input type="checkbox"/> Diffusive Sampler (3M) |
| <input checked="" type="checkbox"/> Asbestos | <input type="checkbox"/> Diffusive Sampler (SKC) |
| <input checked="" type="checkbox"/> Bulk Asbestos | <input type="checkbox"/> Diffusive Sampler (AT) |
| <input type="checkbox"/> Beryllium | <input type="checkbox"/> WASP ¹ (Formaldehyde) |
| <input type="checkbox"/> WASP ¹ (Thermal Desorption Tubes) | |
| <input type="checkbox"/> Pharmaceutical Round Robin | |
| <input type="checkbox"/> Compressed/Breathing Air Round Robin | |
| <input type="checkbox"/> NVLAP (determined at the time of site assessment) | |

¹ Workplace Analytical Scheme for Proficiency



**National Voluntary
Laboratory Accreditation Program**



SCOPE OF ACCREDITATION TO ISO/IEC 17025:2005

AmeriSci New York
 DBA: AmeriSci New York
 117 E. 30th Street
 New York, NY 10016
 Mr. Paul Mucha
 Phone: 212-679-8600 Fax: 212-679-2711
 E-Mail: pmucha@amerisci.com
 URL: http://www.amerisci.com

BULK ASBESTOS FIBER ANALYSIS (PLM)

NVLAP LAB CODE 200546-0

NVLAP Code Designation / Description

18/A01 EPA-600/M4-82-020: Interim Method for the Determination of Asbestos in Bulk Insulation Samples


2010-07-01 through 2011-06-30

Effective dates

Dally S. Bruce

For the National Institute of Standards and Technology

United States Department of Commerce
National Institute of Standards and Technology



Certificate of Accreditation to ISO/IEC 17025:2005

NVLAP LAB CODE: 200546-0

AmeriSci New York
New York, NY


is accredited by the National Voluntary Laboratory Accreditation Program for specific services,
listed on the Scope of Accreditation, for:

BULK ASBESTOS FIBER ANALYSIS

*This laboratory is accredited in accordance with the recognized International Standard ISO/IEC 17025:2005.
This accreditation demonstrates technical competence for a defined scope and the operation of a laboratory quality
management system (refer to joint ISO-ILAC-IAF Communiqué dated January 2009).*

2010-07-01 through 2011-06-30

Effective dates



Jolly A. Bruce
For the National Institute of Standards and Technology

APPENDIX B
Bulk Material Sampling Analytical Results



AmeriSci New York

117 EAST 30TH ST.
NEW YORK, NY 10016

TEL: (212) 679-8600 • FAX: (212) 679-3114

PLM Bulk Asbestos Report

STV Incorporated
Attn: Doug Glorie
225 Park Avenue South

New York, NY 10003

Date Received 05/16/11 AmeriSci Job # 211053251
Date Examined 05/20/11 P.O. #
Page 1 of 8

RE: 3015141; DC Department Of Real Estate Service (DRES);
2850 New York Ave., NE Facility, Washington, D.C. -
Washington Times Building, Renovation Of Six Metropolitan
Police Department Units

| Client No. / HGA | Lab No. | Asbestos Present | Total % Asbestos |
|--|--------------|------------------|---|
| 2850-0512-01 1 Location: CMU Mortar/ Rack Storage Room Wall Analyst Description: Grey, Homogeneous, Non-Fibrous, Cementitious, Bulk Material Asbestos Types: Other Material: Non-fibrous 100 % | 211053251-01 | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| 2850-0512-02 1 Location: CMU Mortar/ Warehouse Wall Analyst Description: Grey, Homogeneous, Non-Fibrous, Cementitious, Bulk Material Asbestos Types: Other Material: Non-fibrous 100 % | 211053251-02 | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| 2850-0512-03 1 Location: CMU Mortar/ Loading Dock Wall Analyst Description: Grey, Homogeneous, Non-Fibrous, Cementitious, Bulk Material Asbestos Types: Other Material: Non-fibrous 100 % | 211053251-03 | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| 2850-0512-04 2 Location: Brick Mortar/ Exterior West Facade Analyst Description: Grey, Homogeneous, Non-Fibrous, Cementitious, Bulk Material Asbestos Types: Other Material: Non-fibrous 100 % | 211053251-04 | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| 2850-0512-05 2 Location: Brick Mortar/ Exterior South Facade Analyst Description: Grey, Homogeneous, Non-Fibrous, Cementitious, Bulk Material Asbestos Types: Other Material: Non-fibrous 100 % | 211053251-05 | No | NAD (by CVES) by David W. Roderick on 05/20/11 |

PLM Bulk Asbestos Report

3015141; DC Department Of Real Estate Service (DRES);
 2850 New York Ave., NE Facility, Washington, D.C. -
 Washington Times Building, Renovation Of Six Metropolitan
 Police Department Units

| Client No. / HGA | Lab No. | Asbestos Present | Total % Asbestos |
|---|---|------------------|---|
| 2850-0512-06 2 | 211053251-06 Location: Brick Mortar/ Exterior South Facade | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| Analyst Description: Grey, Homogeneous, Non-Fibrous, Cementitious, Bulk Material Asbestos Types: Other Material: Non-fibrous 100 % | | | |
| 2850-0512-07 3 | 211053251-07 Location: 6"X6" Brown Ceramic Tile Grout/ Lobby Storage Room | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| Analyst Description: Brown, Homogeneous, Non-Fibrous, Cementitious, Bulk Material Asbestos Types: Other Material: Non-fibrous 100 % | | | |
| 2850-0512-08 3 | 211053251-08 Location: 6"X6" Brown Ceramic Tile Grout/ Lobby Storage Room | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| Analyst Description: Brown, Homogeneous, Non-Fibrous, Cementitious, Bulk Material Asbestos Types: Other Material: Non-fibrous 100 % | | | |
| 2850-0512-09 3 | 211053251-09 Location: 6"X6" Brown Ceramic Tile Grout/ Lobby Storage Room | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| Analyst Description: Brown, Homogeneous, Non-Fibrous, Cementitious, Bulk Material Asbestos Types: Other Material: Non-fibrous 100 % | | | |
| 2850-0512-10 4 | 211053251-10 Location: Yellow Mastic Associated With Brown Ceramic Tile Covebase/ Lobby Storage Room | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| Analyst Description: Yellow, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Non-fibrous 100 % | | | |
| 2850-0512-11 4 | 211053251-11 Location: Yellow Mastic Associated With Brown Ceramic Tile Covebase/ Lobby Storage Room | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| Analyst Description: Yellow, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Non-fibrous 100 % | | | |

PLM Bulk Asbestos Report

3015141; DC Department Of Real Estate Service (DRES);
2850 New York Ave., NE Facility, Washington, D.C. -
Washington Times Building, Renovation Of Six Metropolitan
Police Department Units

| Client No. / HGA | Lab No. | Asbestos Present | Total % Asbestos |
|---|---|------------------|---|
| 2850-0512-12 4 | 211053251-12 Location: Yellow Mastic Associated With Brown Ceramic Tile Covebase/ Lobby | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| Analyst Description: Yellow, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Non-fibrous 100 % | | | |
| 2850-0512-13 5 | 211053251-13 Location: Expansion Joint Floor/ Corridor At TCG Room | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| Analyst Description: Black, Homogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Cellulose 80 %, Non-fibrous 20 % | | | |
| 2850-0512-14 5 | 211053251-14 Location: Expansion Joint Floor/ Storage Locker Door | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| Analyst Description: Black, Homogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Cellulose 80 %, Non-fibrous 20 % | | | |
| 2850-0512-15 5 | 211053251-15 Location: Expansion Joint Floor/ Loading Dock Floor | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| Analyst Description: Black, Homogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Cellulose 80 %, Non-fibrous 20 % | | | |
| 2850-0512-16 6 | 211053251-16 Location: Paper Covering Over Fiberglass Duct Insulation/ Corridor At TCG Room | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| Analyst Description: Silver/Brown, Heterogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Cellulose 40 %, Fibrous glass 10 %, Non-fibrous 50 % | | | |
| 2850-0512-17 6 | 211053251-17 Location: Paper Covering Over Fiberglass Duct Insulation/ Fleet Services Office | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| Analyst Description: Silver/Brown, Heterogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Cellulose 40 %, Fibrous glass 10 %, Non-fibrous 50 % | | | |

PLM Bulk Asbestos Report

3015141; DC Department Of Real Estate Service (DRES);
 2850 New York Ave., NE Facility, Washington, D.C. -
 Washington Times Building, Renovation Of Six Metropolitan
 Police Department Units

| Client No. / HGA | Lab No. | Asbestos Present | Total % Asbestos |
|---|---|------------------|---|
| 2850-0512-18 6 | 211053251-18 Location: Paper Covering Over Fiberglass Duct Insulation/ Mezzanine Men's Locker Room | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| Analyst Description: Silver/Brown, Heterogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Cellulose 40 %, Fibrous glass 10 %, Non-fibrous 50 % | | | |
| 2850-0512-19 7 | 211053251-19 Location: Expansion Joint Wall/ Warehouse | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| Analyst Description: Black, Homogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Cellulose 80 %, Non-fibrous 20 % | | | |
| 2850-0512-20 7 | 211053251-20 Location: Expansion Joint Wall/ Warehouse | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| Analyst Description: Black, Homogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Cellulose 80 %, Non-fibrous 20 % | | | |
| 2850-0512-21 7 | 211053251-21 Location: Expansion Joint Wall/ Warehouse | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| Analyst Description: Black, Homogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Cellulose 80 %, Non-fibrous 20 % | | | |
| 2850-0512-22 8 | 211053251-22 Location: Paper Covering Over Fiberglass Pipe Insulation/ Warehouse At Eyewash | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| Analyst Description: Silver/Off White, Heterogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Cellulose 40 %, Fibrous glass 10 %, Non-fibrous 50 % | | | |
| 2850-0512-23 8 | 211053251-23 Location: Paper Covering Over Fiberglass Pipe Insulation/ Fleet Service Office | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| Analyst Description: Silver/Off White, Heterogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Cellulose 40 %, Fibrous glass 10 %, Non-fibrous 50 % | | | |

PLM Bulk Asbestos Report

3015141; DC Department Of Real Estate Service (DRES);
 2850 New York Ave., NE Facility, Washington, D.C. -
 Washington Times Building, Renovation Of Six Metropolitan
 Police Department Units

| Client No. / HGA | Lab No. | Asbestos Present | Total % Asbestos |
|--|--|------------------|---|
| 2850-0512-24 8 | 211053251-24 Location: Paper Covering Over Fiberglass Pipe Insulation/ Mezzanine Janitor's Closet | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| Analyst Description: Silver/Off White, Heterogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Cellulose 40 %, Fibrous glass 10 %, Non-fibrous 50 % | | | |
| 2850-0512-25 9 | 211053251-25 Location: Black Vibration Cloth/ Ink Room Unit #1 | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| Analyst Description: Black, Homogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Synthetic fibers 35 %, Non-fibrous 65 % | | | |
| 2850-0512-26 9 | 211053251-26 Location: Black Vibration Cloth/ Ink Room Unit #3 | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| Analyst Description: Black, Homogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Synthetic fibers 35 %, Non-fibrous 65 % | | | |
| 2850-0512-27 9 | 211053251-27 Location: Black Vibration Cloth/ Ink Room Unit #3 | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| Analyst Description: Black, Homogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Synthetic fibers 35 %, Non-fibrous 65 % | | | |
| 2850-0512-28 10 | 211053251-28 Location: Brown Wallpaper/ James Nickell Office | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| Analyst Description: Tan, Homogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Cellulose 40 %, Non-fibrous 60 % | | | |
| 2850-0512-29 10 | 211053251-29 Location: Brown Wallpaper/ James Nickell Office | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| Analyst Description: Tan, Homogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Cellulose 40 %, Non-fibrous 60 % | | | |

PLM Bulk Asbestos Report

3015141; DC Department Of Real Estate Service (DRES);
 2850 New York Ave., NE Facility, Washington, D.C. -
 Washington Times Building, Renovation Of Six Metropolitan
 Police Department Units

| Client No. / HGA | Lab No. | Asbestos Present | Total % Asbestos |
|---|--|------------------|---|
| 2850-0512-30 10 | 211053251-30 Location: Brown Wallpaper/ James Nickell Office | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| Analyst Description: Tan, Homogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Cellulose 40 %, Non-fibrous 60 % | | | |
| 2850-0512-31 11 | 211053251-31 Location: Gray Linoleum/ Pre-Press Room | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| Analyst Description: Grey/Brown, Homogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Cellulose 30 %, Non-fibrous 70 % | | | |
| 2850-0512-32 11 | 211053251-32 Location: Gray Linoleum/ Pre-Press Room | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| Analyst Description: Grey/Brown, Homogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Cellulose 30 %, Non-fibrous 70 % | | | |
| 2850-0512-33 11 | 211053251-33 Location: Gray Linoleum/ Image And Scanning Storage Room | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| Analyst Description: Grey/Brown, Homogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Cellulose 30 %, Non-fibrous 70 % | | | |
| 2850-0512-34 12 | 211053251-34 Location: Brown Mastic Associated With Gray Linoleum/ Pre-Press Room | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| Analyst Description: Yellow, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 % | | | |
| 2850-0512-35 12 | 211053251-35 Location: Brown Mastic Associated With Gray Linoleum/ Pre-Press Room | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| Analyst Description: Yellow, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 % | | | |

PLM Bulk Asbestos Report

3015141; DC Department Of Real Estate Service (DRES);
 2850 New York Ave., NE Facility, Washington, D.C. -
 Washington Times Building, Renovation Of Six Metropolitan
 Police Department Units

| Client No. / HGA | Lab No. | Asbestos Present | Total % Asbestos |
|--|---|------------------|---|
| 2850-0512-36 12 | 211053251-36 Location: Brown Mastic Associated With Gray Linoleum/ Image And Scanning Storage Room | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| Analyst Description: Yellow, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 % | | | |
| 2850-0512-37 13 | 211053251-37 Location: Gray With Silver Flecks Flooring Material/ Image And Scanning Storage Room | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| Analyst Description: Grey, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Cellulose Trace, Fibrous glass Trace, Non-fibrous 100 % | | | |
| 2850-0512-38 13 | 211053251-38 Location: Gray With Silver Flecks Flooring Material/ Image And Scanning Storage Room | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| Analyst Description: Grey, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Cellulose Trace, Fibrous glass Trace, Non-fibrous 100 % | | | |
| 2850-0512-39 13 | 211053251-39 Location: Gray With Silver Flecks Flooring Material/ Image And Scanning Storage Room | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| Analyst Description: Grey, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Cellulose Trace, Fibrous glass Trace, Non-fibrous 100 % | | | |
| 2850-0512-40 14 | 211053251-40 Location: Black Expansion Joint Under Gray Caulk/ Exterior Facade | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| Analyst Description: Black, Homogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Cellulose 15 %, Non-fibrous 85 % | | | |
| 2850-0512-41 14 | 211053251-41 Location: Black Expansion Joint Under Gray Expansion Joint Caulk/ Exterior Facade | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| Analyst Description: Black, Homogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Cellulose 15 %, Non-fibrous 85 % | | | |


Client Name: STV Incorporated

PLM Bulk Asbestos Report

3015141; DC Department Of Real Estate Service (DRES);
2850 New York Ave., NE Facility, Washington, D.C. -
Washington Times Building, Renovation Of Six Metropolitan
Police Department Units

| Client No. / HGA | Lab No. | Asbestos Present | Total % Asbestos |
|---|---|------------------|---|
| 2850-0512-42 14 | 211053251-42 Location: Black Expansion Joint Under Gray Caulk/ Exterior Facade | No | NAD (by CVES) by David W. Roderick on 05/20/11 |
| Analyst Description: Black, Homogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Cellulose 15 %, Non-fibrous 85 % | | | |

Reporting Notes:

Analyzed by: David W. Roderick 

*NAD/NSD =no asbestos detected; NA =not analyzed; NA/PS=not analyzed/positive stop; PLM Bulk Asbestos Analysis by EPA 600/M4-82-020 per 40 CFR 763 (NVLAP Lab Code 200546-0), ELAP PLM Method 198.1 for NY friable samples or 198.6 for NOB samples (NY ELAP Lab ID11480);

Note:PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. NAD or Trace results by PLM are inconclusive, TEM is currently the only method that can be used to determine if this material can be considered or treated as non asbestos-containing in NY State (also see EPA Advisory for floor tile, FR 59,146,38970,8/1/94) National Institute of Standards and Technology Accreditation requirements mandate that this report must not be reproduced except in full without the approval of the lab. This PLM report relates ONLY to the items tested. AIHA Lab # 102843.

Reviewed By: _____ END OF REPORT _____

PROJECT NO.: 3015141

CLIENT: DC Department of Real Estate Services (DRES)

PROJECT SITE: 2850 New York Ave NE Facility, Washington, D.C.

Project Manager: D. Glorie

LOCATION(S) SURVEYED: Washington Times Building

PROPOSED PROJECT: Renovations of six metropolitan police department units

DATE(S) OF INSPECTION: 5/12/2011

Inspector(s): D. Glorie, R. Fields

STV Incorporated
225 Park Avenue South, New York, NY 10003
Phone : 212-505-4930 / Fax: 212-529-5237

RESULTS TO: D. Glorie FAX No.: 212-529-5237
Douglas.glorie@stvinc.com

TURNAROUND TIME: 5 Day
 4 HR. 12 HR. 24 HR. 48 HR.

| HA | SAMPLE NO. | MATERIAL DESCRIPTION | SAMPLE LOCATION | APPROX. QUANTITY (LF/SF) | FIELD NOTES |
|----|--------------|--|-------------------------|--------------------------|-------------|
| 1 | 2850-0512-01 | CMU Mortar | Rack Storage Room Wall | | |
| 1 | 2850-0512-02 | CMU Mortar | Warehouse Wall | | |
| 1 | 2850-0512-03 | CMU Mortar | Loading Dock Wall | | |
| 2 | 2850-0512-04 | Brick Mortar | Exterior - West Façade | 101 | |
| 2 | 2850-0512-05 | Brick Mortar | Exterior - South Façade | 32 | |
| 2 | 2850-0512-06 | Brick Mortar | Exterior - South Façade | 32 | |
| 3 | 2850-0512-07 | 6"x6" Brown Ceramic Tile Grout | Lobby Storage Room | 110 | |
| 3 | 2850-0512-08 | 6"x6" Brown Ceramic Tile Grout | Lobby Storage Room | 211 | |
| 3 | 2850-0512-09 | 6"x6" Brown Ceramic Tile Grout | Lobby Storage Room | 211 | |
| 4 | 2850-0512-10 | Yellow Mastic associated with Brown Ceramic Tile Cove Base | Lobby Storage Room | | |
| 4 | 2850-0512-11 | Yellow Mastic associated with Brown Ceramic Tile Cove Base | Lobby Storage Room | | |
| 4 | 2850-0512-12 | Yellow Mastic associated with Brown Ceramic Tile Cove Base | Lobby | | |

CHAIN OF CUSTODY

| | | | | |
|------------------------------|--------|---------|--------------------------|--------|
| Retrieved by: Doug Glorie | (Sign) | 4/16/11 | Relinquished by: AUCM | (Sign) |
| Received by: A. S. ... | (Sign) | 5/16/11 | Received by: AUCM | (Sign) |

PROJECT NO.: 3015141
CLIENT: DC Department of Real Estate Services (DRES)
PROJECT SITE: 2850 New York Ave NE Facility, Washington, D.C.
Project Manager: D. Glorie

LOCATION(S) SURVEYED: Washington Times Building
PROPOSED PROJECT: Renovations of six metropolitan police department units
DATE(S) OF INSPECTION: 5/12/2011
Inspector(s): D. Glorie, R. Fields

STV Incorporated
 225 Park Avenue South, New York, NY 10003
 Phone: 212-505-4930 / Fax: 212-529-5237

RESULTS TO: D. Glorie FAX No.: 212-529-5237
 Douglas.glorie@stvinc.com

TURNAROUND TIME: 5 Day
 4 HR. 12 HR. 24 HR. 48 HR.

| HA | SAMPLE NO. | MATERIAL DESCRIPTION | SAMPLE LOCATION | APPROX. QUANTITY (LF/SF) | FIELD NOTES |
|----|--------------|--|-----------------------------|--------------------------|-------------|
| 5 | 2850-0512-13 | Expansion Joint - Floor | Corridor at TCG Room | | |
| 5 | 2850-0512-14 | Expansion Joint - Floor | Storage Locker Door | | |
| 5 | 2850-0512-15 | Expansion Joint - Floor | Loading Dock Floor | | |
| 6 | 2850-0512-16 | Paper Covering over Fiberglass Duct Insulation | Corridor at TCG Room | 1 | |
| 6 | 2850-0512-17 | Paper Covering over Fiberglass Duct Insulation | Fleet Services Office | 2 | |
| 6 | 2850-0512-18 | Paper Covering over Fiberglass Duct Insulation | Mezzanine Men's Locker Room | 3 | |
| 7 | 2850-0512-19 | Expansion Joint - Wall | Warehouse | 10 | |
| 7 | 2850-0512-20 | Expansion Joint - Wall | Warehouse | 1 | |
| 7 | 2850-0512-21 | Expansion Joint - Wall | Warehouse | 2 | |
| 8 | 2850-0512-22 | Paper Covering over Fiberglass Pipe Insulation | Warehouse at Eyewash | | |
| 8 | 2850-0512-23 | Paper Covering over Fiberglass Pipe Insulation | Fleet Service Office | | |
| 8 | 2850-0512-24 | Paper Covering over Fiberglass Pipe Insulation | Mezzanine Janitor's Closet | | |

CHAIN OF CUSTODY

| | | | | | |
|--|--------|---------|-------------------------------------|-----|--------|
| Relinquished by: Doug Glorie (print) | (Sign) | 5/16/11 | Relinquished by: AUCM (print) | / / | (Sign) |
| Received by: R. Fields (print) | (Sign) | 5/16/11 | Received by: AUCM (print) | / / | (Sign) |

GENERAL NOTES: All inconclusive NOBs to be analyzed by TEM. Please stop at 1 sensitive in any homogeneous group.

PROJECT NO.: 3015141
LOCATION(S) SURVEYED: Washington Times Building
CLIENT: DC Department of Real Estate Services (DRES)
PROPOSED PROJECT: Renovations of six metropolitan police department units
PROJECT SITE: 2850 New York Ave NE Facility, Washington, D.C.
DATE(S) OF INSPECTION: 5/12/2011
Inspector(s): D. Glorie, R. Fields

STV Incorporated
 225 Park Avenue South, New York, NY 10003
 Phone : 212-505-4930 / Fax: 212-529-5237
RESULTS TO: D. Glorie FAX No.: 212-529-5237
 Douglas.glorie@stvinc.com

TURNAROUND TIME: 5 Day
 4 HR. 12 HR. 24 HR. 48 HR.

| HA | SAMPLE NO. | MATERIAL DESCRIPTION | SAMPLE LOCATION | APPROX. QUANTITY (LF/SF) | FIELD NOTES |
|----|--------------|--|---------------------------------|--------------------------|-------------|
| 9 | 2850-0512-25 | Black Vibration Cloth | Ink Room, Unit #1 | | |
| 9 | 2850-0512-26 | Black Vibration Cloth | Ink Room, Unit #3 | | |
| 9 | 2850-0512-27 | Black Vibration Cloth | Ink Room, Unit #3 | | |
| 10 | 2850-0512-28 | Brown Wallpaper | James Nickell Office | | |
| 10 | 2850-0512-29 | Brown Wallpaper | James Nickell Office | 1 | |
| 10 | 2850-0512-30 | Brown Wallpaper | James Nickell Office | 25 | |
| 11 | 2850-0512-31 | Gray Linoleum | Pre-Press Room | 3 | |
| 11 | 2850-0512-32 | Gray Linoleum | Pre-Press Room | 5 | |
| 11 | 2850-0512-33 | Gray Linoleum | Image and Scanning Storage Room | 10 | |
| 12 | 2850-0512-34 | Brown Mastic associated with Gray Linoleum | Pre-Press Room | 21 | |
| 12 | 2850-0512-35 | Brown Mastic associated with Gray Linoleum | Pre-Press Room | 1 | |
| 12 | 2850-0512-36 | Brown Mastic associated with Gray Linoleum | Image and Scanning Storage Room | 1 | |

CHAIN OF CUSTODY

| | | | | |
|---|---------|----------------------------|---------|----------------------------|
| Relinquished by: Doug Glorie (Sign) | 5/16/11 | Relinquished by: (Sign) | 5/16/11 | Relinquished by: (Sign) |
| Received by: (Sign) | 5/16/11 | Received by: (Sign) | 5/16/11 | Received by: (Sign) |

PROJECT NO.: 3015141
CLIENT: DC Department of Real Estate Services (DRES)
PROJECT SITE: 2850 New York Ave NE Facility, Washington, D.C.
Project Manager: D. Glorie

LOCATION(S) SURVEYED: Washington Times Building
PROPOSED PROJECT: Renovations of six metropolitan police department units
DATE(S) OF INSPECTION: 5/12/2011
Inspector(s): D. Glorie, R. Fields

STV Incorporated
 225 Park Avenue South, New York, NY 10003
 Phone : 212-505-4930 / Fax: 212-529-5237

RESULTS TO: D. Glorie FAX No.: 212-529-5237
 Douglas.glorie@stvinc.com

TURNAROUND TIME: 5 Day
 4 HR. 12 HR. 24 HR. 48 HR.

| HA | SAMPLE NO. | MATERIAL DESCRIPTION | SAMPLE LOCATION | APPROX. QUANTITY (LF/SF) | FIELD NOTES |
|----|--------------|--|---------------------------------|--------------------------|-------------|
| 13 | 2850-0512-37 | Gray with Silver Flecks Flooring Material | Image and Scanning Storage Room | | |
| 13 | 2850-0512-38 | Gray with Silver Flecks Flooring Material | Image and Scanning Storage Room | | |
| 13 | 2850-0512-39 | Gray with Silver Flecks Flooring Material | Image and Scanning Storage Room | | |
| 14 | 2850-0512-40 | Black Expansion Joint under Gray Caulk | Exterior Facade | | |
| 14 | 2850-0512-41 | Black Expansion Joint under Gray Expansion Joint Caulk | Exterior Facade | | |
| 14 | 2850-0512-42 | Black Expansion Joint under Gray Caulk | Exterior Facade | 211053251 | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

CHAIN OF CUSTODY

| Retinquished by: | (Sign) | 5/16/11 | AWPM | Reinquished by: | (Sign) |
|--------------------|--------------------|---------|------|-----------------|--------|
| Doug Glorie | <i>[Signature]</i> | | | | |
| Received by: | (Sign) | 5/16/11 | AWPM | Received by: | (Sign) |
| <i>[Signature]</i> | | | | | |

**APPENDIX C
Previous Survey Report**

HAZARDOUS MATERIALS

BACKGROUND

Froehling and Robertson (F&R) was contracted by Atelier Architects to perform a limited, non-destructive hazardous materials survey of select areas of the former Washington Times Warehouse, located at 2850 New York Ave, NE in Washington, DC. This survey includes a limited sampling of the 1st and 2nd floor offices located in the southwest corner of the building which are currently occupied by District of Columbia government agencies. The survey was performed by Environmental Protection Agency-Asbestos Hazard Emergency Response Act (EPA-AHERA) accredited asbestos building inspector and District of Columbia licensed lead inspector, Alan Lederman, on July 13th, 15th, and 16th, 2010.

The scope of the hazardous materials survey at the former Washington Times Warehouse consisted of the following items only:

- Non-invasive survey for suspect asbestos-containing materials (ACMs)
- Screening of surface coatings that may contain lead-based paint (LBP)
- Collection of lead dust wipes on select surfaces
- Non-invasive Inventory of suspect PCB-containing and mercury-containing components

The following were outside of the scope of our services; however F&R made some on-site observations where feasible to provide Atelier Architects and DC Department of Real Estate Services (DRES) with as much information as possible about this facility:

- Sub-surface soil and groundwater investigation
- Indoor air quality investigation
- Chemical and hazardous waste inventory
- Environmental records review
- All other services not specifically referenced as being part of this investigation

ASBESTOS-CONTAINING MATERIAL (ACM)

1. Methodology

For this project, a non-invasive visual survey and sampling for suspect ACM was conducted at the above referenced site. All samples were collected in general accordance with EPA-AHERA protocols and submitted under chain of custody to EMSL Analytical, Inc. (EMSL) located in Beltsville, Maryland, for analysis. EMSL is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) to analyze suspect asbestos-containing bulk materials. A total of fifty-seven (57) bulk samples were collected and analyzed using Polarized Light Microscopy (PLM) via EPA Method 600/R-93/116.

2. Sampling Results

| Sample # | Sample Location | Sample Description | Analytical Results |
|-----------------|---|--|---------------------------|
| 2850-01 | Warehouse 1 st Floor Offices | 12"x12" White Vinyl Floor Tile with Black Flecks | No Asbestos Detected |

**TABLE 1
 ACM LABORATORY RESULTS**

| Sample # | Sample Location | Sample Description | Analytical Results |
|-----------------|---|---|---------------------------|
| 2850 -02 | Warehouse 1 st Floor Offices | Black Floor Tile Mastic | No Asbestos Detected |
| 2850 -03 | Warehouse 1 st Floor Offices | 12"x12" Blue Vinyl Floor Tile with White Flecks | No Asbestos Detected |
| 2850 -04 | Warehouse 1 st Floor Offices | Black Floor Tile Mastic | No Asbestos Detected |
| 2850 -05 | Warehouse Mezzanine Offices | 12"x12" Gray Vinyl Floor Tile with Black Flecks | No Asbestos Detected |
| 2850 -06 | Warehouse Mezzanine Offices | Brown Floor Tile Mastic | No Asbestos Detected |
| 2850 -07 | Warehouse Stairwell at Front Entrance | 12"x12" Solid Gray Vinyl Floor Tile | No Asbestos Detected |
| 2850 -08 | Warehouse Stairwell at Front Entrance | Brown Mastic | No Asbestos Detected |
| 2850 -09 | Northwest Corner Offices | 12"x12" Gray Vinyl Floor Tile with White Flecks | No Asbestos Detected |
| 2850 -10 | Northwest Corner Offices | Tan Carpet Mastic | No Asbestos Detected |
| 2850 -11 | 2 nd Floor Southwest Offices | Sheetrock | No Asbestos Detected |
| 2850 -12 | 2 nd Floor Southwest Offices | Sheetrock Joint Compound | No Asbestos Detected |
| 2850 -13 | 2 nd Floor Southwest Offices | White 2'x2' Ceiling Tile | No Asbestos Detected |
| 2850 -14 | 1 st Floor Southwest Offices | Sheetrock | No Asbestos Detected |
| 2850-15 | 1 st Floor Southwest Offices | Sheetrock Joint Compound | No Asbestos Detected |
| 2850 -16 | 1 st Floor Southwest Offices | 12"x12" Purple Vinyl Floor Tile | No Asbestos Detected |
| 2850-17 | 1 st Floor Southwest Offices | Stairwell Plaster | No Asbestos Detected |
| 2850-18 | 1 st Floor Southwest Offices | Stairwell Plaster | No Asbestos Detected |
| 2850-19 | 1 st Floor Southwest Offices | Stairwell Plaster | No Asbestos Detected |
| 2850-20 | 1st Floor Southwest Offices | Exterior Window Caulk | 20% Chrysotile |
| 2850-21 | Warehouse Mezzanine Offices | White 2'x4' Ceiling Tile | No Asbestos Detected |
| 2850-22 | Warehouse Mezzanine Offices | Sheetrock | No Asbestos Detected |
| 2850-23 | Warehouse Mezzanine Offices | Sheetrock Joint Compound | No Asbestos Detected |
| 2850-24 | Warehouse Mezzanine Offices | Gray 2'x4' Ceiling Tile | No Asbestos Detected |

**TABLE 1
 ACM LABORATORY RESULTS**

| Sample # | Sample Location | Sample Description | Analytical Results |
|-----------------|--|---|---------------------------|
| 2850-25 | Warehouse Mezzanine Offices | White Sink Basin Coating | No Asbestos Detected |
| 2850-26 | Warehouse Mezzanine Catwalk | White Pipe Seam Sealant | No Asbestos Detected |
| 2850-27 | Warehouse Mezzanine Offices | White Duct Seam Sealant | No Asbestos Detected |
| 2850-28 | Warehouse Northeast Corner | Sheetrock | No Asbestos Detected |
| 2850-29 | Warehouse Northeast Corner | Sheetrock Joint Compound | No Asbestos Detected |
| 2850-30 | South Central Garage Door Bay | Sheetrock | No Asbestos Detected |
| 2850-31 | South Central Garage Door Bay | Sheetrock Joint Compound | No Asbestos Detected |
| 2850-32 | Warehouse Storage | Sheetrock on Cinderblock Columns | No Asbestos Detected |
| 2850-33 | Warehouse Storage | Sheetrock Joint Compound on Cinderblock Columns | No Asbestos Detected |
| 2850-34 | Northwest Corner Offices | Sheetrock | No Asbestos Detected |
| 2850-35 | Northwest Corner Offices | Sheetrock Joint Compound | No Asbestos Detected |
| 2850-36 | South Exterior Wall | Expansion Joint Caulk | 18% Chrysotile |
| 2850-37 | Dispatch Office | Exterior Window Caulk | No Asbestos Detected |
| 2850-38 | Northeast Corner Building Entrance | Exterior Door Caulk | No Asbestos Detected |
| 2850-39 | Warehouse Mezzanine Offices | Remnant Black Floor Tile Mastic | 3% Chrysotile |
| 2850-40 | Warehouse Mezzanine Offices | Tan Duct Seam Sealant | No Asbestos Detected |
| 2850-41 | Warehouse Mezzanine Offices | Vinyl Covebase | No Asbestos Detected |
| 2850-42 | Warehouse Mezzanine Offices | Vinyl Covebase Mastic | No Asbestos Detected |
| 2850-43 | Warehouse Mezzanine Offices | Rubber Flooring | No Asbestos Detected |
| 2850-44 | Warehouse 1 st Floor Offices-Ceiling Deck | Gray Spray-On Fireproofing | No Asbestos Detected |
| 2850-45 | Warehouse 1 st Floor Offices-Ceiling Deck | Gray Spray-On Fireproofing | No Asbestos Detected |
| 2850-46 | Warehouse 1 st Floor Vertical I-Beams Adjacent to Offices | Gray Spray-On Fireproofing | No Asbestos Detected |
| 2850-47 | Warehouse 1 st Floor Horizontal I-Beams Adjacent to Offices | Gray Spray-On Fireproofing | No Asbestos Detected |

| TABLE 1 ACM LABORATORY RESULTS | | | |
|-----------------------------------|---|---|----------------------|
| Sample # | Sample Location | Sample Description | Analytical Results |
| 2850-48 | Warehouse 1 st Floor at Southeast Corner Entrance-Ceiling Deck | Gray Spray-On Fireproofing | No Asbestos Detected |
| 2850-49 | Warehouse 1 st Floor East End-Ceiling Deck | Gray Spray-On Fireproofing | No Asbestos Detected |
| 2850-50 | Warehouse 1 st Floor East End-Vertical I-Beam | Gray Spray-On Fireproofing | No Asbestos Detected |
| 2850-51 | Warehouse 1 st Floor East End-Horizontal I-Beam | Gray Spray-On Fireproofing | No Asbestos Detected |
| 2850-52 | Warehouse 1 st Floor East End-Ceiling Deck | Gray Spray-On Fireproofing | No Asbestos Detected |
| 2850-53 | Generator Room | Generator Breeching Insulation | No Asbestos Detected |
| 2850-54 | Generator Room | Generator Breeching Insulation | No Asbestos Detected |
| 2850-55 | Generator Room | Generator Breeching Insulation | No Asbestos Detected |
| 2850-56 | Warehouse Storage Space | Interior Door Insulation | No Asbestos Detected |
| 2850-57 | Warehouse Storage Space | Tan Drywall Mastic on Cinderblock Columns | No Asbestos Detected |

Please see **Table 2** below for a summary of the ACM located within the surveyed areas of the former Washington Times Warehouse.

| TABLE 2 ACM SUMMARY | | | | | |
|-------------------------------------|--------------------------------------|--------------------|----------|-----------|------------------|
| Sample Description | Location | Estimated Quantity | Friable? | Condition | Asbestos Content |
| Expansion Joint Caulk | Expansion Joints Throughout Exterior | 250 Linear Feet | No | Fair | 18% Chrysotile |
| Remnant Black Floor Tile Mastic | Warehouse Mezzanine Offices | 1,500 Square Feet | No | Fair | 3% Chrysotile |
| Exterior Metal Fire Door Insulation | Exterior Metal Doors | 5 | Yes | Unknown | Presumed ACM |

F&R offers the following observations in regards to the information presented in **Table 2**:

- Asbestos-containing window caulk was identified on the southwest corner of the building, however as directed by DC Department of Real Estate Services (DRES), this area is outside of the scope our survey. No window caulk similar to the identified asbestos-containing caulk was identified within the project scope area.
- Areas behind solid walls and ceilings were inaccessible and could not be visually surveyed for the presence of ACM. ACM including, but not limited to, thermal pipe and pipe fitting insulation may exist in these locations.

- The estimates provided are preliminary and are not meant for contractor bidding purposes. Additional and/or greater quantities of these ACM's may be discovered during renovation/demolition activities. Additional field verification will be needed to confirm these quantities.
- This survey excluded the 1st and 2nd floor offices located in the southwest corner of the building which are currently occupied by District of Columbia government agencies. If renovation/demolition activities are to take place in these areas an asbestos survey of these areas should be performed.



Photograph 1: Asbestos-containing remnant black floor tile mastic



Photograph 2: Suspect asbestos-containing exterior fire door

LEAD

1. Methodology

Lead-Based Paint Screening

A lead-based paint (LBP) screening was performed to test a representative number of painted surfaces for the presence of lead. The testing was conducted by using a Niton XL-309 X-Ray Fluorometer (XRF) Lead Paint Analyzer. The XRF contains a small radioisotopic source and operates on the principle of x-ray fluorescence, whereby lead atoms in paint are stimulated to emit characteristic x-rays, which are then detected by the instrument. The XRF can measure surface or non-surface concentrations of lead with 95% accuracy at the District of Columbia action level of 1.0 mg/cm². Levels of lead are reported in units of milligrams per square centimeter (mg/cm²). The XRF is able to accurately detect as little as 0.1 mg/cm² of lead. The XRF classifies painted surfaces as "positive" or "negative" for lead content based on the District of Columbia action level (1.0 mg/cm²) and the performance characteristics of the XRF.

Positive: Lead is present at or above the District of Columbia action level of 1.0 mg/cm² on *one or more* layers of paint on a specific component.

Negative: Lead is not present at or above the District of Columbia action level of 1.0 mg/cm² in any layer of paint on a specific component.

The survey was conducted using the methodology recommended by the U.S. EPA/Department of Housing and Urban Development (HUD). It is important to note that this survey was not a

comprehensive, surface-by-surface evaluation, but rather a screening survey of major painted components, which may contain LBP.

Lead Wipe Sampling

F&R collected lead dust wipe samples in areas of the building with heavy ink staining. The samples were collected utilizing American Society for Testing and Materials (ASTM) Standard E1792-96a approved wipes and were collected within a one square foot template to determine the lead concentration in micrograms per square foot (ug/ft²). The samples were analyzed by EMSL Analytical, Inc. (EMSL) located in Beltsville, Maryland, an Environmental Lead Laboratory Accreditation Program (ELLAP) accredited laboratory, utilizing Flame Atomic Absorption Spectrometry (AAS) via EPA Method SW 846 3050B*/7000B).

2. Results

Lead-Based Paint Screening

A total of 48 readings were taken as part of this survey. Based on the results of this survey, the following surfaces should be assumed to contain LBP or lead-based glazing (defined as having a concentration above the District of Columbia Action Level of 1.0 milligrams per square centimeter):

- White ceramic wall tile in warehouse mezzanine level restrooms
- Orange and white metal I-Beams throughout
- Metal door lintels

The following surfaces were determined to contain lead-containing paint (paint with detectable lead concentrations but below the District of Columbia Action Level):

- Blue metal stair stringer in northeast corner stairwell
- Red metal lockers in warehouse mezzanine level locker rooms



Photograph 3: Metal window lintel with lead-based paint.



Photograph 4: Ceramic wall tile with lead-based glazing.

Lead Wipe Sampling

Please find the results of the lead wipe analysis in Table 3 below:

| TABLE 3 LEAD WIPE ANALYSIS | |
|-------------------------------------|------------------------|
| Sample Location | Lead Concentration |
| Central Garage Door Bay-East Wall | 12 ug/ft ² |
| Ink Mixing Tank Berm | 640 ug/ft ² |
| Central Main Warehouse Floor | <10 ug/ft ² |
| Warehouse Machine and Electric Shop | 14 ug/ft ² |
| Main Warehouse-East Wall | 11 ug/ft ² |

F&R is not aware of any lead in dust standards for a government or commercial use space such as this one. That being the case, F&R compared the results of the lead dust wipes to EPA/HUD standards for residential properties with children six years of age and under. All of the lead dust wipe samples collected contained lead concentrations below the EPA/HUD standard for floors with child occupied housing of 40 ug/ft² with the exception of the sample collected from the Ink Mixing Tank Berm area.



Photograph 5: Ink mixing tank berm with standing pools of ink.

3. Applicable Regulations and Recommendations

Lead-Based Paint

Positive and negative lead-based paint results are based on District of Columbia Guidelines. It is important to note that even if a component is negative based on the District of Columbia's standard, it may still contain concentrations of lead in the paint, which when disturbed, may generate lead dust greater than the Permissible Exposure Limit (PEL) of 50 micrograms per cubic millimeter (ug/m³) as an 8-hour Time Weighted Average (TWA) established by the OSHA "Lead Exposure in Construction Rule (29 CFR 1926.62)."

The OSHA standard gives no guidance on acceptable levels of lead in paint at which no exposure to airborne lead (above the action level) would be expected. Rather, OSHA defines airborne concentrations, and references specific types of work practices and operations from which a lead hazard may be generated (reference 29 CFR 1926.62, section d). Environmental and personnel monitoring should be conducted during any removal/demolition process (as appropriate) to verify that actual personal exposures are below the Permissible Exposure Limit (PEL). Under OSHA requirements, the contractor performing the work will be required to conduct this monitoring and follow all of the other requirements found under 29 CFR 1926.62.

Based on the levels of lead found on painted building components at the former Washington Times Warehouse, it is anticipated that these components can be disposed of as non-hazardous waste. However, it is recommended that a Toxic Characteristic Leaching Procedure (TCLP) sample of the waste stream from demolition and renovation activities be collected to verify compliance with Resource Conservation and Recovery Act (RCRA) regulations related to lead. Should painted components from this facility be sent to a recycling facility, this report should be made available to the accepting facility to properly notify them of the lead content of these components. Please note that compliance with RCRA regulations does not relieve the demolition contractor of the personnel air monitoring and respiratory protection required under 29 CFR 1926.62.

Lead Contamination From Printing Operations

F&R recommends that all areas of standing ink and sludge be remediated by a licensed hazardous waste contractor. The effectiveness of these efforts should be evaluated utilizing clearance through surface wipe sampling. Furthermore, F&R recommends that air sampling in this space be conducted prior to occupancy to determine if the printing operations have resulted in off-gassing of such contaminants as Volatile Organic Compounds (VOCs).

PCBS

1. Methodology

Light ballasts are the electrical components attached to fluorescent light fixtures usually found under a metal cover plate. Prior to 1978, ballasts were commonly manufactured with polychlorinated biphenyls (PCBs). PCBs were used in fluorescent light ballasts because of their electrical insulating properties. Ballasts made after 1978 are usually marked "Non-PCB." F&R conducted a visual non-invasive survey to identify if the "Non-PCB" label was present on ballasts throughout the building.

2. Results

F&R observed fluorescent lighting fixtures throughout the building and inspected a representative number for the "Non-PCB" label. F&R observed the "Non-PCB" label on all of the ballasts inspected. F&R recommends that all fluorescent light ballasts fixtures in the building that do not contain the "Non-PCB" label be assumed to contain PCBs. Ballasts with a clearly marked "Non-PCB" are not regulated and can be disposed of with general construction and demolition debris. The light fixtures without the "Non-PCB" labeling should be removed, disposed of and/or recycled according to Federal and District of Columbia waste disposal guidelines, by an appropriately licensed/certified contractor.

MERCURY-CONTAINING COMPONENTS

1. Methodology

Mercury is used in several building components including fluorescent lamps, high-intensity discharge (HID) lamps, thermostats and thermometers. F&R conducted a visual non-invasive survey to identify mercury-containing components throughout the building.

2. Results

During this survey, F&R personnel observed the following building components suspected to contain mercury in the surveyed portions of the building:

- Approximately one thousand, six hundred (1,600) fluorescent lamps located throughout the building
- Approximately forty (40) HID lamps located throughout the building
- Three (3) thermometers associated with mechanical equipment in the 1st floor warehouse space mechanical room
- Eight (8) thermostats throughout the building with mercury switches.

The mercury-containing building components that are to be impacted as part of renovation/demolition activities should be removed, disposed of and/or recycled according to Federal and District of Columbia hazardous waste disposal guidelines by an appropriately licensed/certified contractor.



Photograph 6: Thermostat with mercury-containing switches.



Photograph 7: Mercury-containing HID lamp.

MISCELLANEOUS NON-SCOPE ITEMS

During our survey, F&R observed chemicals, waste products, and stained walls and floors that were indicative of the building's former use as a printing facility. These items included:

- 55-gallon drums of solvents located throughout the building
- 55-gallon drums of used ink rags located throughout the building
- Photo processing chemicals in the northwest corner offices
- Ink stained walls and floors with the heaviest staining being in the ink tank mixing room and the photo processing room in the northwest corner offices
- Piping troughs in the main warehouse area with a heavy black sludge accumulated on the bottom

MPD Assessment Report
2850 New York Avenue, NE
Washington, DC

F&R recommends that all waste products be removed from the site by a licensed hazardous waste contractor. All chemicals that will not be utilized by the next building tenant should either be removed from the site by the current owner or disposed of by a licensed hazardous waste contractor. Should the next building tenant utilize any of the chemicals left on-site, these chemicals should be kept in an appropriate storage area such as a Flammable Cabinet.

Areas of the building with standing ink or sludge, specifically the ink tank mixing area, the photo processing room in the northwest corner offices, and the piping troughs located in the main warehouse area, should be remediated by a District of Columbia Licensed Hazardous Waste Contractor. The effectiveness of these efforts should be evaluated utilizing clearance through surface wipe sampling. Air sampling is recommended before the next tenant moves into this space to determine if the printing operations have resulted in off-gassing of such contaminants as Volatile Organic Compounds (VOCs).

Should any earth moving activities or dewatering activities take place on this site, it is recommended that the soil and groundwater on-site be evaluated to determine if the former printing operations have impacted soil and groundwater.



Photograph 8: Piping troughs with standing sludge in main warehouse.



Photograph 9: Photo processing room in northwest corner offices.

CONCLUSIONS AND RECOMMENDATIONS

F&R has the following recommendations to make in regards to hazardous materials at the former Washington Times warehouse:

| TABLE 4 HAZARDOUS MATERIALS RECOMMENDATION TABLE | | | | |
|---|--|--|--|--|
| Finding No. | Location | Issue | Regulation/Guideline | Recommendation |
| 1 | Exterior and Warehouse Mezzanine Offices | Asbestos-containing expansion joint caulk on building exterior, remnant black floor tile mastic in warehouse mezzanine offices, and suspect asbestos-containing metal fire doors on building exterior. | EPA National Emission Standard for Hazardous Air Pollutants (NESHAP) | These materials can be left in place under an Asbestos Operations & Maintenance (O&M) Program provided that these materials remain undamaged and are not impacted by renovation/demolition activities. If these materials become damaged or are to be impacted by renovation/demolition activities they should be removed by a District of Columbia Licensed Asbestos Abatement Contractor. |
| 2 | Throughout | Lead-based paint was identified on metal I-Beams throughout, metal window lintels throughout, and white ceramic wall tiles in the warehouse 2 nd floor offices. | EPA Resource Conservation and Recovery Act (RCRA)/OSHA Lead in Construction Rule | These materials can be left in place under a Lead Operations & Maintenance (O&M) Program provided that the paint/glazing on these surfaces remains in an undamaged condition. Should the paint or glaze on these surfaces become damaged these components should be repaired or replaced by a District of Columbia Licensed Lead Abatement Contractor. Any contractor impacting these surfaces during renovation or demolition activities should follow all worker protection requirements under the OSHA Lead in Construction Rule. |

**TABLE 4
 HAZARDOUS MATERIALS RECOMMENDATION TABLE**

| Finding No. | Location | Issue | Regulation/Guideline | Recommendation |
|-------------|------------|--|---|---|
| 3 | Throughout | Areas of pooled ink and sludge | EPA Resource Conservation and Recovery Act (RCRA) | F&R recommends that all areas of standing ink and sludge be remediated by a District of Columbia Licensed Hazardous Waste Contractor. The effectiveness of these efforts should be evaluated utilizing clearance through surface wipe sampling. Furthermore, F&R recommends that air sampling in this space be conducted prior to occupancy to determine if the printing operations have resulted in off-gassing of such contaminants as Volatile Organic Compounds (VOCs). |
| 4 | Throughout | Potentially PCB-containing light ballasts. | EPA Resource Conservation and Recovery Act (RCRA) | Ballasts can remain in place; however they should be checked for the "Non-PCB" label prior to disposal associated with renovation activities. Those ballasts that contain the label can be disposed of as non-hazardous waste. Those ballasts that do not contain the label should be disposed of PCB waste or recycled by a licensed hazardous waste contractor. |
| 5 | Throughout | The following building components are located within the building which are suspected to contain mercury: approximately 1,600 fluorescent light ballasts throughout the building, approximately 40 HID lamps throughout the building, 3 thermometers associated with mechanical equipment in the 1 st floor warehouse space, 8 thermostats throughout the building with mercury switches. | EPA Resource Conservation and Recovery Act (RCRA) | These components can stay in place, however if they are to be impacted by renovation or demolition activities they should either be recycled or disposed of as mercury-containing waste by a licensed hazardous waste contractor. |

**TABLE 4
 HAZARDOUS MATERIALS RECOMMENDATION TABLE**

| Finding No. | Location | Issue | Regulation/Guideline | Recommendation |
|-------------|------------|---|---|--|
| 6 | Throughout | Miscellaneous chemicals and wastes associated with printing operations. | EPA Resource Conservation and Recovery Act (RCRA) | <p>F&R recommends that all waste products be removed from the site by a licensed hazardous waste contractor. All chemicals that will not be utilized by the next building tenant should either be removed from the site by the current owner or disposed of by a licensed hazardous waste contractor. Should the next building tenant utilize any of the chemicals left on-site, these chemicals should be kept in an appropriate storage area such as a Flammable Cabinet.</p> <p>Areas of the building with standing ink or sludge, specifically the ink tank mixing area, the photo processing room in the northwest corner offices, and the piping troughs located in the main warehouse area, should be remediated by a licensed hazardous waste contractor. The effectiveness of these efforts should be evaluated utilizing clearance through surface wipe sampling. Air sampling is recommended before the next tenant moves into this space to determine if the printing operations have resulted in off-gassing of such contaminants as Volatile Organic Compounds (VOCs).</p> <p>Should any earth moving activities or dewatering activities take place on this site, it is recommended that the soil and groundwater on-site be evaluated to determine if the former printing operations have impacted soil and groundwater.</p> |

LIMITATIONS

This report has been prepared for the exclusive use by Atelier Architects and their associates. This service was performed in accordance with generally accepted environmental practices. No other warranty, expressed or implied, is made.

Our conclusions and recommendations are based, in part, upon information provided to us by others and on our site observations. We have not verified the completeness or accuracy of the information provided by others, unless otherwise noted. Our observations and recommendations are based upon conditions readily visible at the site at the time of our site visit, and upon current industry standards. During F&R's non-invasive inspection, accessible areas were visually surveyed for the presence of suspected ACM, LBP, PCB-containing Light Ballasts and Mercury-containing components. Inaccessible areas, such as behind solid walls or above solid ceiling were not surveyed and therefore suspected ACM may be present in those areas. Areas inspected for the above-referenced materials were limited to those designated by the client.

To preserve the integrity of the roof structure, the roofs were not sampled. The investigation was based on materials found in building above soil level. Any materials buried underneath the foundation were not accessible and will be considered to be an asbestos containing material until sampling rebuts the assumption.


During this study, suspect material samples were analyzed for asbestos and/or lead. As with any similar survey of this nature, actual conditions exist only at the precise locations from which suspect samples were collected. Certain inferences are based on the results of this sampling and related testing to form a professional opinion of conditions in areas beyond those from which the samples were collected. No other warranty, expressed or implied, is made.

Under this scope of services, F&R assumes no responsibility regarding response actions (e.g. O&M Plans, Encapsulation, Abatement, Removal, Notifications, etc.) initiated as a result of these findings. F&R assumes no liability for the duties and responsibilities of the Client with respect to compliance with these regulations. Compliance with regulations is the sole responsibility of the Client and should be conducted in accordance with local, state, and/or federal requirements, whichever is more stringent. All abatement activities or response actions should be performed by appropriately qualified and licensed-personnel and/or companies, as warranted.

Froehling & Robertson, Inc. by virtue of providing the services described in this report, does not assume the responsibility of the person(s) in charge of the site, or otherwise undertake responsibility for reporting to any local, state, or federal public agencies any conditions at the site that may present a potential danger to public health, safety, or the environment. The client agrees to notify the appropriate local, state, or federal public agencies as required by law, or otherwise to disclose, in a timely manner, any information that may be necessary to prevent any danger to public health, safety, or the environment. The contents of the report should not be construed in any way as a recommendation to purchase, sell, or develop the project site.

APPENDIX

FLOOD INSURANCE MAP





HAYES ARCHITECTS

Building Code Abstract 2006 IBC with [DCMR 12 Supplement](#)

Chapter 3 Use and Occupancy

Original Use: F-1 Factory Industrial Moderate Hazard
Existing Use: B Business
Proposed Use: Separated Mixed Use
A-3 Assembly (over 50 occupants / over 750 sf)
B Business
S-2 Storage / Enclosed Parking Garage

Chapter 4 Special Use and Occupancy

Motor-Vehicle-Related Occupancy
Enclosed Parking Garage
Floor sloped to drain or main door
Vehicle barriers per 1607.7
Hazardous Materials
Control Areas (4) with fire barriers

Chapter 5 Building Heights and Areas

Existing Height: 2 story / 25 feet
Allowable Area: 35,454 A-3 gsf (increase for sprinkler and frontage)
85,836 B gsf (increase for sprinkler and frontage)
97,032 S-2 gsf (increase for sprinkler and frontage)
Existing Area: 100,000 gsf 1st Floor
17,000 sf 2nd Floor
11,000 sf mezzanine
Incidental use Table 508.2: Storage > 100 sf / sprinkler
Furnace > 400,000 btu / boiler > 15 psi / sprinkler
Separation of Occupancies: B, S-2: 1 hour
A, B: 1 hour

Chapter 6 Types of Construction

Type of Construction: IIB Non-Combustible
Exterior Bearing Walls: 0 hour rated
Interior Bearing Walls: 0 hour rated
Exterior Non-Bearing Walls: 0 hour > 10 feet separation; 1 hour < 10 feet separation
Structural Frame: 0 hour rated
Floor: 0 hour rated
Roof: 0 hour rated

Chapter 7 Fire-Resistance-Rated Construction

707.4: 1 hour shaft enclosure stair connecting less than 4 stories with 1 hour door
706.5 fire barriers top of floor to underside of deck

Chapter 8 Interior Finishes

Class B materials in exits and corridors for A and B uses

Chapter 9 Fire Protection Systems

Automatic Sprinkler System: required / provided

Standpipes: Not required / not provided

Fire Alarm and Detection: Manual FA Required / provided (no manual pulls / sprinkler)

Generator Room fire detection required

Fire Extinguishers: required / provided

[Chapter 9A 908.0 coordination meeting prior to design of FA system](#)

Chapter 10 Means of Egress

Occupant Load:

1:50 locker rooms and exercise rooms

1:7 A-3 (concentrated / chairs)

1:100 gross business

1:300 gross storage / mechanical equipment

[F1011.5 post occupant load for assembly uses](#)

Number of Exits:

3 exits 1st story with 1/4 diagonal separation

2 exits mezzanine with 1/4 diagonal separation

Spaces with one exit < 50 occupants

2 exits boiler room > 500 sf / 40,000 btuh

Exit Enclosure:

1 hour stairs connecting less than 4 stories

use exit only as means of egress

[EX1003.6 tight fitting doors at stairway enclosure](#)

Travel Distance:

300 feet travel distance B Use (sprinkler protected)

400 feet travel distance S-2 Use (sprinkler protected)

250 feet travel distance A-3 Use (sprinkler protected)

100 feet common path of travel B Use (sprinkler protected)

75 feet for common path of travel

50 feet dead end B Use (sprinkler protected)

20 feet dead end

[EX605.6 dead end 35 feet \(75 feet for B and S-2 with sprinkler and fire alarm\)](#)

Egress Width:

36" occupant load < 50 occupants

44" minimum width

.2" per occupant stairs; .15" corridors / doors

Ceiling height:

7'-6" with 6'-8" projections

[EX601.3 minimum ceiling height shall be 7 feet](#)

Exit Access Corridors:

0 hour rated

Egress not through kitchens, storage, closets

Change in elevation <12" with ramp

Door width: 32" clear opening; side opening or power operated
Swing in direction of travel > 50 occupants
Level landings (2% max) 44" minimum
Panic hardware > 50 occupants; electrical rooms over
1200 amps

Stairs: 44" width
36" width < 50 occupants; 24" to equipment
11" tread and 7" riser (4" minimum riser)
Section 3403.4 allows existing stairs if space and
construction will not permit rebuilding
guardrail to meet 42" height and 4" spacing
handrails on both sides of stairs
alternating tread device access to unoccupied roof
[1005A signs at interior stairs for level and direction](#)

Means of Egress Illumination: 90 minute emergency lighting 1 fc; emergency lighting for
exit signs / means of egress / exit discharge / exterior landings

Chapter 11 Accessibility

Existing buildings to comply with Section 3409
[DC deletes Chapter 34](#)

Chapter 12 Interior Environment

7'-6" ceiling height (7'-0" at toilet and storage rooms)
non-absorbent floor and 6" up wall; 2'-0"

Chapter 16 Structural Design

[EX1006.1 code official authorized to accept existing floors and approve operational
controls that limit the live load on any such floor](#)

Chapter 27 Electrical Systems

Generator installation per NFPA 110 and International Fire Code

Chapter 28 Mechanical Systems

[EX609.1 Mechanical system work to comply with requirements of District of Columbia
Mechanical Code](#)

Chapter 29 Plumbing Systems

Assembly Use: 1 water closet per 125 men and 65 women
1 lavatory per 200 men and women
Business Use: 1 water closet per 25 men and women
1 lavatory per 40 men and women
separate facilities for men and women > 15 occupants
no more than 1 story travel to facilities
[EX1005.4.1 at least one accessible toilet room](#)

EX610.1 where occupant load in a story increased 20%, plumbing fixtures provided per plumbing code

Chapter 30 Elevators

Hoistway shaft enclosure per Section 707

Chapter 34 Existing Structures (DC deletes Chapter 34)

3409.4 accessible entrance, route to primary function, signage, parking

3410.4 Structural analysis required

Chapter 3J Classification of Work

EX306.2 follow Chapter 8

Chapter 5J Alterations – Level 1

EX503.1 Flame spread requirements of building code

EX506 Meet building code for accessibility unless technically infeasible

Chapter 6J Alterations – Level 2

EX601.2 meet Level I requirements

EX601.3 minimum ceiling height shall be 7 feet

EX603.5.2 guards per building code

EX603.6 corridors for B Use with required capacity greater than 50 to comply with building code

EX604.2.2 sprinkler or mixed use with 1 hour separation from sprinkler / non-sprinkler

EX605.3.2 mezzanine >50 occupants / 100 feet travel (sprinkler) 2 exits

EX605.6 dead end 35 feet (75 feet for B and S-2 with sprinkler and fire alarm)

EX609.1 Mechanical systems work to comply with requirements of District of Columbia Mechanical Code

EX610.1 where occupant load in a story increased 20%, plumbing fixtures provided per plumbing code

Chapter 7J Alterations – Level 3

EX701.2 meet Level 1 and Level 2 requirements

EX709.1 if costs exceed 50% assessed value, downspouts not to be connected to sanitary or combined storm / sanitary sewer if feasible to conform to storm water discharge of P-1101.2.2

Chapter 8J Change in Use

EX812.1 follow Chapter 7 Alterations

Chapter 12J Compliance Alternatives

Similar to Chapter 34 of IBC for evaluation

Zoning Code Abstract

Property Address: 2850 New York Avenue, NE
Washington, DC 20002

Historic District: No

Zone: M General Industry

Lot Size: 6.7Acres

Maximum FAR: 6.0

Existing Use: Business

Proposed Use: Business / Parking Garage

External Effects: per Section 825

Allowable Height: 90 feet

Existing Height: 25 feet / 2 stories

Setbacks:

- Side: none
- Rear: none 20 feet above grade: 2.5" / foot / 12 feet minimum

Required Parking:

- Office: 1 per 800 gsf / 123 spaces


Parking provided: 192 spaces cars
27 spaces trucks

Required Loading: 2 berths 12' x 30'
2 platforms 100 sf
1 delivery space 15' x 20'


Loading Provided: 13 berths 12' x 30'
4 platforms 100 sf

Parking Garages: no vehicular entrance or exit nearer than 40' to a street
intersection as measured from the intersection of the curb
lines extended


Parking Lots: no vehicular entrance or exit nearer than 40' to a street
intersection as measured from the intersection of the curb
lines extended
Lighting used to illuminate a parking lot confined to the
surface of the lot



EXISTING 1ST FLOOR PLAN



EXISTING 2ND FLOOR / MEZZANINE FLOOR PLAN



LOT STAKE OUT

LOT 12
SQUARE 4373

APPROVED FOR THE CITY OF WASHINGTON
DATE: 1/1/1917

BY: [Signature]

SCALE: 1" = 20'

THESE PLANS HAVE BEEN APPROVED BY THE BOARD OF PUBLIC WORKS OF THE DISTRICT OF COLUMBIA, SUBJECT TO THE FOLLOWING CONDITIONS:

1. The contractor shall be responsible for the accuracy of the field work.
2. The contractor shall be responsible for the accuracy of the dimensions shown on the plans.
3. The contractor shall be responsible for the accuracy of the location of the lines shown on the plans.
4. The contractor shall be responsible for the accuracy of the location of the corners shown on the plans.
5. The contractor shall be responsible for the accuracy of the location of the center lines shown on the plans.
6. The contractor shall be responsible for the accuracy of the location of the right-of-way lines shown on the plans.
7. The contractor shall be responsible for the accuracy of the location of the utility lines shown on the plans.
8. The contractor shall be responsible for the accuracy of the location of the existing structures shown on the plans.
9. The contractor shall be responsible for the accuracy of the location of the proposed structures shown on the plans.
10. The contractor shall be responsible for the accuracy of the location of the proposed parking areas shown on the plans.

APPROVED FOR THE CITY OF WASHINGTON
DATE: 1/1/1917

BY: [Signature]

APPROVED FOR THE CITY OF WASHINGTON
DATE: 1/1/1917

BY: [Signature]

APPROVED FOR THE CITY OF WASHINGTON
DATE: 1/1/1917

BY: [Signature]

WE Bowers Inc. Roof Top Unit Assessment Forms and Summary

On July 07, 08 and 09, 2010; WE Bowers performed diagnostic service work on Roof Top Units 301 thru 309 at the 2850 New York Avenue Building. Due to the high outdoor air temperature the controls in the units would not allow for the gas furnaces to come on. The Technician's work sheets are attached here in. The summary of their findings are as follows:

RTU #301

Circuit 1 low on refrigerant, circuit is leaking and needs repaired

RTU #302

Bad thermostat
Bad Compressor #1
Condenser fan #3 bad
Circuit #2 low on refrigerant, check for leak and repair
Pressure wash condenser coil

RTU #303

Contactors for Compressor #1 needs replaced
Bad Condenser Fan cycle switch in circuit #1
Circuit #2 low on refrigerant, find leak and repair

RTU 304

Circuit #1 and #2 low on refrigerant, check for leak and repair
Pressure wash condenser coil

RTU #305

Bad Compressor #2 module protection
Condenser fan cycle switch bad, circuit #2
Circuit #1 low on refrigerant, check for leak and repair

RTU #306

Compressor #2 off on low pressure
Compressor #1 operates but trips on high pressure control
Circuit #2 low on refrigerant, check for leak and repair
Pressure wash condenser coil

RTU #307

Condenser fan #3 bad

RTU #308

All components good, system operated normally

RTU #309

Both blower and compressor contactors are bad and need to be replaced

In the design phase of the project if it is determined that any of these units are to be reused then the repairs noted above will have to be made before the units can be placed back into service.

BOWERS

W.E. Bowers, Inc.
 Mechanical Construction,
 HVAC and Plumbing Service

12401 Kiln Court • Suite A
 Beltsville, MD 20705
 301 • 419 • 2488
 Service Fax: 301 • 419 • 2310

| T/S | Qty. | Description of Materials |
|-----|------|--------------------------|
| / | | |

Vacuum Pump and Oil Oil Disposal
 Oxy-Acetylene/Nitro Reclaim/Recovery

| Make | Unit | MN # | SN # |
|------|------|------|------|
| / | | | |

| Make | Unit | MN # | SN # |
|------|------|------|------|
| / | | | |

SUBCONTRACTORS USED

Billing Name _____ Date of Labor 7/9/10
 Customer Name WASHINGTON TIME BLDG. Customer PO # _____
 Site Location New York Ave Bowers WO # 100707-0003
WASHINGTON D.C. Job # _____

Description of Work Performed

Checks operation of 9 TRANE RTU AT
 THE OLD WASHINGTON TIME BUILDING. INSPECTED
 Blower section, Air in fan and belt tension.
 Ran units in cooling mode, checked operation
 and force settings. trouble shot units that
 was present, found the cause and used
 pressure on the expansion system. See
 expansion report for details.
 - NOT ABLE TO CHECK units in heat this even-
 ing. Awaiting unit order and indoor temp.

JOB COMPLETE JOB INCOMPLETE PRICING REQUESTED SUPERVISOR FOLLOW-UP

| Service Techs / Plumbers / Helpers | RT | OT | Bowers PO# |
|------------------------------------|----|----|------------|
| PHUONG ALUYEN 7/7/10 | 8 | | |
| PHUONG ALUYEN 7/8/10 | 8 | | |
| PHUONG ALUYEN 7/9/10 | 8 | | |

The undersigned acknowledges the work described above was ordered by him and that the material and labor hours and other items should meet with his approval.

Signed WASHINGTON TIME BLDG. Date: 7/9/10

Print Name DEPT. REFUSES TO SIGN



W.E. Bowers, Inc.
 Mechanical Construction,
 Plumbing and HVAC Service

12401 Kiln Court • Suite A
 Beltsville, MD 20705
 301 • 419 • 2488
 Construction Fax: 301 • 419 • 2711
 Service Fax: 301 • 419 • 2310

RTU # 301 OAT: 99°F

Date: 7/7/10 Technician: PHUONG NGUYEN

Manufacturer: TRANE Model # SENCC754HC8 Serial # 587F71881
 Filter Size and Quantity: 35-16X20X2 Belt Size and Quantity: 2-CX1012
 Voltage L1-L2: 463 L2-L3: 465 L1-L3: 465

1. Space Temp: 85 °F Space Temp Setpoint: 70 °F
2. Lower temperature setpoint to initiate a call for cooling
3. Compressor #1 amp draw loaded L1: 43.8 L2: 42.9 L3: 44.0 FLA: 72
4. Compressor #1 amp draw unloaded L1: L2: L3:
5. Compressor #2 amp draw loaded L1: 71.9 L2: 74.2 L3: 72.6 FLA: 72
6. Compressor #2 amp draw unloaded L1: L2: L3:
7. Compressor #1 High pressure: 220 psi Low pressure: 21 psi
 Superheat: 60 °F Subcooling: 7 °F
8. Compressor #2 High pressure: 351 psi Low pressure: 71 psi
 Superheat: 21 °F Subcooling: 23 °F
9. Full Cooling Return air temp: 85 °F Discharge air temp: 73 °F Evaporator Δ T: 13 °F
10. Raise temperature to call for heat
11. Heat #1 amps L1: L2: L3: FLA:
12. Heat #2 amps L1: L2: L3: FLA:
13. Full Heating Return air temp: °F Discharge air temp: °F Entering/Leaving Air Δ T: °F
14. Return setpoint to normal
15. Blower motor amps: L1: 36.0 L2: 35.1 L3: 34 FLA: 52.8
16. Belts changed OK Yes No
17. Filters changed OK Yes No
18. Condensate drain lines clear and free flowing? Yes No
19. Add condensate pan tablets? Yes No
20. Electrical connections tight? Yes No
21. Contactor contact points? Pass Fail

Notes: - Circuit #1 was low on ref. need to leak check and repair leak.
- Not able to check the heat mode due to high space temp.



W.E. Bowers, Inc.
 Mechanical Construction,
 Plumbing and HVAC Service

12401 Kiln Court • Suite A
 Beltsville, MD 20705
 301 • 419 • 2488
 Construction Fax: 301 • 419 • 2711
 Service Fax: 301 • 419 • 2310

RTU # 302 OAT: 80°F

Date: 7/9/10 Technician: FRANK NGUYEN

Manufacturer: TRANE Model # SFHCC754HC83 Serial # 587E71885
 Filter Size and Quantity: 35-16X20X2 Belt Size and Quantity: 2- CXP09
 Voltage L1-L2: 465 L2-L3: 465 L1-L3: 464

1. Space Temp: 80 °F Space Temp Setpoint: 70 °F
2. Lower temperature setpoint to initiate a call for cooling
3. Compressor #1 amp draw loaded L1: BAD COMPRESSOR FLA: 72
4. Compressor #1 amp draw unloaded L1: _____ L2: _____ L3: _____
5. Compressor #2 amp draw loaded L1: 38.1 L2: 38.5 L3: 40.1 FLA: 72
6. Compressor #2 amp draw unloaded L1: _____ L2: _____ L3: _____
7. Compressor #1 High pressure: _____ psi Low pressure: _____ psi
 Superheat: _____ °F Subcooling: _____ °F
8. Compressor #2 High pressure: 160 psi Low pressure: 14 psi
 Superheat: _____ °F Subcooling: _____ °F
9. Full Cooling Return air temp: _____ °F Discharge air temp: _____ °F Evaporator Δ T: _____ °F
10. Raise temperature to call for heat
11. Heat #1 amps L1: _____ L2: _____ L3: _____ FLA: _____
12. Heat #2 amps L1: _____ L2: _____ L3: _____ FLA: _____
13. Full Heating Return air temp: _____ °F Discharge air temp: _____ °F Entering/Leaving Air Δ T: _____ °F
14. Return setpoint to normal
15. Blower motor amps: L1: 38.3 L2: 39.5 L3: 39.8 FLA: 58.2
16. Belts changed OK Yes No
17. Filters changed OK Yes No
18. Condensate drain lines clear and free flowing? Yes No
19. Add condensate pan tablets? Yes No
20. Electrical connections tight? Yes No
21. Contactor contact points? Pass Fail

Notes: - BAD T-STAT
- BAD COMP #1
- BAD CIRCUIT #1 COND. FAN MOTOR # 2
- CIRCUIT # 2 WAS LOW ON REF. NEED TO LEAK
CHECK AND REPAIR.
- RECOMMENDS TO PRESS. WASH THE COND. COIL.

RTU # 303

OAT: 90.2°F

Date: 7/8/10 Technician: PHILIP W. WILSON

Manufacturer: TRANE Model # SEHC0754H083 Serial # 587F7185
 Filter Size and Quantity: 25-16x20x2 Belt Size and Quantity: 2-CX105
 Voltage L1-L2: 464 L2-L3: 465 L1-L3: 465

1. Space Temp: 84 °F Space Temp Setpoint: 70 °F
2. Lower temperature setpoint to initiate a call for cooling
3. Compressor #1 amp draw loaded L1: 60.1 L2: 59.8 L3: 60.5 FLA: 72
4. Compressor #1 amp draw unloaded L1: _____ L2: _____ L3: _____
5. Compressor #2 amp draw loaded L1: 37.6 L2: 36.9 L3: 37.1 FLA: 72
6. Compressor #2 amp draw unloaded L1: _____ L2: _____ L3: _____
7. Compressor #1 High pressure: 270 psi Low pressure: 52 psi
 Superheat: 27 °F Subcooling: 18 °F
8. Compressor #2 High pressure: 200 psi Low pressure: 20 psi
 Superheat: _____ °F Subcooling: 18 °F
9. Full Cooling Return air temp: 84 °F Discharge air temp: 73 °F Evaporator Δ T: 11 °F
10. Raise temperature to call for heat
11. Heat #1 amps L1: _____ L2: _____ L3: _____ FLA: _____
12. Heat #2 amps L1: _____ L2: _____ L3: _____ FLA: _____
13. Full Heating Return air temp: _____ °F Discharge air temp: _____ °F Entering/Leaving Air Δ T: _____ °F
14. Return setpoint to normal
15. Blower motor amps: L1: 30.4 L2: 30.5 L3: 24.7 FLA: 52.8
16. Belts changed OK Yes No
17. Filters changed OK Yes No
18. Condensate drain lines clear and free flowing? Yes No
19. Add condensate pan tablets? Yes No
20. Electrical connections tight? Yes No
21. Contactor contact points? Pass Fail

Notes: - NEED TO REPLACE COMPRESSOR CONTACTOR (BUBBING BAD SPACES TO A 120V coil).
- BAD COND. FAN CYCLE SWITCH IN CIRCUIT #1 (RTSPT)
- CIRCUIT #2 WAS LOW ON REF. NEED TO LEAK CHECK AND REPAIR.

RTU # 304

CAT: 85° F

Date: 7/9/10 Technician: PHUONG NGUYEN

Manufacturer: TRANE Model # 5FHCCT54H08 Serial # 582F71850
Filter Size and Quantity: 35-16X20X2 Belt Size and Quantity: 2-CX109
Voltage L1-L2: _____ L2-L3: _____ L1-L3: _____

1. Space Temp: 85 °F Space Temp Setpoint: 70 °F
2. Lower temperature setpoint to initiate a call for cooling
3. Compressor #1 amp draw loaded L1: SYSTEM L2: FLAT L3: _____ FLA: 72
4. Compressor #1 amp draw unloaded L1: _____ L2: _____ L3: _____
5. Compressor #2 amp draw loaded L1: SYSTEM L2: FLAT L3: _____ FLA: 72
6. Compressor #2 amp draw unloaded L1: _____ L2: _____ L3: _____
7. Compressor #1 High pressure: _____ psi Low pressure: _____ psi
Superheat: _____ °F Subcooling: _____ °F
8. Compressor #2 High pressure: _____ psi Low pressure: _____ psi
Superheat: _____ °F Subcooling: _____ °F
9. Full Cooling Return air temp: _____ °F Discharge air temp: _____ °F Evaporator Δ T: _____ °F
10. Raise temperature to call for heat
11. Heat #1 amps L1: _____ L2: _____ L3: _____ FLA: _____
12. Heat #2 amps L1: _____ L2: _____ L3: _____ FLA: _____
13. Full Heating Return air temp: _____ °F Discharge air temp: _____ °F Entering/Leaving Air Δ T: _____ °F
14. Return setpoint to normal
15. Blower motor amps: L1: 41.5 L2: 40.0 L3: 42.0 FLA: 58.2
16. Belts changed OK Yes No
17. Filters changed OK Yes No
18. Condensate drain lines clear and free flowing? Yes No
19. Add condensate pan tablets? Yes No
20. Electrical connections tight? Yes No
21. Contactor contact points? Pass Fail

Notes: CIRCUIT #1 - FLAT, NEEDS TO LEAK CHECK AND REPAIR.
CIRCUIT #2 - FLAT, NEEDS TO LEAK CHECK AND REPAIR.
RECOMMEND TO PREP. WASH THE COILS.

RTU # 305 OAT: 97°F

Date: 7/8/10 Technician: PHUONG NGUYEN

Manufacturer: TRANE Model # 2FHCC754HC72 Serial # 587E7854
Filter Size and Quantity: 35-16x20x2 Belt Size and Quantity: 2-CX103
Voltage L1-L2: 463 L2-L3: 466 L1-L3: 465

1. Space Temp: 85 °F Space Temp Setpoint: 70 °F
2. Lower temperature setpoint to initiate a call for cooling
3. Compressor #1 amp draw loaded L1: 40.2 L2: 41.2 L3: 40.2 FLA: 52.2
4. Compressor #1 amp draw unloaded L1: L2: L3:
5. Compressor #2 amp draw loaded L1: L2: L3: FLA: 72
6. Compressor #2 amp draw unloaded L1: L2: L3:
7. Compressor #1 High pressure: 220 psi Low pressure: 17 psi
Superheat: °F Subcooling: °F
8. Compressor #2 High pressure: 355 psi Low pressure: 68 psi
Superheat: 35 °F Subcooling: 28 °F
9. Full Cooling Return air temp: 85 °F Discharge air temp: 77 °F Evaporator Δ T: 8 °F
10. Raise temperature to call for heat
11. Heat #1 amps L1: L2: L3: FLA:
12. Heat #2 amps L1: L2: L3: FLA:
13. Full Heating Return air temp: °F Discharge air temp: °F Entering/Leaving Air Δ T: °F
14. Return setpoint to normal
15. Blower motor amps: L1: 27.7 L2: 28.6 L3: 26.1 FLA: 52.8
16. Belts changed OK Yes No
17. Filters changed OK Yes No
18. Condensate drain lines clear and free flowing? Yes No
19. Add condensate pan tablets? Yes No
20. Electrical connections tight? Yes No
21. Contactor contact points? Pass Fail

Notes: - CIRCUIT #1 WAS LOW ON REF.
- FOUND BAD COMP #2 MODULE PROTECTION
- BAD CIRCUIT #2 CONDENSER FAN CYCLE SWITCH



W.E. Bowers, Inc.
 Mechanical Construction,
 Plumbing and HVAC Service

12401 Kiln Court • Suite A
 Beltsville, MD 20705
 301 • 419 • 2488
 Construction Fax: 301 • 419 • 2711
 Service Fax: 301 • 419 • 2310

RTU # 306 OAT: 96.5°F

Date: 7/2/10 Technician: PHUONG NGUYEN

Manufacturer: TRANE Model # SFHDC754H Serial # 587E71853
 Filter Size and Quantity: 35-16x20x2 Belt Size and Quantity: 2-CX112
 Voltage L1-L2: 46.8 L2-L3: 47.0 L1-L3: 47.2

1. Space Temp: 87° °F Space Temp Setpoint: 70° °F
2. Lower temperature setpoint to initiate a call for cooling
3. Compressor #1 amp draw loaded L1: 75 L2: 77 L3: 74.8 FLA: 72
4. Compressor #1 amp draw unloaded L1: _____ L2: _____ L3: _____
5. Compressor #2 amp draw loaded L1: OFF L2: OFF L3: OFF FLA: 72
6. Compressor #2 amp draw unloaded L1: _____ L2: _____ L3: _____
7. Compressor #1 High pressure: 375 psi Low pressure: 77 psi
 Superheat: N/A °F Subcooling: N/A °F
8. Compressor #2 High pressure: N/A psi Low pressure: N/A psi
 Superheat: N/A °F Subcooling: N/A °F
9. Full Cooling Return air temp: 87° °F Discharge air temp: 87° °F Evaporator Δ T: _____ °F
10. Raise temperature to call for heat
11. Heat #1 amps L1: _____ L2: _____ L3: _____ FLA: _____
12. Heat #2 amps L1: _____ L2: _____ L3: _____ FLA: _____
13. Full Heating Return air temp: _____ °F Discharge air temp: _____ °F Entering/Leaving Air Δ T: _____ °F
14. Return setpoint to normal
15. Blower motor amps: L1: 22.3 L2: 23.0 L3: 24.5 FLA: 52
16. Belts changed OK Yes No
17. Filters changed OK Yes No
18. Condensate drain lines clear and free flowing? Yes No
19. Add condensate pan tablets? Yes No
20. Electrical connections tight? Yes No
21. Contactor contact points? Pass Fail

Notes: - COMP #1 OPERATED ON HIGH PRESS. AND TRIPPED OUT ON HI PRESS. CONTROL.
- COMP #2 WAS OFF ON LOW PRESS. SWITCH. SYSTEM IN FLTH. NEED TO DO A CHECK AND REPAIR.
- NEED TO CLEAN THE COND. COIL.
- NOT ABLE TO CHECK HEAT MODE DUE TO HIGH SPACE TEMP.

RTU # ³⁰⁷ ~~514~~

OAT: 80°F

Date: 7/8/10 Technician: PHUONG NGUYEN

Manufacturer: TRANE Model # BYC170B4HACA Serial # B37144143D
Filter Size and Quantity: 10-14x20x1 Belt Size and Quantity: 1-Bx63
Voltage L1-L2: 463 L2-L3: 465 L1-L3: 464

1. Space Temp: 86° °F Space Temp Setpoint: 70° °F
2. Lower temperature setpoint to initiate a call for cooling
3. Compressor #1 amp draw loaded L1: 9.2 L2: 8.8 L3: 9.7 FLA: 11.2
4. Compressor #1 amp draw unloaded L1: ← L2: ← L3: ←
5. Compressor #2 amp draw loaded L1: 10.2 L2: 9.1 L3: 10.9 FLA: 11.2
6. Compressor #2 amp draw unloaded L1: ← L2: ← L3: ←
7. Compressor #1 High pressure: 285 psi Low pressure: 78 psi
Superheat: 13 °F Subcooling: 15 °F
8. Compressor #2 High pressure: 890 psi Low pressure: 77 psi
Superheat: 12 °F Subcooling: 18 °F
9. Full Cooling Return air temp: 86 °F Discharge air temp: 69 °F Evaporator Δ T: 17 °F
10. Raise temperature to call for heat
11. Heat #1 amps L1: ← L2: ← L3: ← FLA: ←
12. Heat #2 amps L1: ← L2: ← L3: ← FLA: ←
13. Full Heating Return air temp: ← °F Discharge air temp: ← °F Entering/Leaving Air Δ T: ← °F
14. Return setpoint to normal
15. Blower motor amps: L1: 5.9 L2: 6.0 L3: 5.8 FLA: 6.8
16. Belts changed OK Yes No
17. Filters changed OK Yes No
18. Condensate drain lines clear and free flowing? Yes No
19. Add condensate pan tablets? Yes No
20. Electrical connections tight? Yes No
21. Contactor contact points? Pass Fail

Notes: - BAD COND. FAN #3
- NOT ABLE TO CHECK THE HEAT MAKE, DUE TO
HIGH SPACE TEMP.

RTU # 208 OAT: 95°F

Date: 7/7/10 Technician: PHUONG LIAVEN

Manufacturer: TRANE Model # SEHFE204LBR Serial # C07M12498
Filter Size and Quantity: 12-20x20x2 Belt Size and Quantity: 2-BX7
Voltage L1-L2: 464 L2-L3: 466 L1-L3: 464

1. Space Temp: 86° °F Space Temp Setpoint: 70° °F
2. Lower temperature setpoint to initiate a call for cooling
3. Compressor #1 amp draw loaded L1: 15.1 L2: 14.5 L3: 14.3 FLA: 18.2
4. Compressor #1 amp draw unloaded L1: 15.1 L2: 14.5 L3: 14.3
5. Compressor #2 amp draw loaded L1: 15.1 L2: 14.5 L3: 14.3 FLA: _____
6. Compressor #2 amp draw unloaded L1: _____ L2: _____ L3: _____
7. Compressor #1 High pressure: 300 psi Low pressure: 74 psi
Superheat: 12 °F Subcooling: 20 °F
8. Compressor #2 High pressure: 300 psi Low pressure: 74 psi
Superheat: 12 °F Subcooling: 20 °F
9. Full Cooling Return air temp: 86° °F Discharge air temp: 63.8 °F Evaporator Δ T: 21.7 °F
10. Raise temperature to call for heat
11. Heat #1 amps L1: _____ L2: _____ L3: _____ FLA: _____
12. Heat #2 amps L1: _____ L2: _____ L3: _____ FLA: _____
13. Full Heating Return air temp: _____ °F Discharge air temp: _____ °F Entering/Leaving Air Δ T: _____ °F
14. Return setpoint to normal
15. Blower motor amps: L1: 7.2 L2: 7.2 L3: 7.0 FLA: 13.8
16. Belts changed OK Yes No
17. Filters changed OK Yes No
18. Condensate drain lines clear and free flowing? Yes No
19. Add condensate pan tablets? Yes No
20. Electrical connections tight? Yes No
21. Contactor contact points? Pass Fail

Notes: All operations normal. Not able to check system holding mode due to high space temp. (Gas Heat)

RTU # 309 OAT: 85°F

Date: 7/9/10 Technician: PHILIP W. WATSON

Manufacturer: TRANE Model # RYK048G4H00R Serial # B35143180A
 Filter Size and Quantity: 1-16x30x1 Belt Size and Quantity: 3/8" 1/2"
 Voltage L1-L2: 464 L2-L3: 464 L1-L3: 465

1. Space Temp: 83° °F Space Temp Setpoint: 20° °F
2. Lower temperature setpoint to initiate a call for cooling
3. Compressor #1 amp draw loaded L1: 5.3 L2: 5.0 L3: 5.2 FLA: 8.0
4. Compressor #1 amp draw unloaded L1: _____ L2: _____ L3: _____
5. Compressor #2 amp draw loaded L1: _____ L2: _____ L3: _____ FLA: _____
6. Compressor #2 amp draw unloaded L1: _____ L2: _____ L3: _____
7. Compressor #1 High pressure: 240 psi Low pressure: 62 psi
 Superheat: 29 °F Subcooling: 14 °F
8. Compressor #2 High pressure: _____ psi Low pressure: _____ psi
 Superheat: _____ °F Subcooling: _____ °F
9. Full Cooling Return air temp: 81.5 °F Discharge air temp: 62.7 °F Evaporator Δ T: 19 °F
10. Raise temperature to call for heat
11. Heat #1 amps L1: _____ L2: _____ L3: _____ FLA: _____
12. Heat #2 amps L1: _____ L2: _____ L3: _____ FLA: _____
13. Full Heating Return air temp: _____ °F Discharge air temp: _____ °F Entering/Leaving Air Δ T: _____ °F
14. Return setpoint to normal
15. Blower motor amps: L1: 1.7 L2: 1.0 L3: 1.3 FLA: 1.6
16. Belts changed NONE Yes [] No
17. Filters changed OK Yes [] No
18. Condensate drain lines clear and free flowing? Yes No []
19. Add condensate pan tablets? Yes [] No
20. Electrical connections tight? Yes No []
21. Contactor contact points? Pass [] Fail

Notes: - NEED TO REPLACE BOTH BLOWER AND COMP.
CONTACTORS (3 poles 25A 24V coil 2 poles 20A 24V coil)



EMSL Analytical, Inc.

10768 Baltimore Avenue, Beltsville, MD 20705

Phone: (301) 937-5700 Fax: (301) 937-5701 Email: beltsvillelab@emsl.com

Attn: **Alan Lederman**
Froehling & Robertson
7798 Waterloo Road
Jessup, MD 20794

Customer ID: FROE62
Customer PO:
Received: 07/13/10 2:30 PM
EMSL Order: 191006538

Fax: (443) 733-1015 Phone: (443) 733-1011
Project: **2850 NEW YORK AVE**

EMSL Proj:
Analysis Date: 7/14/2010


Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|----------------------------------|---------------------------------|---|--------------|--------------------------|----------------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 2850-01 <i>191006538-0001</i> | 12X12 WHT VFT W/ BLK FLECKS | Gray Non-Fibrous Heterogeneous | | 100% Non-fibrous (other) | None Detected |
| 2850-02 <i>191006538-0002</i> | BLK MSTC | Brown/Black Non-Fibrous Heterogeneous | 8% Cellulose | 92% Non-fibrous (other) | None Detected |
| 2850-03 <i>191006538-0003</i> | 12X12 BLUE VFT W/ WHT FLECKS | Blue Non-Fibrous Heterogeneous | | 100% Non-fibrous (other) | None Detected |
| 2850-04 <i>191006538-0004</i> | BLK MSTC | Black Non-Fibrous Heterogeneous | 5% Cellulose | 95% Non-fibrous (other) | None Detected |
| 2850-05 <i>191006538-0005</i> | 12X12 GRAY W/ BLK FLECKS | Gray Non-Fibrous Heterogeneous | | 100% Non-fibrous (other) | None Detected |
| 2850-06 <i>191006538-0006</i> | BRN MSTC | Brown Non-Fibrous Heterogeneous | 5% Cellulose | 95% Non-fibrous (other) | None Detected |
| 2850-07 <i>191006538-0007</i> | 12X12 SOLID GRAY VFT | Gray Non-Fibrous Heterogeneous | | 100% Non-fibrous (other) | None Detected |

Initial report from 07/14/2010 12:28:25

Analyst(s)

Alexis Turner (35)



Joe Centifonti, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.
Samples analyzed by EMSL Analytical, Inc. 10768 Baltimore Avenue, Beltsville MD NVLAP Lab Code 200293-0



EMSL Analytical, Inc.

10768 Baltimore Avenue, Beltsville, MD 20705

Phone: (301) 937-5700 Fax: (301) 937-5701 Email: beltsvillelab@emsl.com

Attn: **Alan Lederman**
Froehling & Robertson
7798 Waterloo Road
Jessup, MD 20794

Customer ID: FROE62
Customer PO:
Received: 07/13/10 2:30 PM
EMSL Order: 191006538

Fax: (443) 733-1015 Phone: (443) 733-1011
Project: **2850 NEW YORK AVE**

EMSL Proj:
Analysis Date: 7/14/2010


Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|----------------------------------|------------------------------|--|----------------------------|--------------------------|----------------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 2850-08 <i>191006538-0008</i> | TAN MSTC | Yellow Non-Fibrous Heterogeneous | | 100% Non-fibrous (other) | None Detected |
| 2850-09 <i>191006538-0009</i> | 12X12 GRAY W/ WHT FLECKS | Gray Non-Fibrous Heterogeneous | | 100% Non-fibrous (other) | None Detected |
| 2850-10 <i>191006538-0010</i> | TAN CARPET MSTC | Brown Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 2850-11 <i>191006538-0011</i> | DRYWALL 2ND FL OFFICES | Brown/Gray Non-Fibrous Heterogeneous | 15% Cellulose | 85% Non-fibrous (other) | None Detected |
| 2850-12 <i>191006538-0012</i> | JOINT CMPD 2ND FL OFFICES | White Non-Fibrous Heterogeneous | | 100% Non-fibrous (other) | None Detected |
| 2850-13 <i>191006538-0013</i> | 2X2 CT 2ND FL OFFICES | Gray/White Fibrous Heterogeneous | 50% Cellulose 40% Glass | 10% Non-fibrous (other) | None Detected |
| 2850-14 <i>191006538-0014</i> | DRYWALL 1ST FL OFFICES | White Non-Fibrous Heterogeneous | 15% Cellulose | 85% Non-fibrous (other) | None Detected |

Initial report from 07/14/2010 12:28:25

Analyst(s)

Alexis Turner (35)



Joe Centifonti, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.
Samples analyzed by EMSL Analytical, Inc. 10768 Baltimore Avenue, Beltsville MD NVLAP Lab Code 200293-0



EMSL Analytical, Inc.

10768 Baltimore Avenue, Beltsville, MD 20705

Phone: (301) 937-5700 Fax: (301) 937-5701 Email: beltsvillelab@emsl.com

Attn: **Alan Lederman**
Froehling & Robertson
7798 Waterloo Road
Jessup, MD 20794

Customer ID: FROE62
Customer PO:
Received: 07/13/10 2:30 PM
EMSL Order: 191006538

Fax: (443) 733-1015 Phone: (443) 733-1011
Project: **2850 NEW YORK AVE**

EMSL Proj:
Analysis Date: 7/14/2010


Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|----------------------------------|---------------------------------|--|----------------------------|--------------------------|-----------------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 2850-15 <i>191006538-0015</i> | JOINT CMPD 1ST FL OFFICES | White Non-Fibrous Heterogeneous | | 100% Non-fibrous (other) | None Detected |
| 2850-16 <i>191006538-0016</i> | 12X12 PURPLE VFT 1ST FL OFFICES | Gray Non-Fibrous Heterogeneous | | 100% Non-fibrous (other) | None Detected |
| 2850-17 <i>191006538-0017</i> | STAIRWELL PLSTR 1ST FL OFFICES | White Non-Fibrous Heterogeneous | | 100% Non-fibrous (other) | None Detected |
| 2850-18 <i>191006538-0018</i> | STAIRWELL PLSTR 1ST FL OFFICES | White Non-Fibrous Heterogeneous | | 100% Non-fibrous (other) | None Detected |
| 2850-19 <i>191006538-0019</i> | STAIRWELL PLSTR 1ST FL OFFICES | White Non-Fibrous Heterogeneous | 3% Cellulose | 97% Non-fibrous (other) | None Detected |
| 2850-20 <i>191006538-0020</i> | EXT WINDOW CAULK | Brown/Gray Non-Fibrous Heterogeneous | | 80% Non-fibrous (other) | 20% Chrysotile |
| 2850-21 <i>191006538-0021</i> | 2X4 CT (WHT) MEZZANINE OFFICES | Gray/White Fibrous Heterogeneous | 50% Cellulose 40% Glass | 10% Non-fibrous (other) | None Detected |

Initial report from 07/14/2010 12:28:25

Analyst(s)

Alexis Turner (35)



Joe Centifonti, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.
Samples analyzed by EMSL Analytical, Inc. 10768 Baltimore Avenue, Beltsville MD NVLAP Lab Code 200293-0



EMSL Analytical, Inc.

10768 Baltimore Avenue, Beltsville, MD 20705

Phone: (301) 937-5700 Fax: (301) 937-5701 Email: beltsvillelab@emsl.com

Attn: **Alan Lederman**
Froehling & Robertson
7798 Waterloo Road
Jessup, MD 20794

Customer ID: FROE62
Customer PO:
Received: 07/13/10 2:30 PM
EMSL Order: 191006538

Fax: (443) 733-1015 Phone: (443) 733-1011
Project: **2850 NEW YORK AVE**

EMSL Proj:
Analysis Date: 7/14/2010


Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|----------------------------------|---|--|----------------------------|--------------------------|----------------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 2850-22 <i>191006538-0022</i> | DRYWALL MEZZANINE OFFICES | Brown/White Non-Fibrous Heterogeneous | 15% Cellulose | 85% Non-fibrous (other) | None Detected |
| 2850-23 <i>191006538-0023</i> | JOINT CMPD MEZZANINE OFFICES | Brown/White Non-Fibrous Heterogeneous | 5% Cellulose | 95% Non-fibrous (other) | None Detected |
| 2850-24 <i>191006538-0024</i> | 2X4 GRAY CT MEZZANINE OFFICES | Gray/White Fibrous Heterogeneous | 45% Cellulose 35% Glass | 20% Non-fibrous (other) | None Detected |
| 2850-25 <i>191006538-0025</i> | WHT SINK BASIN COATING MEZZANINE OFFICES | Gray Non-Fibrous Homogeneous | 10% Cellulose | 90% Non-fibrous (other) | None Detected |
| 2850-26 <i>191006538-0026</i> | HT PIPE SEAM SEALANT MEZZANINE WALKWAY | Silver/Cream Non-Fibrous Heterogeneous | 10% Glass | 90% Non-fibrous (other) | None Detected |
| 2850-27 <i>191006538-0027</i> | HT DUCT SEAM SEALANT MEZZANINE WALKWAY | Cream Non-Fibrous Heterogeneous | | 100% Non-fibrous (other) | None Detected |
| 2850-28 <i>191006538-0028</i> | DRYWALL WAREHOUSE N WALL | White Non-Fibrous Heterogeneous | 8% Cellulose | 92% Non-fibrous (other) | None Detected |

Initial report from 07/14/2010 12:28:25

Analyst(s)

Alexis Turner (35)



Joe Centifonti, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.
Samples analyzed by EMSL Analytical, Inc. 10768 Baltimore Avenue, Beltsville MD NVLAP Lab Code 200293-0



EMSL Analytical, Inc.

10768 Baltimore Avenue, Beltsville, MD 20705

Phone: (301) 937-5700 Fax: (301) 937-5701 Email: beltsvillelab@emsl.com

Attn: **Alan Lederman**
Froehling & Robertson
7798 Waterloo Road
Jessup, MD 20794

Customer ID: FROE62
Customer PO:
Received: 07/13/10 2:30 PM
EMSL Order: 191006538

Fax: (443) 733-1015 Phone: (443) 733-1011
Project: **2850 NEW YORK AVE**

EMSL Proj:
Analysis Date: 7/14/2010

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|---------------------------|---|---|---------------|--------------------------|----------------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 2850-29 191006538-0029 | JOINT CMPD WAREHOUSE N WALL | White Non-Fibrous Heterogeneous | | 100% Non-fibrous (other) | None Detected |
| 2850-30 191006538-0030 | DRYWALL S CENTRAL GARAGE DOOR BAY | Brown/White Non-Fibrous Heterogeneous | 20% Cellulose | 80% Non-fibrous (other) | None Detected |
| 2850-31 191006538-0031 | JOINT CMPD S CENTRAL GARAGE DOOR BAY | White Non-Fibrous Heterogeneous | 15% Cellulose | 85% Non-fibrous (other) | None Detected |
| 2850-32 191006538-0032 | DRYWALL WAREHOUSE COLUMN 5 | Brown/White Non-Fibrous Heterogeneous | 20% Cellulose | 80% Non-fibrous (other) | None Detected |
| 2850-33 191006538-0033 | JOINT CMPD WAREHOUSE COLUMN 5 | White Non-Fibrous Heterogeneous | 15% Cellulose | 85% Non-fibrous (other) | None Detected |
| 2850-34 191006538-0034 | DRYWALL WASHINGTON TIMES OFFICE | Brown/White Non-Fibrous Heterogeneous | 25% Cellulose | 75% Non-fibrous (other) | None Detected |
| 2850-35 191006538-0035 | JOINT CMPD WASHINGTON TIMES OFFICE | Gray/White Non-Fibrous Heterogeneous | 8% Cellulose | 92% Non-fibrous (other) | None Detected |

Initial report from 07/14/2010 12:28:25

Analyst(s)

Alexis Turner (35)

Joe Centifonti, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.
Samples analyzed by EMSL Analytical, Inc. 10768 Baltimore Avenue, Beltsville MD NVLAP Lab Code 200293-0



EMSL Analytical, Inc.

10768 Baltimore Avenue, Beltsville, MD 20705

Phone: (301) 937-5700 Fax: (301) 937-5701 Email: beltsvillelab@emsl.com

Attn: **Alan Lederman**
Froehling & Robertson
7798 Waterloo Road
Jessup, MD 20794

Customer ID: FROE62
Customer PO:
Received: 07/15/10 2:40 PM
EMSL Order: 191006664

Fax: (443) 733-1015 Phone: (443) 733-1011
Project: **2850 NEW YORK AVE**

EMSL Proj:
Analysis Date: 7/15/2010


Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|----------------------------------|---|---|------------------------------|---------------------------------------|-----------------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 2850-36 <i>191006664-0001</i> | EXPANSION JOINT CAULK | Gray Non-Fibrous Heterogeneous | | 82% Non-fibrous (other) | 18% Chrysotile |
| 2850-37 <i>191006664-0002</i> | WINDOW CAULK | Gray Non-Fibrous Heterogeneous | 3% Synthetic 2% Cellulose | 95% Non-fibrous (other) | None Detected |
| 2850-38 <i>191006664-0003</i> | DOOR CAULK | White/Red Non-Fibrous Heterogeneous | | 70% Non-fibrous (other) 30% Quartz | None Detected |
| 2850-39 <i>191006664-0004</i> | BLK FT MSTC/2ND FL MEZZ OFFICES | Black Non-Fibrous Heterogeneous | | 97% Non-fibrous (other) | 3% Chrysotile |
| 2850-40 <i>191006664-0005</i> | TAN DUCT SEAM SEALANT/2ND FL MEZZ OFFICES | Gray/Tan Fibrous Heterogeneous | 15% Cellulose | 85% Non-fibrous (other) | None Detected |
| 2850-41 <i>191006664-0006</i> | VINYL COVE BASE/2ND FL MEZZ OFFICES | Gray Non-Fibrous Heterogeneous | | 100% Non-fibrous (other) | None Detected |
| 2850-42 <i>191006664-0007</i> | COVE BASE MSTC/2ND FL MEZZ OFFICES | Tan Non-Fibrous Heterogeneous | | 100% Non-fibrous (other) | None Detected |

Initial report from 07/16/2010 12:48:18

Analyst(s)

Emily Baker (23)



Joe Centifonti, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.
Samples analyzed by EMSL Analytical, Inc. 10768 Baltimore Avenue, Beltsville MD NVLAP Lab Code 200293-0



EMSL Analytical, Inc.

10768 Baltimore Avenue, Beltsville, MD 20705

Phone: (301) 937-5700 Fax: (301) 937-5701 Email: beltsvillelab@emsl.com

Attn: **Alan Lederman**
Froehling & Robertson
7798 Waterloo Road
Jessup, MD 20794

Customer ID: FROE62
Customer PO:
Received: 07/15/10 2:40 PM
EMSL Order: 191006664

Fax: (443) 733-1015 Phone: (443) 733-1011
Project: **2850 NEW YORK AVE**

EMSL Proj:
Analysis Date: 7/15/2010


Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|---|--|--------------------------------------|----------------------------|--------------------------|----------------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 2850-43-flooring <i>191006664-0008</i> | RUBBER FLOORING/2ND FL MEZZ OFFICES | Gray Non-Fibrous Heterogeneous | | 100% Non-fibrous (other) | None Detected |
| 2850-43-Mastic <i>191006664-0008A</i> | RUBBER FLOORING/2ND FL MEZZ OFFICES | Tan Fibrous Heterogeneous | 20% Synthetic | 80% Non-fibrous (other) | None Detected |
| 2850-44 <i>191006664-0009</i> | GRAY FIREPROOFING/ WAREHOUSE 1ST FL W SIDE OFFICE | Gray Fibrous Heterogeneous | 60% Glass 20% Min. Wool | 20% Non-fibrous (other) | None Detected |
| 2850-45 <i>191006664-0010</i> | GRAY FIREPROOFING/ WAREHOUSE 1ST FL OFCS CEIL DECK | Gray Fibrous Heterogeneous | 30% Min. Wool 50% Glass | 20% Non-fibrous (other) | None Detected |
| 2850-46 <i>191006664-0011</i> | GRAY FIREPROOFING/ WAREHOUSE 1ST FL VERT I BEAM | Gray Fibrous Heterogeneous | 60% Min. Wool 25% Glass | 15% Non-fibrous (other) | None Detected |

Initial report from 07/16/2010 12:48:18

Analyst(s)

Emily Baker (23)



Joe Centifonti, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.
Samples analyzed by EMSL Analytical, Inc. 10768 Baltimore Avenue, Beltsville MD NVLAP Lab Code 200293-0



EMSL Analytical, Inc.

10768 Baltimore Avenue, Beltsville, MD 20705

Phone: (301) 937-5700 Fax: (301) 937-5701 Email: beltsvillelab@emsl.com

Attn: **Alan Lederman**
Froehling & Robertson
7798 Waterloo Road
Jessup, MD 20794

Customer ID: FROE62
Customer PO:
Received: 07/15/10 2:40 PM
EMSL Order: 191006664

Fax: (443) 733-1015 Phone: (443) 733-1011
Project: **2850 NEW YORK AVE**

EMSL Proj:
Analysis Date: 7/15/2010

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|---------------------------|---|----------------------------------|----------------------------|-------------------------|---------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 2850-47 191006664-0012 | GRAY FIREPROOFING/ WAREHOUSE 1ST FL HORIZ. I BEAM | Gray Fibrous Heterogeneous | 20% Glass 75% Min. Wool | 5% Non-fibrous (other) | None Detected |
| 2850-48 191006664-0013 | GRAY FIREPROOFING/ WAREHOUSE 1ST FL @ SE CORNER ENT | Gray Fibrous Heterogeneous | 60% Min. Wool 25% Glass | 15% Non-fibrous (other) | None Detected |
| 2850-49 191006664-0014 | GRAY FIREPROOFING/ WAREHSE 1ST FL E END CEIL DECK | Gray Fibrous Heterogeneous | 70% Min. Wool 20% Glass | 10% Non-fibrous (other) | None Detected |
| 2850-50 191006664-0015 | GRAY FIREPROOFING/ WAREHSE 1ST FL E END VERT I BEAM | Gray Fibrous Heterogeneous | 75% Min. Wool 20% Glass | 5% Non-fibrous (other) | None Detected |
| 2850-51 191006664-0016 | GRAY FIREPROOFING/ WAREHSE 1ST FL E END HOR I BEAM | Gray Fibrous Heterogeneous | 80% Min. Wool 10% Glass | 10% Non-fibrous (other) | None Detected |

Initial report from 07/16/2010 12:48:18

Analyst(s)

Emily Baker (23)

Joe Centifonti, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.
Samples analyzed by EMSL Analytical, Inc. 10768 Baltimore Avenue, Beltsville MD NVLAP Lab Code 200293-0



EMSL Analytical, Inc.

10768 Baltimore Avenue, Beltsville, MD 20705

Phone: (301) 937-5700 Fax: (301) 937-5701 Email: beltsvillelab@emsl.com

Attn: Alan Lederman
Froehling & Robertson
7798 Waterloo Road
Jessup, MD 20794

Customer ID: FROE62
Customer PO:
Received: 07/15/10 2:40 PM
EMSL Order: 191006664

Fax: (443) 733-1015 Phone: (443) 733-1011
Project: 2850 NEW YORK AVE

EMSL Proj:
Analysis Date: 7/15/2010

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Table with 7 columns: Sample, Description, Appearance, % Fibrous, % Non-Fibrous, Asbestos % Type. Rows include samples 2850-52 through 2850-57 with their respective descriptions and analysis results.

Initial report from 07/16/2010 12:48:18

Analyst(s)
Emily Baker (23)

Signature of Joe Centifonti
Joe Centifonti, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted.
Samples analyzed by EMSL Analytical, Inc. 10768 Baltimore Avenue, Beltsville MD NVLAP Lab Code 200293-0



EMSL ANALYTICAL, INC.
LABORATORY • PRODUCTS • TRAINING

Asbestos Chain of Custody

EMSL Order Number (Lab Use Only):

191006538

EMSL ANALYTICAL, INC.
10768 BALTIMORE AVENUE
BELTSVILLE, MD 20705
PHONE: (301) 937-5700
FAX: (301) 937-5701

| | | | |
|--|---------------------------|--|----------------------|
| Company: <u>Froehling & Robertson</u> | | EMSL-Bill to: <input checked="" type="checkbox"/> Same <input type="checkbox"/> Different If Bill to is Different note instructions in Comments** | |
| Street: <u>7798 Waterloo Rd.</u> | | Third Party Billing requires written authorization from third party | |
| City: <u>Jessup</u> | State/Province: <u>MD</u> | Zip/Postal Code: <u>20794</u> | Country: <u>U.S.</u> |
| Report To (Name): <u>Alan Lederman</u> | | Fax #: <u>443-733-1015</u> | |
| Telephone #: <u>443-733-1011</u> | | Email Address: <u>alederman@fandr.com</u> | |
| Project Name/Number: <u>2850 New York Ave</u> | | U.S. State Samples Taken: <u>DC</u> | |
| Please Provide Results: <input type="checkbox"/> Fax <input checked="" type="checkbox"/> Email | | Purchase Order: | |

Turnaround Time (TAT) Options* - Please Check

3 Hour
 6 Hour
 24 Hour
 48 Hour
 72 Hour
 96 Hour
 1 Week
 2 Week

*For TEM Air 3 hours/6 hours, please call ahead to schedule. *There is a premium charge for 3 Hour TEM AHERA or EPA Level II TAT. You will be asked to sign an authorization form for this service. Analysis completed in accordance with EMSL's Terms and Conditions located in the Analytical Price Guide.

| | | |
|---|--|--|
| PCM - Air <input type="checkbox"/> NIOSH 7400 <input type="checkbox"/> w/ OSHA 8hr. TWA PLM - Bulk (reporting limit) <input checked="" type="checkbox"/> PLM EPA 600/R-93/116 (<1%) <input type="checkbox"/> PLM EPA NOB (<1%) Point Count <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) Point Count w/Gravimetric <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) <input type="checkbox"/> NYS 198.1 (friable in NY) <input type="checkbox"/> NYS 198.6 NOB (non-friable-NY) <input type="checkbox"/> NIOSH 9002 (<1%) | TEM - Air <input type="checkbox"/> 4-4.5hr TAT (AHERA only) <input type="checkbox"/> AHERA 40 CFR, Part 763 <input type="checkbox"/> NIOSH 7402 <input type="checkbox"/> EPA Level II <input type="checkbox"/> ISO 10312 TEM - Bulk <input type="checkbox"/> TEM EPA NOB <input type="checkbox"/> NYS NOB 198.4 (non-friable-NY) <input type="checkbox"/> Chatfield SOP <input type="checkbox"/> TEM Mass Analysis-EPA 600 sec. 2.5 TEM - Water: EPA 100.2 Fibers >10µm <input type="checkbox"/> Waste <input type="checkbox"/> Drinking All Fiber Sizes <input type="checkbox"/> Waste <input type="checkbox"/> Drinking | TEM- Dust <input type="checkbox"/> Microvac - ASTM D 5755 <input type="checkbox"/> Wipe - ASTM D6480 <input type="checkbox"/> Carpet Sonication (EPA 600/J-93/167) Soil/Rock/Vermiculite <input type="checkbox"/> PLM CARB 435 - A (0.25% sensitivity) <input type="checkbox"/> PLM CARB 435 - B (0.1% sensitivity) <input type="checkbox"/> TEM CARB 435 - B (0.1% sensitivity) <input type="checkbox"/> TEM CARB 435 - C (0.01% sensitivity) <input type="checkbox"/> EPA Protocol (Semi-Quantitative) <input type="checkbox"/> EPA Protocol (Quantitative) Other: <input type="checkbox"/> |
|---|--|--|

Check For Positive Stop - Clearly Identify Homogenous Group

Samplers Name: Alan Lederman Samplers Signature: [Signature]

| Sample # | Sample Description | Volume/Area (Air) HA # (Bulk) | Date/Time Sampled |
|----------|--------------------|----------------------------------|----------------------|
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

Client Sample # (s): 2850-01 - 2850-35 Total # of Samples: 35

Relinquished (Client): [Signature] Date: 7/13/10 Time: 2:30 PM

Received (Lab): [Signature] Date: 7/13/10 Time: 2:30 PM

Comments/Special Instructions:

- 2850-01 - 12"x12" white VFT w/ Black flecks
- 2850-02 - Black Mastix
- 2850-03 - 12"x12" Blue VFT w/ White Flecks
- 2850-04 - Black Mastix
- 2850-05 - 12"x12" Gray with Black Flecks
- 2850-06 - Brown Mastix
- 2850-07 - 12"x12" Solid Gray VFT
- 2850-08 - ~~Red~~ Tan Mastix
- 2850-09 - 12"x12" Gray w/ White Flecks
- 2850-10 - Tan Carpet Mastix
- 2850-11 - Drywall - 2nd Floor Offices
- 2850-12 - Joint Compound - "
- 2850-13 - 2'x2' ceiling Tile - "
- 2850-14 - Drywall - 1st Floor Offices
- 2850-15 - ~~Joint~~ Joint Compound - 1st Floor Offices
- 2850-16 - 12"x12" Purple VFT - 1st Floor Offices
- 2850-17 - Stairwell Plaster - 1st Floor Offices
- 2850-18 " - " - " - "
- 2850-19 " - " - " - "
- 2850-20 - Exterior Window Caulk

| | |
|---------|---|
| 2850-21 | 2'x4' Ceiling Tile ^(White) - Mezzanine offices |
| 2850-22 | Drywall - Mezzanine Offices |
| 2850-23 | Joint Compound - Mezzanine offices |
| 2850-24 | 2'x4' Gray Ceiling Tile - Mezzanine offices |
| 2850-25 | White Sink Basin Coating - Mezzanine offices |
| 2850-26 | White Pipe Seam Sealant - Mezzanine Walkways |
| 2850-27 | White Duct Seam Sealant - Mezzanine offices |
| 2850-28 | Drywall - Warehouse North Wall |
| 2850-29 | Joint Compound - Warehouse North Wall |
| 2850-30 | Drywall - South Central Garage Door Bay |
| 2850-31 | Joint Compound - South Central Garage Door Bay |
| 2850-32 | Drywall - Warehouse Columns |
| 2850-33 | Joint Compound - Warehouse Columns |
| 2850-34 | Drywall - Washington Times Office |
| 2850-35 | Joint Compound - Washington Times Office |



EMSL ANALYTICAL, INC.
LABORATORY PRODUCTS TRAINING

Asbestos Chain of Custody

EMSL Order Number (Lab Use Only):

EMSL ANALYTICAL, I
10768 BALTIMORE AVE
BELTSVILLE MD 20
PHONE: (301) 937-5700
FAX: (301) 937-5701

| Company: <u>Froehling & Robertson</u> | | EMSL-Bill to: <input checked="" type="checkbox"/> Same <input type="checkbox"/> Different <small>If Bill to is Different note instructions in Comments**</small> | |
|---|---|---|---|
| Street: <u>7798 Waterloo Rd.</u> | | <i>Third Party Billing requires written authorization from third party</i> | |
| City: <u>Jessup</u> | State/Province: <u>MD</u> | Zip/Postal Code: <u>20794</u> | Country: <u>U.S.</u> |
| Report To (Name): <u>Alan Lederman</u> | | Fax #: <u>443-733-1015</u> | Email Address: <u>alederman@fandr.com</u> |
| Telephone #: <u>443-733-1011</u> | | Project Name/Number: <u>2850 New York Ave</u> | |
| Please Provide Results: <input type="checkbox"/> Fax <input type="checkbox"/> Email <input type="checkbox"/> Purchase Order: | | U.S. State Samples Taken: <u>D.C.</u> | |
| Turnaround Time (TAT) Options* - Please Check | | | |
| <input type="checkbox"/> 3 Hour | <input type="checkbox"/> 6 Hour | <input checked="" type="checkbox"/> 24 Hour | <input type="checkbox"/> 48 Hour |
| <input type="checkbox"/> 72 Hour | <input type="checkbox"/> 96 Hour | <input type="checkbox"/> 1 Week | <input type="checkbox"/> 2 Week |
| <small>*For TEM Air 3 hours/6 hours, please call ahead to schedule. *There is a premium charge for 3 Hour TEM AHERA or EPA Level II TAT. You will be asked to sign an authorization form for this service. Analysis completed in accordance with EMSL's Terms and Conditions located in the Analytical Price Guide</small> | | | |
| PCM - Air <input type="checkbox"/> NIOSH 7400 <input type="checkbox"/> w/ OSHA 8hr. TWA | | TEM - Air <input type="checkbox"/> 4-4.5hr TAT (AHERA only) <input type="checkbox"/> AHERA 40 CFR, Part 763 <input type="checkbox"/> NIOSH 7402 <input type="checkbox"/> EPA Level II <input type="checkbox"/> ISO 10312 | |
| PLM - Bulk (reporting limit) <input checked="" type="checkbox"/> PLM EPA 600/R-93/116 (<1%) <input type="checkbox"/> PLM EPA NOB (<1%) Point Count <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) Point Count w/Gravimetric <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) <input type="checkbox"/> NYS 198.1 (friable in NY) <input type="checkbox"/> NYS 198.6 NOB (non-friable-NY) <input type="checkbox"/> NIOSH 9002 (<1%) | | TEM - Bulk <input type="checkbox"/> TEM EPA NOB <input type="checkbox"/> NYS NOB 198.4 (non-friable-NY) <input type="checkbox"/> Chatfield SOP <input type="checkbox"/> TEM Mass Analysis-EPA 600 sec. 2.5 TEM - Water: EPA 100.2 Fibers >10µm <input type="checkbox"/> Waste <input type="checkbox"/> Drinking All Fiber Sizes <input type="checkbox"/> Waste <input type="checkbox"/> Drinking | |
| <input type="checkbox"/> Microvac - ASTM D 5755 <input type="checkbox"/> Wipe - ASTM D6480 <input type="checkbox"/> Carpet Sonication (EPA 600/J-93/167) | | Soil/Rock/Vermiculite <input type="checkbox"/> PLM CARB 435 - A (0.25% sensitivity) <input type="checkbox"/> PLM CARB 435 - B (0.1% sensitivity) <input type="checkbox"/> TEM CARB 435 - B (0.1% sensitivity) <input type="checkbox"/> TEM CARB 435 - C (0.01% sensitivity) <input type="checkbox"/> EPA Protocol (Semi-Quantitative) <input type="checkbox"/> EPA Protocol (Quantitative) | |
| <input type="checkbox"/> Other: | | | |
| <input type="checkbox"/> Check For Positive Stop - Clearly Identify Homogenous Group | | | |
| Samplers Name: <u>Alan Lederman</u> | | Samplers Signature: <u>Alan L</u> | |
| Sample # | Sample Description | Volume/Area (Air) HA # (Bulk) | Date/Time Sampled |
| <u>2850-36</u> | <u>Expansion Joint Caulk</u> | | |
| <u>2850-37</u> | <u>Window Caulk</u> | | |
| <u>2850-38</u> | <u>Door Caulk</u> | | |
| <u>2850-39</u> | <u>Black Floor Tile Mastix / 2nd Floor Mezzanine offices</u> | | |
| <u>2850-40</u> | <u>Tan Duct Seam Sealant / 2nd Floor Mezzanine offices</u> | | |
| <u>2850-41</u> | <u>Vinyl Covebase / 2nd Floor Mezzanine offices</u> | | |
| <u>2850-42</u> | <u>Covebase Mastix / 2nd Floor Mezzanine offices</u> | | |
| <u>2850-43</u> | <u>Rubber Flooring / 2nd Floor Mezzanine offices</u> | | |
| Client Sample # (s): <u>2850-36</u> - <u>2850-57</u> | | Total # of Samples: <u>22</u> | |
| Relinquished (Client): <u>Alan L</u> | | Date: <u>7/15/10</u> | Time: <u>2:30 PM</u> |
| Received (Lab): <u>J. Bonaventura</u> | | Date: <u>7/15/10</u> | Time: <u>2:40 PM</u> |
| Comments/Special Instructions: | | | |



EMSL ANALYTICAL, INC.
LABORATORY • PRODUCTS • TRAINING

Asbestos Chain of Custody

EMSL Order Number (Lab Use Only):

EMSL ANALYTICAL, INC.
10768 BALTIMORE AVENUE
BELTSVILLE, MD 20705
PHONE: (301) 937-5700
FAX: (301) 937-5701

Additional Pages of the Chain of Custody are only necessary if needed for additional sample information

| Sample # | Sample Description | Volume/Area (Air) HA # (Bulk) | Date/Time Sampled |
|---------------------------------|--|----------------------------------|----------------------|
| 2850-44 | Grey Fireproofing / Warehouse 1 st Floor West side office | | |
| 2850-45 | Grey Fireproofing / Warehouse 1 st Floor offices ceiling Deck | | |
| 2850-46 | Grey Fireproofing / Warehouse 1 st Floor Vertical I-Beams | | |
| 2850-47 | Grey Fireproofing / Warehouse 1 st Floor Horizontal I-Beam | | |
| 2850-48 | Gray Fireproofing / Warehouse 1 st Floor @ SE Corner Entrance | | |
| 2850-49 | Gray Fireproofing / Warehouse 1 st Floor East End Ceiling Deck | | |
| 2850-50 | Gray Fireproofing / Warehouse 1 st Floor East End Vertical I-Beam | | |
| 2850-51 | Gray Fireproofing / Warehouse 1 st Floor East End Horizontal I-Beam | | |
| 2850-52 | Gray Fireproofing / Warehouse 1 st Floor East End ceiling Deck | | |
| 2850-53 | Generator Breeding Insulation | | |
| 2850-54 | " | | |
| 2850-55 | " | | |
| 2850-56 | Interior Fire Door Insulation | | |
| 2850-57 | Tan Drywall Mastix | | |
| | | | |
| | | | |
| *Comments/Special Instructions: | | | |

Page ____ of ____ pages



EMSL Analytical, Inc.

10768 Baltimore Avenue, Beltsville, MD 20705

Phone: (301) 937-5700 Fax: (301) 937-5701 Email: beltsvillelab@emsl.com

Attn: **Alan Lederman**
Froehling & Robertson
7798 Waterloo Road
Jessup, MD 20794

Customer ID: FROE62
Customer PO:
Received: 07/15/10 2:40 PM
EMSL Order: 191006665
EMSL Proj:

Fax: (443) 733-1015 Phone: (443) 733-1011
Project: **2850 NEW YORK AVE**

Test Report: Lead in Dust by Flame AAS (SW 846 3050B*/7000B)

| <i>Client Sample Description</i> | <i>Lab ID</i> | <i>Collected</i> | <i>Analyzed</i> | <i>Area Sampled</i> | <i>Lead Concentration</i> |
|--------------------------------------|---------------|------------------|-----------------|---------------------|---------------------------|
| LEADWIPE-01 | 0001 | 7/15/2010 | 7/16/2010 | 144 in ² | 12 µg/ft ² |
| Site: CENTRAL BAY FOOR AREA - E WALL | | | | | |
| LEADWIPE-02 | 0002 | 7/15/2010 | 7/16/2010 | 144 in ² | 640 µg/ft ² |
| Site: MIXING TANK AREA | | | | | |
| LEADWIPE-03 | 0003 | 7/15/2010 | 7/16/2010 | 144 in ² | <10 µg/ft ² |
| Site: CENTER OF MAIN WAREHOUSE | | | | | |
| LEADWIPE-04 | 0004 | 7/15/2010 | 7/16/2010 | 144 in ² | 14 µg/ft ² |
| Site: MACHINE & ELECTRIC SHOP | | | | | |
| LEADWIPE-05 | 0005 | 7/15/2010 | 7/16/2010 | 144 in ² | 11 µg/ft ² |
| Site: MAIN WAREHOUSE - E WALL | | | | | |

Initial report from 07/16/2010 15:18:29

Joe Centifonti, Laboratory Manager
or other approved signatory

Reporting limit is 10 ug/wipe. The QC data associated with these sample results included in this report meet the method quality control requirements, unless specifically indicated otherwise. Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities.

* slight modifications to methods applied Samples received in good condition unless otherwise noted. Quality Control Data associated with this sample set is within acceptable limits, unless otherwise noted

Samples analyzed by EMSL Analytical, Inc. 10768 Baltimore Avenue, Beltsville MD AIHA-LAP, LLC--ELLAP Lab 102891



EMSL ANALYTICAL, INC.
LABORATORY • PRODUCTS • TRAINING

Lead (Pb) Chain of Custody

EMSL Order ID (Lab Use Only):

19100665

EMSL ANALYTICAL, INC.
10768 BALTIMORE AVE
BELTSVILLE, MD 20705
PHONE: (301) 937-5700
FAX: (301) 937-5701

| | | | |
|--|---------------------------|---|---------------------------------------|
| Company: <u>Fraehling & Robertson</u> | | EMSL-Bill to: <input checked="" type="checkbox"/> Same <input type="checkbox"/> Different <small>If Bill to is Different note instructions in Comments**</small> | |
| Street: <u>7798 Waterloo Rd.</u> | | <i>Third Party Billing requires written authorization from third party</i> | |
| City: <u>Jessup</u> | State/Province: <u>MD</u> | Zip/Postal Code: <u>20794</u> | Country: <u>U.S.</u> |
| Report To (Name): <u>Alan Lederman</u> | | Fax #: <u>443-733-1015</u> | |
| Telephone #: <u>443-733-1011</u> | | Email Address: <u>alederman@fandr.com</u> | |
| Project Name/Number: <u>2850 New York Ave.</u> | | | |
| Please Provide Results: <input type="checkbox"/> Fax <input checked="" type="checkbox"/> Email | | Purchase Order: | U.S. State Samples Taken: <u>D.C.</u> |

Turnaround Time (TAT) Options* - Please Check

| | | | | | | | |
|----------------------------------|----------------------------------|--|-----------------------------------|---------------------------------|---------------------------------|---------------------------------|----------------------------------|
| <input type="checkbox"/> 3 Hours | <input type="checkbox"/> 6 Hours | <input checked="" type="checkbox"/> 24 Hours | <input type="checkbox"/> 48 Hours | <input type="checkbox"/> 3 Days | <input type="checkbox"/> 4 Days | <input type="checkbox"/> 5 Days | <input type="checkbox"/> 10 Days |
|----------------------------------|----------------------------------|--|-----------------------------------|---------------------------------|---------------------------------|---------------------------------|----------------------------------|

*Analysis completed in accordance with EMSL's Terms and Conditions located in the Price Guide

| Matrix | Method | Instrument | Reporting Limit | Check |
|---|------------------------------------|-------------------------|------------------|-------------------------------------|
| Chips <input type="checkbox"/> mg/cm ² <input type="checkbox"/> % by wt. | SW846-7000B/7420 or AOAC 974.02 | Flame Atomic Absorption | 0.01% | <input type="checkbox"/> |
| | NIOSH 7082 | Flame Atomic Absorption | 4 µg/filter | <input type="checkbox"/> |
| Air | NIOSH 7105 | Graphite Furnace AA | 0.03 µg/filter | <input type="checkbox"/> |
| | NIOSH 7300 modified | ICP-AES | 0.5 µg/filter | <input type="checkbox"/> |
| | SW846-7000B/7420 | Flame Atomic Absorption | 10 µg/wipe | <input checked="" type="checkbox"/> |
| Wipe* <input checked="" type="checkbox"/> ASTM <input type="checkbox"/> non ASTM <small>*if no box is checked, non-ASTM Wipe is assumed</small> | SW846-6010B or C | ICP-AES | 0.5 µg/wipe | <input type="checkbox"/> |
| | SW846-1311/7420/SM 3111B | Flame Atomic Absorption | 0.4 mg/L (ppm) | <input type="checkbox"/> |
| TCLP | SW846-6010B or C | ICP-AES | 0.1 mg/L (ppm) | <input type="checkbox"/> |
| | SW846-7420 | Flame Atomic Absorption | 40 mg/kg (ppm) | <input type="checkbox"/> |
| Soil | SW846-7421 | Graphite Furnace AA | 0.3 mg/kg (ppm) | <input type="checkbox"/> |
| | SW86-6010B or C | ICP-AES | 1 mg/kg (ppm) | <input type="checkbox"/> |
| | SM3111B or SW846-7000B/7420 | Flame Atomic Absorption | 0.4 mg/L (ppm) | <input type="checkbox"/> |
| Wastewater | EPA 200.9 | Graphite Furnace AA | 0.003 mg/L (ppm) | <input type="checkbox"/> |
| | SW846-6010B or C | ICP-AES | 1 mg/kg (ppm) | <input type="checkbox"/> |
| | EPA 200.9 | Graphite Furnace AA | 0.003 mg/L (ppm) | <input type="checkbox"/> |
| Drinking Water | EPA 200.9 | Graphite Furnace AA | 0.003 mg/L (ppm) | <input type="checkbox"/> |

| | |
|------------------|------------------------------|
| Other: | Preservation Method (Water): |
| Name of Sampler: | Signature of Sampler: |

| Sample # | Location | Volume/Area | Date/Time Sampled |
|--------------|-----------------------------------|-------------------------|-------------------|
| ⊙ | | 144 Inches ² | |
| Lead Wipe-01 | Central Bay Door Area - East Wall | " | 7/15/10 |
| Lead Wipe-02 | Mixing Tank Area | " | ↓ |
| Lead Wipe-03 | Center of Main Warehouse | " | |
| Lead Wipe-04 | Machine and Electric Shop | " | |
| Lead Wipe-05 | Main Warehouse - East Wall | " | |

| | | | |
|-------------------|----------------|---------------------|----------|
| Client Sample #'s | <u>01 - 05</u> | Total # of Samples: | <u>5</u> |
|-------------------|----------------|---------------------|----------|

| | | | | | |
|------------------------|----------------------|-------|----------------|-------|----------------|
| Relinquished (Client): | <u>Alan Lederman</u> | Date: | <u>7/15/10</u> | Time: | <u>2:30 PM</u> |
| Received (Lab): | <u>K. Forworth</u> | Date: | <u>7/15/10</u> | Time: | <u>2:40 pm</u> |

Comments: walk in

| Reading No | Area | Component | Substrate | Condition | Color | Units | Action Level | PbC | PbC Error | LBP Y/N |
|------------|-------------------------------|-----------------------|----------------|-------------|---------------|-------------------|--------------|------------|------------|------------|
| 1 | | CALIBRATION | | | | mg / cm ^2 | 1 | 0.9 | 0.2 | N/A |
| 2 | | CALIBRATION | | | | mg / cm ^2 | 1 | 1 | 0.2 | N/A |
| 3 | | CALIBRATION | | | | mg / cm ^2 | 1 | 0.9 | 0.3 | N/A |
| 4 | Exterior-NE Corner | Garage Door | Metal | Good | Red | mg / cm ^2 | 1 | 0 | 0.02 | No |
| 5 | Exterior-NE Corner | Garage Door Frame | Metal | Good | Red | mg / cm ^2 | 1 | 0 | 0.02 | No |
| 6 | Exterior-NE Corner | Wall | Cinderblock | Good | Blue | mg / cm ^2 | 1 | 0 | 0.02 | No |
| 7 | Exterior-NE Corner | Bollard | Metal | Fair | Yellow | mg / cm ^2 | 1 | 0 | 0.04 | No |
| 8 | Exterior-NE Corner | Door Frame | Metal | Fair | Purple | mg / cm ^2 | 1 | 0 | 0.02 | No |
| 9 | Exterior-NE Corner | Door | Metal | Poor | Purple | mg / cm ^2 | 1 | 0 | 0.08 | No |
| 10 | Exterior-NE Corner | Door Lintel | Metal | Fair | White | mg / cm ^2 | 1 | 5.1 | 1.2 | Yes |
| 11 | Main Warehouse | Wall | Cinderblock | Good | Blue | mg / cm ^2 | 1 | 0 | 0.01 | No |
| 12 | Main Warehouse | Ceiling | Metal | Poor | White | mg / cm ^2 | 1 | 0 | 0.04 | No |
| 13 | Main Warehouse | I-Beam | Metal | Good | White | mg / cm ^2 | 1 | 0 | 0.03 | No |
| 14 | Main Warehouse | Door Frame | Metal | Fair | Red | mg / cm ^2 | 1 | 0 | 0.03 | No |
| 15 | Main Warehouse | Door | Metal | Fair | Blue | mg / cm ^2 | 1 | 0 | 0.02 | No |
| 16 | Main Warehouse | Door Lintel | Metal | Fair | Blue | mg / cm ^2 | 1 | 4 | 1.1 | Yes |
| 17 | Main Warehouse | Window Frame | Metal | Good | Red | mg / cm ^2 | 1 | 0 | 0.02 | No |
| 18 | Main Warehouse | Bollard | Concrete | Good | Yellow | mg / cm ^2 | 1 | 0 | 0.06 | No |
| 19 | Main Warehouse | I-Beam | Metal | Good | White | mg / cm ^2 | 1 | 2.7 | 0.9 | Yes |
| 20 | Main Warehouse | I-Beam | Metal | Good | White | mg / cm ^2 | 1 | 2.2 | 0.7 | Yes |
| 21 | Main Warehouse | Stair Stringer | Metal | Good | Blue | mg / cm ^2 | 1 | 0 | 0.06 | No |
| 22 | Main Warehouse | Stair Rail | Metal | Good | Blue | mg / cm ^2 | 1 | 0 | 0.02 | No |
| 23 | Main Warehouse | Stair Riser | Metal | Good | Blue | mg / cm ^2 | 1 | 0 | 0 | No |
| 24 | Warehouse Mezzanine Offices | Wall | Sheetrock | Good | White | mg / cm ^2 | 1 | 0 | 0.04 | No |
| 25 | Warehouse Mezzanine Offices | Duct | Metal | Fair | White | mg / cm ^2 | 1 | 0 | 0.05 | No |
| 26 | Men's Locker Room | Wall | Cinderblock | Good | White | mg / cm ^2 | 1 | 0 | 0.06 | No |
| 27 | Men's Locker Room | Wall | Sheetrock | Good | White | mg / cm ^2 | 1 | 0 | 0.06 | No |
| 28 | Men's Locker Room | Lockers | Metal | Good | Red | mg / cm ^2 | 1 | 0.4 | 0.1 | No |
| 29 | Men's Locker Room | Wall | Sheetrock | Good | White | mg / cm ^2 | 1 | 0 | 0 | No |
| 30 | Men's Locker Room | Window Sill | Wood | Good | Blue | mg / cm ^2 | 1 | 0 | 0 | No |
| 31 | Men's Locker Room | Ceiling Tile Supports | Metal | Good | Black | mg / cm ^2 | 1 | 0 | 0.02 | No |
| 32 | Men's Locker Room | I-Beam | Metal | Good | Orange | mg / cm ^2 | 1 | 3.2 | 1.3 | Yes |
| 33 | Mezzanine Women's Room | Wall Tile | Ceramic | Good | White | mg / cm ^2 | 1 | 6.4 | 2.3 | Yes |
| 34 | Mezzanine Women's Room | Floor Tile | Ceramic | Good | Gray | mg / cm ^2 | 1 | 0 | 0.02 | No |
| 35 | Main Warehouse | Floor | Concrete | Good | Gray | mg / cm ^2 | 1 | 0 | 0.02 | No |
| 36 | NW Corner Offices | Door | Metal | Good | Gray | mg / cm ^2 | 1 | 0 | 0.02 | No |
| 37 | NW Corner Offices | Door Frame | Metal | Good | Gray | mg / cm ^2 | 1 | 0 | 0.03 | No |
| 38 | NW Corner Offices | Wall | Sheetrock | Good | White | mg / cm ^2 | 1 | 0 | 0.04 | No |

| Reading No | Area | Component | Substrate | Condition | Color | Units | Action Level | PbC | PbC Error | LBP Y/N |
|------------|-------------------|--------------|-----------|-----------|-------|------------|--------------|-----|-----------|---------|
| 39 | NW Corner Offices | Ceiling | Sheetrock | Good | White | mg / cm ^2 | 1 | 0 | 0.02 | No |
| 40 | NW Corner Offices | Wall | Sheetrock | Good | Gray | mg / cm ^2 | 1 | 0 | 0.03 | No |
| 41 | NW Corner Offices | Window Frame | Metal | Good | Gray | mg / cm ^2 | 1 | 0 | 0.04 | No |
| 42 | NW Corner Offices | Door | Metal | Good | Gray | mg / cm ^2 | 1 | 0 | 0.05 | No |
| 43 | NW Corner Offices | Door Frame | Metal | Good | Gray | mg / cm ^2 | 1 | 0 | 0.02 | No |
| 44 | NW Corner Offices | Door Frame | Metal | Good | Brown | mg / cm ^2 | 1 | 0 | 0.02 | No |
| 45 | NW Corner Offices | Door | Wood | Good | Brown | mg / cm ^2 | 1 | 0 | 0.02 | No |
| 46 | | CALIBRATION | | | | mg / cm ^2 | 1 | 0.9 | 0.2 | N/A |
| 47 | | CALIBRATION | | | | mg / cm ^2 | 1 | 1 | 0.2 | N/A |
| 48 | | CALIBRATION | | | | mg / cm ^2 | 1 | 0.9 | 0.3 | N/A |



EXPLANATION OF XRF DATA

The table header displays Inspector's name and license number, XL-309 serial number, the job site location, and sampling date.

| <u>Column</u> | <u>Description</u> |
|----------------------|---|
| Reading No | Consecutive sample numbers assigned by the instrument at testing time. |
| Site | Testing site location(s). |
| Component | The major building component being tested. |
| Substrate | The type of material underlying the painted coating. |
| Color | Color of the painted or varnished surface. |
| Result | Result of the test: NEG = negative POS = positive NULL = incomplete test / reading error |
| | <i>There is no inconclusive range for the Niton XL-309.</i> |
| Action Level | Concentration of lead defined as lead-based paint. |
| Pbc | Combined L and K-Shell x-ray readings of lead level. |



W.P. HICKMAN
SYSTEMS, INC.™

30700 Solon Industrial Parkway
Solon, OH 44139 ■ 440-248-7760
Fax: 440-248-6524

LITHO. IN U.S.A.

PERFORMANCE WARRANTY

Building Name WASHINGTON TIMES
 Building Address 2850 NEW YORK AVE. NE WASHINGTON, DC 20002
 Building Owner WASHINGTON TIMES
 Roof Identification SECTION D, E, & F
 Contractor BREEDING CONSTRUCTION
 System Type ASPHALT BUR
 Total Sq./Ft. Coverage 31000 SQ. FT.
 Flashing Type HOT COMPOSITION
 Completion Date 11/29/2006

W.P. Hickman Systems, Inc. ("Hickman"), an Ohio Corporation, guarantees to the Building Owner, subject to the terms, conditions and limitations stated herein, it will repair or cause to be repaired any leaks into the building interior through the above described Hickman Roof Assembly System as supplied by W.P. Hickman and installed by the above named Contractor, for a period of TWENTY (20) years from the date of completion stated above.

Full Coverage

During the term of this Warranty, Hickman will, upon prompt written notice by the Building Owner as hereinafter provided, take appropriate action to repair leaks which may occur. Hickman will inspect the roof and, if a leak is within the coverage of this Warranty, will at its own expense make or cause to be made all necessary repairs to the Hickman Roof Assembly to put it into watertight condition. Should investigation reveal that a leak is caused by something other than causes covered by this warranty, investigation and repair cost shall be assumed and paid by the Building Owner, who shall effect prompt and adequate repairs in a manner compatible with the Hickman System. The Building Owner will be responsible for the removal or replacement of any traffic surfaces or other appurtenances built over the roof are required in order to put the Hickman Roof Assembly in watertight condition.

Limitations

This Warranty is not an insurance policy, nor does it obligate Hickman to repair leaks if determined to be a result of the following:

- A. Building design or construction.
- B. Damage to the roofing system by any natural disasters, including but not limited to floods, lightning, hail, earthquakes, hurricane rated winds, etc.
- C. Structural movement below the roof membrane and flashings.
- D. Misuse of roof surface, abuse, vandalism, civil disobedience, acts of war, exposure to damaging chemicals, including but not limited to solvents, oils and acids.
- E. Condensation within the assembly or moisture vapor/liquid infiltration throughout but not limited to walls, windows, etc.
- F. Failure of the Owner to promptly notify Hickman in writing and receive written approval for:
 1. Changes in building usage.
 2. Modifications or additions of items to the existing roof.
- G. Lack of positive drainage.
- H. Metal components other than Hickman Metal Flash.
- I. Loss or erosion of surfacing materials including, but not limited to, reflective coatings, granules, or aggregate are not covered by this warranty.

Hickman hereby assumes no responsibility for incidental or consequential damage to the structure, its contents, loss of time, profits, energy or any inconvenience from any type of roof leak or damage. Hickman's sole responsibility hereunder is the cost of repairs to put the membrane assembly into a watertight condition.

Hickman's exclusive responsibility and liability under this Warranty is to make repairs that may be required to return the roof to a watertight condition in accord with the obligations which are Hickman's responsibility under this Warranty.

TO THE FULLEST EXTENT PERMITTED BY APPLICABLE LAW, HICKMAN HEREBY DISCLAIMS ANY IMPLIED WARRANTIES, INCLUDING ANY WARRANTY OF MERCHANTABILITY AND ANY WARRANTY OF FITNESS FOR A PARTICULAR PURPOSE, OR, LIMITS SUCH WARRANTY TO THE DURATION AND TO THE EXTENT OF THE EXPRESS WARRANTY REPRESENTED BY THIS WARRANTY. There are no warranties which extend beyond the description of the face hereof. This warranty will be governed by and construed under the laws of the state of Ohio without regard to conflict-of-laws principles that would require the application of any other law.

Owners Responsibility

In the event of a leak in the roofing system or flashing assembly, the Building Owner must notify Hickman in writing within ten (10) days after the discovery of the leak and provide access to the roof. THE HICKMAN SERVICE WARRANTY DOES NOT ABSOLVE THE BUILDING OWNER/CUSTOMER OF MAINTENANCE RESPONSIBILITY THAT IS REQUIRED TO KEEP THIS WARRANTY IN FULL FORCE AND EFFECTIVE. Refer to the W.P. Hickman Roof Membrane System Care & Maintenance Information Packet for maintenance guidelines.

As Hickman does not practice engineering or architecture, neither the issuance of this Warranty or any review of the building's construction by our representatives shall constitute any additional warranty.

W.P. Hickman shall have no obligation under this Warranty unless W.P. Hickman and the installing applicator have been paid in full for all materials, supplies, services, warranty costs and other costs which are included in, or incidental to, the Roofing System.

Ninety days prior to the expiration of this warranty, you may contact W.P. Hickman for service options available at that time.

Transfer of Warranty

This Warranty may be transferred by the Building Owner to a subsequent purchaser of the property by giving not less than ten days written notice to Hickman of such proposed transfer, during which time Hickman will inspect the roofing system to make a written report to the Building Owner and the proposed purchaser of its findings and any adjustments required. Refer to Care & Maintenance Guide for more information.

W.P. Hickman Systems, Inc.

Authorized Signature *Ken Utzer*
 Title WARRANTY MANAGER
 Date 07/20/2007

REPRESENTATIVE COPY

©2000 GOES 3534
All Rights Reserved

A P P E N D I X D

- D-1 Summary of Limited Asbestos Survey Results**
- D-2 Summary of Asbestos-Containing Materials**

**TABLE D-1
DRAFT SUMMARY OF LIMITED ASBESTOS SURVEY RESULTS
RENOVATIONS TO ACCOMMODATE
COLLOCATION OF SIX (6) METROPOLITAN POLICE DEPARTMENT
UNITS AT 2850 NEW YORK AVENUE, NE
WASHINGTON, DISTRICT OF COLUMBIA**

| HOMOGENEOUS AREA | DATE | SAMPLE NUMBER | MATERIAL DESCRIPTION | SAMPLE LOCATION | PLM RESULT |
|------------------|-----------|---------------|--|---------------------------------|------------|
| 1 | 5/12/2011 | 2850-0512-01 | CMU Mortar | Rack Storage Room Wall | NAD |
| 1 | 5/12/2011 | 2850-0512-02 | CMU Mortar | Warehouse Wall | NAD |
| 1 | 5/12/2011 | 2850-0512-03 | CMU Mortar | Loading Dock Wall | NAD |
| 2 | 5/12/2011 | 2850-0512-04 | Brick Mortar | Exterior – West Façade | NAD |
| 2 | 5/12/2011 | 2850-0512-05 | Brick Mortar | Exterior – South Façade | NAD |
| 2 | 5/12/2011 | 2850-0512-06 | Brick Mortar | Exterior – South Façade | NAD |
| 3 | 5/12/2011 | 2850-0512-07 | 6"x6" Brown Ceramic Tile Grout | Lobby Storage Room | NAD |
| 3 | 5/12/2011 | 2850-0512-08 | 6"x6" Brown Ceramic Tile Grout | Lobby Storage Room | NAD |
| 3 | 5/12/2011 | 2850-0512-09 | 6"x6" Brown Ceramic Tile Grout | Lobby Storage Room | NAD |
| 4 | 5/12/2011 | 2850-0512-10 | Yellow Mastic associated with Brown Ceramic Tile Cove Base | Lobby Storage Room | NAD |
| 4 | 5/12/2011 | 2850-0512-11 | Yellow Mastic associated with Brown Ceramic Tile Cove Base | Lobby Storage Room | NAD |
| 4 | 5/12/2011 | 2850-0512-12 | Yellow Mastic associated with Brown Ceramic Tile Cove Base | Lobby | NAD |
| 5 | 5/12/2011 | 2850-0512-13 | Expansion Joint – Floor | Corridor at TCG Room | NAD |
| 5 | 5/12/2011 | 2850-0512-14 | Expansion Joint – Floor | Storage Locker Door | NAD |
| 5 | 5/12/2011 | 2850-0512-15 | Expansion Joint – Floor | Loading Dock Floor | NAD |
| 6 | 5/12/2011 | 2850-0512-16 | Paper Covering over Fiberglass Duct Insulation | Corridor at TCG Room | NAD |
| 6 | 5/12/2011 | 2850-0512-17 | Paper Covering over Fiberglass Duct Insulation | Fleet Services Office | NAD |
| 6 | 5/12/2011 | 2850-0512-18 | Paper Covering over Fiberglass Duct Insulation | Mezzanine Men's Locker Room | NAD |
| 7 | 5/12/2011 | 2850-0512-19 | Expansion Joint – Wall | Warehouse | NAD |
| 7 | 5/12/2011 | 2850-0512-20 | Expansion Joint – Wall | Warehouse | NAD |
| 7 | 5/12/2011 | 2850-0512-21 | Expansion Joint – Wall | Warehouse | NAD |
| 8 | 5/12/2011 | 2850-0512-22 | Paper Covering over Fiberglass Pipe Insulation | Warehouse at Eyewash | NAD |
| 8 | 5/12/2011 | 2850-0512-23 | Paper Covering over Fiberglass Pipe Insulation | Fleet Service Office | NAD |
| 8 | 5/12/2011 | 2850-0512-24 | Paper Covering over Fiberglass Pipe Insulation | Mezzanine Janitor's Closet | NAD |
| 9 | 5/12/2011 | 2850-0512-25 | Black Vibration Cloth | Ink Room, Unit #1 | NAD |
| 9 | 5/12/2011 | 2850-0512-26 | Black Vibration Cloth | Ink Room, Unit #3 | NAD |
| 9 | 5/12/2011 | 2850-0512-27 | Black Vibration Cloth | Ink Room, Unit #3 | NAD |
| 10 | 5/12/2011 | 2850-0512-28 | Brown Wallpaper | James Nickell Office | NAD |
| 10 | 5/12/2011 | 2850-0512-29 | Brown Wallpaper | James Nickell Office | NAD |
| 10 | 5/12/2011 | 2850-0512-30 | Brown Wallpaper | James Nickell Office | NAD |
| 11 | 5/12/2011 | 2850-0512-31 | Gray Linoleum | Pre-Press Room | NAD |
| 11 | 5/12/2011 | 2850-0512-32 | Gray Linoleum | Pre-Press Room | NAD |
| 11 | 5/12/2011 | 2850-0512-33 | Gray Linoleum | Image and Scanning Storage Room | NAD |
| 12 | 5/12/2011 | 2850-0512-34 | Brown Mastic associated with Gray | Pre-Press Room | NAD |
| 12 | 5/12/2011 | 2850-0512-35 | Brown Mastic associated with Gray | Pre-Press Room | NAD |
| 12 | 5/12/2011 | 2850-0512-36 | Brown Mastic associated with Gray | Image and Scanning Storage Room | NAD |
| 13 | 5/12/2011 | 2850-0512-37 | Gray with Silver Flecks Flooring Material | Image and Scanning Storage Room | NAD |
| 13 | 5/12/2011 | 2850-0512-38 | Gray with Silver Flecks Flooring Material | Image and Scanning Storage Room | NAD |
| 13 | 5/12/2011 | 2850-0512-39 | Gray with Silver Flecks Flooring Material | Image and Scanning Storage Room | NAD |
| 14 | 5/12/2011 | 2850-0512-40 | Black Expansion Joint under Gray Expansion Joint Caulk | Exterior Façade | NAD |
| 14 | 5/12/2011 | 2850-0512-41 | Black Expansion Joint under Gray Expansion Joint Caulk | Exterior Façade | NAD |
| 14 | 5/12/2011 | 2850-0512-42 | Black Expansion Joint under Gray Expansion Joint Caulk | Exterior Façade | NAD |

Notes:

1. NAD - No Asbestos Detected

2. For additional asbestos sample results, refer to the report titled "Space Program, District of Columbia, Department of Real Estate Services, Metropolitan Police Department" (MPD Space Program report) prepared by Atelier Architects, Inc. dated July 23, 2010.



**TABLE D-2
DRAFT SUMMARY OF POSITIVE ASBESTOS BULK SAMPLE RESULTS
RENOVATIONS TO ACCOMMODATE
COLLOCATION OF SIX (6) METROPOLITAN POLICE DEPARTMENT
UNITS AT 2850 NEW YORK AVENUE, NE
WASHINGTON, DISTRICT OF COLUMBIA**

| SAMPLE NUMBER | MATERIAL DESCRIPTION | SAMPLE LOCATION | FRIABILITY | CONDITION | APPROXIMATE QUANTITY | UNITS |
|----------------------|--|--------------------------------------|-------------------|------------------|-----------------------------|--------------|
| 2850-36 | Expansion Joint Caulk (Prior Report) | Expansion Joints Throughout Exterior | No | Fair | 250 | LF |
| 2850-39 | Remnant Black Floor Tile Mastic (Prior Report) | Warehouse Mezzanine Offices | No | Fair | 1500 | SF |
| Presumed | Exterior Metal Fire Door Insulation (Prior Report) | Exterior Metal Doors | Yes | Unknown | 8 | Each |
| Presumed | Roofing Materials (Prior Report) | Roof | No | Fair | 300 | SF |

Notes:

1. Information in this table provided by the report titled "Space Program, District of Columbia, Department of Real Estate Services, Metropolitan Police Department" (MPD Space Program report) prepared by Atelier Architects, Inc. dated July 23, 2010

APPENDIX E
Sample Location Plans



LEGEND


2850-0512-17 ASBESTOS SAMPLE LOCATION

AREAS NOT ACCESSIBLE AND/OR NOT IN SCOPE OF WORK

1ST FLOOR PLAN

1/16"=1'-0"

0 8' 16' 32'



CONSULTANTS

SEALS

PROJECT IDENTIFICATION
 DEPARTMENT OF REAL ESTATE SERVICES
 MPD RELOCATION
 2850 NEW YORK AVENUE
 WASHINGTON, DC 20002

| MARK | DATE | DESCRIPTION | BY |
|------|------|-------------|----|
| | | | |
| | | | |
| | | | |
| | | | |

ISSUE BLOCK
 PROJECT NO.: 3015141-0001
 CAD FILE: ENV-02.dwg
 DESIGNED BY: D.G.
 DRAWN BY: L.S.
 CHECKED BY: P.B.
 APPROVED BY: D.H.
 COPYRIGHT: STV INCORPORATED

SHEET TITLE
 ASBESTOS SAMPLE LOCATION PLAN
 1ST FLOOR


ENV-2



STV Incorporated

7125 Ambassador Road, Suite 200
Baltimore, MD 212344
www.stvinc.com

CONSULTANTS



LEGEND
2850-0512-17 ASBESTOS SAMPLE LOCATION
 AREAS NOT ACCESSIBLE AND/OR NOT IN SCOPE OF WORK

MEZZANINE PLAN
NTS

SEALS

PROJECT IDENTIFICATION

DEPARTMENT OF REAL ESTATE SERVICES
MPD RELOCATION
2850 NEW YORK AVENUE
WASHINGTON, DC 20002

ISSUE BLOCK

| | |
|-----------------------------|--------------|
| PROJECT NO.: | 3015141-0001 |
| CAD FILE: | ENV-03.dwg |
| DESIGNED BY: | D.G. |
| DRAWN BY: | L.S. |
| CHECKED BY: | P.B. |
| APPROVED BY: | D.H. |
| COPYRIGHT: STV INCORPORATED | |

SHEET TITLE

ASBESTOS SAMPLE LOCATION PLAN
MEZZANINE LEVEL

ENV-3

APPENDIX F

Photo Log

Photo Log
Limited Asbestos Survey Report
DRES/MPD
2850 New York Avenue NE Facility



Photo 1 –View of Asbestos Expansion Joint Caulk Previously Sampled



Photo 2: View of Asbestos Remnant Black Floor Tile Mastic Previously Sampled



Photo 3 –View of CMU Mortar Sample 2850-0512-01



Photo 4 –View of 6"x6" Brown Ceramic Floor Tile Sample 2850-0512-07



Photo 5 –View of Expansion Joint – Floor Sample 2850-0512-13



Photo 6 –View of Paper Covering Over Fiberglass Duct Insulation Sample 2850-0512-16



Photo 7–View of Expansion Joint - Wall Sample 2850-0512-19



Photo 8–View of Paper Covering Over Fiberglass Pipe Insulation Sample 2850-0512-22



Photo 9–View of Black Vibration Cloth Sample 2850-0512-25



Photo 10–View of Assumed Asbestos Roofing Materials