# DCAM-17-CS-0041 Amendment No. 3 Exhibit C

Attachment N

Property Conditions Report

Attachment N3

Ward 6






**Property Condition Report** 



Southwest Health Center 850 Delaware Ave SW Washington, DC

Comprehensive Facility Condition Assessment
And Space Utilization Study
DCAM-13-NC-0162

October 3, 2014





Innovation for the Built Environment
economic - energy - environmental - social



4tell™ Solutions, LP
15 Franklin St
Portland, ME 04101
207.828.7900
www.4tellsolutions.com



# TABLE OF CONTENTS

		ontents	
Exe	cutive	Summary	3
	1.1	General Description	3
	1.2	Scope of Work	3
	1.3	Definitions	
	1.4	Limiting Conditions	
	1.5	Building Summary	
	1.6	Summary of Findings	
	1.7	Facility Condition Index	
	1.8	Planning Horizon Category Needs: Current Year to Year 6	
	1.9	Building System Needs: Immediate	
	1.10	Building System Needs: Year 2 - Year 6	
Α	SubSt	tructure Systems	
	A10	FOUNDATIONS	
В	Shell	Systems	15
	B10	SUPERSTRUCTURE	15
	B20	EXTERIOR ENCLOSURE	
	B30	Roofing	
C	Interi	ors Systems	. 21
	C10	INTERIOR CONSTRUCTION	21
	C20	STAIRS	23
	C30	INTERIOR FINISHES	
D	Servi	ces Systems	. 29
	D10	CONVEYING SYSTEMS	29
	D20	PLUMBING	30
	D30	HVAC	
	D50	ELECTRICAL SYSTEMS	
G	Build	ing Sitework Systems	. 45
	G20	SITE IMPROVEMENTS	45

# **Appendices**

Appendix A: Expenditure Forecast Appendix B: Photographic Record

Appendix C: Survey Information Resulting In Plant Adaptation Recommendations

Appendix D: Routine and Predictive Maintenance Actions

# **EXECUTIVE SUMMARY**

#### 1.1 GENERAL DESCRIPTION

4tell Solutions, LP ("4tell") was retained by Washington DC's Department of General Services to undertake Property Condition Assessments (PCAs) on Municipal Facilities. The purpose of the PCAs are to inventory the elemental components in the buildings, identify key attributes of those components, determine estimated remaining useful lives (RULs) and replacement costs of those components, and to identify physical deficiencies and repair costs needing immediate attention.

#### 1.2 SCOPE OF WORK

The Property Condition Assessments were carried out by 4tell Solutions, LP and were conducted following guidance in ASTM International's "Standard Guide for Property Condition Assessments: Baseline Condition Assessment Process (ASTM E2018-08)" as well as guidance from Washington DC's Department of General Services regarding additional survey information and cost estimates for possible plant adaptations. The Property Condition Report (PCR) summarizes the PCA process which includes the following:

- Document Reviews and Interviews
- Walk Through Site Assessment Surveys
- Building Components:
  - o Itemized Inventories
  - Conditions
  - Opinions of remaining useful life (RUL)
  - Opinions of replacement costs at RUL
- Physical Deficiencies
  - Opinions of probable costs to remedy
- Survey Information Resulting in Plant Adaptation Recommendations
  - o ADA Accessibility
  - o Safety and Security
  - Fire Protection
  - o Access Control
  - o Haz Mat
  - o LEED Potential
  - Green Roof for Low Impact Development



#### 1.3 DEFINITIONS

Property Condition Report (PCR) - The work product resulting from completing a PCA is a Property Condition Report. The PCR incorporates the information obtained during the Walk-Through Site Assessment Survey, the Document Review and Interviews to develop Opinions of Probable Costs for components at their RUL along with costing for remediating physical deficiencies identified.

<u>Document Reviews and Interviews</u> - Includes document reviews, research, and interviews to augment the walk-through survey so as to assist the consultant's understanding of the subject property and identification of physical deficiencies.

<u>Walk Through Site Assessment Survey</u> - The walk-through survey identifies the subject property's elemental components, conditions, RULs, replacement costs at RUL, and costs to remediate identified physical deficiencies.

<u>Costing</u> - Replacement and repair costs are based on unit rates published from the 17th Annual Edition of the <u>Whitestone Facility Maintenance and Repair Cost Reference Guide</u> combined with local experience gained by 4tell. The quantities associated with each item have been estimated during a walk-through site assessment and do not represent exact measurements or quantities.

<u>Current Replacement Value (CRV) Methodology</u> – The value to replace the property as determined by the property's square footage and a square foot unit cost based on building classification using the Whitestone Facility Operations Cost Reference Guide.

Physical Deficiencies - In defining good commercial and customary practice for conducting a baseline PCA, the goal is to identify and communicate physical deficiencies to a user. The term physical deficiencies means the presence of conspicuous defects or material deferred maintenance of a subject property's material systems, components, or equipment as observed during the field observer's walk-through survey. This definition specifically excludes deficiencies that may be remedied with routine maintenance, miscellaneous minor repairs, normal operating maintenance, etc., and excludes de minimis conditions that generally do not present material physical deficiencies of the subject property.

<u>Survey Information Resulting in Plant Adaptation Recommendations</u> - These are methodical questions based upon defined industry or Owner standards resulting in a general costing amount that gives an Owner a cash expenditure to plan on within proformas.

<u>Life Cycle</u> - There are various approaches for determining an elemental component's service life such as a "modeling" approach where an industry standard expected useful life (EUL) is added to a component's date of installation resulting in a modeled or calculated expectation of replacement for that item. The methodology used in 4tell's reported value for the expected replacement of an elemental component is a field assessed opinion of remaining useful life (RUL). Observed RUL takes into account a field assessor's observation of the elemental component along with other factors such as maintenance records or observed measurable parameters.



<u>Planning Horizon</u> – Since the life cycles of many elemental components exceed industry standard cash flow proformas, 4tell's Property Condition Report (PCR) only includes a timeframe of importance to an Owner's immediate cash flow planning. In the case of this report, Washington DC's Department of General Services requested a planning horizon window of 6 years. The Planning Horizon years and remaining useful lives (RULs) as defined in this report's approach are summarized in the table below:

Planning Horizon	Remaining Useful Life (RUL)
Year 1 - "Immediate" or "Current"	0
Year 2	1
Year 3	2
Year 4	3
Year 5	4
Year 6	5



#### 1.4 LIMITING CONDITIONS

This report has been prepared for the exclusive and sole use of the Department of General Services. The report may not be relied upon by any other person or entity without the express written consent of 4tell Solutions, LP.

Any reliance on this report by a third party, any decisions that a third party makes based on this report, or any use at all of this report by a third party is the responsibility of such third parties. 4tell Solutions, LP accepts no responsibility for damages, if any, suffered by any third party as a result of decisions made, or actions taken, based on this report.

The assessment of the building/site components was performed using methods and procedures that are consistent with standard commercial and customary practice as outlined in ASTM Standard E 2018-08 for PCA assessments. As per this ASTM Standard, the assessment of the building/site components was based on a visual walk-through site visit, which captured the overall condition of the site at that specific point in time only.

No legal surveys, soil tests, environmental assessments, geotechnical assessments, detailed barrier-free compliance assessments, seismic assessments, detailed engineering calculations, or quantity surveying compilations have been made. No responsibility, therefore, is assumed concerning these matters. 4tell Solutions, LP did not design nor construct the building(s) or related structures and therefore will not be held responsible for the impact of any design or construction defects, whether or not described in this report. No guarantee or warranty, expressed or implied, with respect to the property, building components, building systems, property systems, or any other physical aspect of the property is made.

The recommendations and opinions of probable costs associated with these recommendations, as presented in this report, are based on walk-through non-invasive observations of the parts of the building which were readily accessible during our visual review. Conditions may exist that are not as per the general condition of the system being observed and reported in this report. Opinions of probable costs presented in this report are also based on information received during interviews with operations and maintenance staff. In certain instances, 4tell Solutions, LP has been required to assume that the information provided is accurate and cannot be held responsible for incorrect information received during the interview process. Should additional information become available with respect to the condition of the building and/or site elements, 4tell Solutions, LP requests that this information be brought to our attention so that we may reassess the conclusions presented herein.

The opinions of probable costs are intended for global budgeting purposes only. The scope of work and the actual costs of the work recommended can only be determined after a detailed examination of the site element in question, understanding of the site restrictions, understanding of the effects on the ongoing operations of the site/building, definition of the construction schedule, and preparation of tender documents. We expressly waive any responsibilities for the effects of any action taken as a result of these endeavors unless we are specifically advised of prior to, and participate in the action, at which time, our responsibility will be negotiated.

Our opinions and recommendations presented in our reports will be rendered in accordance with generally accepted professional standards and are not to be construed as a warranty or guarantee

Plan MF-033

regarding existing or future physical conditions at the Site or regarding compliance of Site systems/components and procedures/operations with the various regulating codes, standards, regulations, ordinances, etc.

# 1.5 BUILDING SUMMARY


Item	Description	
Project Name	Southwest Health Center	
Full Address	850 Delaware Ave SW Washington, DC 20024	
Year Built	1940	
Gross Building Area (SF)	26,859	
Current Replacement Value	\$ 9,106,276	
CRV/GSF (\$/Sq Ft)	\$339.04 / Sq Ft	

#### 1.6 SUMMARY OF FINDINGS

This report represents summary-level findings for the Property Condition Assessment. The deficiencies identified in this assessment can be combined with potential new construction requirements to develop an overall Long Term Capital Needs Plan that can be the basis for a facility wide capital improvement funding strategy. Key findings from the Assessment include:


Key Finding	Metric	
Current Year Facility Condition Index	2.65%	
Property Replacement Value (in Current Dollars)	\$9,106,276	
Current Year Capital Needs (included in FCI)	\$240,920	
Current Year Non-Capital Needs (not included in FCI)	\$62,625	
Year 2 to Year 6 Capital Needs	\$989,800	

# **Expenditure Forecast Over Study Period**



#### 1.7 FACILITY CONDITION INDEX

The Facility Condition Index (FCI) gives an indication of a building's or portfolio's overall state of condition. The values are based on a 0-100%+ scale and are derived by dividing the repair costs for a facility by a theoretical replacement value. This replacement value is based on building type from the 17th Annual Edition of the Whitestone Facility Maintenance and Repair Cost Reference. Typically, the FCI is calculated using only the current condition values, not taking into account the future need identified in the life cycle evaluation. Accounting principles indicate that a value of 65%, or the "rule of two-thirds", be utilized for the FCI threshold for identifying potential replacement candidates. Once the current repair costs reach 65%, or roughly two-thirds of the full replacement value of the estimated cost to replace a facility, it may not be prudent to continue to fund repairs. In cases where aggressive facilities planning is expected to be necessary, this threshold may be adjusted to address more pressing need.




Southwest Health Center Current Year FCI = 2.65%

MF-033


The chart below indicates the effects of the FCI ratio per year, assuming the required funds and expenditures ARE made to address the identified actions each year.

Year by Year Effects of FCI Over the Study Period



The Chart below indicates the cumulative effects of the FCI ratio over the study period assuming the required funds and expenditures are **NOT** provided to address the identified works and deferred maintenance each year.

**Cumulative Effects of FCI over the Study Period** 






# 1.8 PLANNING HORIZON CATEGORY NEEDS: CURRENT YEAR TO YEAR 6

The deficiencies are sorted by categories which define briefly the reason the need exists. A requirement may have more than one applicable category. The category is selected based on the need priority, the most heavily impacted building system and the category with the greatest life safety significance.

## **Planning Horizon Needs by Category**



Plan Types	Total Cost
Deferred Maintenance	\$101,681
Plant Adaptation	\$91,350
Routine Maint Minor Repairs	\$284,400
Capital Replacement	\$815,915
Total	\$1,293,346

The following is a list of the Plan Types with a brief description:

#### Capital Replacement

Indicates the need for replacement or major refurbishment of an asset, typically based on age and use but required in the future within a reasonable planning horizon.

### **Deferred Maintenance**

MF-033



Indicates a deficiency or a conditional, performance, or failure related issue with an elemental component that has persisted past a reasonable time frame and should have been remedied prior to the time of assessment.

### **Routine Maint. Minor Repairs**

Indicates the need for normal or ongoing minor component renewal or repair, generally required to sustain the anticipated life cycle of the asset.


#### Plant Adaptation

Indicates the need for alterations to the property for improvement in safety and security, ADA, hazardous materials abatement, green roof and LEED requirements.

Note that the Category selected is the primary factor understood to be the cause for the recommendation. However, there may be more than one driver of the need for repair, replacement, or upgrade.

# 1.9 BUILDING SYSTEM NEEDS: IMMEDIATE

# Distribution of Immediate Needs by Building System




Building Systems	Estimated Costs	Percentage of Total Cost	
B Shell	\$47,400	15.6%	
D Services	\$240,920	79.4%	
Z General	\$15,225	5.0%	
Total	\$303,545	100.0%	



# 1.10 BUILDING SYSTEM NEEDS: YEAR 2 - YEAR 6

# Distribution of Capital Needs by Building System



Building Systems	Estimated Costs	Percentage of Total Cost
B Shell	\$381,432	38.5%
C Interiors	\$104,626	10.6%
D Services	\$400,617	40.5%
G Building Sitework	\$27,000	2.7%
Z General	\$76,125	7.7%
Total	\$989,800	100.0%

13 Powered by iPlan™ © 4tell™ Solutions, LP

# A SUBSTRUCTURE SYSTEMS

# A10 FOUNDATIONS

Item	Description	
A1011 Wall Foundations	Foundation Wall and Footings, No Basement	
Condition	Good	
RUL	6	
Plan Type	Capital Replacement	
Quantity	388	
Unit of Measure	LF	
Unit Cost	\$366	

### **Comments**

The building's substructure includes cast in place concrete strip footings, foundation walls and spread column footings typical of a building without a basement. Also included are under drains. The foundation appeared to be in good condition.

# B SHELL SYSTEMS

## **B10** SUPERSTRUCTURE

Item	Description
B1012 Upper Floors Construction	Superstructure, Cast in Place Concrete Beams and Slab
Condition	Good
RUL	6
Plan Type	Capital Replacement
Quantity	26859
Unit of Measure	SF
Unit Cost	\$18.36

### **Comments**

The superstructure of the building is composed almost entirely of cast-in-place reinforced concrete columns, beams, and slabs. The structure appeared to be in good condition.

Item	Description	
B1014 Ramps	Accessible Ramp - Concrete	
Condition	Good	
RUL	40	
Plan Type	Capital Replacement	
Quantity	35	
Unit of Measure	LF	
Unit Cost	\$500	

# **Comments**

The building's exterior features include a concrete ramp. Ramp is cast in place concrete construction with painted steel handrails (or similar). The ramp appeared to be in good condition.





The access ramp to the building.

# **B20** EXTERIOR ENCLOSURE


Item	Description
B2011 Exterior Wall Construction	Exterior Walls, Brick Masonry, Solid
Condition	Good
RUL	11
Plan Type	Capital Replacement
Quantity	7900
Unit of Measure	SF
Unit Cost	\$48.41

# **Comments**

The exterior walls are composed of multiple wythes of brick and/or other unit masonry. Walls feature sandstone and/or limestone details and accents. The walls appeared to be in good condition for their age; however, require repointing.

16





The exterior brick walls

Туре	Component Description	Plan Type	Year	Expenditures (\$)
B2011	Repointing Brick - 50% of Brick	Routine Maint Minor Repairs	2014	\$47,400

Item	Description
B2021 Windows	Windows, Wood Framed (per SF)
Condition	Poor - Fair
RUL	3
Plan Type	Capital Replacement
Quantity	1700
Unit of Measure	SF
Unit Cost	\$41.91

The building's fenestration is composed primarily of wood framed exterior window units with single pane glazing. Price is per square foot. The windows appeared to be in fair to poor condition as they

MF-033

were reported to be original to the building; however, there are no issues of water ingress. It is expected that the units will require replacements within the next few years.



Example of wood framed windows.

Туре	Component Description	Plan Type	Year	Expenditures (\$)
B2021	Replace Windows, Wood Framed (per SF)	Capital Replacement	2017	\$71,247

Item	Description
B2032 Solid Exterior Doors	Exterior Doors, Swinging, Wood
Condition	Good
RUL	6
Plan Type	Capital Replacement
Quantity	5
Unit of Measure	Each
Unit Cost	\$1,298.31



Exterior doors include swinging wood doors in wood or metal frames with hinges, lock sets or other similar hardware, and closers. The doors appeared to be in good condition.



Main entrance doors.

### B30 Roofing

Item	Description
B3011 Roof Finishes	Roof Covering, Built-up Roof
Condition	Poor - Fair
RUL	3
Plan Type	Capital Replacement
Quantity	7000
Unit of Measure	SF
Unit Cost	\$10.46

### **Comments**

The roof coverings include a built-up roofing system. Asset includes deck insulation and metal roof edge details. There are two roof levels, the lower roof level over the north side of the building and the

MF-033

main building over the south side of the building. The roof appeared to be in fair condition and is starting to reach the end of its expected useful life.



The roof covering consists of a built up roof system.

Туре	Component Description	Plan Type	Year	Expenditures (\$)
B3011	Replace Roof Covering, Built-up Roof	Capital Replacement	2017	\$73,185

# C Interiors Systems

# C10 INTERIOR CONSTRUCTION

Item	Description
C1011 Fixed Partitions	Toilet Partitions, Painted Metal
Condition	Fair - Good
RUL	4
Plan Type	Capital Replacement
Quantity	13
Unit of Measure	Each
Unit Cost	\$812.99

### **Comments**

Restrooms include floor and/or ceiling mounted partitions of metal construction or similar. The units appeared to be in fair to good condition.



Typical metal toilet partitions.



Туре	Component Description	Plan Type	Year	Expenditures (\$)
C1011	Replace Toilet Partitions, Painted Metal	Capital Replacement	2018	\$10,569

Item	Description
C1021 Interior Doors	Interior Doors, Wood, Solid Core
Condition	Good
RUL	6
Plan Type	Capital Replacement
Quantity	1
Unit of Measure	Each
Unit Cost	\$1,343.55

The interior doors include solid core wood doors in wood or metal frames, with hinges, closers, passage or lock set hardware and/or panic devices where appropriate. The doors appeared to be in good condition for their age with minor wear throughout.





Typical interior door.

# C20 STAIRS

Item	Description
C2011 Regular Stairs	Metal, Painted, Interior Stairs
Condition	Good
RUL	6
Plan Type	Capital Replacement
Quantity	6
Unit of Measure	Sq Ft
Unit Cost	\$12,000

# **Comments**



# C30 INTERIOR FINISHES

Item	Description	
C3012 Wall Finishes to Interior Walls	Wall Finish, Plaster	
Condition	Good	
RUL	75	
Plan Type	Capital Replacement	
Quantity	26859	
Unit of Measure	SF	
Unit Cost	\$12.57	

### **Comments**

Interior wall finishes include a multi-coat plaster finish on lath or similar substrate. The walls appeared to be in good condition.

Item	Description
C3024 Flooring	Floor Finish, Ceramic Tile
Condition	Good
RUL	16
Plan Type	Capital Replacement
Quantity	465
Unit of Measure	SF
Unit Cost	\$13.49

#### **Comments**

Interior floor finishes include thin set or mud set ceramic tile with tile or wood base. The flooring appeared to be in good condition and aging as per its expected useful life.



Item	Description
C3024 Flooring	Floor Finish, Terrazzo
Condition	Good
RUL	40
Plan Type	Capital Replacement
Quantity	170
Unit of Measure	SF
Unit Cost	\$25

The terrazzo is located at the stair landings throughout the building and appeared to be in good condition.

Item	Description
C3024 Flooring	Floor Finish, Vinyl Tile - 12"x12"
Condition	Good
RUL	11
Plan Type	Capital Replacement
Quantity	670
Unit of Measure	SF
Unit Cost	\$3.04

# **Comments**

Interior floor finishes include standard Vinyl Composition Tile (VCT) flooring and related base. The flooring appeared to be in good condition.






Typical 12" x 12" tiles in select locations throughout the building.

Item	Description
C3024 Flooring	Floor Finish, Vinyl Tile - 9"x9"
Condition	Poor - Fair
RUL	3
Plan Type	Capital Replacement
Quantity	15470
Unit of Measure	SF
Unit Cost	\$6.08

Interior floor finishes include standard Vinyl Composition Tile (VCT) flooring and related base. These vinyl tiles were reported to have asbestos containing material within the tile/substrate. The price for replacement has been increased, as their will be abatement required.



Typical 9"x9" tile with sections that have been replaced.

Туре	Component Description	Plan Type	Year	Expenditures (\$)
C3024	Replace Floor Finish, Vinyl Tile - 9"x9"	Capital Replacement	2017	\$94,058

Item	Description
C3031 Ceiling Finishes	Ceiling Finish, Plaster, Painted
Condition	Good
RUL	11
Plan Type	Capital Replacement
Quantity	26859
Unit of Measure	SF
Unit Cost	\$12.57

Interior ceiling finishes include a multi-coat plaster on metal lath (or similar). The ceilings appeared to be in good condition.

# D SERVICES SYSTEMS

# D10 CONVEYING SYSTEMS

Item	Description
D1011 Passenger Elevators	Elevator, Passenger, Cable
Condition	Poor
RUL	0
Plan Type	Capital Replacement
Quantity	1
Unit of Measure	Each
Unit Cost	\$118,700.20

### **Comments**

The elevator is manufactured by Otis and is original to the building. There have been reported issues with the unit and its anticipated that it will require replacement within the next year.



Elevator that service all three floors.



Туре	Component Description	Plan Type	Year	Expenditures (\$)
D1011	Replace Elevator, Passenger, Cable	Capital Replacement	2014	\$118,700

# D20 PLUMBING

Item	Description
D2011 Water Closets	Flush Tank Water Closets
Condition	Good
RUL	6
Plan Type	Capital Replacement
Quantity	13
Unit of Measure	Each
Unit Cost	\$843.66

# **Comments**

Plumbing fixtures include water closets, vitreous china, tank type, 1 piece.





Typical water closet throughout the building.

Item	Description
D2014 Sinks	Sink, Stainless Steel
Condition	Good
RUL	16
Plan Type	Capital Replacement
Quantity	27
Unit of Measure	Each
Unit Cost	\$1,007.80

Plumbing fixtures include sinks that are stainless steel.

Item	Description
D2014 Sinks	Service Sink, Iron, Enamel
Condition	Good
RUL	6

@Plan			MF-033

Plan Type	Capital Replacement
Quantity	13
Unit of Measure	Each
Unit Cost	\$1,012.39

Plumbing fixtures include service sink(s) with trim, enameled cast iron.

Item	Description
D2023 Domestic Water Supply Equipment	Domestic Water System, Distribution - Average (per SF)
Condition	Fair
RUL	3
Plan Type	Capital Replacement
Quantity	26856
Unit of Measure	SF
Unit Cost	\$3.11

# **Comments**

The building's domestic water distribution includes a main line, water meter, and backflow preventer. Rough-in included. This asset does not include a water heater. Price per building SF. The plumbing was reported to be in fair condition.

Type	Component Description	Plan Type	Year	Expenditures (\$)
D2023	Replace Domestic Water System, Distribution - Average (per SF)	Capital Replacement	2017	\$83,522



Item	Description
D2023 Domestic Water Supply Equipment	Water Heater, Domestic, Gas
Condition	Fair - Good
RUL	4
Plan Type	Capital Replacement
Quantity	1
Unit of Measure	Each
Unit Cost	\$3,500

The domestic hot water is provided by a 120-gallon natural gas water heater. The unit appeared to be in fair to good condition.



Gas fire water heater manufactured by State.



Туре	Component Description	Plan Type	Year	Expenditures (\$)
D2023	Replace Water Heater, Domestic, Gas	Capital Replacement	2018	\$3,500

Item	Description
D2031 Waste Piping	Domestic Water System, Sanitary Waste - Average (per SF)
Condition	Poor - Fair
RUL	2
Plan Type	Capital Replacement
Quantity	26859
Unit of Measure	SF
Unit Cost	\$2.47

The building includes an average density sanitary waste system, composed of cast iron piping, with gravity discharge to the municipal sewer. Price per building SF. The domestic lines are starting to show corrosion on the exterior of the piping.

Туре	Component Description	Plan Type	Year	Expenditures (\$)
D2031	Replace Domestic Water System, Sanitary Waste - Average (per SF)	Capital Replacement	2016	\$66,342

34

Powered by iPlan™ © 4tell™ Solutions, LP




MF-033

# D30 HVAC

Item	Description
D3021 Boilers	Boiler, Steam, Gas Fired, 1,000 Mbh - Boiler #1
Condition	Poor
RUL	0
Plan Type	Capital Replacement
Quantity	1
Unit of Measure	Each
Unit Cost	\$20,539.10

# **Comments**

The boiler is manufactured by Weil-McLain and was reported that it broken down two years ago and has not worked since. This boiler requires replacement.



Boiler number 1 that isn't functioning.



Туре	Component Description	Plan Type	Year	Expenditures (\$)
D3021	Replace Boiler, Steam, Gas Fired, 1,000 Mbh - Boiler #1	Capital Replacement	2014	\$20,539

Item	Description
D3021 Boilers	Boiler, Steam, Gas Fired, 1,000 Mbh - Boiler #2
Condition	Poor
RUL	2
Plan Type	Capital Replacement
Quantity	1
Unit of Measure	Each
Unit Cost	\$20,539.10

The boiler is manufactured by Weil-McLain and was reported that it recently broken down and was repaired and reinstated within the last few months. It is expected that the unit will require replacement within the next few years.



Boiler #2 that is functioning.

Туре	Component Description	Plan Type	Year	Expenditures (\$)
D3021	Replace Boiler, Steam, Gas Fired, 1,000 Mbh - Boiler #2	Capital Replacement	2016	\$20,539

Item	Description
D3023 Auxiliary Equipment	Heating, Cast Iron Radiators or Similar (per SF)
Condition	Good
RUL	11
Plan Type	Capital Replacement
Quantity	26859
Unit of Measure	SF
Unit Cost	\$10.85

HVAC in the building includes cast iron radiators with steam or hot water distribution piping, including simplex condensate return and steam condensate meter (steam). Price per building SF.





Cast iron radiator that is found throughout the building.

Item	Description
D3031 Chilled Water Systems	Chiller, Reciprocal, With Air-Cooled Condenser
Condition	Poor
RUL	0
Plan Type	Deferred Maintenance
Quantity	50
Unit of Measure	Each
Unit Cost	\$1,500

The cooling medium for air conditioning is provided by an air-cooled reciprocating chiller. The unit was reported that it has not been functioning for more than five years. It requires replacement.



Chiller that is not functioning.

Туре	Component Description	Plan Type	Year	Expenditures (\$)
D3031	Replace Chiller, Reciprocal, With Air-Cooled Condenser	Deferred Maintenance	2014	\$75,000

Item	Description
D3041 Air Distribution Systems	Air Handler, Central, Heating and Cooling, 10,000 cfm
Condition	Poor
RUL	0
Plan Type	Deferred Maintenance
Quantity	1
Unit of Measure	Each
Unit Cost	\$26,680.99

HVAC in the building includes a constant volume central air handling unit with heating and cooling coils. It was reported that the unit has not worked in more than five-ten years. It requires replacement.



Туре	Component Description	Plan Type	Year	Expenditures (\$)
D3041	Replace Air Handler, Central, Heating and Cooling, 10,000 cfm	Deferred Maintenance	2014	\$26,681

Item	Description
D3051 Terminal Self-Contained Units	Air Conditioner, Window, 1 Ton
Condition	Fair
RUL	6
Plan Type	Capital Replacement
Quantity	50
Unit of Measure	Each
Unit Cost	\$1,569.72

The cooling for the building is completed by window mounted units.

#### D50 ELECTRICAL SYSTEMS

Item	Description
D5012 Low Tension Service & Dist.	Electrical Distribution: Branch Wiring, Devices, Equipment & Disconnects - Average Density (per SF)
Condition	Fair
RUL	3
Plan Type	Capital Replacement
Quantity	26859

<b>OPlan</b>		033
Unit of Measure	SF	
Unit Cost	\$3.63	

The building includes a typical electrical distribution system. Price includes an average concentration of interior and exterior branch wiring, equipment disconnects, devices, boxes, receptacles, cover plates, etc. Price is per building SF. The majority of the branch wiring and equipment appeared and were reported to be in fair condition.

Туре	Component Description	Plan Type	Year	Expenditures (\$)
D5012	Replace Electrical Distribution: Branch Wiring, Devices, Equipment & Disconnects - Average Density (per SF)	Capital Replacement	2017	\$97,498

Item	Description
D5012 Low Tension Service & Dist.	Main Electrical Service, 800 Amp, w/ Main Disconnect(s), Main Distribution Switches
Condition	Fair
RUL	3
Plan Type	Capital Replacement
Quantity	1
Unit of Measure	Each
Unit Cost	\$21,973.24

#### **Comments**

The main disconnect switch for the building is located in the basement and is manufactured by The Shull Company.





Main disconnect for the building.

Туре	Component Description	Plan Type	Year	Expenditures (\$)
D5012	Replace Main Electrical Service, 800 Amp, w/ Main Disconnect(s), Main Distribution Switches	Capital Replacement	2017	\$21,973

Item	Description
D5022 Lighting Equipment	Fluorescent Lighting Fixture
Condition	Fair
RUL	3
Plan Type	Capital Replacement
Quantity	27859
Unit of Measure	Sq Ft
Unit Cost	\$3.67

Interior lighting includes fluorescent tube lamps in fixtures of varying description. The units appeared to be in fair condition.



Туре	Component Description	Plan Type	Year	Expenditures (\$)
D5022	Replace Fluorescent Lighting Fixture	Capital Replacement	2017	\$102,243

Item	Description
D5037 Fire Alarm Systems	Fire Alarm Control Panel
Condition	Poor - Fair
RUL	2
Plan Type	Capital Replacement
Quantity	1
Unit of Measure	Each
Unit Cost	\$5,000

The fire alarm system includes a multi-zone fire alarm control panel. It appeared to have surpassed its theoretical expected useful life; however, the unit is still functioning, which warrants the increased life.



Fire alarm panel.

Туре	Component Description	Plan Type	Year	Expenditures (\$)
D5037	Replace Fire Alarm Control Panel	Capital Replacement	2016	\$5,000

#### G BUILDING SITEWORK SYSTEMS

#### G20 SITE IMPROVEMENTS

Item	Description
G2022 Paving & Surfacing	Paving & Surfacing
Condition	Poor - Fair
RUL	2
Plan Type	Capital Replacement
Quantity	6000
Unit of Measure	Sq Ft
Unit Cost	\$4.50

#### **Comments**

The asphalt parking on the east side of the property appeared to be in fair to poor condition and is near the end of its useful life.

Туре	Component Description	Plan Type	Year	Expenditures (\$)
G2022	Replace Paving & Surfacing	Capital Replacement	2016	\$27,000

Item	Description
G2041 Fences & Gates	Chain Link Fence, 8 Ln Ft - New
Condition	Good
RUL	19
Plan Type	Capital Replacement
Quantity	64
Unit of Measure	Ln Ft
Unit Cost	\$18.50



There is a section of fencing around the building that is new, and appears to be in good condition.

Item	Description
G2041 Fences & Gates	Chain Link Fence, 8 Ln Ft - Old
Condition	Good
RUL	6
Plan Type	Capital Replacement
Quantity	430
Unit of Measure	Ln Ft
Unit Cost	\$18.50

#### **Comments**

The fencing appeared to be in good condition.



### **APPENDICES**

**Appendix A: Expenditure Forecast** 

**Appendix B: Photographic Record** 

**Appendix C: Survey Information Resulting In Plant Adaptation** 

Recommendations

**Appendix D: Predictive Maintenance Templated Actions** 

## Appendix A: Expenditure Forecast

## 4tell

#### 6 YEAR CAPITAL EXPENDITURE FORECAST

Southwest Health Center 850 Delaware Ave SW, Washington, DC 0590E-0800, 6

Elemen No.	t Actions	Last Assigned Condition	or ReplacementC	RUL** (Yrs)	Qty	Units	Unit Cost	Plan Type	2014	2015	2016	2017	2018	2019	Total**
				10			\$		0	- 1	2	3	. 4	5	
	TRUCTURE TRUCTURE SUB-TOTALS								50	10	50	501	50	50	50
SHEL		LC III IL			8 50		, -								
2021	EXTERIOR ENCLOSURE	Poor - Fair	40	3	1,700.00	SF	\$41.91	Capital Panlanament				\$71,247			\$71,247
2021	Replace Windows, Wood Framed (per SF)	Poor - Fair	1 40		1 1,700.00 1	- ar	1 \$47.81	Capital Replacement		_	_	3/1,24/	-		3/ 1/24/
30	ROOFING														
3011	Replace Roof Covering, Built-up Roof	Poor - Fair	30	3	7,000.00	SF	\$10.46	Capital Replacement			_	\$73,185			\$73,185
SHEL	L BUB-TOTALS							10	30 1	10	\$0	\$144,452	\$9	30	\$144,43
INTE		,			r		,								
1011	INTERIOR CONSTRUCTION Replace Tollet Partitions, Painted Metal	Fair - Good	20	4	13.00	Each	\$812.99	Capital Replacement					\$10,569		\$10,569
William.	propried resident distributions, resident metal												7		
30	INTERIOR FINISHES	D	30		45 470 00	0.5	40.00	6-1-18-1				\$94,058			\$94,058
3024	Replace Floor Finish, Vinyl Tite - 9"x9"	Poor - Fair	30	3	15,470.00	SF	\$6,08	Capital Replacement				\$94,000	1		984,000
	RIORS SUB-TOTALS								\$0	\$0	50	\$04,058	\$10,569	\$0	\$104,62
SERV															11
1011	CONVEYING SYSTEMS Replace Elevator, Passenger, Cable	Poor	25	0	1.00	Each	**********	Capital Replacement	\$118,700						\$118,700
	III GARALLI VALUES	1 331			1				1-4-1-1-0						
20	PLUMBING														
2023	Replace Domestic Water System, Distribution - Average (per SF)	Falr	40	3	26,856.00	SF	\$3,11	Capital Replacement				\$83,522			\$83,522
2023	Replace Water Heater, Domestic, Gas	Fair - Good	15	4	1.00	Each	\$3,500.00	Capital Replacement					\$3,500		\$3,500
2031	Replace Domestic Water System, Sanitary	Poor - Fair	40	2	26,859.00	SF	\$2.47	Capital Replacement			\$66,342				\$66,342
Treated.	[Waste - Average (per SF)										_				
30	IHVAC														
3021	Replace Boiler, Steam, Gas Fired, 1,000 Mbh -	Poor	30	0	1.00	Each	\$20,539.10	Capital Replacement	\$20,539						\$20,539
	Replace Boiler, Steam, Gas Fired, 1,000 Mbh =						_			_					
3021	Boller #2	Poor	30	2	1,00	Each	\$20,539,10	Capital Replacement			\$20,539				\$20,539
3031	Replace Chiller, Reciprocal, With Air-Cooled	Poor	20	0	50.00	Each	\$1,500.00	Meterror Maintenance	\$75,000						\$75,000
voned III	Condenser Replace Air Handler, Central, Heating and			020				factories and the second	_		-				
3041	Cooling, 10,000 cfm	Poor	20	0	1.00	Each	\$26,680.99	Perermo filatotamence	\$26,681						\$26,681
	THE WHITE AND EXPLORATED											_			
50	Replace Main Electrical Service, 800 Amp, W/		-			_					-	_	-		
5012	Main Disconnect(s), Main Distribution	Fair	40	3	1.00	Each	\$21,973.24	Capital Replacement				\$21,973			\$21,973
	Switches														
5012	Replace Electrical Distribution: Branch Wiring, Devices, Equipment & Disconnects - Average	Fair	40	3	26,659.00	SF	\$3.63	Capital Replacement				\$97,498			\$97,498
5012	Density (per SF)	FØII	40	3	20,000.00	31	45.00	Suprim Replacement							
5022	Replace Fluorescent Lighting Fixture	Fair	20	3	27,859.00	Sq Ft	\$3.67	Capital Replacement				\$102,243			\$102,24
5037	Replace Fire Alarm Control Panel	Poor - Fair	20	2	1.00	Each	\$5,000.00	Capital Replacement			\$5,000	1			\$5,000
	ICES SUB-TOYALS								II STANDARD		191.501	-	\$3,500		\$641,537

From the flux  $0.322\,{\rm fm}^{-1}$  Subset of All Parks and Subset of the Frontier Subset of the Frontier of the Frontier Subset of the Fr

An Des Departs 25 2010

SPECIAL CONSTRUCTION AND DEMOLITI								10	\$0.0	- 50	30	50	30.	30
SPECIAL CONSTRUCTION AND DEMOLITE								50	50	50	50	50	50	\$0
BUILDING SITEWORK						,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,								
20 SITE IMPROVEMENTS														****
022 Replace Paving & Surfacing	Poor - Fair	15	2	6,000.00	Sq Ft	\$4.50	Capital Replacement			\$27,000				\$27,000
BUILDING STYLWORK AUBYOYALS								50	50	\$27,000	30	50	\$0	\$27,000
GENERAL SUB-YOYALS					_			10	90	\$0	\$0	\$0	\$0	\$0
						Ex	penditure Totals per Year	\$240,920	50	\$118,881	\$543,726	\$14,069	\$0	\$917,58
				<u> </u>			FCIT By Year	2 85%	0.00%	1,21%	5.07%	0.15%	0.00%	
						CRV		6.00.0	W.W.	III CALLED	- A. O. M.	200	0.000	

Notes

\* - EUL is the Estimated Useful Life of an Asset

\* - RUL, is the Remaining Useful Life of an Asset

\*\* - RUL, is the Remaining Useful Life of an Asset

\*\* - Kont-Escalated and Mon-foliated Adultated Dollars

+ - FGI Formula (As Currently Programmed):

(Defarred Maintenance + Capital Renewal + Capital Replacement) Building Replacement Value)

#### 6 YEAR ROUTINE MAINTENANCE EXPENDITURE FORECAST

4tell

Southwest Health Center 850 Delaware Ave SW, Washington, DC 0580E-0800, 6

No.	Actority	Last Assigned Contition	of Replecement(C yole (Yrs)	RUL** (Yrs)	9ty	Unita	Unit Cost	Priority	Plan Type	2014	2015	2016	2017	2018	2011	Total
	AUGTURE										-	10	10			50
BUBBI	RUCTURE SUB-TOTALS			_	_	_				50	10	80	39	10	10	39
20	EXTERIOR ENCLOSURE	T	V 3						Y							
2011	Repointing Brick - 50% of Brick	Good	1	D	3,950.00	Sq ft	\$12.00	Priority 2	Routine Maint Minor Repairs	\$47,400	\$47,400	\$47,400	\$47,400	\$47,400	\$47,400	\$284,400
	SUBTOTALS			100				_		\$47.40h	147,400	\$47,400	147,450	\$47,400	\$47,400	\$354,400
	ORS SUB-TOTALS									\$0	50	50	50	50	30	50
	ES SUB-YOYALS									40	50	50	10	10	61	10
EQUIP	MENT & FURNISHING									\$0	10	30	- 50	10	30	50
SPECIA	L CONSTRUCTION AND DEMOLITION L CONSTRUCTION AND DEMOLITION BUT	B-TOTALS								\$-0	60	59	10	50	- 50:	19
HURLO	NG SITEWORK SUE-TOTALS									10	30	10	10	10	10	50
	GENERAL REQUIREMENTS	T			I											
GENER 10					1.00	Each	\$15,225.00	Priority 4	Plant Adaptation	\$15,225	\$15,225	\$15,225	\$15,225	\$15,225	\$15,225	\$91,340
0	ADA Remediation	Good	1_1_1	0	1.00	L ENGH	1214,520,001	Tribing 4	1 Transverse	A	4 2/10/20	***********			4.0,240	******

oten
- - EUL is the Estimated Useful Life of an Asse

\*\* - HUL is the Remaining Useful Life of an Asset


		2014 IPIan S	coring		
Condition	Boom		From	To	Rating
Gnod	10	100%	0%	20%	Good
Fair-Good		80%	20%	40%	Fair
Enir:		60%	40%	60%	Poor
Poor-Fair	4	40%	60%	80%	Poor
Poor	2	20%	80%	100%	Ums afisfactory

		ion Rating For Southwe				WHITE STATE I	No. of Concession, Name of Street, or other party of the last of t	Actual Asset	Max	Asset Weighting	Asset Condition	Max. Possible	Cond	Condition
Plan Type	Condition	Element No.	Asset	Oty	UOM	Unit Cost (5)	Asset Value (5)	Condition Score	Possible Score	Based Upon Azzet Value	Weighted	Weighted Score	CHI	Rating
10 Foundations								61-41						
apital Replacement	Good	A10 Foundations	Foundation Wall and Footings, No Basement	388.00	LF	365.00	142,008.00	10	10,00	100%	10,00	10.00		
Property of the second		A10 Foundations					142,005.005	10]			10.00	10.00	2%	Good
10 SuperStructure	W 12					-				***				
apital Replacement	Good	B10 SuperStructure	Accessible Ramp - Concrete	35,00	LF	500.00	17,500.00	10	10.00	3%	0.34	0.34		_
apital Replacement	Good	B10 SuperStructure	Superstructure, Cast in Place Concrete Beams and State	26,859.00	SF	18.36	463,131.24	10	10,00	97%	9,68	9.86		
		#10 SuperStructure			111		\$10,531,24	20)			10,00	10.00	94	Good
20 Exterior Enclosure		Total Control	100 T	4 700 00	age: 1	41.91	71,247.00	A	10.00	15%	0.62	1,55		1
apital Replacement		BZ0 Exterior Enclosure	Windows, Wood Framed (per SF) Exterior Doors, Swinging, Wood	1,700,00	Each	1,209.31	6,491.54	10	10.00	1%	0.14	0.14		
apital Replacement	Good	B20 Exterior Enclosure B20 Exterior Enclosure	Exterior Doors, Swinging, Wood  Exterior Walls, Brick Masonry, Solid	7,990.00		48,41	382,439.00	10	10.00	83%	8.31	8.31	_	
apital Replacement	Good	B20 Exterior Engineers	Jexterior waits, Brick Masonry, Solid	7,000.00	Jor 1	40.41	400,177.54	241	10.00		9.07	18.00	9%	Good
30 Roofing								31.01						
apital Replacement	Poor - Fair	B30 Roofing	Roof Covering, Built-up Roof	7,000.00	SF	10.40	73,185.00	4	10.00	100%	4.00	10.00		
Control of the last of the las	And the second	930 Roofing	damenta (see All Maria See All	C III			73,188 00.	4			4.00	10.00	60%	Noor
10 Interior Constructi	on													_
apital Replacement	Fair - Good	C10 Interior Construction	Tollet Partitions, Painted Metal		Each	812.09	10,568.86		10.00	89%	7,10	8.87		
apital Replacement	Good	C10 Interior Construction	Interior Doors, Wood, Solid Care	1.00	Each	1,343.55	1,343.55	10		11%	1.13	1,13		-
		610 Interior Comstruction	96)				11,912.40	10			6.23	19.00	18%	(Internal
20 Stairs		I was a second			1			461	40.00	100%	10.00	10.00		
apital Replacement	Good	C20 Stairs	Metal, Painted, Interior Stairs	n.04	Sq Ft	12,000.00	72,000.00	10	10.00	10074	10.00	10.00	0%	Good
30 Interior Finishes		UZU OTRIFA			_		12/8/04/064	1191			10.00	15.09	F. F. S.	15000
apital Replacement	Poor - Fair	C30 Interior Finishes	Floor Finish, Vinyl Tile - 9"x9"	15,470.00	lee I	6.08	94,057.60	4	10.00	12%	0.48	1.20		
apital Replacement	Good	C30 Interior Finishes	Celling Finish, Plaster, Painted	26,859.00		12.57	337,483.34	10		43%	4.32	4.32	"-	
apital Replacement	Good	C30 Interior Finishes	Wall Finish, Plaster	28,859.00		12,57	337,483,34	10		43%	4,32	4.32		
apital Replacement	Good	C30 Interior Finishes	Floor Finish, Vinyl Tile - 12"x12"	670.00		3,04	2,035,80	10		0%	0.03	0.03		7
apital Replacement	Good	C30 Interior Finishes	Floor Finish, Ceramic Tile	465.00		13,49	6,274.25	10		1%	0.08	80,0		
apital Replacement	Good	C30 Interior Finishes	Floor Finish, Terrazzo	170.00		25.00	4,250.00	10		1%	0.05	0.05		
Action of Assessment Con-	Import.	C20 Interior Finishes	HASOLOM WORKS	W 0000	date 1		751,555.37	541		2 5000	9.28	10.00	716	Good
10 Conveying System	n .													
apital Replacement	Poor		Elevator, Passenger, Cable	1,00	Each	118,700.20	118,700.20	2	10.00	100%	2.00	10.00		
		D10 Conveying Bystem		11	Catholic 1	· Contained in a	118,700,201				2.00	10.00	35%	Post
20 Plumbing	-	Table 1 To 1 T					45 464 841	10	10.00	6%	0.64	0.64		
apital Replacement	Good	D20 Plumbing	Service Sink, iron, Enamel  Domestic Water System, Distribution -	13.0	Each	1,012.39	13,101.01	10	100000			-		
apital Replacement	Fair	D20 Plumbing		26,858,00	SF	3.11	83,522.16	6	10.00	41%	2,45	4.08		
apital Replacement	Good	D20 Plumbing	Average (per SF) Sink, Stainless Steel	27.0	Each	1,007.80	27,210,40	10	10.00	13%	1.33	1,33		
apital Replacement	Fair - Good	D20 Plumbing	Water Heater, Domestic, Gas		Each	3,500.00	3,500.00	n	10.00	2%	0.14	0.17		
apital Replacement	Good	D20 Plumbing	Flush Tank Water Closets		Each	843.66	10,967.50	10	10.00	5%	0.54	0.54		
A COLOR OF THE PARTY OF THE PAR	The second		Domestic Water System, Sanitary	26,859.0		2.47	66,341.73		10.00	32%	1,30	3.24		
apital Replacement	Poor - Fair	D20 Plumbing	Waste - Average (per SF)	20,059.0	nat.	2.47		.4		SMADE:				
		020 Flambing					204,702.08	(48)	Ų.		6.390	10,00	20%5	FAIL
30 HVAC													_	
Deferred Maintenance	Poor	D30 HVAC	Air Handler, Central, Heating and Cooling, 10,000 cfm		Each	26,680,99	28,680.99	2	10,00	5%	0,10	0.62		
apital Replacement	Fair	D30 HVAC	Air Conditioner, Window, 1 Ton	50.0	Each	1,569.72	78,486,00	6	10.00	15%	0.92	1.53		
Capital Replacement	Good	D30 HVAC	Heating, Cast Iron Radiators or Similar (per SF)	26,859.0	SF	10.85	291,420.15	10	10,00	57%	5,68	5,68		
			Boiler, Steam, Gas Fired, 1,000 Mbh -		Each	20,539.10	20,539.10		10.00	4%	0.08	0.40		

Deferred Maintenance	Poor	D30 HVAC	Chiller, Reciprocal, With Air-Cooled Condenser	60.00 Ea	th 1,500.00	75,000.00	2	10,00	15%	0,29	1.48		
Capital Replacement	Poor	D30 HVAC	Boller, Steam, Gas Fired, 1,000 Mbh - Boller #2	1.00 Ear	th 20,539.10	20,639.10	2	10.00	4%	0.08	0.40		
	///	636 HVAC				812,668.34	24			7.16	10.00	26%	F#III
<b>050 Electrical Systems</b>											M David	44	
Capital Replacement	Poor - Fair	D50 Electrical Systems	Fire Alarm Control Panel	1.00 Eac	th 5,000.00	5,000.00	4	10.00	2%	0.09	0.22		
	Fair	D50 Electrical Systems	Fluorescent Lighting Fixture	27,859.00 54	F1 3.67	102,242.53	- 6	10.00	45%	2.71	4.51		
Capital Replacement	Fair	D50 Electrical Systems	Main Electrical Service, 600 Amp, wi Main Disconnect(s), Main Distribution Switches	1.00 Eac	th 21,973.24	21,973.24	6	10.00	10%	0.68	0.97		
Capital Replacement	Fair	D50 Electrical Systems	Electrical Distribution: Branch Wiring, Devices, Equipment & Disconnects - Average Density (per 8F)	26,859.00 SF	3,63	97,498.17		10.00	43%	2.58	4.30		
		050 Electrical System				226,713.64	223			5.10	19,99	40%	Poor
G20 Site Improvements						20 POCOU		SUCCESS IN		V - LVIII	10 5000		
Canital Replacement	Poor - Fair	G20 Site Improvements	Paving & Surfacing	6,000.00 Sq	Ft 4.50	27,000.00	4	10.00	75%	2,99	7,47		
Capital Replacement	Good	G20 5ite Improvements	Chain Link Fence, 8 Ln Ft - New	64.00 Ln	Ft 18.50	1,104.00	10	10.00	3%	0.33	0.33		
Capital Replacement	Good	G20 Site Improvements	Chain Link Fence, 8 Ln Ft - Old	430.00 Ln	Ft 18.50	7,955.00	10	10.00	22%	2,20	2,20		
TARREST TO SERVICE AND ADDRESS OF THE PARTY	A. Contraction	G20 Site Improvemen			recount recover	36,139,001	241			6.12	10.00	45%	Poor

# Appendix B: Photographic Record






Accessible Ramp - Concrete :- The access ramp to the building.



Exterior Walls, Brick Masonry, Solid:- The exterior brick walls



Windows, Wood Framed (per SF) :- Example of wood framed windows.



Exterior Doors, Swinging, Wood:- Main entrance doors.



Roof Covering, Built-up Roof :- The roof covering consists of a built up roof system.




Toilet Partitions, Painted Metal:- Typical metal toilet partitions.



Interior Doors, Wood, Solid Core :- Typical interior door.



Floor Finish, Vinyl Tile - 12"x12":- Typical 12" x 12" tiles in select locations throughout the building.



Floor Finish, Vinyl Tile - 9"x9" :- Typical 9"x9" tile with sections that have been replaced.




Elevator, Passenger, Cable:- Elevator that service all three floors.



Flush Tank Water Closets :- Typical water closet throughout the building.



Water Heater, Domestic, Gas:- Gas fire water heater manufactured by State.



Boiler, Steam, Gas Fired, 1,000 Mbh - Boiler #1:-Boiler number 1 that isn't functioning.



Boiler, Steam, Gas Fired, 1,000 Mbh - Boiler #2:-Boiler #2 that is functioning.






Heating, Cast Iron Radiators or Similar (per SF):-Cast iron radiator that is found throughout the building.



Chiller, Reciprocal, With Air-Cooled Condenser:-Chiller that is not functioning.



Main Electrical Service, 800 Amp, w/ Main Disconnect(s), Main Distribution Switches: - Main disconnect for the building.



Fire Alarm Control Panel:- Fire alarm panel.

# Appendix C: Survey Information Resulting In Plant Adaptation Recommendations



Access Control	
Does the facility have a key card proximity entry system	No
Are all windows at grade level locked or fixed at all times	Yes
Is there at least one clearly marked and designated entrance for visitors	Yes
Are there signs posted for visitors to report to main office or through a designated entrance	No
Access to public transport loading area is restricted to other vehicles during loading/unloading	No
Lighting is provided at entrances and points of possible intrusion	Yes
Outside hardware has been removed from all doors except at points of entry	No
Basement windows are protected with grill or well cover	Yes
Restricted areas are properly identified	Yes
Access to electrical panels are restricted	Yes
Are there control gates to separate distinct areas of the building after hours without changing means of egress	No
Are all perimeter doors equipped with recessed magnetic contact – door position door sensors	No
Are interior doors with specific vulnerability equipped with door position monitoring sensors	No

ADA	
How many additional designated car parking stalls are needed for compliance.	0
How many additional designated can parking stalls are needed for compliance.	0
How many additional signs for accessible parking are needed for compliance.	0
How many LF of curb ramps are required from the parking area to the sidewalks.	0
How many additional passenger drop off areas are required	0
How many additional signs directing to accessible parking or accessible building entrances to the facility are required	0



How many LF of a straight entrance ramp with handrails are needed to allow wheelchair access	0
How many LF of existing exterior ramps and stairs are not equipped with the required handrails.	0
How many buzzers or intercoms used for assistance and service at exterior entrance doors or parking space are needed.	0
How many entrance doors are not wide enough to accommodate wheelchair access, and clear floor space beside the door swing is lacking	0
How many vestibule doors are set too close to the front doors for wheelchair access	0
How many lever action hardware are missing at all accessible locations	0
How many obstacles or protrusion from the wall are impeding access.	0
How many SF of existing carpeting is not securely attached or has a pile thickness exceeding 1/2".	0
How many stair handrails do not extend beyond the top and bottom risers.	0
How many signs used to indicate accessible entrances and general information are not provided	0
How many telephones are installed higher than what is essential for basic operation	0
How many objects are mounted higher than 27" off the floor, project more than 4" into walks, halls, corridors, passageways, or aisles	0
How many visual alarms need to be added to existing audible fire alarm systems.	0
How many cup dispensers are required at an existing non- conforming water fountain.	1
How many elevator control panels and hall buttons are mounted higher than 54" above the floor.	1
How many control panels do not have raised elevator markings and hall buttons.	0
How many elevators do not have audible signals at floor level changes.	1
How many elevators do not have safety stops installed	0
	· · · · · · · · · · · · · · · · · · ·



How many elevators do not have communication equipment set up for speech impaired communication	0
How many existing restroom doors are not wide enough to accommodate wheelchair access.	4
How many grab bars need to be installed in accessible stalls at 36" above the floor.	0
How many bathrooms require modification to existing toilet room accessories and mirrors	0
How many existing lavatory faucets need paddle type faucets added	4
How many drain pipes are below lavatory with insulation; protect against contact with hot, sharp, or abrasive surfaces	0
How many pull stations alarms are needed in unisex bathroom	0

Fire Protection	
Does the facility have a fire sprinkler system	No
Does the facility have wall mounted fire extinguishers	Yes
Does the kitchen and cooking area have hood vent mounted fire suppression systems	No
Does combustion equipment have dedicated fire sprinkler system e.g. boilers, hot water heater	No
Are current fire protection system inspections up to date and onsite	Yes
A record of Fire Inspection by the local or state Fire Officer is maintained	No
Exit signs are clearly visible and pointing in the correct direction	Yes
Does the facility have monitored fire alarm system	Yes



Is the fire alarm control panel solid-state, modular design type, incorporating the following standard features: lamp test, red alarm and amber LEDs per zone,	
positive and negative ground fault indicators , power ON indicator,	
two (2) auxiliary form C alarm contacts with disconnect switches and lights,	
one (1) auxiliary form C trouble contact, regulated 24Vdc four-wire smoke detector power supply,	
and remote reset connection	
Is the power supply to the fire alarm control panel from an individual circuit	
Does the activation of any initiating device including but not limited to	
manual pull stations, smoke detectors, heat detectors and flow switches shall cause all signals	
to sound continuously until manually reset; flash all visual alarm indicator lights; illuminate	
respective zone indicator lamps in the control panel; illuminate respective zone indicator lamps	
in the graphic display on the door of the control panel; and illuminate respective zone indicator	
lamps in the remote annunciator	
Are the audible and visual devices such as combination  Yes  horn/strobe indicating	
type wired to separate zones so that audible devices correctly provide code three temporal output	
and visual devices correctly provide ADA compliant strobe effect	
Is the fire alarm wiring enclosed in ¾" metal conduit raceway to the manufacturer's instructions	
Is there a smoke detector directly above the fire alarm control panel	
Are there smoke detectors within 5'-0" on each side of the fire doors?	
Are there duct-type smoke detectors on the supply side of HVAC units rated	
greater than 2000 cfm but less than 15,000 cfm	

MF-033

Are there duct-type smoke detectors on both the supply side and return side of the  HVAC units rated 15,000 cfm or more	No
Are there duct-type smoke detectors at all smoke damper locations within the HVAC system ductwork?	No
Is there additional wiring to close the damper and turn off the associated HVAC unit	

Green Roof Feasibility	LINE LINE
Asset	Z1010.4 Consider: Green Roof Plantings Investments - Main Roof
Quantity	1 SF
Unit Cost	\$0.00
Total Cost	\$0.00
Is the roof a sloped system	No
Is the roof less than 5 years in age	No
Does the roof have significant amounts of penetration and equipment	No
Will structural modification need to be made to support a green roof	Yes

Green Roof Feasibility		
Asset	Z1010.4 Consider: Green Roof White Membrane Investments - Main Roof	
Quantity	1 SF	
Unit Cost	\$0.00	
Total Cost	\$0.00	
Is the roof a sloped system	No	
Is the roof less than 5 years in age	No	
Does the roof have significant amounts of penetration and equipment	No	
Will structural modification need to be made to support a green roof	Yes	



Green Roof Feasibility	
Asset	Z1010.4 Consider: Green Roof White Membrane Investments - Lower Roof
Quantity	1 SF
Unit Cost	\$0.00
Total Cost	\$0.00
Is the roof a sloped system	No
Is the roof less than 5 years in age	No
Does the roof have significant amounts of penetration and equipment	No
Will structural modification need to be made to support a green roof	Yes

Green Roof Feasibility		
Asset	Z1010.4 Consider: Green Roof Plantings Investments - Lower Roof	
Quantity	1 SF	
Unit Cost	\$0.00	
Total Cost	\$0.00	
Is the roof a sloped system	No	
Is the roof less than 5 years in age	No	
Does the roof have significant amounts of penetration and equipment	No	
Will structural modification need to be made to support a green roof	Yes	

Hazardous Materials	
Does the facility have a current AHERA Asbestos Inspection on File	No
Does the facility currently have a Asbestos Containing material OM plan in place	No



Has all the material identified in the AHERA report been abated	No
Has the facility been tested for Lead Paint	Yes
Does the facility have a Lead containing paint OM plan in place	Yes
Has all the lead identified in the LBP report been abated	No
Has the facility been tested for Lead in Water	No
Does the facility have a Lead in water OM plan in place	No
Does the facility have a UST	Yes
. Comments	Has been decommissioned
Does the tank have a leak detection system	No
Does the facility have a AST	No
Does the AST have a leak containment system	No
Are transformers PCB free	No
Is there any known PCB containing equipment onsite	No

LEED		
SS.C1	Is the Building LEED Certified Design and Construction	No
	If No, level of effort to achieve	Easy
SS.C2	Does the facility have a Building Exterior and Hardscape Management Plan	No
	If No, level of effort to achieve	Easy
SS.C3	Does the facility have an Integrated Pest Management, Erosion Control, and Landscape Management Plan	No
	If No, level of effort to achieve	Easy
SS.C4	Does the facility provide car pooling or Alternative Commuting Transportation options or incentives	No
	If No, level of effort to achieve	Easy

MF-033

SS.C5	Does the way the site is developed Protect or Restore Open Habitat	No
	If No, level of effort to achieve	Easy
SS.C6	Does the facility have retention ponds rain gardens to control the quantity of Storm water	No
	If No, level of effort to achieve	Not Feasible
SS.C7.1	Does the facility have non asphalt / macadam based paving such as light colored pavers or concrete	No
	If No, level of effort to achieve	Not Feasible
SS.C7.2	Does the facility have a cool roof (white or light color roof surface)	No
	If No, level of effort to achieve	Easy
SS.C8	Are measures installed preventing operable exterior lighting from encroaching on adjacent properties	No
	If No, level of effort to achieve	Easy
WE.P1	The facility has a Minimum Indoor Plumbing Fixture and Fitting Efficiency policy	No
	If No, level of effort to achieve	Easy
WE.C1	Does the facility have a water meter for the whole building	Yes
	Does the facility have sub meters for boiler wtr, cooling tower wtr, irrigation wtr, fire sprinkler	No
	If No, level of effort to achieve	Easy
WE.C2	Are all of the plumbing fixtures at the facility non-water saving devices	Yes
	Are some of the plumbing fixture at the facility are non-water saving devices (10-25%)	Yes
	Are all of the plumbing fixture at the facility water saving devices (100%)	No
	If No, level of effort to achieve	Hard



WE.C3	Does the Building use native planting that does not require irrigation	No
	If No, level of effort to achieve	Not Feasible
	Does the Building have an irrigation system with a rain gauge and time system	No
	If No, level of effort to achieve	Not Feasible
	Does the Building hand water on an as needed basis	No
	If No, level of effort to achieve	Easy
WE.C4	Does the Cooling Tower utilize a Chemical Management System	No
	If No, level of effort to achieve	Not Feasible
	Does the Cooling Tower utilize a Non- Potable Water Source (not public drinking water system)	No
	If No, level of effort to achieve	Not Feasible
EA.P1	Does the Building have an Energy Efficiency Best Management Practices policy	No
	If No, level of effort to achieve	Hard
EA.P2	Has an energy audit been performed and were E.C.M.s implemented to achieve Min Energy Eff Performance	No
	If No, level of effort to achieve	Easy
EA.P3	Does the Building have a Fundamental Refrigerant Management program	No
	If No, level of effort to achieve	Easy
EA.C1	Is it feasible for the facility to achieve an EnergyStar rating of 71 or higher	No
	If No, level of effort to achieve	Easy
EA.C2.1	Have building lighting and HVAC systems been Investigated and Analyzed for retro Commissioning	No
	If No, level of effort to achieve	Easy



EA.C2.2	Has the Building performed retro Commissioning of the building lighting and HVAC systems	No
	If No, level of effort to achieve	Easy
EA.C2.3	Is the Building performing ongoing Commissioning of the building lighting and HVAC systems	No
	If No, level of effort to achieve	Easy
EA.C3.1	Does the Building have a HVAC or Lighting — Building Automation System	No
	If No, level of effort to achieve	Easy
EA.C3.2	re the HVAC and lighting systems individually metered at 40%	No
	If No, level of effort to achieve	Easy
	Are the HVAC and lighting systems individually metered at 80%	No
	If No, level of effort to achieve	Easy
EA.C4	Does the Building use on-site or off-site renewable energy	No
	If No, level of effort to achieve	Hard
EA.C5	Does the Building have an Enhanced Refrigerant Management	No
	If No, level of effort to achieve	Not Feasible
EA.C6	Does the Building have an Emissions Reduction Reporting program	No
	If No, level of effort to achieve	Easy
MR.P1	Does the Building have a Sustainable Purchasing Policy	No
16	If No, level of effort to achieve	Easy
MR.P2	Does the Building have a Solid Waste Management Policy	No
	If No, level of effort to achieve	Easy
MR.C1	Does the Building have a Sustainable Purchasing program for Ongoing Consumables	No



	If No, level of effort to achieve	Easy
MR.C2.1	Is a Sustainable Purchasing policy used for purchasing at least 40% of Electric-Powered Equipment	No
	If No, level of effort to achieve	Easy
MR.C2.2	Is a Sustainable Purchasing policy used for purchasing at least 40% of Furniture	No
	If No, level of effort to achieve	Easy
MR.C3	Is a Sustainable Purchasing policy used when making Facility Alterations and Additions	No
	If No, level of effort to achieve	Easy
MR.C4	Is a Sustainable Purchasing policy used to reduce Mercury content in Lamps purchased	No
	If No, level of effort to achieve	Easy
MR.C5	Is a Sustainable Purchasing policy used when making Food purchases at the Building	No
	If No, level of effort to achieve	Easy
MR.C6	Has the Building performed a Waste Stream Audit	No
	If No, level of effort to achieve	Easy
MR.C7	Has the Building implemented a policy to reduce the quantity Ongoing Consumables going into landfills	No
	If No, level of effort to achieve	Easy
MR.C8	Has the Building implemented a policy to reduce the quantity durable goods (furniture, equipment) going into landfills	No
	If No, level of effort to achieve	Easy
MR.C9	Does the Building recycle building materials during construction which prevents material going to landfill	Yes
IEQ.P1	Has the Building performed a Minimum Indoor Air Quality (IAQ) Performance evaluation of the facility	No

MF-033

	If No, level of effort to achieve	Easy
IEQ.P2	Is the facility and surrounding area smoke free - Environmental Tobacco Smoke (ETS) Control	No
	If No, level of effort to achieve	Easy
IEQ.P3	Does the Building have a Green Cleaning Policy	No
	If No, level of effort to achieve	Easy
IEQ.C1.1	Does the Building have an Indoor Air Quality Management Program	No
	If No, level of effort to achieve	Easy
IEQ.C1.2	Does the Building have Outdoor Air Delivery Monitoring	No
	If No, level of effort to achieve	Easy
IEQ.C1.3	Has the Building modified the HVAC systems to allow Increased Ventilation	No
	If No, level of effort to achieve	Hard
IEQ.C1.4	Does the Building have a plan to Reduce Particulates in Air Distribution	No
	If No, level of effort to achieve	Easy
IEQ.C1.5	Does the Building have a policy to enhance IAQ performance during Facility Alterations and Additions	No
	If No, level of effort to achieve	Easy
IEQ.C2.1	Has the Building performed an Occupant Survey for IAQ	No
	If No, level of effort to achieve	Easy
IEQ.C2.2	Does the Building allow for the Controllability of Systems—Lighting by occupants	Yes
IEQ.C2.3	Does the Building allow for the Occupant Comfort—Thermal Comfort Monitoring	No
	If No, level of effort to achieve	Hard
IEQ.C2.4	Does the Building take advantage of Daylight and Views for tenant comfort	No
	If No, level of effort to achieve	Not Feasible



	***	
IEQ.C3.1	Does the Building have a High Performance Cleaning Program	No
	If No, level of effort to achieve	Easy
IEQ.C3.2	Does the Building have a Custodial Effectiveness Assessment	No
	If No, level of effort to achieve	Easy
IEQ.C3.3	Does the Building Purchase Sustainable Cleaning Products and Materials	No
	If No, level of effort to achieve	Easy
IEQ.C3.4	Does the Building use Sustainable Cleaning Equipment	No
	If No, level of effort to achieve	Easy
IEQ.C3.5	Does the Building have Indoor Chemical and Pollutant Source Control	No
	If No, level of effort to achieve	Easy
IEQ.C3.6	Does the Building have an Indoor Integrated Pest Management	Yes
IO.C1.1	Does the Building have an Innovation in Operations program	No
	If No, level of effort to achieve	Easy
1O.C2	Does the Building have a LEED Accredited Professional on staff	No
	If No, level of effort to achieve	Hard
IO.C3	Is the Building Documenting Sustainable Building Cost Impacts	No
	If No, level of effort to achieve	Easy

Safety Security	
Do all areas of the Building, including bathrooms, hallways, and offices, have the ability to receive an announcement via the P.A. System	No
Do all areas of the Building have the ability to privately call the main office or for emergency	No



Does the general office, principal's office, assistant principal's office have CCTV receptacles	No
Is there an automated notification system to lockdown the building envelope	No
Does the facility have a monitored burglar alarm system	No
Are all classrooms and all other rooms that are grade- accessible will be equipped with motion detector	No
Are all general corridor or lobby areas plus rooms with specific vulnerability equipped with motion detectors?	No
Is the main office and one or more additional locations(s) accessed by designated staff equipped with IDS arm/disarm keypads	No
Are alarm monitoring and response performed by DCPS via their existing central alarm monitoring facility via either dial-up telephone lines or LAN/WAN	No
Is there a video surveillance system that provides general surveillance of the site, common areas and building entry and exit points	Yes
Does the facility have monitored video surveillance system at the interior	No
Does the facility have monitored video surveillance system at the exterior	Yes
Does the facility have exterior door hardware that allows controlled access to the building?	Yes
Does the facility have exterior card access readers that allow controlled access to the building?	No
Does the facility have allow occupants a quick, unimpeded egress from the building?	Yes
Does the facility have interor door hardware that allows controlled access to classrooms?	No
Does the facility have interior card access readers that allow controlled access within the building?	No
Does the facility have Magnetometers that monitor for the entry of "unwanted items" into the building?	No
Does the facility have equipment that allows announcements to be made during large gatherings?	No

## Appendix D: Routine and Predictive Maintenance Actions

## **Benchmark Routine and Predictive Maintenance Actions**

Uniformat Level 3 Code	Uniformat Level 3 Description	Description	Units	Trade	iPlan Plan Type
A1020	Special Foundations	Inspect Special Foundations	Sq Ft	Contract Cement Masons	Predictive Maint Test Inspec
B1010	Floor Construction	Refinish Floor Construction	Sq Ft	Contract Painter	Routine Maint Minor Repairs
B1010	Floor Construction	Repair Floor Construction	Sq Ft	Contract Carpenter	Routine Maint Minor Repairs
B2010	Exterior Walls	Refinish Exterior Walls	Sq Ft	Contract Painter	Routine Maint Minor Repairs
B2020	Exterior Windows	Repair Exterior Windows	Sq Ft	Contract Carpenter	Routine Maint Minor Repairs
B2020	Exterior Windows	Refinish Exterior Windows	Each	Contract Painter	Routine Maint Minor Repairs
B2030	Exterior Doors	Maintain Exterior Doors	Each	Staff Gen Maint Worker	Routine Maint Minor Repairs
B2030	Exterior Doors	Refinish Exterior Doors	Each	Contract Painter	Routine Maint Minor Repairs
B2030	Exterior Doors	Replace Exterior Doors	Each	Contract Maint Worker	Routine Maint Minor Repairs
B3020	Roof Openings	Maintain Roof Openings	Each	Staff Carpenter	Routine Maint Minor Repairs
B3020	Roof Openings	Repair Roof Openings	Each	Contract Carpenter	Routine Maint Minor Repairs
B3010	Roof Coverings	Maintain Roof Coverings	Sq Ft	Staff Gen Maint Worker	Routine Maint Minor Repairs
B3010	Roof Coverings	Replace Roof Coverings	Sq Ft	Contract Roofer	Routine Maint Minor Repairs
B3010	Roof Coverings	Inspect Roof Coverings	Sq Ft	Contract Roofer	Predictive Maint Test Inspec
C1010	Partitions	Refinish Partitions	Each	Contract Painter	Routine Maint Minor Repairs
C1020	Interior Doors	Maintain Interior Doors	Each	Staff Gen Maint Worker	Routine Maint Minor Repairs
C1020	Interior Doors	Replace Interior Doors	Each	Contract Maint Worker	Routine Maint Minor Repairs
C1030	Fittings	Refinish Fittings	Ln Ft	Contract Painter	Routine Maint Minor Repairs
C2010	Stair Construction	Refinish Stair Construction	Sq Ft	Contract Painter	Routine Maint Minor Repairs
C2010	Stair Construction	Repair Stair Construction	Sq Ft	Contract Carpenter	Routine Maint Minor Repairs
C3010	Wall Finishes	Refinish Wall Finishes	Sq Ft	Contract Painter	Routine Maint Minor Repairs
C3010	Wall Finishes	Repair Wall Finishes	Sq Ft	Contract Carpenter	Routine Maint Minor Repairs
C3010	Wall Finishes	Clean Wall Finishes	Sq Ft	Staff Painter	Routine Maint Minor Repairs
C3020	Floor Finishes	Repair Floor Finishes	Sq Ft	Contract Carpet Layer	Routine Maint Minor Repairs
C3020	Floor Finishes	Refinish Floor Finishes	Sq Ft	Contract Painter	Routine Maint Minor Repairs
C3030	Ceiling Finishes	Repair Ceiling Finishes	Sq Ft	Contract Carpenter	Routine Maint Minor Repairs

<b>∂</b> Plan					MF-033
C3030	Ceiling Finishes	Refinish Ceiling Finishes	Sq Ft	Contract Painter	Routine Maint Minor Repairs
D1010	Elevators and Lifts	Maintain Elevators and Lifts	Each	Contract Elev Mechanic	Routine Maint Minor Repairs
D1020	Escalators & Moving Walks	Maintain Escalators & Moving Walks	Each	Contract Elev Mechanic	Routine Maint Minor Repairs
D1090	Other Conveying Systems	Maintain Other Conveying Systems	Each	Staff Gen Maint Worker	Routine Maint Minor Repairs
D2010	Plumbing Fixtures	Repair Plumbing Fixtures	Each	Staff Plumber	Routine Maint Minor Repairs
D2010	Plumbing Fixtures	Replace Plumbing Fixtures	Each	Staff Plumber	Routine Maint Minor Repairs
D2010	Plumbing Fixtures	Reseal Plumbing Fixtures	Each	Staff Plumber	Routine Maint Minor Repairs
D2020	Domestic Water Distribution	Lubricate Domestic Water Distribution	Each	Staff Plumber	Routine Maint Minor Repairs
D2020	Domestic Water Distribution	Inspect Domestic Water Distribution	Each	Staff Plumber	Predictive Maint Test Inspec
D2020	Domestic Water Distribution	Overhaul Domestic Water Distribution	Each	Staff Plumber	Routine Maint Minor Repairs
D2020	Domestic Water Distribution	Repack Domestic Water Distribution	Each	Contract Plumber	Routine Maint Minor Repairs
D2020	Domestic Water Distribution	Clean Domestic Water Distribution	Each	Staff Plumber	Routine Maint Minor Repairs
D2020	Domestic Water Distribution	Drain Domestic Water Distribution	Each	Contract Plumber	Routine Maint Minor Repairs
D2020	Domestic Water Distribution	Check Domestic Water Distribution	Each	Staff Plumber	Predictive Maint Test Inspec
D2030	Sanitary Waste	Maintain Sanitary Waste	Each	Staff Plumber	Routine Maint Minor Repairs
D2030	Sanitary Waste	Replace Sanitary Waste	K Ln Ft	Contract Plumber	Routine Maint Minor Repairs
D2040	Rain Water Drainage	Replace Rain Water Drainage	K Ln Ft	Contract Plumber	Routine Maint Minor Repairs
D2040	Rain Water Drainage	Maintain Rain Water Drainage	Each	Staff Plumber	Routine Maint Minor Repairs
D2040	Rain Water Drainage	Repair Rain Water Drainage	Each	Contract Plumber	Routine Maint Minor Repairs
D2040	Rain Water Drainage	Overhaul Rain Water Drainage	Each	Staff Plumber	Routine Maint Minor Repairs
D2090	Other Plumbing Systems	Check Other Plumbing Systems	Each	Staff Plumber	Predictive Maint Test Inspec
D2090	Other Plumbing Systems	Repair Other Plumbing Systems	Each	Contract Plumber	Routine Maint Minor Repairs
D3010	Energy Supply	Maintain Energy Supply	Each	Staff HVAC Technician	Routine Maint Minor Repairs
D3010	Energy Supply	Repair Energy Supply	Each	Contract HVAC Technician	Routine Maint Minor Repairs
D3020	Heat Generating Systems	Maintain Heat Generating Systems	Each	Staff HVAC Technician	Routine Maint Minor Repairs
D3020	Heat Generating Systems	Lubricate Heat Generating Systems	Each	Staff HVAC Technician	Routine Maint Minor Repairs
D3020	Heat Generating Systems	Repair Heat Generating Systems	Each	Contract HVAC Technician	Routine Maint Minor Repairs
D3020	Heat Generating Systems	Inspect Heat Generating Systems	Each	Staff HVAC Technician	Predictive Maint Test Inspec
D3020	Heat Generating Systems	Clean Heat Generating Systems	Each	Staff HVAC Technician	Routine Maint Minor Repairs
D3030	Cooling Generating Systems	Maintain Cooling Generating Systems	Each	Staff HVAC Technician	Routine Maint Minor Repairs
D3030	Cooling Generating Systems	<b>Lubricate Cooling Generating Systems</b>	Each	Staff HVAC Technician	Routine Maint Minor Repairs
D3030	Cooling Generating Systems	Inspect Cooling Generating Systems	Each	Staff HVAC Technician	Predictive Maint Test Inspec

@Plan					MF-033
D3040	Distribution Systems	Maintain Distribution Systems	Each	Staff HVAC Technician	<b>Routine Maint Minor Repairs</b>
D3040	Distribution Systems	Repair Distribution Systems	Each	Contract HVAC Technician	Routine Maint Minor Repairs
D3050	Terminal & Package Units	Maintain Terminal & Package Units	Each	Staff HVAC Technician	Routine Maint Minor Repairs
D3050	Terminal & Package Units	Repair Terminal & Package Units	Each	Contract HVAC Technician	Routine Maint Minor Repairs
D3060	<b>Controls &amp; Instrumentation</b>	Maintain Controls & Instrumentation	Each	Staff HVAC Technician	Routine Maint Minor Repairs
D3060	Controls & Instrumentation	Inspect Controls & Instrumentation	Each	Staff HVAC Technician	Predictive Maint Test Inspec
D3060	<b>Controls &amp; Instrumentation</b>	Repair Controls & Instrumentation	Each	Contract HVAC Technician	Routine Maint Minor Repairs
D4010	Sprinklers	Overhaul Sprinklers	Each	Staff Plumber	Routine Maint Minor Repairs
D4010	Sprinklers	Test Sprinklers	Each	Staff Plumber	Predictive Maint Test Inspec
D4010	Sprinklers	Inspect Sprinklers	Each	Staff Electrician	Predictive Maint Test Inspec
D4010	Sprinklers	Repair Sprinklers	Each	Contract Electrician	Routine Maint Minor Repairs
D4030	Fire Protection Specialties	Maintain Fire Protection Specialties	Each	Staff Gen Maint Worker	Routine Maint Minor Repairs
D4030	Fire Protection Specialties	Repair Fire Protection Specialties	Each	Contract Carpenter	Routine Maint Minor Repairs
D4030	Fire Protection Specialties	Inspect Fire Protection Specialties	Each	Staff Gen Maint Worker	Predictive Maint Test Inspec
D4030	Fire Protection Specialties	Refinish Fire Protection Specialties	Each	Contract Painter	Routine Maint Minor Repairs
D5010	Electrical Serv & Dist	Maintain Electrical Serv & Dist	Each	Staff Electrician	Routine Maint Minor Repairs
D5010	Electrical Serv & Dist	Repair Electrical Serv & Dist	Each	Contract Electrician	Routine Maint Minor Repairs
D5010	Electrical Serv & Dist	Maintain Electrical Serv & Dist	Each	Staff Electrician	Routine Maint Minor Repairs
D5020	Lighting & Branch Wiring	Maintain Lighting & Branch Wiring	Each	Staff Electrician	Routine Maint Minor Repairs
D5020	Lighting & Branch Wiring	Inspect Lighting & Branch Wiring	Each	Staff Electrician	Predictive Maint Test Inspec
D5020	Lighting & Branch Wiring	Repair Lighting & Branch Wiring	Each	Contract Electrician	Routine Maint Minor Repairs
D5020	Lighting & Branch Wiring	Clean Lighting & Branch Wiring	Each	Staff Electrician	Routine Maint Minor Repairs
D5030	Communications & Security	Maintain Communications & Security	Each	Staff Electrician	Routine Maint Minor Repairs
D5030	Communications & Security	Check Communications & Security	Each	Staff Electrician	Predictive Maint Test Inspec
D5030	Communications & Security	Repair Communications & Security	Each	Contract Electrician	Routine Maint Minor Repairs
D5030	Communications & Security	Inspect Communications & Security	Each	Staff Electrician	Predictive Maint Test Inspec
D5090	Other Electrical Systems	Clean Other Electrical Systems	Each	Staff Electrician	Routine Maint Minor Repairs
D5090	Other Electrical Systems	Maintain Other Electrical Systems	Each	Staff Electrician	Routine Maint Minor Repairs
D5090	Other Electrical Systems	Test Other Electrical Systems	Each	Staff Electrician	Predictive Maint Test Inspec
E1010	Commercial Equipment	Maintain Commercial Equipment	Each	Staff Electrician	Routine Maint Minor Repairs
E1020	Institutional Equipment	Test Institutional Equipment	Each	Staff Plumber	Predictive Maint Test Inspec
E1020	Institutional Equipment	Maintain Institutional Equipment	Each	Staff Plumber	Routine Maint Minor Repairs

<b>∂</b> Plan					MF-033
E1020	Institutional Equipment	Resolder Institutional Equipment	K Ln Ft	Contract Plumber	Routine Maint Minor Repairs
E1020	Institutional Equipment	Re-tape Institutional Equipment	K Ln Ft	Staff Plumber	Routine Maint Minor Repairs
F1010	Special Structures	Refinish Special Structures	Each	Contract Painter	Routine Maint Minor Repairs
F1040	Special Facilities	Lubricate Special Facilities	Each	Staff Plumber	Routine Maint Minor Repairs
F1040	Special Facilities	Check Special Facilities	Each	Staff Plumber	Predictive Maint Test Inspec
F1040	Special Facilities	Repair Special Facilities	Each	Contract Carpenter	Routine Maint Minor Repairs
G2010	Roadways	Patch Roadways	Sq Ft	Staff Road Worker	Routine Maint Minor Repairs
G2010	Roadways	Resurface Roadways	Sq Ft	Contract Road Worker	Routine Maint Minor Repairs
G2020	Parking Lots	Patch Parking Lots	Sq Ft	Staff Road Worker	Routine Maint Minor Repairs
G2020	Parking Lots	Inspect Parking Lots	Each	Staff Electrician	Predictive Maint Test Inspec
G2020	Parking Lots	Paint Parking Lots	Each	Contract Painter	Routine Maint Minor Repairs
G2040	Site Development	Maintain Site Development	Each	Staff Gen Maint Worker	Routine Maint Minor Repairs
G2040	Site Development	Replace Site Development	Each	Contract Electrician	Routine Maint Minor Repairs
G2040	Site Development	Maintain Site Development	Each	Staff Gen Maint Worker	Routine Maint Minor Repairs
G2040	Site Development	Replace Site Development	Each	Contract Electrician	Routine Maint Minor Repairs
G3010	Water Supply	Inspect Water Supply	Each	Staff Plumber	Predictive Maint Test Inspec
G3010	Water Supply	Resolder Water Supply	Ln Ft	Contract Plumber	Routine Maint Minor Repairs
G3010	Water Supply	Lubricate Water Supply	Each	Staff Plumber	Routine Maint Minor Repairs
G3010	Water Supply	Maintain Water Supply	Each	Staff Plumber	Routine Maint Minor Repairs
G3060	Fuel Distribution	Resolder Fuel Distribution	Ln Ft	Contract HVAC Technician	Routine Maint Minor Repairs
G4020	Site Lighting	Replace Site Lighting	Each	Contract Electrician	Routine Maint Minor Repairs








Prepared by: 4Tell Solutions 15 Franklin Street Portland, ME 04101


**Project:** Space Analysis **DGS No.** 033

**Southwest Health Center** 850 Delaware Ave SW, Washington, DC, 20024









-							127	Cental Courses Russ	Switzer.	Uncategorant .	0-304	Warmadials Plans	Bacard Fluor	Southeast Haith Center	9F-533
							0	Dr. Cffice	1900st	DPILE	0.511	Warmadiate Faste	Secured Finds	Studiosat Hydro Guster	W/401
1							100	Crewit Matter Surrey	Santan	Uncalegorized	0.302	Plantacard Fine	Second France	Sco./Inwest Health Carrier	MA-DOS
							1	mental morage	Section	mproger.	VG - 170	COST BATTERS	2004 (884	Southwest Health Carter	WF-030
							2	Ceneral Invester	Patrick	191	NG. 174	Cymal 7mi	100 E 100	Southware Present Centrel	87°-003
							150	Constitute Section Contracts	\$10000	PAS	A11 - E14	Ground France	200,1854	Studiesed Health Center	97-032
1							20	PROBRIEGE CONT.	ı	1041	A11-115	FEET FOR CHELTER Fame	PER PER	SAUDINER TRESTS CANSES	MP-655
1								Management of the state of the	ı	N. S.			2007.004	Section 1880 Chief	#F-032
1		l						Canada Managa	l	patradecant a	100	COLUMN TOWN	400,000	SOLUTIONS PLANTS CAMPS	-
			Ī				2	Lenning Designation	Madell	Degraphical Party	101	Chestron France	100,000	COURTMENT SHIPPING CHIEFE	M-000
1								Contract of Street	Name of Street	And a Control of	ant - ma	Action and the state of	2004 1884	SOLDWIN HARM CANAL	1000
1									The second		the par	Total Street	2001 3001	THE PERSON NAMED IN COLUMN	
									-					Control of the last of the las	-
							4	Royal San			WW. WW			San American	200.00
							it	Demonstrate Office	11001	Direct	111	SOUNT THE	2004 All A	Truthwell Proof Cornel	MF-025
							3	Densial Bull Office		Circus	401-105	12.0	2001 mag	Standbreed Health Center	167,033
							91	Regionary Room	П	CHEST CONTRACTOR	311	Fret Elem Ground Floor	Fielding	Social ready Center	46.000
							977	Outstr Office Cathlett	THEFT	Chicatellectring	VG-104	Crossed Poor	Prat F(00)	Disables of Feyn Certain	MP-000
							5	Destall Offin	Ш	Office	AD- ID	First Figur - Creamil Proper	ADM AND	Biodhwat Harm Certai	MF-000
							2000	Seminar States		Macmallande	200 - 444		PER PER	CONTRACT LABOUR CRUMA	100-48
		l					1 1	The state of the s	- Change	Contraction of the least	141 - PA	Separate Front	00043044	Oddress seas cease.	100-00
1							111	dollar flore							
							b	BUILDING STREET		Children	100	Chand Plant	full full	Statement Harm Contact	HC 244
							z	Stanowski		Burnet	111	Count Page	Free Floor	ADDRESS HEST Come	110.78
				- 2			425	Secretary Lithy	CHARLES	<b>Инападатани</b>	116	Ground Proof	Field Floor	Structure of Females Colonial	110-01
							17	Equality	Vinter	Emilia de	3118	Consess Plants	/y=/y=	Southwest Health Certeil	(40,03)
							182	Services.		Amcaragorpad	141	County Floor	1007300	Bridheed Heath Certain	Into em
							10	Bully fit assessed at any shall	L	The Parket	111	Count Fact	FERR FRAN		MP-003
			Ì					NAME OF TAXABLE PARTY.	Witness	111.Free!	611	Committee Proper	FYE FED	Southwest Health Carties	Min 000
-		l					100	President Little	Chinasa	City.		Columb Factor	10001000	Coursess Links Count.	100-4M
								Particular deposits	Ostano	appendix.	100	Charles Amber	100,000		200-08
											1				
								Particular Francisco Strains	L. Carriero		2		1	Seattle and March Parker	1
							285	Cyc Cantilles Berry	Unitered	Neglecontrad -	103	Chound Flore	THE STATE OF	Statement Haster Corner	Mar. an
		-					103	Boilding Carolete	Ц	9636	ı	Copyright Proces	PHFF	Such and Search of the Country	mr.ou
							600	Wallet Heaville	Utions	Organizational	125	Groved Floor	F1014500	DOUBNING THE REST CHIEF!	66-000
							200	Estating Ram Commer	William	100	101	Copund Phos	Fratrice	Doyal May M. Carrier	MF-033
							×	Parent Viterature	Chimag	SWA	86.103	Custome Place	200,4804	StatiSweet Intally Comer	AP-US
			ı					The state of the s	Į.	Visita.	100	Chinada Calabrida	1000000000	Manager spidiges (Minerales)	040-10
									1						
							*	STANSOCIAL CREAT PROTEINS		INCE	100	Organic Phase	Fried Fried	Doubleast Halff Come	ME-000
							ш	Converse Section County		Case	10.10	Crowne Plaza	Fred Films	Southwell Issue Come	10.00
							100	Kape Notes	Ш	per-chaptery	101.10	Grown Plant	1987 900	Doubleself People Corties	ur all
							111	Esan Rope		Uncalegorized	M-108	Copyright Floor	Fact Floor	Studiesell Presid Contact	the sail
							#	Brand Money		par observe	N.109	Crown Floor	FORFAIR	Blodfored Health Center	100 600
							=	Esam Hopo	L	Overegorate	W.TES	Ground Floor	Fret Floor	Studensel Places Contact	man.
							481	NAME ADDRESS	1	THE PROPERTY.	ALL LA	OWNER SHIPS	Fatt State	COURTMENT THEATTH CANTER	CE29-498
							133	Section access	L	paraceaucus	214.00	Control branch	VAR PRO	Could seek Franch County	800 348
							8	CHIEG CRIM		CPEIR	119	Ground Page		Doublest Next Chilbri	Mr-632
								Country of Country	L	Contract of the Contract of th		Comment Printer		Section of the sectio	Princing.
		l						The second second	L		100	Complete Services		About tales (passing)	Wr-fill
			Ī					Contract Country and Country	Vienna	- Arien	101		-	Designation of the latest of t	200-00
							200	The state of the s	ĺ						
							Ħ	HAT OTHE	-	OBH	125	Glound Phase	Fred Files	Daymont toward Compa	EL CLU
							4,033	Ancesgueent	1	THE PROPERTY.	1310	france	Tiene marrie	Southwest Health Center	Mr.CD
							-	Davi	Chamba	sances.	9010	Standard	the same	Student Health Come:	TER-STR
					100		#	Descript Security	Name and Address of	1294	8018	Bennett	Name (sec.)	PRINCIPAL PRINCIPAL	SED UN
							317	Chies Resm	MINNINE	Uncategorizad	8104	Systematic	Second.	Southwest Houlth Cartier	m/cm
							ŝ	Au Hander Storm	USunt	patrobarran	HITE	Basement	Transport.	Stationed Parkin Comme	#F-013
							261	Sautrical Busines	TOWNER.	Chiman News	(tta)	Tanana .	Beenged	Southwest Health Social	1000,000
							200	Thorage Reach	L	Minage .	1010	figuraph.	Terrent.	StauSheed Health Compa	M2-933
							511	Now Room		Surine Records	1100	Basses44	Banacher	Southwest Husers Course	M.C.
100	On time many transmitter	İ	CHIEF STATE	Chiesin	Organije										
		İ	7	7			Deministry								
Bource	Bource Manager Managered Source		Boulde Boulde	Reserving Source	Room # Bource	Comments	BOF	Owner Nomendature for Room	Noom (Filed)	Room # Resent Use Type	Reom #	Floor Type	Floor	Butestill	Abbraviation
		7					Der Unter Bien		100						

Patri Typiz Soume Committee Transporter Committee Committee Transporter Committee Transporter Committee Committee Committee Committee Committee Committee Committee Committee Committee Committee Committee Committee Committee Committee Committe									Derrie et Marage	Chart	1000		THE PERSON NAMED IN	ThatFall	Comment Number Comme	100-48
								29	William III		Ties.	114	He was a second	Tel.	Shumment Health Center	STO-ME
Procession   Pro								120	Office	П	Office	313	Name and Address of the Owner, where the Owner, which is the Owner, where the Owner, which is the Owner, where the Owner, which is the Owne	TO TO THE PERSON NAMED IN	DOLDWING THE COUNTY	Mr.gy
Probation   Profession   Prof								101	The second		The same of the sa	117			Total Name Control	1000 m
Problem   Profess   Prof								8 1	School Sales		Charlesoning			The second	SULPHINE THAT CHIEF	Winds
Column   C								000	Other state of the last of the	П	Sapiest Special	100	A STREET, SALES	1007 1000	medical part of the control	1000.00
									Missing Co. Tell	Utered		100	I Although and a second	Total Part	Studiesest Fleetill, Center	BEAT.
Mathema								74	Means section			225	THE PERSON NAMED IN	met a france	Sauthwest Negati Control	Mr. case
Mathema								150	this.	SHEET	Diset	H	Title wantable Pare	TUTE	Studiosed Jineth Code	No. of Street
Colonial C								110	Matterly Lipiters	United	Uncategorized		Intermediate Francis	THE PERSON NAMED IN	Doublewall Health Certist	MF/430
Problematic Colors   Table								ist	Series.	patent	HAI.		Warman Francisco	10471	Southwest Health Corner	W.III
Colonida   Colonida								13	Opening's Valentiness	Ulliant	Tukel	ave.	Henrydek Pan	Train-	180	MF-000
Authorization   Professor								-00	fallered flored Carrier	SHIRE	Unital Ingerional	118	Interestable Pres	TAPA.	Studiosel Harth Career	Micani
A SEASING   Part   Pa								=	Sylvery Schooling Comes Althor	Ultiplet	the second	116	Internacional Property	Transference	Southwest Health Contact	MICH
Coloniaries Colini   Charles   Part								217	Office	Ottore	OPIA	111	Internacional Phone	Transf Floor	Southwest Health Certain	97.001
Colonia   Part								707	Otto	Detect		11	Internation Pro-	THE STATE OF THE S	Southwest Health Center	HE THE
Coloniary   Part   Pa								176	2ft.e	Datesto.		124	Internation of the	Theology	Sandress Frank Combi	100,000
Columbia   Part   Par								246	Office .	Deplety	Office	104	INC. PROPERTY PARTY	mappe.	Southwest Inspire Comme	M0-000
Colonia   Property   Property   Colonia   Property   Property   Property   Colonia   Property   Prop									Servician .	Officer	CINCAD COLUMN	204	Harrydale Fau	may true.	Studensed Fleeth Corner	BEO'AR
Control   Cont									Spiriture	United	Graph Springer	122	Distriction of the	Transferra	Stythese Health Contar	110.44
Colonia National   Colonia   Colon									DIAM FROM LUMBY	Statistics	Uncaregutter	301	Dismedula Foo	Undfund.	doublest teath Cestal	MI-GSI
Colonida   Part   Par								190	Total Service	UN6688	100 mg/s	10-210	11446444	Security Chie	Southwest Heath Contact	SEC.
Building								7	Strage Genet	10mant	Chart	TD-218	Internation for	Sunti	Courtment Hearth Corner	MP-GEN
Reduction									Straigh Classic	Utiliand	Ches	10-210	Utamadwa F	Secretary.	Sudheed Heath Cottle	40.03
Contenting								100	Spendar	District	Uncertaggerized	18-20	Interestable Face	Decard For	Bouthwest In with Center	97.035
Process   Proc								37	Purage Chast	Ultimat		10.210	The second of the	Sware Pro-	Significant Heath Corner	80,430
Content   Princ Cute   Content   Princ Cute								100	Pai Sirpe	Uttawe	Secondarian.	78 - 215	Hermital Fina	Secret Pro-	Sucheed read dele-	800-00
Decided (March Color)   Decide Color (March	A			VIII.				(23)	Haller	Transmit.	(Max	10-214	Title or man and in the Party of	3-471	Biodissell (Martin Chrise)	000-00
Contenting   Proc.									Water Illighton	person	Uncategorised	111-210	Transmitted Fina	Search Fee	Saldinead Hallin Control	100-14
Deband Name Common   Proc								70	District.	34660		412-91	Internation for	Securit Pag	Southwest Sweeth Combar	W.C.
Proc   Proc		7						7	Table Bridge	Seetill	UKSTAMPTON	10.20	THE PERSON NAMED IN	Secretar	Southwest Health Center	MUM
Deband Name Common   Common Name Common								#	Often (C)	COSE-	Otta	18.25	We was the Part	Second Pres	Studiesed Hasin Center	BCOVIN
Proc   Proc								ni i	270.0 81	USUATI	Cinca	10.20	the read are Fixed	and losses	Single-seed reports Comme	NF-623
Page   Page										United	The state of the s	B - 304		1	the state of the s	
Proc   Proc								1		10	1	11	The second second	The same of the sa	Donate Harry Comm	100.00
Page   Page								953	The same of the sa	The last	Contract of the last	10 000	100000000000000000000000000000000000000		Statement State Coule	1000
Proc   Proc								g a	Married Land Branch	Oliver of the last	1	100	The state of the s		Comment of the Comment	
Process   Proc								1	Control of the latest divine o		-	10.00	THE PERSON NAMED IN	The second second	Harry distriction	an out
Process   Proc								8	Just Sunt Best year	Cheman	Detr	10-202	THE PROPERTY.	Declary Free	Double of safety Charles	807-033
Proc   Proc								100	Article Reserve	Willet	Uncategorites	10.201	Intervalue Par	Sactor Free	Brichwell Jwell Conter	887-038
Page   Page								100	hope	Willed	Bacage	2006	(Harrischule Fill)	Secondified	Southwest Haldt Certain	100.00
Proc.   Proc								1	G		Turkt	300	Uta madish from	5dF	Structured Feating College	100-09
Page   Page								12	Hatty A		Speed	2007	Utempedale Paul	Section Pro-	Southwest Freedy Center	100.44
Process   Proc								100	Part Part	petiti		101	THE PERSON FOR	September 1	Sjummer Heldin Certer	tende .
Page   Page								12	Donati	Distant 1	Cases	208	He was use Fun	Santa of Fine	Southeast resit Certair	- Marie
Press   Pres								500	Similar Simila Simila Simila Simila Simila Simila Simila Simila Simila Simila	#####	riskir .	H	I de mandala Pina	Decired Flori	Southwest Newth Center	800-38
Belleding Place   Plac								410	Line Manager Office	Officer	-	100	Irlant militala Fiso	Gettor Free	Sauthwest Health Collect	ME-003
Reducting Paper   Pape								E	ATTENDED TO THE PERSON NAMED IN COLUMN TO THE PERSON NAMED IN COLU	Unicade	-	774	Ide recurs for	Sacratif Fac	Southwell was Carse	div.
Bidding Place   Place								182	Ampi Country Roses	Detail		111	Hermone Fa	Sacrat Flat	Southwest Hastin Corner	EC0.4M
Redding Place   Place   Place   Place   Place   Place   Place   Remark in Type   Remark in								0	Some Very Reserve - Production	United	Testart	0.20	War washing from	Secret Flu	Studiowed Physics Contact	ME-000
Bildridig Pasc Pasc 1732 Boomé finem (in 1794 particular)  Commonth (in 1794 particular)  Com								=	Sergi Condu	- 1	1811	D-246	Married Walls	Second Fran	Southwest Health Corner	100.48
Redding Place   Place   Place   Place   Place   Place   Place   Reach   Research   Place   Reach   Rea									Senial Creati	1		0.00			Street Street Comm	1
Bildfürg Pasc Pasc Typs Boomé Resm Vin Type Bo									Sent Market	1		0.71			Summer team Owner	100
Bildfüllig Floor Floor Type Book of Sean-Vall-Type Book of Sean-Vall								3	e al Carrier de Con	-	CHARGO STATE	105.0	ī	The same of	Confirmed Health Confer	an out
Building Floor Type Roam of Reservior Type Roam of Reservior Type Roam (In Type Roam Utilization Connections for Roam Roam Roam Utilization Connections for Roam Roam Roam Utilization Connections for Roam Roam Roam Utilization Connections Roam Roam Utilization Connections Roam Roam Utilization Connections Roam Roam Utilization Connections Roam Roam Utilization Connections Roam Roam Utilization Connections Roam Roam Utilization Connections Roam Roam Utilization Connections Roam Roam Utilization Connections Roam Roam Utilization Connections Roam Roam Utilization Connections Roam Roam Utilization Connections Roam Roam Utilization Connections Roam Roam Utilization Connections Roam Roam Utilization Connections Roam Roam Roam Utilization Connections Roam Roam Roam Utilization Connections Roam Roam Roam Utilization Connections Roam Roam Roam Roam Utilization Connections Roam Roam Roam Utilization Connections Roam Roam Roam Roam Roam Roam Roam Roam								8 2	A STATE OF THE PARTY OF THE PAR		The Party of the P	0.000		The same of	Company Man Comm	100
Balddig Face Pace Type Roam 6 from 1/1 Type Roam 6 from 1/1 Type Roam 6 from 1/2 Type Roam 6	2,007	1,000						Commen							The Samuel Annual States	Anna Anna
	Gross Bquar	Canble Square	Owner Nomenclature Source	Room Utilization	Same Day Source	-	Comments	MD MUTTER	Demer Nemenolature for Room	Raom Utilization	Rosen Use Type	Roun &	Flaor Typs	Flaor	Building	A biomy little

(Prom Anternation	eutonii .	Plane	Hour Type	Heren a	House Use Type	Major (Impation (IMMACS)	Dener Namenaturies for Name	Mensured   BQF (Rotton)	Comments	Hanni F Seúnse	Hours the Searce	Romin Contration Source	Owner homenstature Source	Madesured Source	Yetal Messure Gross Squark Feet
MF-033	Southwest Health Center	There Flower	Intermediate Fixed	303	Cont	Utezes	Storage Chart	82							
W7-033	Southwest Health Center:	Third Floor	intermediate Floor	136	Statust	WASHI	Digital	34							
WF-002	Southwest Health Center	Trent F==	Titleresestiale Fluor	327	Utcategorand	atteant	Cheeter Machanical Room	33							
MF-632	Sudhwell Heath Center	Third Poor	Internacional Picor	223	Stolage	Utiletel	Biggles	22							
MF-032	Southwest Health Center	TitleFee	Intermediate Pione	324	diorage	Sitteed	Burpres	- 27							
MF-032 MF-233	Stadewall Freight Center	Theid Fame	Northedate Flore	125	dmrege:	Without	Darpees	38						100	
97-010	Southwest meath Center	Third Floor	intermediate Pales	228	Cavets	'Utraed	Klevator :	28							
Section	Print Hills on State	Thoughton.	Sancrasatura Pinas	2.56	Manhorated	- Children	Non-Erro	14							