

# KRAMER HEERY

#### **GOVERNMENT OF THE DISTRICT OF COLUMBIA** DEPARTMENT OF GENERAL SERVICES

The following components make up the evaluated fees:

- 1. Topo & Boundary
- 2. Field Investigation & Additional Recommendation
- 3. Demo Plan
- 4. Site & Utility Plan
- 5. Grading Plan
- 6. Landscape & Hardscape Plan
- 7. Soil Management Plan
- 8. Specifications

- 9. Arborist Services
- 10. Sediment Control / SWM Plan
- 11. Meetings / Community Outreach
- 12. Building Plat
- 13. Dry Utility Coordination
- 14. Design & Construction Documents

	MHG
Topo & Boundary	\$11,000
Field Investigation & Additional Recommendation	Included
Demo Plan	Included
Site & Utility Plan	Included
Grading Plan	\$5,500
Landscape & Hardscape Plan	\$7,500
Soil Management Plan	Included
Specifications	\$1,500
Arborist Services	\$5,000
Sediment Control / SWM Plan	\$10,000
Meetings / Community Outreach	\$8,000
Building Plat	Included
Dry Utility Coordination	Included
Design & Construction Documents	Included
Total Fees	\$48,500
* Arborist Fees Not Included	
Add	
Geotechnical Reports	\$17,520
Archeological Phase 1 Reports	\$15,904

I would like to recommend moving forward with **Macris, Hendricks, & Glascock, P.A (MHG)** to provide Civil Engineering / Landscape Design services for the Kalorama Park Site Remediation project.

Please contact me if you need more information or clarification on this recommendation.

Sincerely,

Shahrokh Ghahramani Digitally signed by Shahrokh Ghahramani DN: cn=Shahrokh Ghahramani, e=Department of General Services (RRAMER | Hery), o,=Capital Construction Services (CPR Portfolio), email=Shahrokh, Ghahramani@dc, gov, c=US Date: 2014.04.21 15:49:10 -0400'

#### Shahrokh Ghahramani

Project Manager KRAMER | Heery Department of General Services Capital Construction Services (DPR Portfolio)

#### GOVERNMENT OF THE DISTRICT OF COLUMBIA DEPARTMENT OF GENERAL SERVICES



Contracts & Procurement Division

#### Purchase Order Agreement

Date: November 28, 2012

P.O. Number: TBA

THIS PURCHASE ORDER is issued by the Government of the District of Columbia, acting by and through its **DEPARTMENT OF GENERAL SERVICES** (the "Department" or "DGS") to the contractor listed below. Assuming this Purchase Order is countersigned by the contractor without modification of any kind, it shall constitute a binding legal contract between the Department and the contractor. The terms of this Purchase Order are as follows:

- 1. Contractor. This Purchase order is being issued to Turf Center Lawns, Inc.
- 2. Items Purchased. The Department desires to purchase, and the contractor agrees to provide, landscaping services at Kalorama Park, as further explained on <u>Exhibit A</u>. Turf Center Lawns will provide all labor, materials, and supervision to perform this work.
- 3. Price. For the work described above, the Contractor will be paid a lump sum of \$5,377. In no event shall the Contractor be paid more than this amount unless the Contractor is authorized to exceed this limit in advance and in writing by DGS' contracting officer.
- 4. Delivery/Completion Date. The work that is the subject of this Purchase Order Agreement shall be completed within two (2) weeks of execution of this Purchase Order Agreement.
- 5. Billing. All invoices shall be submitted directly to the Department at the address specified above. Properly prepared invoices with the necessary backup shall be paid within thirty (30) days of receipt. Invoices not paid by that date shall bear interest in accordance with the Prompt Payment Act.
- 6. Insurance. At all times while working under this Purchase Order Agreement, the Contractor shall maintain the following insurance: (i) a comprehensive general liability policy having a policy limit of at least One Million Dollars (\$1,000,000) and including completed operations coverage; and (ii) workers compensation coverage at the statutory limit. Such policies shall be endorsed to add the District of Columbia, including, but not limited to, its Department of General Services, and the respective agents, employees and offices of each as additional insureds.
- 7. Terms & Conditions. The District of Columbia's Standard Contract Provisions shall be incorporated by reference into this Purchase Order. The Contractor will perform work in accordance with the 2006 edition of the International Building, Plumbing, Mechanical, Fire, Fuel, and Energy Conservation Code and the 2008 edition of the District of Columbia Construction Code Supplement, ordinances, and regulations, which are enforced by the District of Columbia and relevant federal agencies.

#### Page 2

- 8. Special Provisions.
- A. [Intentionally omitted was Building Code]
- B. [Intentionally omitted was Security]
- C. Warranty. Contractor shall provide a warranty for the Work if noted in the proposal.
- D. [Intentionally omitted was Punchlist]
- E. [Intentionally omitted was Work site]
- **F.** Indemnification. To the fullest extent permitted by law, the Contractor shall indemnify and hold harmless the Department and the Department's consultants and agents and employees from and against claims, damages, losses and expenses, including but not limited to attorneys' fees, arising out of or resulting from performance of the Work, provided that such claim, damage, loss or expense is attributable to bodily injury, sickness, disease or death, or to injury to or destruction of tangible property (other than the Work itself), but only to the extent caused by the negligent acts or omissions of the Contractor, a subcontractor, anyone directly or indirectly employed by them or anyone for whose acts they may be liable, regardless of whether or not such claim, damage, loss or expense is caused in part by a party indemnified hereunder.

ACCEPTED BY:

#### **ISSUED BY:**

By:		By:	2 Alatte
Name:	JW Lanum	Name:	Robert Patt
Title:	Associate Director,	Title:	Vice Prosiduat
	Contracts & Procurement Division	Date:	12/1/2017
Delegat	tion: October 11, 2011		1

Turf Center Lawns, Inc.

P.O. Box 9 Spencerville, MD 20868

Phone # (301) 384-9300

Fax # (301) 384-9304

www.turfcenterlawns.com

	Proposal Submitted To: DC Department of Parks and Recreation Brent Sisco 1250 U Street NW   Washington, DC 20009 Job Site if different address		SPECIALIZIN CO Grading-Turf M Sodding-Lawn Athletic Fields- Construction &	G IN PROBLEM MPLETE fanagement-Lan Renovations-To Play Grounds Maintenance	I LAWNS dscaping p Dressing
			Rep	Custome	Phone
-			ĸ	202.615	.9824
INS GAI OP1	TALLATION OF THE FOLLOWING: 25 LIGUST LLON I" CALIPER, INCLUDES SOIL AMENDM FIONAL; SMALLER SIZE CANOPY RED BUD FO	RUM 3 GALLON, 6 FOREST PANSY R ENTS AND MULCH RINGS AND STAF DREST PANSY	ED BUD 6' HT, 1 (ING OF TREES.	5	2,737.00
	- Al	Date	Subtotal		\$5,377.00

William Patton Sr.

**Customer Signature** 

We propose hereby to furnish material and labor - complete in accordance with above specification. A deposit of 30% is required and balance due upon completion of job. 1.5% month on unpaid balance. No alterations or amendments to this contract shall be valid unless agreed to in writing by both parties hereto. All material is guaranteed to be as specified. All work to be completed in a workmanlike manner according to standard practices. Any alteration or deviation from above specifications involving extra costs will be executed only upon written orders, and will become an extra charge over and above the estimate. All agreements contingent upon strikes, accidents or delays beyond our control. Owner to carry fire, tornado and other necessary insurance. Our workers are fully covered by Workmen's Compensation Insurance.

MHIC LIC #42094

Sales Tax (6.0%)

Total

\$0.00

\$5,377.00

# Proposal

Date	Proposal #
11/29/2012	32910

# **PROJECT MANUAL**

# **KALORAMA PARK**

# PHASE I

October 17, 2014

Macris, Hendricks & Glascock, P.A. Engineers • Planners • Surveyors • Landscape Architects 9220 Wightman Road, Suite 12C Montgomery Village, Maryland 20886-1279





#### **PROJECT DIRECTORY**

# October 17, 2014 **OWNER:** District of Columbia Department of General Services / Department of Parks & Recreation 1250 U Street, NW 4<sup>th</sup> Floor Washington, DC 20009 (202) 478-2427 Attention: Shahrokh Ghahramani **CIVIL ENGINEER & LAND SURVEYOR:** Macris, Hendricks & Glascock, P.A. 9220 Wightman Road, Suite 120 Montgomery Village, MD 20886 (301) 670-0840 Attention: Patrick G. La Vay, P.E. **ARBORICULTURE & ENVIRONMENTAL CONSULTANT:** Norton Land Design

17830 New Hampshire Avenue, Suite 101 Ashton, MD 20861 (240) 342-2632 Attention: Michael Norton

LANDSCAPE ARCHITECT:

Macris, Hendricks & Glascock, P.A. 9220 Wightman Road, Suite 120 Montgomery Village, MD 20886 (301) 670-0840 Attention: Patrick G. La Vay, P.E.

**GEOTECHNICAL ENGINEER:** 

ECS Capitol Services, PLLC 655 15<sup>th</sup> Street, NW Washington, DC 20005 (202) 400-2188 Attention: Stephen Patt, P.E.

DATE:

# TABLE OF CONTENTS

## DIVISION 2 SITEWORK

- 02050 Geotechnical Investigations
- 02055 Soils
- 02230 Site Clearing
- 02231 Tree Preservation
- 02311 Rough Grading
- 02315 Excavation and Fill
- 02320 Backfill
- 02750 Portland Cement Concrete Pavement
- 02923 Landscape Grading
- 02930 Exterior Plant Material

#### SECTION 02050 - SUBSURFACE INVESTIGATIONS

#### PART 1 GENERAL

#### 1.1 SUMMARY

- A. Section includes the results of the subsurface investigations made on the Project site for the purposes of determining the subsurface conditions relative to the following:
  - 1. General descriptions of the subsurface soil and groundwater conditions at the site.
  - 2. Evaluation of previously constructed areas to assess the amount of unsuitable debris material left from previous construction activity.
  - 3. Comments on geotechnical aspects of the associated construction that were readily apparent at the time of the preliminary investigation.
  - 4. Infiltration rates and subsurface information applicable to stormwater management areas.
  - 5. Recommendations for earthwork requirements, excavation and construction related information for the substrate conditions encountered in the test borings.
- B. Technical Memo #1, dated June 29, 2012, included in this section was prepared by David Volkert & Associates Engineering, P.C. and is available to prospective bidders and/or contractors for informational purposes only. The opinions expressed in these reports are those of the engineer and represent their interpretation of the subsurface conditions, tests and results of analyses that they performed. Should the data in these reports not be adequate for the contractor's purposes, the contractor may make his own investigations, tests and analyses prior to bidding. Contractors desiring to conduct additional subsurface explorations prior to bidding should contact the Owner for arrangements to enter the project site.
- C. Technical Memo #2, dated June 6, 2012, included in this section was prepared by David Volkert & Associates Engineering, P.C. and is available to prospective bidders and/or contractors for informational purposes only. The opinions expressed in these reports are those of the engineer and represent their interpretation of the subsurface conditions, tests and results of analyses that they performed. Should the data in these reports not be adequate for the contractor's purposes, the contractor may make his own investigations, tests and analyses prior to bidding. Contractors desiring to conduct additional subsurface explorations prior to bidding should contact the Owner for arrangements to enter the project site.
- D. The Geotechnical Services Report, dated August 15, 2014, included in this section was prepared by ECS Capitol Services, PLLC and is available to prospective bidders and/or contractors for informational purposes only. The report has been prepared for design purposes only and may not be sufficient to prepare an accurate bid for construction. Contractors wishing to obtain copies of this report may secure them from ECS Capitol Services, PLLC at a nominal charge with the understanding that its scope is limited solely to design considerations. The opinions expressed in these reports are those of the geotechnical engineer and represent their interpretation of the subsurface conditions, tests and results of analyses that they performed. Should the data in these reports not be adequate for the contractor's purposes, the contractor may make his own investigations,

tests and analyses prior to bidding. Contractors desiring to conduct additional subsurface explorations prior to bidding should contact the Architect for arrangements to enter the project site.

- E. The Contractor, at his own expense, may conduct additional subsurface investigations, tests and analyses with the prior approval of the Owner.
- F. Field logs and laboratory data sheets are available only in the office of the geotechnical engineer and will be available only at his discretion.

## PART 2 PRODUCTS

2.1 NOT USED

## PART 3 EXECUTION

3.1 NOT USED

## END OF SECTION 02050

# David Volkert & Associates Engineering, P.C.

ENGINEERS • LANDSCAPE ARCHITECTS • PLANNERS • ENVIRONMENTAL SCIENTISTS 5028 Wisconsin Ave., NW, Suite 403, Washington, DC 20016 Phone: (202) 237-6269, Fax: (202) 237-6279, E-mail: dc@volkert.com

# **TECHNICAL MEMO 1 - SITE INVESTIGATION NOTES**

PROJECT: Kalorama Park

Volkert No. 230405.60

DATE OF INVESTIGATION: June 6, 2012

1:00 pm - 4:00 pm

LOCATION: Project Site

DATE OF REPORT: June 18, 2012

Prepared by: Oliver Boehm and Bereket Merzi, Volkert



ATTENDEES AT MEETING:

Name	Organization	Attendance
Brent Sisco	Department of Parks Recreation (DPR)	Х
Bereket Merzi	Volkert, Inc.	Х
Oliver Boehm	Volkert, Inc.	X

Task 1:Review of Existing Documentation: Photographs of previous construction activities<br/>provided by DPR.



Photographs of construction of timber retaining wall.



Photographs of construction debris and soil medium below lawn and planting areas.

## Task 2:Investigation of the Existing Conditions for Compliance

On June 6, 2012 Volkert conducted an investigation at the Kalorama Park site. The purpose of our investigation was to evaluate the conditions in the field and determine if further steps are required to complete the construction of the site.

We took samples at 6 locations throughout the site. Five of these were test pits were in lawn areas (TP#1 through TP#5) and one was a composite sample taken in the planting bed (TP#6) adjacent to the basketball court. Various excavations in this planting bed were taken to understand the condition of the entire area.

We also conducted a visual evaluation of the berms (B1, B2, and B3), planting beds, and other constructed elements. Our investigation of the site revealed that various elements of the proposed improvements were not properly constructed. The following are our findings and recommendations.



## A. Site Plan

Site Plan from sheet 4 of the construction drawings, dated 11/6/2009

# **B.** Soil Condition – Test Pits

## Locations (See Site Plan, above)

The location for the test pits were determined based on observations during renovation of the park. It is believed that construction procedures used did not comply with the construction drawings, which resulted in construction debris being buried under the lawn areas.



## Weather Conditions

Weather conditions were sunny and fair with low humidity. Rain fall occurred the previous day.

#### General Method

The pits were dug using small hand tools (pick ax, shovel, and a manual auger). The pits were dug to a depth sufficient to determine the extent of construction and nature of the soil medium.



#### TP#1 - Test Pit No. 1:





TP#1: 0"-12"



#### TP#1: 12"-18'



# TP#1: 0"-12"

The top layer of test pit #1 consists of clay like medium that appears to be bonded together. Grass has not established to a satisfactory condition and appears in only small patches. At 6" we encountered a slightly loamy sand mix.

#### **TP#1: 12"-18"**

At 12 to 18 inches, we encountered layers of sand and construction debris, such as filter fabric. The filter fabric layer was found at 18" between two layers of sand. The sand layers were 2"-3" thick each.

#### TP#1: 18"-24"

At 18 to 24 inches, we encountered sandy soil and construction debris. The construction debris consisted of pieces of concrete, asphalt, brick, and filter fabric.

#### TP#1: 24" and deeper

As the boring process continued it was clear the layer of sand mixed with construction debris extended throughout the area around TP#1.

OBSERVATION	INITIAL RECOMMENDATIONS
See Above.	Remove top 12" of material and provide suitable
	mix.

#### TP#2 - Test Pit No. 2:





The top layer of test pit #2 consists of clay like medium that appears to be bonded together. Grass has not established to a satisfactory condition and appears in only small patches. At 6" we encountered a slightly loamy sand mix.

At 12 to 18 inches, we encountered layers of sand and construction debris, such as filter fabric. The filter fabric layer was found at 18" between two

layers of sand. The sand layers were 2"-3" thick each.





#### TP#2: 12"-18"



#### TP#1: 18"-24"

TP#1: 12"-18"

At 18 to 24 inches we encountered sandy soil and construction debris. The construction debris consisted of pieces of concrete, asphalt, brick, and filter fabric.

#### TP#1: 24" and deeper

As the boring process continued it was clear the layer of sand mixed with construction debris extended throughout the area around TP#2.

OBSERVATION	INITIAL RECOMMENDATIONS
See Above.	a. Remove top 12" of material and provide
	suitable mix.
	b. Treat with sod or seed.

#### TP#3 - Test Pit No. 3:





#### TP#3: 0"-12"



#### TP#3: 12"-24"

#### TP#3: 0"-12"

At the top layer of test pit #3 the grass seemed to have taking normally. However, the grass mix appeared to contain weeds. At 2 to12 inches we encountered natural soil with some small rocks.

#### **TP#3: 12"-24"**

At 18 to 24 inches we encountered a slightly sandy medium with some small rocks. The soil moisture appeared suitable.

OBSERVATION	INITIAL RECOMMENDATIONS
See Above.	a. Remove top 6" of material and provide
	suitable mix.
	b. Treat with sod or seed.

#### TP#4 - Test Pit No. 4:





**TP#4: 0"-12"** 

At 0 to 12 inches we encountered soil mixed with sand, clay and construction entrance debris. Soil excavation was hindered by numerous stones and hard soil.

#### **GENERAL:**

Review of the construction drawings indicates that this area was a construction entrance during the construction of the site improvements. The stones and the hard subsurface encountered may be the result of improper removal of the construction entrance material.

OBSERVATION	INITIAL RECOMMENDATIONS
See Above.	a. Remove top 36" of material and provide
	suitable mix.
	b. Treat with sod or seed.







**TP#5: 0"-12"** At 0 to 12 inches we encountered natural soil. Soil appeared to be slightly dryer than expected, but otherwise acceptable.

TP#5: 0"-12"

OBSERVATION	INITIAL RECOMMENDATIONS
See Above.	a. Remove top 6" of material and provide suitable mix

#### **TP#6 - Test Pit at Planting Bed:**







## TP#6: 0"-6"

At 0 to 6 inches we encountered a layer of mulch on wet soil. The clay like medium appeared to be inadequate. However, the plants appeared healthy. Roots of shrubs have spread through the planting medium. Weeds are abundant. Roots of weeds remain on the top 1 inch of the planting soil.

TP: 0"-6"



TP: 6"-12"

#### TP#6: 6"-12"

At 6 to 12 inches the soil medium was continuously moist with minor construction debris.

OBSERVATION	INITIAL RECOMMENDATIONS
See Above.	Remove weeds (Also see recommendations in
	the Plantings section).

# C. Berms (Adjacent to Bioswales) & Drainage



Bioswale details from sheet 8 of the construction drawings, dated 11/6/2009



Berm B1



Catch Basin at Berm B1

OBSERVATION	INITIAL RECOMMENDATIONS
• Bioswale appears to be working normally.	a. Prepare bare areas around the catch basin for
• Berm is mostly well covered with lawn. In some area, bare patches	new lawn.
appear.	b. Treat area with seed or sod.
• Soil uphill of the berm appears to be adequate (See TP#3 above).	c. Flush catch basin and cleanout pipes.
• Catch basin at the end of bioswale has standing water. The outfall pipe	
appears to be clogged.	



Berm B2



Catch Basin at Berm B2

OBSERVATION	INITIAL RECOMMENDATIONS
• Bioswale appears to be working normally.	a. Treat area with seed or sod.
• Berm is mostly well covered with lawn. In some area, bare patches	b. Flush catch basin and cleanout pipes.
appear.	
• Catch basin at the end of bioswale is dry.	



Berm B3



# Catch Basin at Berm B3

OBSERVATION	INITIAL RECOMMENDATIONS
• Bioswale appears to be working normally.	a. Prepare bare areas around the catch basin for
• Berm is mostly well covered with lawn. In some area, bare patches	new lawn.
appear.	b. Treat area with seed or sod.
• Catch basin at the end of bioswale has miscellaneous debris.	c. Remove debris in catch basin. Flush catch
	basin and cleanout pipes.

# **D.** Plantings



Landscape Plan from sheet 16 of the construction drawings, dated 11/6/2009, Note: Timber retaining wall is not shown



OBSERVATION	INITIAL RECOMMENDATIONS
There are weeds throughout the site.	a. Remove weeds.



# **OBSERVATION**

- Vines and trees are hanging over planted materials and site features. •
- Trees at the 19<sup>th</sup> Street NW entrance into the park appear to be in • poor health. Roots may have been damaged from construction activity.

#### **INITIAL RECOMMENDATIONS**

Prune shrubs and ground cover. a.

- Have tree roots pruned and treated by b. arborist.
- Trees that are dead or dying should be c. replaced or treated as directed by arborist.





## Shrubs and Groundcover at West Entrance

OBSERVATION	INITIAL RECOMMENDATIONS
• Most shrubs and other plantings in the 19 <sup>th</sup> Street entrance planters are	a. Remove filter fabric, debris, and weeds.
in poor condition. Soil condition seems to be a loamy clay. Unlike the	b. Remove top 6" of soil in planter boxes and
condition in Soil Test Pit Area 6, the plants in this area do not seem to	replace with planting soil. Install heavy duty
have access to the moisture and are in decay. Planting beds at the west	filter fabric. Cut opening in fabric to allow
entrance of the park are full of weeds and grass. Grass adjacent to	shrubs to grow. Install a 3" thick layer of
planters is in poor condition. Filter fabric and debris is exposed	mulch to the top of timber plank. Shrubs
around planters.	should stay in place, undisturbed.
-	c. Treat area around planter boxes with sod or
	seed

# E. Areas Around Walls And Planters



0	BSERVATION	INITIAL RECOMMENDATIONS	
•	Pavement between basketball court and retaining wall is missing and hazardous. Foundation of previously existing basketball court remains in place,	a. b.	Remove top 12" of old basket ball hoop concrete foundation. Install basketball court surface with a
	and is an obstruction to anyone using the court.		concrete base at gap between retaining wall and existing court. Provide a continuous expansion joint between wall and subbase.





Terraced Timber Retaining Wall and Planter				
OBSERVATION		INITIAL RECOMMENDATIONS		
•	Terraced wall was installed by second contractor without plans.	a. Remove planting and filter fabric at the north		
•	Terraced planting bed at the north ends is eroding and existing filter	sod or seed. Provide $\pm 18$ " dia. rounded loose		
	fabric is falling apart.	stone edging between grass and planter to separate lawn from planting (see images		
		above). There should be no digging past 12".		

#### T:\230405 - Kalorama Park Improvements\02 General Data\Reports\20120606 Site Investigation.doc

# F. Fencing



0	BSERVATION	INITIAL RECOMMENDATIONS
•	New black fence and previously existing fence are poorly tied	a. Correctly tie new fence fabric to fence posts.
	together with miscellaneous fence fabric.	

# David Volkert & Associates Engineering, P.C.

ENGINEERS • LANDSCAPE ARCHITECTS • PLANNERS • ENVIRONMENTAL SCIENTISTS 5028 Wisconsin Ave., NW, Suite 403, Washington, DC 20016 Phone: (202) 237-6269, Fax: (202) 237-6279, E-mail: dc@volkert.com

# **TECHNICAL MEMO 2 - RECOMMENDATIONS**

PROJECT: Kalorama Park (Volkert No. 230405.60)

DATE OF REPORT: June 29, 2012

Prepared by: Oliver Boehm and Bereket Merzi, Volkert

# **Description of Technical Memo 1 Site Investigation Notes - Task 1: Review of Existing Documentation and Task 2: Investigation of the Existing Conditions for Compliance**

On June 6, 2012 Volkert conducted an investigation at the Kalorama Park site. The purpose of our investigation was to evaluate the conditions in the field and determine if further steps are required to complete the construction of the site.

We took samples at 6 locations throughout the site. Five of these were test pits in lawn areas (TP#1 through TP#5) and one was a composite sample taken in the planting bed (TP#6) adjacent to the basketball court. The location for the test pits were determined based on observations during renovation of the park. It is believed that construction procedures during the two previous contracts did not comply with the construction drawings, which resulted in construction debris being buried under the lawn areas.

We also conducted a visual evaluation of the berms (B1, B2, and B3), planting beds, and other constructed elements. Our investigation of the site revealed that various elements of the proposed improvements were not properly constructed or have deteriorated.

A thorough report of the Site Investigation is documented in Technical Memo #1 submitted on June 18, 2012 by Volkert for review.

#### **Task 3: Recommendations for Improvements**

This plan represents the site improvement zones and berms, which are describe in this technical memo. This information will be used to develop biddable plans and specifications for improvements to Kalorama Park.



#### A. Soil Test Pit Areas 1 and 2 are combined to make up Site Improvements Zone A Test Pit Area #1 (See Technical Memo #1, Site Investigation Notes, For Detailed Information)

**TP#1: 0''-12'':** The top layer of test pit #1 consists of clay like medium that appears to be bonded together. Grass has not established to a satisfactory condition and appears in only small patches. At 6'' we encountered a slightly loamy sand mix.

**TP#1: 12"-18":** At 12 to 18 inches, we encountered layers of sand and construction debris, such as filter fabric. The filter fabric layer was found at 18" between two layers of sand. The sand layers were 2"-3" thick each.

**TP#1: 18"-24":** At 18 to 24 inches, we encountered sandy soil and construction debris. The construction debris consisted of pieces of concrete, asphalt, brick, and filter fabric.

**TP#1: 24" and deeper:** As the boring process continued it was clear the layer of sand mixed with construction debris extended throughout the area around TP#1.

## Test Pit Area #2 (See Technical Memo #1, Site Investigation Notes, For Detailed Information)

**TP#2: 0"-12":** The top layer of test pit #2 consists of clay like medium that appears to be bonded together. Grass has not established to a satisfactory condition and appears in only small patches. At 6" we encountered a slightly loamy sand mix.

**TP#2: 12"-18":** At 12 to 18 inches, we encountered layers of sand and construction debris, such as filter fabric. The filter fabric layer was found at 18" between two layers of sand. The sand layers were 2"-3" thick each.

**TP#2: 18"-24":** At 18 to 24 inches we encountered sandy soil and construction debris. The construction debris consisted of pieces of concrete, asphalt, brick, and filter fabric.

**TP#2: 24" and deeper:** As the boring process continued it was clear the layer of sand mixed with construction debris extended throughout the area around TP#2.

# FINAL RECOMMENDATIONS FOR SITE IMPROVEMENTS ZONE A

- 1. The contractor shall remove all soil in the area to a depth of three feet. Soil shall be hauled from site and disposed. Additional depth may be required if conditions below three feet warrant soil removal. The approximate area of the soil removal is 7,860 Square Feet which equals 97 Cubic Yards.
- 2. The contractor shall bring in new landscape quality soil to reach current grades. Soil shall be placed in 12 inch lifts and lightly compacted at each lift. It is recommended that the following soil mix be used: "Sandy Loam" determined by mechanical analysis and based on the "USDA Classification System". The introduced soil shall meet the following mechanical analysis:

Texture Class	:	% of Total Weight
Clay	:	10 - 15
Silt	:	30 - 40
Sand	:	50 - 70
Organic Matter	:	3 - 4
pH level	:	5 - 7

**3.** The contractor shall provide and established lawn with sod. It is recommended that the following grass mix be used:

**Proportioned by weight as follows:** 

20 percent Tall Fescue- "Inferno".
20 percent Tall Fescue- "Second Millennium"
20 percent Tall Fescue- "Magellan"
20 percent Tall Fescue- "Avenger"

20 percent Kentucky Bluegrass- "Liberator"

Sod of grass species shall have not less than 95 percent germination, not less than 85 percent pure seed, and not more than 0.5 percent weed seed.

4. The contractor shall maintain the lawn area for a 90 day period. At end of maintenance period, a healthy, well-rooted, even-colored, viable lawn should established, free of weeds, open joints, bare areas,

and surface irregularities. Maintenance shall include:

- a. Watering, fertilizing, weeding, mowing, trimming, replanting, and performing other operations as required to establish healthy, viable lawn.
- b. Roll, regrade, and replant bare or eroded areas to produce a uniformly smooth lawn.
- c. Water lawn with gentle spray, unless rainfall precipitation is adequate.
- d. Mow lawn as soon as top growth is tall enough to cut.
- e. Apply fertilizer after initial mowing and when grass is dry.

#### B. Soil Test Pit Area 4 is Site Improvements Zone B (See Site Plan on page 1) Test Pit Area #4 (See Technical Memo #1, Site Investigation Notes, For Detailed Information)

**TP#4: 0"-12":** At 0 to 12 inches we encountered soil mixed with sand, clay and construction entrance debris. Soil excavation was hindered by numerous stones and hard soil.

**GENERAL:** Review of the construction drawings indicates that this area was a construction entrance during the construction of the site improvements. The stones and the hard subsurface encountered may be the result of improper removal of the construction entrance material.

# FINAL RECOMMENDATIONS FOR SITE IMPROVEMENTS ZONE B

- 1. The contractor shall remove all soil in the area to a depth of three feet. Soil shall be hauled from site and disposed. Additional depth may be required if conditions below three feet warrant soil removal. The approximate area of the soil removal is 1,630 Square Feet which equals 181 Cubic Yards.
- 2. The contractor shall bring in new landscape quality soil to reach current grades. Soil shall be placed in 12 inch lifts and lightly compacted at each lift. It is recommended that the following soil mix be used: "Sandy Loam" determined by mechanical analysis and based on the "USDA Classification

System". The introduced soil shall meet the following mechanical analysis: <u>Texture Class</u> : % of Total Weight

Texture Class	:	% of Tot
Clay	:	10 - 15
Silt	:	30 - 40
Sand	:	50 - 70
Organic Matter	:	3 - 4
pH level	:	5 - 7

**3.** The contractor shall provide and established lawn with sod. It is recommended that the following grass mix be used:

Proportioned by weight as follows:

20 percent Tall Fescue- "Inferno".

20 percent Tall Fescue- "Second Millennium"

20 percent Tall Fescue- "Magellan"

20 percent Tall Fescue- "Avenger"

20 percent Kentucky Bluegrass- "Liberator"

Sod of grass species shall have not less than 95 percent germination, not less than 85 percent pure seed, and not more than 0.5 percent weed seed.

- 4. The contractor shall maintain the lawn area for a 90 day period. At end of maintenance period, a healthy, well-rooted, even-colored, viable lawn should established, free of weeds, open joints, bare areas, and surface irregularities. Maintenance shall include:
  - a. Watering, fertilizing, weeding, mowing, trimming, replanting, and performing other operations as required to establish healthy, viable lawn.
  - b. Roll, regrade, and replant bare or eroded areas to produce a uniformly smooth lawn.
  - c. Water lawn with gentle spray, unless rainfall precipitation is adequate.
  - d. Mow lawn as soon as top growth is tall enough to cut.
  - e. Apply fertilizer after initial mowing and when grass is dry.

#### C. Soil Test Pit Areas 3 and 5 are Site Improvements Zone C (See Site Plan on page 1) Test Pit Area #3 (See Technical Memo #1, Site Investigation Notes, For Detailed Information)

**TP#3: 0"-12":** At the top layer of test pit #3 the grass seemed to have taking normally. However, the grass mix appeared to contain weeds. At 2 to12 inches we encountered natural soil with some small rocks. **TP#3: 12"-24":** At 18 to 24 inches we encountered a slightly sandy medium with some small rocks. The soil moisture appeared suitable.

#### Test Pit Area #5 (See Technical Memo #1, Site Investigation Notes, For Detailed Information)

**TP#5: 0"-12":** At 0 to 12 inches we encountered natural soil. Soil appeared to be slightly dryer than expected, but otherwise acceptable.

# FINAL RECOMMENDATIONS FOR SITE IMPROVEMENTS ZONE C

- 1. The contractor shall remove top 3 inches of soil and turf. Soil and turf shall be hauled from site and disposed. The approximate area of the soil removal is 5,380 Square Feet which equals 200 Cubic Yards.
- 2. The contractor shall bring in new landscape quality soil to reach current grades. It is recommended that the following soil mix be used:

"Sandy Loam" determined by mechanical analysis and based on the "USDA Classification System". The introduced soil shall meet the following mechanical analysis:

Texture Class	:	% of Total Weight
Clay	:	10 - 15
Silt	:	30 - 40
Sand	:	50 - 70
Organic Matter	:	3 - 4
pH level	:	5 - 7

**3.** The contractor shall provide and established lawn with sod. It is recommended that the following grass mix be used:

**Proportioned by weight as follows:** 

- 20 percent Tall Fescue- "Inferno".20 percent Tall Fescue- "Second Millennium"
- 20 percent Tall Fescue- "Magellan"
- 20 percent Tall Fescue- "Avenger"
- 20 percent Kentucky Bluegrass- "Liberator"

Sod of grass species shall have not less than 95 percent germination, not less than 85 percent pure seed, and not more than 0.5 percent weed seed.

- 4. The contractor shall maintain the lawn area for a 90 day period. At end of maintenance period, a healthy, well-rooted, even-colored, viable lawn should established, free of weeds, open joints, bare areas, and surface irregularities. Maintenance shall include:
  - a. Watering, fertilizing, weeding, mowing, trimming, replanting, and performing other operations as required to establish healthy, viable lawn.
  - b. Roll, regrade, and replant bare or eroded areas to produce a uniformly smooth lawn.
  - c. Water lawn with gentle spray, unless rainfall precipitation is adequate.
  - d. Mow lawn as soon as top growth is tall enough to cut.
  - e. Apply fertilizer after initial mowing and when grass is dry.

D. Soil Test Pit Area 6, the eroded area north of the terraced timber retaining wall, and the planting areas at the entrance into the park from 19<sup>th</sup> Street NW are combined in Site Improvements Zone D (See Site Plan on page 1)

#### Test Pit Area #6 (See Technical Memo #1, Site Investigation Notes, For Detailed Information)

**TP#6: 0"-6":** At 0 to 6 inches we encountered a layer of mulch on wet soil. The clay like medium appeared to be inadequate. However, the plants appeared healthy. Roots of shrubs have spread through the planting medium. Weeds are abundant. Roots of weeds remain on the top 1 inch of the planting soil.

TP#6: 6"-12": At 6 to 12 inches the soil medium was continuously moist with minor construction debris.

#### Terraced Timber Wall North End (See Technical Memo #1, Site Investigation Notes, For Detailed Information)

Terraced timber wall was installed by second contractor without plans. Layout was coordinated with DPR. Terraced planting bed at the north ends is eroding and existing filter fabric is falling apart.

#### 19<sup>th</sup> Street Entrance (See Technical Memo #1, Site Investigation Notes, For Detailed Information)

Trees at the 19<sup>th</sup> Street NW entrance into the park appear to be in poor health. Roots may have been damaged from construction activity.

Most shrubs and other plantings in the 19<sup>th</sup> Street entrance planters are in poor condition. Soil condition seems to be a loamy clay. Unlike the condition in Soil Test Pit Area 6, the plants in this area do not seem to have access to the moisture and are in decay. Planting beds at the west entrance of the park are full of weeds and grass. Grass adjacent to planters is in poor condition. Filter fabric and debris is exposed around planters.

# FINAL RECOMMENDATIONS FOR SITE IMPROVEMENTS ZONE D

- **1.** In lawn areas, the contractor shall remove top 3 inches of soil and turf. Soil and turf shall be hauled from site and properly disposed.
- 2. In planting areas at the 19<sup>th</sup> Street entrance, the contractor shall remove 6 inches of soil, mulch, and plants. The contractor shall bring in 6 inches of new soil, mulch, filter fabric, and plants.
- **3.** In the terraced timber wall area, the contractor shall remove mulch and weeds. Place filter fabric over the existing soil. Cut out opening for shrubs and wrap around base of shrub. Place a layer of mulch (3" min.) over filter fabric.
- 4. At the north end of the terraced timber wall area, the contractor shall remove plants outside the planter and install sod. Install ±18" dia. rounded loose stone edging between grass and terraced timber wall to separate new lawn from planter.
- 5. The contractor shall bring in new landscape quality soil to reach current grades. It is recommended that the following soil mix be used:

"Sandy Loam" determined by mechanical analysis and based on the "USDA Classification System". The introduced soil shall meet the following mechanical analysis:

Texture Class	:	% of Total Weight
Clay	:	10 - 15
Silt	:	30 - 40
Sand	:	50 - 70
Organic Matter	:	3 - 4
pH level	:	5 - 7

- 6. The contractor shall maintain new plants for a 90 day period. At end of maintenance period, healthy, well-rooted, even-colored, viable plants should established, free of weeds. Maintenance shall include:
  - a. Watering, fertilizing, weeding, trimming, replanting, and performing other operations as required to establish healthy, plants.
  - b. Water plants with gentle spray, unless rainfall precipitation is adequate.
  - c. Fertilize as recommended by plant supplier.

#### E. Berms

Berms B1, B2, and B3 (See Technical Memo #1, Site Investigation Notes, For Detailed Information)

**Berm B1:** Berm was mostly well covered with lawn. In some area, bare patches appear. Soil uphill of the berm appeared to be adequate (See TP#3 above).

**Berm B2:** Bioswale appeared to be working normally. Berm was mostly well covered with lawn. In some area, bare patches appear.

**Berm B3:** Bioswale appeared to be working normally. Berm was mostly well covered with lawn. In some area, bare patches appear.

# FINAL RECOMMENDATIONS FOR SITE IMPROVEMENTS

**IMPORTANT:** The area described as berm, includes the adjacent bioswale which is designed to retain storm water. The composition of the bioswale is different from the surrounding lawn areas. The contractor shall make sure that this area is not damaged during construction activities.



- 1. The contactor shall prepare surface to receive new seeding:
  - Remove existing grass, vegetation, and turf. Do not mix into surface soil.
  - Loosen surface soil. Apply soil amendments and fertilizers according to planting soil mix proportions and mix thoroughly into top of soil.
  - Remove stones larger than 2 inches in any dimension and sticks, roots, trash, and other extraneous matter.
  - Legally dispose of waste material, including grass, vegetation, and turf, off site.
  - Restore existing grade with suitable soil mix before seeding.
- 2. The contractor shall provide and established lawn with seed using a mix or temporary and permanent seeding. It is recommended that the following grass mix be used:

Proportioned by weight as follows:

20 percent Tall Fescue- "Inferno".
20 percent Tall Fescue- "Second Millennium"
20 percent Tall Fescue- "Magellan"
20 percent Tall Fescue- "Avenger"

20 percent Kentucky Bluegrass- "Liberator"

## F. Drainage

Catch Basins (See Technical Memo #1, Site Investigation Notes, For Detailed Information)

Catch basin at berm B1 had standing water. The outfall pipe connected to catch basin at berm B2 appeared to be clogged.

Catch basin at berm B2 was dry.

Catch basin at berm B3 was filled with miscellaneous debris.

# FINAL RECOMMENDATIONS FOR SITE IMPROVEMENTS

- 1. Clean out catch basins and drainage pipes
  - a. Remove and clean inlet grates.
  - b. Remove debris in catch basin and legally dispose.
  - c. Flush catch basin and cleanout pipes.
- G. Weeds

Weeding (See Technical Memo #1, Site Investigation Notes, For Detailed Information)

There are weeds throughout planting areas and lawn areas.

# FINAL RECOMMENDATIONS FOR SITE IMPROVEMENTS

1. Remove weeds by removing the entire plant including roots. This means that the removal of the weeds will include clumps of soil or layers of soil. Dispose of weeds off-site.

#### H. Pavement

Pavement (See Technical Memo #1, Site Investigation Notes, For Detailed Information)

Pavement between basketball court and retaining wall is missing and presents a hazardous condition. Foundation of previously existing basketball court remains in place, and is an obstruction to anyone using the court.

# FINAL RECOMMENDATIONS FOR SITE IMPROVEMENTS

- 1. Remove top 12" from the top of old basket ball hoop concrete foundation.
- 2. Install basketball court surface and a concrete base along the gap between retaining wall and existing court. Provide a continuous expansion joint between wall and subbase.

#### I. Fences

Fencing (See Technical Memo #1, Site Investigation Notes, For Detailed Information)

New black fence and previously existing fence are poorly tied together with miscellaneous fence fabric.

# FINAL RECOMMENDATIONS FOR SITE IMPROVEMENTS

1. Correctly tie new fence fabric to fence posts.

# July 8, 2013 Kalorama erosion project





# Why are we here?

- Goals of Meeting: Focus on making things right
- Agenda:
  - Introduction and Original Work
  - Overview of Site Investigations
  - Overview of Recommendations
  - Current Conditions
  - Looking forward:
    - DPR/DGS Ideas
    - DDOE Input
    - Community Input
  - Next Steps, Progress Updates and Timeline
  - Project Contact Information

# **Original Work**

- Project was initiated in response to community concerns over the erosion problems caused by stormwater during times of heavy rainfall.
- A civil engineering firm (Volkert) was hired to produce construction documents that focused on low impact methods of stormwater reduction and retetention, such as landform changes and planting.
- Soil tests confirmed that grassy areas were very compacted, causing water to sheet flow from NE to SW corner of park.
- Berms were installed to stop the sheet flow, give the water a chance to percolate into the soil. Any excess water flows into overflow drains. Soil directly behind berms were remediated to facilitate better drainage into the soil.
- Original contract was eventually completed, but not at the satisfaction of DPR or the community.
- DPR hired Volkert to conduct site analysis and to make recommendations on remediating previous work.

# Site Recommendations– Improvement Zones

**Zones A & B**: Replace 36" of existing soil. Install sod & provide 90 days worth of maintenance (watering, fertilizing, mowing, replanting, watering and other operations as required to establish healthy, viable lawn).



# Site Recommendations– Improvement Zones

**Zones C & D**: Replace 3" of existing soil. Install sod & provide 90 days worth of maintenance (watering, fertilizing, mowing, replanting, watering and other operations as required to establish healthy, viable lawn).

