









Rules of the Road:

Welcome! Thank you for your participation.

- Please Hold all questions until the end of the presentation.
- Sign-In Before you leave.

Agenda:

- 1. Introduction
- 2. Project Overview and Opportunities
- 3. Project Process and Timeline
- 4. Plans: Existing, Proposed, Playgrounds & Amenities
- 5. Next Steps
- 6. Contact Information
- 7. Community Feedback



HELP PLAN THE FUTURE OF DC'S PARKS AND RECREATION!

SATURDAY, MARCH 14

Kick-Off Meeting 11:00 AM - 1:00 PM Edgewood Recreation Center 300 Evarts Street, NE

WEDNESDAY, MARCH 18

2nd Community Meeting 6:30 PM – 8:30 PM Barry Farm Recreation Center 1230 Sumner Road, SE



TUESDAY, MARCH 24

3rd Community Meeting 6:30 PM – 8:30 PM King Greenleaf Recreation Center 201 N Sreet, SW

SATURDAY, MARCH 28

4th Community Meeting 10:00 AM–12:00 PM Glover Park Recreation Center 4100 Calvert Street, NW























EXISTING CONDITIONS












Tree Inventory Powell Recreation Center Washington, DC January 22, 2020

Map Number	Common Name	Scientific Name	DBH (Trunk Diameter in Inches Measured at 4.5 FT)	Condition	Notes
1	Willow Oak	Quercus phellos	39.4	Good/Fair	Full crown. Good vigor. moderate amount of dead wood throughout crown. Good taper at base. dramatic amount of exposed surface roots. moderate amount of compaction in areas, but possibly not as problematic due to sandy soil
2	White Ash	Fraxinus americana	40.1	Poor	Crown dying back throughout. some vigor remaining. Major decay at old branch breakout wound. Major decay also in main trunk at and below union of two stems, open cavity, sounding mallet indicates trunk hollow all around. notable exposed surface roots. tree located close to asphalt
3	Pin Oak	Quercus palustris	39	Excellent	Canopy very full and vigorous. Minor dead wood throughout crown. tree about 7 ft from sidewalk curb, about 6 ft from asphalt path inside playground. grade raised slightly from nearby path, compaction not as bad
4	Willow Oak	Quercus phellos	48.5	Exc/Good	Crown very full and vigorous. Well developed taper at root flare. Roots constrained by nearby curb and parking area. Root flares come to edge of fence line but then go underground and/or disappear, could have been covered with fill when baseball field was installed, or severed.
5	Scarlet Oak	Quercus coccinea	*23	Fair	Tip dieback in crown, moderate to low vigor. *diameter estimated visually through fence due to no access
6	Ginkgo	Ginkgo biloba	30.3	Good/Fair	3 1
7	Sweetgum	Liquidambar styraciflua	10	Good	Good vigor. Good rooting volume. notable circling root that could become problematic
8	Eastern Redbud	Cercis canadensis	9.8	Fair/Poor	Notable dieback and broken branches. reduced crown size. some wounding and decay at base of trunk
9	Pin Oak	Quercus palustris	30.6	Good	Moderately vigorous and full. Minor dead limbs. notable exposed surface roots. notable soil compaction. moderately close to sidewalk curb and driveway curb
























































SHADE STRUCTURE AND PICNIC TABLES











drinking fountain

bike racks





trash & recycling receptacle

16TH STREET PLAYGROUND



park signs







Next Steps

DGS project website:

https://dgs.dc.gov/page/16th-street-playground-equipment



Contact Information

Department of General Services (DGS)

Wayne Gore/ Community Engagement and Outreach wayne.gore@dc.gov

Department of Parks & Recreation (DPR)

Peter Nohrden, ASLA / Project Manager peter.nohrden@dc.gov

Questions & Comments

