



BENNING PARK REC LEAD WATER TEST RESULTS May 16th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	BENNING PARK REC	5/21/2016	WS- 003777	Utility	2	In mechanical room 1st floor entrance 2nd floor (water source)	WT-042916-3794- A	5.6	WT-042916-3794- B	1.8				
2	BENNING PARK REC	5/21/2016	WS- 003778	Fountain	Ground Floor	In exterior adjacent to pool	WT-042916-3795- A	1.1	WT-042916-3795- B	1.3				
3	BENNING PARK REC	5/21/2016	WS- 003779	Cooler	1	In hallway adjacent staff room	WT-042916-3796- A	< 1	WT-042916-3796- B	< 1				
4	BENNING PARK REC	5/21/2016	WS- 003780	Classroom	1	In art room	WT-042916-3797- A	5.5	WT-042916-3797- B	< 1				
5	BENNING PARK REC	5/21/2016	WS- 003785	Kitchen	1	In kitchen	WT-042916-3802- A	1.4	WT-042916-3802- B	< 1				
6	BENNING PARK REC	5/21/2016	WS- 003786	Cooler	1	In hallway adjacent custodial room	WT-042916-3803- A	< 1	WT-042916-3803- B	< 1				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.