



FILMORE LEAD WATER TEST RESULTS

May 16th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	Filmore Arts Center (West)/Hardy MS	5/14/2016	WS-008759	Classroom	3	In classroom 334 Left	WT-042916-8776- A	< 1	WT-042916-8776- B	< 1				
2	Filmore Arts Center (West)/Hardy MS	5/14/2016	WS-008760	Classroom	3	In classroom 334 Right	WT-042916-8777- A	2.6	WT-042916-8777- B	< 1				
3	Filmore Arts Center (West)/Hardy MS	5/14/2016	WS-008761	Classroom	3	In classroom 304 (music)	WT-042916-8778- A	1.5	WT-042916-8778- B	< 1				
4	Filmore Arts Center (West)/Hardy MS	5/14/2016	WS-008762	Break Room	3	In teacher's lounge room 339	WT-042916-8779- A	< 1	WT-042916-8779- B	< 1				
5	Filmore Arts Center (West)/Hardy MS	5/14/2016	WS-008763	Cooler	3	In hallway across from classroom 302 Left High	WT-042916-8780- A	< 1	WT-042916-8780- B	1.6				
6	Filmore Arts Center (West)/Hardy MS	5/14/2016	WS-008764	Cooler	3	In hallway across from classroom 302 Right Low	WT-042916-8781- A	< 1	WT-042916-8781- B	< 1				
7	Filmore Arts Center (West)/Hardy MS	5/14/2016	WS-008765	Classroom	3	In classroom 302	WT-042916-8782- A	< 1	WT-042916-8782- B	< 1				
8	Filmore Arts Center (West)/Hardy MS	5/14/2016	WS-008766	Classroom	3	In classroom 301 Left	WT-042916-8783- A	< 1	WT-042916-8783- B	< 1				
9	Filmore Arts Center (West)/Hardy MS	5/14/2016	WS-008767	Classroom	3	In classroom 301 Right	WT-042916-8784- A	< 1	WT-042916-8784- B	2.7				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.