Butler Wyatt Clubhouse 2 Lead in Water Test Results

FY26 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	**Filter Installed Date**	**Filter Expiration Date**	**Floor**	**Device Type**	**Device Location**	**Water Filter's Name**	**Date Analyzed**	**1st Draw - Sample ID**	**FT Final Result - 1st Draw (ppb)**	**2nd Draw - Sample ID**	**FT Final Result - 2nd Draw (ppb)**
WS- 001040	12/11/2025	12/11/2026	Ground Floor	Cooler	In hallway near the entrance	WF-12112025-001040	2/25/2026	FT-FY26-01282026-001040-A	<2	FT-FY26-01282026-001040-B	<2
WS- 001041	12/11/2025	12/11/2026	Ground Floor	Cooler	In hallway near the entrance High Left	WF-12112025-001041	2/25/2026	FT-FY26-01282026-001041-A	<2	FT-FY26-01282026-001041-B	<2

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.