Butler-Wyatt Clubhouse 2 Lead in Water Test Results

FY25 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	**Filter Installed Date**	**Filter Expiration Date**	**Floor**	**Device Type**	**Device Location**	**Water Filter's Name**	**Date Analyzed**	**1st Draw - Sample ID**	**FT Final Result - 1st Draw (ppb)**	**2nd Draw - Sample ID**	**FT Final Result - 2nd Draw (ppb)**
WS- 001040	2/19/2024	2/19/2025	Ground Floor	Cooler	In hallway near the entrance	WF-02192024-001040	2/19/2025	FT-FY25-01082025-001040-A	<2	FT-FY25-01082025-001040-B	<2
WS- 001041	2/19/2024	2/19/2025	Ground Floor	Cooler	In hallway near the entrance High Left	WF-02192024-001041	2/19/2025	FT-FY25-01082025-001041-A	<2	FT-FY25-01082025-001041-B	<2

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.