Kenilworth Swing Space Lead in Water Test Results

FY26 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 000417	4/30/2025	4/30/2026	1	Cooler	In 119 health suite	WF-04302025-000417	10/13/2025	FT-FY26-09302025-000417-A	<2	FT-FY26-09302025-000417-B	<2
WS- 000717	4/30/2025	4/30/2026	1	Bottle Filler	In 119 health suite	WF-04302025-000717	10/13/2025	FT-FY26-09302025-000717-A	<2	FT-FY26-09302025-000717-B	<2
WS- 000425	4/30/2025	4/30/2026	3	Break Room	In 304 staff lounge	WF-04302025-000425	10/13/2025	FT-FY26-09302025-000425-A	<2	FT-FY26-09302025-000425-B	<2
WS- 000427	4/30/2025	4/30/2026	Ground Floor	Bottle Filler	In cafeteria bubble	WF-04302025-000427	10/13/2025	FT-FY26-09302025-000427-A	<2	FT-FY26-09302025-000427-B	<2
WS- 000428	4/30/2025	4/30/2026	Ground Floor	Cooler	In cafeteria bubble High Left	WF-04302025-000428	10/13/2025	FT-FY26-09302025-000428-A	<2	FT-FY26-09302025-000428-B	<2
WS- 000429	4/30/2025	4/30/2026	Ground Floor	Cooler	In cafeteria bubble Low Right	WF-04302025-000429	10/13/2025	FT-FY26-09302025-000429-A	<2	FT-FY26-09302025-000429-B	<2
WS- 000419	4/30/2025	4/30/2026	1	Cooler	In hallway adjacent to 101	WF-04302025-000419	10/13/2025	FT-FY26-09302025-000419-A	<2	FT-FY26-09302025-000419-B	<2
WS- 000719	4/30/2025	4/30/2026	1	Bottle Filler	In hallway adjacent to 101	WF-04302025-000719	10/13/2025	FT-FY26-09302025-000719-A	<2	FT-FY26-09302025-000719-B	<2
WS- 000420	4/30/2025	4/30/2026	1	Cooler	In hallway adjacent to 109	WF-04302025-000420	10/13/2025	FT-FY26-09302025-000420-A	<2	FT-FY26-09302025-000420-B	<2
WS- 000718	4/30/2025	4/30/2026	1	Bottle Filler	In hallway adjacent to 109	WF-04302025-000718	10/13/2025	FT-FY26-09302025-000718-A	<2	FT-FY26-09302025-000718-B	<2
WS- 000422	4/30/2025	4/30/2026	2	Cooler	In hallway adjacent to 201	WF-04302025-000422	10/13/2025	FT-FY26-09302025-000422-A	<2	FT-FY26-09302025-000422-B	<2
WS- 000779	4/30/2025	4/30/2026	2	Bottle Filler	In hallway adjacent to 201	WF-04302025-000779	10/13/2025	FT-FY26-09302025-000779-A	<2	FT-FY26-09302025-000779-B	<2
WS- 000421	4/30/2025	4/30/2026	2	Cooler	In hallway adjacent to 213	WF-04302025-000421	10/13/2025	FT-FY26-09302025-000421-A	<2	FT-FY26-09302025-000421-B	<2
WS- 000781	4/30/2025	4/30/2026	2	Bottle Filler	In hallway adjacent to 213	WF-04302025-000781	10/13/2025	FT-FY26-09302025-000781-A	<2	FT-FY26-09302025-000781-B	<2
WS- 000424	4/30/2025	4/30/2026	2	Cooler	In hallway adjacent to 231 Low Right	WF-04302025-000424	10/13/2025	FT-FY26-09302025-000424-A	<2	FT-FY26-09302025-000424-B	<2
WS- 000782	4/30/2025	4/30/2026	2	Bottle Filler	In hallway adjacent to 231	WF-04302025-000782	10/13/2025	FT-FY26-09302025-000782-A	<2	FT-FY26-09302025-000782-B	<2
WS- 000790	4/30/2025	4/30/2026	2	Cooler	In hallway adjacent to 231 High Left	WF-04302025-000790	10/13/2025	FT-FY26-09302025-000790-A	<2	FT-FY26-09302025-000790-B	<2
WS- 000426	4/30/2025	4/30/2026	3	Cooler	In hallway adjacent to 313	WF-04302025-000426	10/13/2025	FT-FY26-09302025-000426-A	<2	FT-FY26-09302025-000426-B	<2
WS- 000803	4/30/2025	4/30/2026	3	Bottle Filler	In hallway adjacent to 313	WF-04302025-000803	10/13/2025	FT-FY26-09302025-000803-A	<2	FT-FY26-09302025-000803-B	<2
WS- 000423	4/30/2025	4/30/2026	2	Cooler	In hallway adjacent to girls' restroom	WF-04302025-000423	10/13/2025	FT-FY26-09302025-000423-A	<2	FT-FY26-09302025-000423-B	<2
WS- 000791	4/30/2025	4/30/2026	2	Bottle Filler	In hallway adjacent to girls' restroom	WF-04302025-000791	10/13/2025	FT-FY26-09302025-000791-A	<2	FT-FY26-09302025-000791-B	<2

Food Prep Sink

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 000432	11/18/2024	11/18/2025	Ground Floor	Food Prep Sink	In kitchen trailer 1st clockwise from outdoor entry	WF-11182024-000432	10/13/2025	FT-FY26-09302025-000432-A	<2	FT-FY26-09302025-000432-B	<2

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.