Langley ES Lead in Water Test Results

FY26 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 004109	2/5/2025	2/5/2026	2	Bottle Filler	In hallway adjacent to room 204	WF-02052025-004109	12/5/2025	FT-FY26-12012025-004109-A	<2	FT-FY26-12012025-004109-B	<2
WS- 004127	2/5/2025	2/5/2026	2	Bottle Filler	In hallway adjacent to room 201	WF-02052025-004127	12/5/2025	FT-FY26-12012025-004127-A	<2	FT-FY26-12012025-004127-B	<2
WS- 004217	2/5/2025	2/5/2026	Basement	Cooler	In hallway adjacent to stairwell 4	WF-02052025-004217	12/5/2025	FT-FY26-12012025-004217-A	<2	FT-FY26-12012025-004217-B	<2
WS- 004222	2/5/2025	2/5/2026	Basement	Cooler	In hallway adjacent to stairwell 3	WF-02052025-004222	12/5/2025	FT-FY26-12012025-004222-A	<2	FT-FY26-12012025-004222-B	<2
WS- 004223	2/5/2025	2/5/2026	Basement	Cooler	In hallway adjacent to room B02	WF-02052025-004223	12/5/2025	FT-FY26-12012025-004223-A	<2	FT-FY26-12012025-004223-B	<2
WS- 004225	8/8/2025	8/8/2026	1	Combo Faucet	In classroom 125	WF-08082025-004225	12/5/2025	FT-FY26-12012025-004225-A	<2	FT-FY26-12012025-004225-B	<2
WS- 004226	2/5/2025	2/5/2026	1	Combo Glass Filler	In classroom 125	WF-02052025-004226	12/5/2025	FT-FY26-12012025-004226-A	<2	FT-FY26-12012025-004226-B	<2
WS- 004227	2/5/2025	2/5/2026	1	Break Room	In staff lounge	WF-02052025-004227	12/5/2025	FT-FY26-12012025-004227-A	<2	FT-FY26-12012025-004227-B	<2
WS- 004228	2/5/2025	2/5/2026	1	Combo Fountain	In staff lounge	WF-02052025-004228	12/5/2025	FT-FY26-12012025-004228-A	<2	FT-FY26-12012025-004228-B	<2
WS- 004229	2/5/2025	2/5/2026	1	Combo Fountain	In classroom 133	WF-02052025-004229	12/5/2025	FT-FY26-12012025-004229-A	<2	FT-FY26-12012025-004229-B	<2
WS- 004230	8/8/2025	8/8/2026	1	Combo Faucet	In classroom 133	WF-08082025-004230	12/5/2025	FT-FY26-12012025-004230-A	<2	FT-FY26-12012025-004230-B	<2
WS- 004231	8/8/2025	8/8/2026	1	Combo Faucet	In classroom 143	WF-08082025-004231	12/5/2025	FT-FY26-12012025-004231-A	<2	FT-FY26-12012025-004231-B	<2
WS- 004232	2/5/2025	2/5/2026	1	Combo Glass Filler	In classroom 143	WF-02052025-004232	12/5/2025	FT-FY26-12012025-004232-A	<2	FT-FY26-12012025-004232-B	<2
WS- 004233	8/8/2025	8/8/2026	1	Combo Faucet	In classroom 149	WF-08082025-004233	12/5/2025	FT-FY26-12012025-004233-A	<2	FT-FY26-12012025-004233-B	<2
WS- 004234	2/5/2025	2/5/2026	1	Combo Glass Filler	In classroom 149	WF-02052025-004234	12/5/2025	FT-FY26-12012025-004234-A	<2	FT-FY26-12012025-004234-B	<2
WS- 004235	2/5/2025	2/5/2026	1	Combo Fountain	In classroom 137	WF-02052025-004235	12/5/2025	FT-FY26-12012025-004235-A	<2	FT-FY26-12012025-004235-B	<2
WS- 004236	8/8/2025	8/8/2026	1	Combo Faucet	In classroom 137	WF-08082025-004236	12/5/2025	FT-FY26-12012025-004236-A	<2	FT-FY26-12012025-004236-B	<2
WS- 004237	2/5/2025	2/5/2026	1	Cooler	In hallway adjacent to principals office	WF-02052025-004237	12/5/2025	FT-FY26-12012025-004237-A	<2	FT-FY26-12012025-004237-B	<2
WS- 004238	2/5/2025	2/5/2026	1	Cooler	In hallway adjacent to room 104	WF-02052025-004238	12/5/2025	FT-FY26-12012025-004238-A	<2	FT-FY26-12012025-004238-B	<2
WS- 004239	2/5/2025	2/5/2026	1	Health Suite	In health suite in treatment room 10	WF-02052025-004239	12/5/2025	FT-FY26-12012025-004239-A	<2	FT-FY26-12012025-004239-B	<2
WS- 004240	8/8/2025	8/8/2026	1	Combo Faucet	In classroom 113	WF-08082025-004240	12/5/2025	FT-FY26-12012025-004240-A	<2	FT-FY26-12012025-004240-B	<2
WS- 004241	2/5/2025	2/5/2026	1	Combo Glass Filler	In classroom 113	WF-02052025-004241	12/5/2025	FT-FY26-12012025-004241-A	<2	FT-FY26-12012025-004241-B	<2
WS- 004242	2/5/2025	2/5/2026	1	Combo Glass Filler	In classroom 122	WF-02052025-004242	12/5/2025	FT-FY26-12012025-004242-A	<2	FT-FY26-12012025-004242-B	<2
WS- 004243	8/8/2025	8/8/2026	1	Combo Faucet	In classroom 122	WF-08082025-004243	12/5/2025	FT-FY26-12012025-004243-A	<2	FT-FY26-12012025-004243-B	<2
WS- 004244	2/5/2025	2/5/2026	2	Cooler	In hallway adjacent to room 201	WF-02052025-004244	12/5/2025	FT-FY26-12012025-004244-A	<2	FT-FY26-12012025-004244-B	<2
WS- 004247	2/5/2025	2/5/2026	2	Combo Fountain	In classroom 208	WF-02052025-004247	12/5/2025	FT-FY26-12012025-004247-A	<2	FT-FY26-12012025-004247-B	<2
WS- 004249	2/5/2025	2/5/2026	2	Combo Fountain	In art room 217	WF-02052025-004249	12/5/2025	FT-FY26-12012025-004249-A	<2	FT-FY26-12012025-004249-B	<2
WS- 004261	2/5/2025	2/5/2026	3	Classroom Faucet	In science lab room 332 on teachers island	WF-02052025-004261	12/5/2025	FT-FY26-12012025-004261-A	<2	FT-FY26-12012025-004261-B	<2
WS- 004265	8/27/2025	8/27/2026	3	Cooler	In hallway adjacent to room 301	WF-08272025-004265	12/5/2025	FT-FY26-12012025-004265-A	<2	FT-FY26-12012025-004265-B	<2
WS- 004268	2/5/2025	2/5/2026	3	Combo Fountain	In room 312	WF-02052025-004268	12/5/2025	FT-FY26-12012025-004268-A	<2	FT-FY26-12012025-004268-B	<2
WS- 006893	2/5/2025	2/5/2026	3	Bottle Filler	In hallway adjacent to room 304	WF-02052025-006893	12/5/2025	FT-FY26-12012025-006893-A	<2	FT-FY26-12012025-006893-B	<2
WS- 007177	2/5/2025	2/5/2026	1	Bottle Filler	In hallway adjacent to principals office	WF-02052025-007177	12/5/2025	FT-FY26-12012025-007177-A	<2	FT-FY26-12012025-007177-B	<2
WS- 012566	2/5/2025	2/5/2026	3	Classroom Faucet	In science lab prep room 333	WF-02052025-012566	12/5/2025	FT-FY26-12012025-012566-A	<2	FT-FY26-12012025-012566-B	<2

Food Prep Sink

Less than 5ppb - Devices requiring no remediation											
Record ID	**Filter Installed Date**	**Filter Expiration Date**	**Floor**	**Device Type**	**Device Location**	**Water Filter's Name**	**Date Analyzed**	**1st Draw - Sample ID**	**FT Final Result - 1st Draw (ppb)**	**2nd Draw - Sample ID**	**FT Final Result - 2nd Draw (ppb)**
WS- 004221	11/24/2025	11/24/2026	Basement	Food Prep Sink	In kitchen fourth clockwise from entry door	WF-11242025-004221	12/5/2025	FT-FY26-12012025-004221-A	<2	FT-FY26-12012025-004221-B	<2

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.