Marvin Gaye RC Lead in Water Test Results

FY25 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	**Filter Installed Date**	**Filter Expiration Date**	**Floor**	**Device Type**	**Device Location**	**Water Filter's Name**	**Date Analyzed**	**1st Draw - Sample ID**	**FT Final Result - 1st Draw (ppb)**	**2nd Draw - Sample ID**	**FT Final Result - 2nd Draw (ppb)**
WS- 000470	12/11/2024	12/11/2025	1	Food Prep Sink	In teaching kitchen	WF-12112024-000470	3/7/2025	FT-FY25-01082025-000470-A	<2	FT-FY25-01082025-000470-B	<2
WS- 000471	4/10/2024	4/10/2025	2	Bottle Filler	In hallway adjacent to music room 202	WF-04102024-000471	3/7/2025	FT-FY25-01082025-000471-A	<2	FT-FY25-01082025-000471-B	<2
WS- 000472	4/10/2024	4/10/2025	2	Cooler	In hallway adjacent to music room 202	WF-04102024-000472	3/7/2025	FT-FY25-01082025-000472-A	<2	FT-FY25-01082025-000472-B	<2

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.