Palisades CC Lead in Water Test Results

FY25 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 004276	12/5/2024	12/5/2025	Ground Floor	Bottle Filler	In hallway next to boys and girls restroom	WF-12052024-004276	3/12/2025	FT-FY25-01082025-004276-A	<2	FT-FY25-01082025-004276-B	<2
WS- 004277	12/5/2024	12/5/2025	Ground Floor	Cooler	In hallway next to boys and girls restroom High Left	WF-12052024-004277	3/12/2025	FT-FY25-01082025-004277-A	<2	FT-FY25-01082025-004277-B	<2
WS- 004278	12/5/2024	12/5/2025	Ground Floor	Cooler	In hallway next to boys and girls restroom Low Right	WF-12052024-004278	3/12/2025	FT-FY25-01082025-004278-A	<2	FT-FY25-01082025-004278-B	<2
WS- 004279	12/10/2024	12/10/2025	Ground Floor	Food Prep Sink	In kitchen	WF-12102024-004279	3/12/2025	FT-FY25-01082025-004279-A	<2	FT-FY25-01082025-004279-B	<2
WS- 004280	4/11/2024	4/11/2025	Ground Floor	Classroom Faucet	In break room / classroom / kitchen	WF-04112024-004280	3/12/2025	FT-FY25-01082025-004280-A	<2	FT-FY25-01082025-004280-B	<2

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.