



Volta Park RC Lead in Water Test Results

FY26 Filter Test

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 012009	3/26/2025	3/26/2026	1	Cooler	In hallway adjacent to office	Low Right	WF-03262025-012009	3/12/2026	FT-FY26-02272026-012009-A	<2	FT-FY26-02272026-012009-B	<2
WS- 012014	3/26/2025	3/26/2026	1	Cooler	In hallway adjacent to office	High Left	WF-03262025-012014	3/12/2026	FT-FY26-02272026-012014-A	<2	FT-FY26-02272026-012014-B	<2
WS- 012036	3/26/2025	3/26/2026	1	Bottle Filler	In hallway adjacent to office		WF-03262025-012036	3/12/2026	FT-FY26-02272026-012036-A	<2	FT-FY26-02272026-012036-B	<2

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.