

## HORACE MANN ELEMENTARY SCHOOL

DGS District of Columbia Department of General Services

October 17, 2012

Bradley Site Design, Inc Setty & Associates International, PLLC ReStl Designers, Inc.

## Marshall Moya Design

Polysonics Corp. | Gorove/Slade Assoc. | Delon Hampton & Assc. | Sustainable Design & LEED | TCT Cost Consultants

# Neighborhood Context



### **COMMERCIAL AND RESIDENTIAL ZONE**

#### Single Family Residential Zone


#### Mann Elementary School Located at the Interface of Both Zones

Glenbrook Rd NM Klingle St NW-

**Battery Kemble Park** 

Cathedral Ave NW

# Commercial, Institutional & Multifamily Residential Zone







Square: 1603 Lot: 0804 Zone: R-1-B Height: 3 Stories - 60' for Schools Lot Occupancy: 60% Allowable: 0.9 Side Yard Setback: 8'-0" Rear Yard Setback: 25'-0"

# Site and Zoning Analysis

#### **SITE AND ZONING ANALYSIS**




#### **Zoning Summary**

Square: 1603 Lot: 0804 Zone: R-1-B Height: 3 Stories - 60' for Schools Lot Occupancy: 60% Allowable: 0.9 Side Yard Setback: 8'-0" Rear Yard Setback: 25'-0"

SUMMER SUN

#### WINTER SUN




Marshall Moya Design

DGS District of Columbia Department of General Services

#### **GENERAL INFORMATION**


Initial year built: 1931 Building Area: 21,903sf Ward: 3






The 1931 D.C. Public School Plan proposes an expansion of the Mann School with a 2-story wing, duplicating the existing Mann School volume at the western side of the site along 45th street, with a new centralized connecting building

# **1931 Historic Plans for Mann**



#### FULLY EXECUTED 1930'S TYPICAL D.C. PUBLIC SCHOOL LAYOUT



Marshall Moya Design District of Columbia Department of General Services

The Commission of Fine Arts and The Historic Preservation Office advised that any additions to the typical 1930's public school layout, occur only on the long face of the existing structures. Additions to the front and the rear of these structures were deemed in conflict to the integrity of the historic designs.




# Proposals for 2013 Renovation Work + Addition











#### **SUMMARY OF ANALYSIS**

#### **PROS:**

Building provides clear flow both inside and outside the campus.

Main lobby entrance plaza will be located on Newark Street creating a formal entry.

Building addition embraces Range, and connects with all natural spaces, transforming the building in a 3D textbook.

Addition and Range benefits from its southern exposure with no overcasting shadows from adjacent buildings.

Outdoor safety is line of sight.

Addition does not alter the newly renovated sports field, and does not impact mature trees.

#### CONS:

New addition obscures north-west corner of existing building.


Temporary trailers will be required.

## **PROPOSAL No. 1 - SITE ANALYSIS**

Marshall Moya Design


DGS District of Columbia Department of General Services

Outdoor safety is controlled by an unobstructed



DGS District of Columbia Department of General Services

#### **PROPOSAL No. 1 - SITE PLAN**



**PROPOSAL No. 1 - PERSPECTIVE VIEW** 


District of Columbia Department of General Services



4. DESIGN VISION 16

### DAILY ACTIVITIES ON THE RANGE





### **ENTRANCE VIEW FROM NEWARK STREET**



#### MAIN ENTRANCE VIEW




### **RENOVATION WORK + ADDITION AERIAL DAY VIEW**









### **SUMMARY OF ANALYSIS**

#### **PROS:**

New addition attached to the west side of the existing building with no need to alter newly renovated sports field.

Main lobby entrance plaza will be located on Newark Street.

Street.

Range benefits from its southern exposure.

#### CONS:

New addition obscures north-west corner of existing building.

Temporary trailers will be required.

Building C will create shadows on its west side.


Range is reduced/compromised.

Building C is not the most advantageous relationship to the DaVinci suite.

### **PROPOSAL No. 2 - SITE ANALYSIS**


Marshall Moya Design DGS District of Columbia Department of General Services Building provides green space towards 45th





DGS District of Columbia Department of General Services


#### **PROPOSAL No. 2 - SITE PLAN**



**PROPOSAL No. 2 - PERSPECTIVE VIEW** 


District of Columbia Department of General Services

4. DESIGN VISION 25









#### **SUMMARY OF ANALYSIS PROS**:

New addition attached to the underground of north side of the existing building, with no need to alter newly renovated sports field.

Main lobby entra Newark Street.

Range benefits from its southern exposure.

CONS:

No direct contact with the range.

Need for second elevator.

Need for sheeting and shoring.

Removal of mature trees.

Limited exterior adjacent play areas to building C.


Temporary trailers will be required.

Slide & lot play space loss.

This concept will cost substantially more for the excavation and foundation systems

### **PROPOSAL No. 3 - SITE ANALYSIS**


Marshall Moya Design DGS District of Columbia
Department of General Services Main lobby entrance plaza will be located on



DGS District of Columbia Department of General Services

### **PROPOSAL No. 3 - SITE PLAN**









DGS District of Columbia Department of General Services

#### **PROPOSAL No. 3 - PERSPECTIVE VIEW**



4. DESIGN VISION 30





#### 4. DESIGN VISION 31



2800 Quebec Street NW, # 1021, Washington DC 20008 P: 202.537.1107 F: 202.364.1998 studio@marshallmoya.com

