



BANNEKER COMM LEAD WATER TEST RESULTS May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1 BANNEKER COMMUNITY CENTER	5/21/2016	WS- 012655	Kitchen	1	Upper level right side kitchenette	WT-042916-12672- A	< 1	WT-042916-12672- B	< 1				
2 BANNEKER COMMUNITY CENTER	5/21/2016	WS- 012656	Classroom	1	Upper level left side GYM	WT-042916-12673- A	< 1	WT-042916-12673- B	< 1				
3 BANNEKER COMMUNITY CENTER	5/21/2016	WS- 012657	Utility	Ground Floor	In men's restroom/locker room lower level (water source)	WT-042916-12674- A	< 1	WT-042916-12674- B	< 1				
4 BANNEKER COMMUNITY CENTER	5/21/2016	WS- 012658	Fountain	Ground Floor	Walking track adjacent to baseball dugout Left High	WT-042916-12675- A	< 1	WT-042916-12675- B	< 1				
5 BANNEKER COMMUNITY CENTER	5/21/2016	WS- 012659	Fountain	Ground Floor	Walking track adjacent to baseball dugout Right Low	WT-042916-12676- A	< 1	WT-042916-12676- B	< 1				
6 BANNEKER COMMUNITY CENTER	5/21/2016	WS- 012660	Fountain	Ground Floor	Walking track concrete fountain	WT-042916-12677- A	< 1	WT-042916-12677- B	< 1				
7 BANNEKER COMMUNITY CENTER	5/21/2016	WS- 012663	Fountain	Ground Floor	At bike park Right High	WT-042916-12680- A	< 1	WT-042916-12680- B	1.2				
8 BANNEKER COMMUNITY CENTER	5/21/2016	WS- 012664	Fountain	Ground Floor	At the bic park Left Low	WT-042916-12681- A	< 1	WT-042916-12681- B	< 1				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.