



Ridge Road RC Lead in Water Test Results

FY25 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 001280	5/31/2024	5/31/2025	Ground Floor	Break Room	In Room 106	WF-05312024-001280	3/18/2025	FT-FY25-01082025-001280-A	<2	FT-FY25-01082025-001280-B	<2
WS- 003804	11/22/2024	11/22/2025	1	Food Prep Sink	In kitchen 108 Right	WF-11222024-003804	3/18/2025	FT-FY25-01082025-003804-A	<2	FT-FY25-01082025-003804-B	<2
WS- 003806	5/31/2024	5/31/2025	1	Cooler	In hallway adjacent to aquatics office 110 High	WF-05312024-003806	3/18/2025	FT-FY25-01082025-003806-A	<2	FT-FY25-01082025-003806-B	<2
WS- 003807	5/31/2024	5/31/2025	1	Bottle Filler	In hallway adjacent to aquatics office 110	WF-05312024-003807	3/18/2025	FT-FY25-01082025-003807-A	<2	FT-FY25-01082025-003807-B	<2
WS- 003808	5/31/2024	5/31/2025	1	Cooler	In hallway adjacent to aquatics office 110 Low	WF-05312024-003808	3/18/2025	FT-FY25-01082025-003808-A	2.1	FT-FY25-01082025-003808-B	<2
WS- 003809	5/31/2024	5/31/2025	1	Cooler	In hallway across for room 106 High	WF-05312024-003809	3/18/2025	FT-FY25-01082025-003809-A	<2	FT-FY25-01082025-003809-B	<2
WS- 003810	5/31/2024	5/31/2025	1	Bottle Filler	In hallway across for room 106	WF-05312024-003810	3/18/2025	FT-FY25-01082025-003810-A	<2	FT-FY25-01082025-003810-B	<2
WS- 003812	5/31/2024	5/31/2025	1	Classroom Faucet	In arts and crafts room 104	WF-05312024-003812	3/18/2025	FT-FY25-01082025-003812-A	<2	FT-FY25-01082025-003812-B	<2

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.