



AITON ES LEAD WATER TEST RESULTS



Initial Filter Test After Installation

Less than 1 ppb - Device Returned to Service										
	Building Location: Building Name	Water Source ID	Date Analyzed	Floor	Device Type	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	Final Result - 2nd Draw (ppb)
1	AITON ELEMENTARY SCHOOL	WS-009520	1/10/2017	2	Break Room	In staff lounge across from room 207	FT-102016-009520-A	< 1	FT-102016-009520-B	< 1
2	AITON ELEMENTARY SCHOOL	WS-009524	1/10/2017	3	Classroom Faucet	In classroom 301	FT-112016-009524-A	< 1	FT-112016-009524-B	< 1
3	AITON ELEMENTARY SCHOOL	WS-009530	1/10/2017	3	Classroom Faucet	In classroom 302 Left	FT-112016-009530-A	< 1	FT-112016-009530-B	< 1
4	AITON ELEMENTARY SCHOOL	WS-009517	1/10/2017	1	Classroom Faucet	In classroom K-2	ST-502016-009517-A	< 1	ST-502016-009517-B	< 1
5	AITON ELEMENTARY SCHOOL	WS-009516	1/10/2017	1	Classroom Faucet	In classroom K-1	ST-602016-009516-A	< 1	ST-602016-009516-B	< 1

Greater than 1 ppb - Devices Shut Off and Corrective Action Taken										
1	AITON ELEMENTARY SCHOOL	WS-009526	1/10/2017	4	Classroom Faucet	In classroom 401 Right	FT-112016-009526-A	14	FT-112016-009526-B	23

First Filter Re-Test (After Filter and Plumbing Check with Aerator Replacement)

Greater than 1 ppb - Devices Remain Shut off, Continued Remediation										
1	AITON ELEMENTARY SCHOOL	WS-009526	2/8/2017	4	Classroom Faucet	In classroom 401 Right	FT-112016-009526-A	640	FT-112016-009526-B	36

Second Filter Re-Test (After Device Replacement)

Greater than 1 ppb - Devices Remain Shut off, Continued Remediation										
1	AITON ELEMENTARY SCHOOL	WS-009526	3/30/2017	4	Classroom Faucet	In classroom 401 Right	FT-112016-009526-A	3.6	FT-112016-009526-B	< 1

Note :
Filter re-tests are only performed to devices that have sampling results greater than 1 ppb