



Arboretum RC Lead in Water Test Results

FY25 Filter Test

| Less than 5ppb - Devices requiring no remediation | | | | | | | | | | | |
|---|-----------------------|------------------------|-------|---------------|---|---------------------|---------------|---------------------------|----------------------------------|---------------------------|----------------------------------|
| Record ID | Filter Installed Date | Filter Expiration Date | Floor | Device Type | Device Location | Water Filter's Name | Date Analyzed | 1st Draw - Sample ID | FT Final Result - 1st Draw (ppb) | 2nd Draw - Sample ID | FT Final Result - 2nd Draw (ppb) |
| WS- 001235 | 2/27/2024 | 2/27/2025 | 1 | Break Room | In room 101 cafeteria | WF-02272024-001235 | 2/18/2025 | FT-FY25-01082025-001235-A | <2 | FT-FY25-01082025-001235-B | <2 |
| WS- 001236 | 9/10/2024 | 9/10/2025 | 1 | Bottle Filler | In hallway adjacent to women's restroom | WF-09102024-001236 | 2/18/2025 | FT-FY25-01082025-001236-A | <2 | FT-FY25-01082025-001236-B | <2 |
| WS- 001237 | 9/10/2024 | 9/10/2025 | 1 | Cooler | In hallway adjacent to women's restroom High Left | WF-09102024-001237 | 2/18/2025 | FT-FY25-01082025-001237-A | <2 | FT-FY25-01082025-001237-B | <2 |
| WS- 001238 | 9/10/2024 | 9/10/2025 | 1 | Cooler | In hallway adjacent to women's restroom Low Right | WF-09102024-001238 | 2/18/2025 | FT-FY25-01082025-001238-A | <2 | FT-FY25-01082025-001238-B | <2 |

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.