



# Banneker CC Lead in Water Test Results

## FY22 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 012655	12/27/2021	12/27/2022	1	Food Prep Sink	In kitchenette in gym	WF-12272021-012655	2/4/2022	FT-FY22-01102022-012655-A	1.0	FT-FY22-01102022-012655-B	<1
WS- 012667	8/6/2021	8/6/2022	1	Cooler	In hallway adjacent to room 102 in lobby High Left	WF-08062021-012667	2/4/2022	FT-FY22-01102022-012667-A	<1	FT-FY22-01102022-012667-B	1.2
WS- 012668	8/6/2021	8/6/2022	1	Cooler	In hallway adjacent to room 102 in lobby Low Right	WF-08062021-012668	2/4/2022	FT-FY22-01102022-012668-A	<1	FT-FY22-01102022-012668-B	<1
WS- 012669	8/6/2021	8/6/2022	1	Bottle Filler	In hallway adjacent to room 102 in lobby	WF-08062021-012669	2/4/2022	FT-FY22-01102022-012669-A	<1	FT-FY22-01102022-012669-B	<1
WS- 012670	8/6/2021	8/6/2022	Basement	Cooler	In hallway adjacent to men's locker room High Left	WF-08062021-012670	2/4/2022	FT-FY22-01102022-012670-A	<1	FT-FY22-01102022-012670-B	<1
WS- 012671	8/6/2021	8/6/2022	Basement	Cooler	In hallway adjacent to men's locker room Low Right	WF-08062021-012671	2/4/2022	FT-FY22-01102022-012671-A	<1	FT-FY22-01102022-012671-B	<1
WS- 012672	8/6/2021	8/6/2022	Basement	Bottle Filler	In hallway adjacent to men's locker room	WF-08062021-012672	2/4/2022	FT-FY22-01102022-012672-A	<1	FT-FY22-01102022-012672-B	<1