



# BURDICK LEAD WATER TEST RESULTS



## Initial Filter Test After Installation

Less than 1 ppb - Device Returned to Service										
	Building Location: Building Name	Water Source ID	Date Analyzed	Floor	Device Type	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	Final Result - 2nd Draw (ppb)
1	BURDICK	WS- 008558	12/24/2016	1	Break Room	Annex, in staff lounge 009	FT-102016-008558-A	< 1	FT-102016-008558-B	< 1
2	BURDICK	WS- 008592	12/24/2016	1	Classroom Faucet	Annex, in classroom 012	FT-122016-008592-A	< 1	FT-122016-008592-B	< 1
3	BURDICK	WS- 008557	12/24/2016	1	Classroom Faucet	Annex, in classroom 017	FT-122016-008557-A	< 1	FT-122016-008557-B	< 1
4	BURDICK	WS- 008561	12/24/2016	1	Classroom Faucet	Annex, in classroom 014	FT-122016-008561-A	< 1	FT-122016-008561-B	< 1
5	BURDICK	WS- 010543	12/24/2016	1	Classroom Faucet	Annex, in classroom 006	FT-122016-010543-A	< 1	FT-122016-010543-B	< 1
6	BURDICK	WS- 008555	12/24/2016	1	Classroom Faucet	Annex, in classroom 013	FT-122016-008555-A	< 1	FT-122016-008555-B	< 1

Greater than 1 ppb - Devices Shut Off and Corrective Action Taken										
1	BURDICK	WS- 008560	12/24/2016	1	Classroom Faucet	Annex, in classroom 016	FT-122016-008560-A	1.4	FT-122016-008560-B	< 1
2	BURDICK	WS- 008556	12/24/2016	1	Classroom Faucet	Annex, in classroom 015	FT-122016-008556-A	1.3	FT-122016-008556-B	< 1

## First Filter Re-Test (After Filter and Plumbing Check with Aerator Replacement)

Less than 1 ppb - Device Returned to Service										
1	BURDICK	WS- 008556	1/25/2017	1	Classroom Faucet	Annex, in classroom 015	FT-122016-008556-A	< 1	FT-122016-008556-B	< 1

Greater than 1 ppb - Devices Remain Shut off, Continued Remediation										
1	BURDICK	WS- 008560	1/25/2017	1	Classroom Faucet	Annex, in classroom 016	FT-122016-008560-A	3.2	FT-122016-008560-B	< 1

## Second Filter Re-Test (After Device Replacement)

Less than 1 ppb - Device Returned to Service										
1	BURDICK	WS- 008560	4/7/2017	1	Classroom Faucet	Annex, in classroom 016	FT-122016-008560-A	< 1	FT-122016-008560-B	< 1

Note :

Filter re-tests are only performed to devices that have sampling results greater than 1 ppb