



# BURROUGHS EC LEAD WATER TEST RESULTS



## Initial Filter Test After Installation

| Less than 1 ppb - Device Returned to Service |                                  |                 |               |          |                  |                 |                      |                               |                      |                               |
|--|----------------------------------|-----------------|---------------|----------|------------------|-----------------|----------------------|-------------------------------|----------------------|-------------------------------|
|  | Building Location: Building Name | Water Source ID | Date Analyzed | Floor    | Device Type      | Device Location | 1st Draw - Sample ID | Final Result - 1st Draw (ppb) | 2nd Draw - Sample ID | Final Result - 2nd Draw (ppb) |
| 1  | BURROUGHS EDUCATIONAL CAMPUS     | WS- 008828      | 12/27/2016    | Basement | Classroom Faucet | In classroom 22 | FT-122016-008828-A   | < 1                           | FT-122016-008828-B   | < 1                           |
| 2  | BURROUGHS EDUCATIONAL CAMPUS     | WS- 008625      | 12/27/2016    | 1        | Classroom Faucet | In classroom 34 | FT-122016-008625-A   | < 1                           | FT-122016-008625-B   | < 1                           |
| 3  | BURROUGHS EDUCATIONAL CAMPUS     | WS- 008631      | 12/27/2016    | 1        | Classroom Faucet | In classroom 25 | FT-122016-008631-A   | < 1                           | FT-122016-008631-B   | < 1                           |
| 4  | BURROUGHS EDUCATIONAL CAMPUS     | WS- 008825      | 12/27/2016    | Basement | Classroom Faucet | In classroom 18 | FT-122016-008825-A   | < 1                           | FT-122016-008825-B   | < 1                           |
| 5  | BURROUGHS EDUCATIONAL CAMPUS     | WS- 008824      | 12/27/2016    | Basement | Classroom Faucet | In classroom 19 | FT-122016-008824-A   | < 1                           | FT-122016-008824-B   | < 1                           |

| Greater than 1 ppb - Devices Shut Off and Corrective Action Taken |                              |            |            |          |                  |                 |                    |     |                    |     |
|---|------------------------------|------------|------------|----------|------------------|-----------------|--------------------|-----|--------------------|-----|
| 1   | BURROUGHS EDUCATIONAL CAMPUS | WS- 008826 | 12/27/2016 | Basement | Classroom Faucet | In classroom 20 | FT-122016-008826-A | 2.7 | FT-122016-008826-B | < 1 |
| 2   | BURROUGHS EDUCATIONAL CAMPUS | WS- 008628 | 12/27/2016 | 1        | Classroom Faucet | In classroom 35 | FT-122016-008628-A | 4.4 | FT-122016-008628-B | < 1 |
| 3   | BURROUGHS EDUCATIONAL CAMPUS | WS- 008827 | 12/27/2016 | Basement | Classroom Faucet | In classroom 21 | FT-122016-008827-A | 3.2 | FT-122016-008827-B | < 1 |

## First Filter Re-Test (After Filter and Plumbing Check with Aerator Replacement)

| Greater than 1 ppb - Devices Remain Shut off, Continued Remediation |                              |            |           |          |                  |                 |                    |     |                    |     |
|---|------------------------------|------------|-----------|----------|------------------|-----------------|--------------------|-----|--------------------|-----|
| 1   | BURROUGHS EDUCATIONAL CAMPUS | WS- 008826 | 1/25/2017 | Basement | Classroom Faucet | In classroom 20 | FT-122016-008826-A | 1.1 | FT-122016-008826-B | < 1 |
| 2   | BURROUGHS EDUCATIONAL CAMPUS | WS- 008628 | 1/25/2017 | 1        | Classroom Faucet | In classroom 35 | FT-122016-008628-A | 1.3 | FT-122016-008628-B | < 1 |
| 3   | BURROUGHS EDUCATIONAL CAMPUS | WS- 008827 | 1/25/2017 | Basement | Classroom Faucet | In classroom 21 | FT-122016-008827-A | 2.9 | FT-122016-008827-B | < 1 |

## Second Filter Re-Test (After Device Replacement)

| Greater than 1 ppb - Devices Remain Shut off, Continued Remediation |                              |            |           |          |                  |                 |                    |     |                    |     |
|---|------------------------------|------------|-----------|----------|------------------|-----------------|--------------------|-----|--------------------|-----|
| 1   | BURROUGHS EDUCATIONAL CAMPUS | WS- 008826 | 3/30/2017 | Basement | Classroom Faucet | In classroom 20 | FT-122016-008826-A | 6.5 | FT-122016-008826-B | < 1 |
| 2   | BURROUGHS EDUCATIONAL CAMPUS | WS- 008628 | 3/30/2017 | 1        | Classroom Faucet | In classroom 35 | FT-122016-008628-A | 2.7 | FT-122016-008628-B | < 1 |
| 3   | BURROUGHS EDUCATIONAL CAMPUS | WS- 008827 | 3/30/2017 | Basement | Classroom Faucet | In classroom 21 | FT-122016-008827-A | 4.7 | FT-122016-008827-B | < 1 |

## Filter Re-Test (h # ° ) o 7 @ )

| O than ppb - Devices Remain Shut off, Continued Remediation |                              |            |           |          |                  |                 |                    |     |                    |     |
|---|------------------------------|------------|-----------|----------|------------------|-----------------|--------------------|-----|--------------------|-----|
| 1   | BURROUGHS EDUCATIONAL CAMPUS | WS- 008826 | 8/11/2017 | Basement | Classroom Faucet | In classroom 20 | FT-122016-008826-A | < 1 | FT-122016-008826-B | < 1 |
| 2   | BURROUGHS EDUCATIONAL CAMPUS | WS- 008628 | 8/11/2017 | 1        | Classroom Faucet | In classroom 35 | FT-122016-008628-A | < 1 | FT-122016-008628-B | < 1 |
| 3   | BURROUGHS EDUCATIONAL CAMPUS | WS- 008827 | 8/11/2017 | Basement | Classroom Faucet | In classroom 21 | FT-122016-008827-A | < 1 | FT-122016-008827-B | < 1 |