



BURROUGHS EC LEAD WATER TEST RESULTS



Initial Filter Test After Installation

Less than 1 ppb - Device Returned to Service										
	Building Location: Building Name	Water Source ID	Date Analyzed	Floor	Device Type	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	Final Result - 2nd Draw (ppb)
1	BURROUGHS EDUCATIONAL CAMPUS	WS- 008828	12/27/2016	Basement	Classroom Faucet	In classroom 22	FT-122016-008828-A	< 1	FT-122016-008828-B	< 1
2	BURROUGHS EDUCATIONAL CAMPUS	WS- 008625	12/27/2016	1	Classroom Faucet	In classroom 34	FT-122016-008625-A	< 1	FT-122016-008625-B	< 1
3	BURROUGHS EDUCATIONAL CAMPUS	WS- 008631	12/27/2016	1	Classroom Faucet	In classroom 25	FT-122016-008631-A	< 1	FT-122016-008631-B	< 1
4	BURROUGHS EDUCATIONAL CAMPUS	WS- 008825	12/27/2016	Basement	Classroom Faucet	In classroom 18	FT-122016-008825-A	< 1	FT-122016-008825-B	< 1
5	BURROUGHS EDUCATIONAL CAMPUS	WS- 008824	12/27/2016	Basement	Classroom Faucet	In classroom 19	FT-122016-008824-A	< 1	FT-122016-008824-B	< 1

Greater than 1 ppb - Devices Shut Off and Corrective Action Taken										
1	BURROUGHS EDUCATIONAL CAMPUS	WS- 008826	12/27/2016	Basement	Classroom Faucet	In classroom 20	FT-122016-008826-A	2.7	FT-122016-008826-B	< 1
2	BURROUGHS EDUCATIONAL CAMPUS	WS- 008628	12/27/2016	1	Classroom Faucet	In classroom 35	FT-122016-008628-A	4.4	FT-122016-008628-B	< 1
3	BURROUGHS EDUCATIONAL CAMPUS	WS- 008827	12/27/2016	Basement	Classroom Faucet	In classroom 21	FT-122016-008827-A	3.2	FT-122016-008827-B	< 1

First Filter Re-Test (After Filter and Plumbing Check with Aerator Replacement)

Greater than 1 ppb - Devices Remain Shut off, Continued Remediation										
1	BURROUGHS EDUCATIONAL CAMPUS	WS- 008826	1/25/2017	Basement	Classroom Faucet	In classroom 20	FT-122016-008826-A	1.1	FT-122016-008826-B	< 1
2	BURROUGHS EDUCATIONAL CAMPUS	WS- 008628	1/25/2017	1	Classroom Faucet	In classroom 35	FT-122016-008628-A	1.3	FT-122016-008628-B	< 1
3	BURROUGHS EDUCATIONAL CAMPUS	WS- 008827	1/25/2017	Basement	Classroom Faucet	In classroom 21	FT-122016-008827-A	2.9	FT-122016-008827-B	< 1

Second Filter Re-Test (After Device Replacement)

Greater than 1 ppb - Devices Remain Shut off, Continued Remediation										
1	BURROUGHS EDUCATIONAL CAMPUS	WS- 008826	3/30/2017	Basement	Classroom Faucet	In classroom 20	FT-122016-008826-A	6.5	FT-122016-008826-B	< 1
2	BURROUGHS EDUCATIONAL CAMPUS	WS- 008628	3/30/2017	1	Classroom Faucet	In classroom 35	FT-122016-008628-A	2.7	FT-122016-008628-B	< 1
3	BURROUGHS EDUCATIONAL CAMPUS	WS- 008827	3/30/2017	Basement	Classroom Faucet	In classroom 21	FT-122016-008827-A	4.7	FT-122016-008827-B	< 1

Note :

Filter re-tests are only performed to devices that have sampling results greater than 1 ppb