



HARRIS CW LEAD WATER TEST RESULTS



Initial Filter Test After Installation

Less than 1 ppb - Device Returned to Service										
	Building Location: Building Name	Water Source ID	Date Analyzed	Floor	Device Type	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	Final Result - 2nd Draw (ppb)
1	HARRIS CW ELEMENTARY SCHOOL	WS- 004308	1/7/2017	1	Classroom Faucet	In classroom 145	FT-112016-004308-A	< 1	FT-112016-004308-B	< 1
2	HARRIS CW ELEMENTARY SCHOOL	WS- 004312	1/7/2017	1	Classroom Faucet	In classroom 153	FT-112016-004312-A	< 1	FT-112016-004312-B	< 1
3	HARRIS CW ELEMENTARY SCHOOL	WS- 004305	1/7/2017	1	Classroom Faucet	In classroom 142	FT-112016-004305-A	< 1	FT-112016-004305-B	< 1
4	HARRIS CW ELEMENTARY SCHOOL	WS- 004306	1/7/2017	1	Classroom Faucet	In classroom 143	FT-112016-004306-A	< 1	FT-112016-004306-B	< 1
5	HARRIS CW ELEMENTARY SCHOOL	WS- 004307	1/7/2017	1	Classroom Faucet	In classroom 144	FT-112016-004307-A	< 1	FT-112016-004307-B	< 1
6	HARRIS CW ELEMENTARY SCHOOL	WS- 004313	1/7/2017	2	Break Room	In staff lounge across from room 222	FT-112016-004313-A	< 1	FT-112016-004313-B	< 1

First Filter Re-Test (After Filter and Plumbing Check with Aerator Replacement)

Greater than 1 ppb - Devices Remain Shut off, Continued Remediation										
1	HARRIS CW ELEMENTARY SCHOOL	WS- 004313	2/8/2017	2	Break Room	In staff lounge across from room 222	FT-112016-004313-A	1.5	FT-112016-004313-B	< 1

Second Filter Re-Test (After Device Replacement)

Greater than 1 ppb - Devices Remain Shut off, Continued Remediation										
1	HARRIS CW ELEMENTARY SCHOOL	WS- 004313	4/7/2017	2	Break Room	In staff lounge across from room 222	FT-112016-004313-A	1	FT-112016-004313-B	< 1

Filter Re-Test (Post Consultation; After Dual Supply Faucet Installation)

Less than 5 ppb - Device Returned to Service										
1	HARRIS CW ELEMENTARY SCHOOL	WS- 004313	8/11/2017	2	Break Room	In staff lounge across from room 222	FT-112016-004313-A	< 1	FT-112016-004313-B	< 1