



Chevy Chase CC Lead in Water Test Results

FY26 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 010051	2/24/2026	2/24/2027	Basement	Cooler	In hallway adjacent to game room	WF-02242026-010051	4/9/2026	FT-FY26-03262026-010051-A	<2	FT-FY26-03262026-010051-B	<2
WS- 010052	2/24/2026	2/24/2027	Basement	Cooler	In hallway adjacent to exit/game room	WF-02242026-010052	4/9/2026	FT-FY26-03262026-010052-A	<2	FT-FY26-03262026-010052-B	<2
WS- 010053	2/24/2026	2/24/2027	1	Cooler	In hallway adjacent to Restroom	WF-02242026-010053	4/9/2026	FT-FY26-03262026-010053-A	<2	FT-FY26-03262026-010053-B	<2
WS- 010054	2/24/2026	2/24/2027	1	Cooler	In hallway adjacent to room 114	WF-02242026-010054	4/9/2026	FT-FY26-03262026-010054-A	<2	FT-FY26-03262026-010054-B	4.0
WS- 010055	12/2/2025	12/2/2026	1	Food Prep Sink	In kitchen	WF-12022025-010055	4/9/2026	FT-FY26-03262026-010055-A	<2	FT-FY26-03262026-010055-B	<2
WS- 010059	2/24/2026	2/24/2027	1	Cooler	In classroom 105	WF-02242026-010059	4/9/2026	FT-FY26-03262026-010059-A	<2	FT-FY26-03262026-010059-B	<2
WS- 010060	2/24/2026	2/24/2027	2	Cooler	In hallway adjacent to restroom	WF-02242026-010060	4/9/2026	FT-FY26-03262026-010060-A	<2	FT-FY26-03262026-010060-B	<2
WS- 010061	2/24/2026	2/24/2027	2	Cooler	In hallway adjacent to art room	WF-02242026-010061	4/9/2026	FT-FY26-03262026-010061-A	<2	FT-FY26-03262026-010061-B	<2

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.