



Chevy Chase CC Lead in Water Test Results

FY25 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 010051	3/5/2024	3/5/2025	Basement	Cooler	In hallway adjacent to game room	WF-03052024-010051	2/18/2025	FT-FY25-01082025-010051-A	<2	FT-FY25-01082025-010051-B	<2
WS- 010052	3/5/2024	3/5/2025	Basement	Cooler	In hallway adjacent to exit/game room	WF-03052024-010052	2/18/2025	FT-FY25-01082025-010052-A	<2	FT-FY25-01082025-010052-B	<2
WS- 010054	3/5/2024	3/5/2025	1	Cooler	In hallway adjacent to room 114	WF-03052024-010054	2/18/2025	FT-FY25-01082025-010054-A	<2	FT-FY25-01082025-010054-B	<2
WS- 010055	12/10/2024	12/10/2025	1	Food Prep Sink	In kitchen	WF-12102024-010055	2/18/2025	FT-FY25-01082025-010055-A	<2	FT-FY25-01082025-010055-B	<2
WS- 010059	3/5/2024	3/5/2025	1	Cooler	In classroom 105	WF-03052024-010059	2/18/2025	FT-FY25-01082025-010059-A	<2	FT-FY25-01082025-010059-B	<2
WS- 010060	3/5/2024	3/5/2025	2	Cooler	In hallway adjacent to restroom	WF-03052024-010060	2/18/2025	FT-FY25-01082025-010060-A	<2	FT-FY25-01082025-010060-B	<2
WS- 010061	3/5/2024	3/5/2025	2	Cooler	In hallway adjacent to art room	WF-03052024-010061	2/18/2025	FT-FY25-01082025-010061-A	<2	FT-FY25-01082025-010061-B	<2

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.