



Chevy Chase RC Lead in Water Test Results

FY26 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 012535	2/24/2026	2/24/2027	1	Cooler	In hallway adjacent to mechanical room High	WF-02242026-012535	4/7/2026	FT-FY26-03262026-012535-A	<2	FT-FY26-03262026-012535-B	<2
WS- 012536	2/24/2026	2/24/2027	1	Cooler	In hallway adjacent to mechanical room Low	WF-02242026-012536	4/7/2026	FT-FY26-03262026-012536-A	<2	FT-FY26-03262026-012536-B	<2
WS- 012537	11/10/2025	11/10/2026	1	Food Prep Sink	In kitchen	WF-11102025-012537	4/7/2026	FT-FY26-03262026-012537-A	<2	FT-FY26-03262026-012537-B	<2

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.