



Columbia Heights Educational Campus Lead in Water Test Results

FY25 Filter Test

Less than 5ppb - Devices requiring no remediation

| Record ID | Filter Installed Date | Filter Expiration Date | Floor | Device Type | Device Location | Water Filter's Name | Date Analyzed | 1st Draw - Sample ID | FT Final Result - 1st Draw (ppb) | 2nd Draw - Sample ID | FT Final Result - 2nd Draw (ppb) |
|------------|-----------------------|------------------------|-------|------------------|---|---------------------|---------------|---------------------------|----------------------------------|---------------------------|----------------------------------|
| WS- 002171 | 9/9/2024 | 9/9/2025 | 1 | Bottle Filler | In hallway across from room C135 | WF-09092024-002171 | 10/14/2024 | FT-FY25-10032024-002171-A | <2 | FT-FY25-10032024-002171-B | <2 |
| WS- 002177 | 2/12/2024 | 2/12/2025 | 2 | Bottle Filler | In hallway adjacent to room A206 | WF-02122024-002177 | 10/14/2024 | FT-FY25-10032024-002177-A | <2 | FT-FY25-10032024-002177-B | <2 |
| WS- 002178 | 2/12/2024 | 2/12/2025 | 2 | Bottle Filler | In hallway adjacent to room A205 | WF-02122024-002178 | 10/14/2024 | FT-FY25-10032024-002178-A | <2 | FT-FY25-10032024-002178-B | <2 |
| WS- 002180 | 2/12/2024 | 2/12/2025 | 2 | Bottle Filler | In locker room E234 | WF-02122024-002180 | 10/14/2024 | FT-FY25-10032024-002180-A | <2 | FT-FY25-10032024-002180-B | <2 |
| WS- 002184 | 2/12/2024 | 2/12/2025 | 3 | Bottle Filler | In hallway adjacent to restrooms | WF-02122024-002184 | 10/14/2024 | FT-FY25-10032024-002184-A | <2 | FT-FY25-10032024-002184-B | <2 |
| WS- 002335 | 2/12/2024 | 2/12/2025 | 1 | Health Suite | In health suite A138 | WF-02122024-002335 | 10/14/2024 | FT-FY25-10032024-002335-A | <2 | FT-FY25-10032024-002335-B | <2 |
| WS- 008025 | 9/9/2024 | 9/9/2025 | 1 | Classroom Faucet | In classroom E121A first clockwise from entry door | WF-09092024-008025 | 10/14/2024 | FT-FY25-10032024-008025-A | <2 | FT-FY25-10032024-008025-B | <2 |
| WS- 008026 | 9/9/2024 | 9/9/2025 | 1 | Classroom Faucet | In classroom E121A second clockwise from entry door | WF-09092024-008026 | 10/14/2024 | FT-FY25-10032024-008026-A | <2 | FT-FY25-10032024-008026-B | <2 |
| WS- 008027 | 9/9/2024 | 9/9/2025 | 1 | Classroom Faucet | In classroom E121A third clockwise from entry door | WF-09092024-008027 | 10/14/2024 | FT-FY25-10032024-008027-A | <2 | FT-FY25-10032024-008027-B | <2 |
| WS- 008028 | 9/9/2024 | 9/9/2025 | 1 | Classroom Faucet | In classroom E121A fourth clockwise from entry door | WF-09092024-008028 | 10/14/2024 | FT-FY25-10032024-008028-A | <2 | FT-FY25-10032024-008028-B | <2 |
| WS- 008057 | 9/9/2024 | 9/10/2025 | 1 | Cooler | In hallway adjacent to room C135 High Right | WF-09092024-008057 | 10/14/2024 | FT-FY25-10032024-008057-A | <2 | FT-FY25-10032024-008057-B | <2 |
| WS- 008059 | 2/12/2024 | 2/12/2025 | 1 | Break Room | In break room C117 | WF-02122024-008059 | 10/14/2024 | FT-FY25-10032024-008059-A | <2 | FT-FY25-10032024-008059-B | <2 |
| WS- 008100 | 2/12/2024 | 2/12/2025 | 2 | Cooler | In hallway adjacent to room A206 High Left | WF-02122024-008100 | 10/14/2024 | FT-FY25-10032024-008100-A | <2 | FT-FY25-10032024-008100-B | <2 |
| WS- 008101 | 2/12/2024 | 2/12/2025 | 2 | Cooler | In hallway adjacent to room A206 Low Right | WF-02122024-008101 | 10/14/2024 | FT-FY25-10032024-008101-A | <2 | FT-FY25-10032024-008101-B | <2 |
| WS- 008102 | 2/12/2024 | 2/12/2025 | 2 | Cooler | In hallway adjacent to room A205 High Left | WF-02122024-008102 | 10/14/2024 | FT-FY25-10032024-008102-A | <2 | FT-FY25-10032024-008102-B | <2 |
| WS- 008103 | 2/12/2024 | 2/12/2025 | 2 | Cooler | In hallway adjacent to room A205 Low Right | WF-02122024-008103 | 10/14/2024 | FT-FY25-10032024-008103-A | <2 | FT-FY25-10032024-008103-B | <2 |
| WS- 008105 | 2/12/2024 | 2/12/2025 | 2 | Cooler | In hallway adjacent to stairwell 2 Low Left | WF-02122024-008105 | 10/14/2024 | FT-FY25-10032024-008105-A | <2 | FT-FY25-10032024-008105-B | <2 |
| WS- 008107 | 2/12/2024 | 2/12/2025 | 2 | Cooler | In hallway adjacent to stairwell 2 High Right | WF-02122024-008107 | 10/14/2024 | FT-FY25-10032024-008107-A | <2 | FT-FY25-10032024-008107-B | <2 |
| WS- 008159 | 2/12/2024 | 2/12/2025 | 3 | Cooler | In hallway adjacent to the restrooms High Left | WF-02122024-008159 | 10/14/2024 | FT-FY25-10032024-008159-A | <2 | FT-FY25-10032024-008159-B | <2 |
| WS- 008160 | 2/12/2024 | 2/12/2025 | 3 | Cooler | In hallway adjacent to the restrooms Low Right | WF-02122024-008160 | 10/14/2024 | FT-FY25-10032024-008160-A | <2 | FT-FY25-10032024-008160-B | <2 |
| WS- 008169 | 2/12/2024 | 2/12/2025 | 2 | Cooler | In locker room E234 High Left | WF-02122024-008169 | 10/14/2024 | FT-FY25-10032024-008169-A | <2 | FT-FY25-10032024-008169-B | <2 |
| WS- 008170 | 2/12/2024 | 2/12/2025 | 2 | Cooler | In locker room E234 Low Right | WF-02122024-008170 | 10/14/2024 | FT-FY25-10032024-008170-A | <2 | FT-FY25-10032024-008170-B | <2 |
| WS- 008201 | 9/9/2024 | 9/10/2025 | 1 | Cooler | In hallway adjacent to choir room E107 High Left | WF-09092024-008201 | 10/14/2024 | FT-FY25-10032024-008201-A | <2 | FT-FY25-10032024-008201-B | <2 |
| WS- 008202 | 9/9/2024 | 9/10/2025 | 1 | Cooler | In hallway adjacent to choir room E107 Low Right | WF-09092024-008202 | 10/14/2024 | FT-FY25-10032024-008202-A | <2 | FT-FY25-10032024-008202-B | <2 |
| WS- 008205 | 2/12/2024 | 2/12/2025 | 1 | Health Suite | In health suite | WF-02122024-008205 | 10/14/2024 | FT-FY25-10032024-008205-A | <2 | FT-FY25-10032024-008205-B | <2 |

Food Prep Sink

Less than 5ppb - Devices requiring no remediation

| Record ID | Filter Installed Date | Filter Expiration Date | Floor | Device Type | Device Location | Water Filter's Name | Date Analyzed | 1st Draw - Sample ID | FT Final Result - 1st Draw (ppb) | 2nd Draw - Sample ID | FT Final Result - 2nd Draw (ppb) |
|------------|-----------------------|------------------------|-------|----------------|-----------------------------|---------------------|---------------|---------------------------|----------------------------------|---------------------------|----------------------------------|
| WS- 008110 | 11/14/2023 | 11/14/2024 | 1 | Food Prep Sink | In kitchen north wall Mid | WF-11142023-008110 | 10/14/2024 | FT-FY25-10032024-008110-A | <2 | FT-FY25-10032024-008110-B | <2 |
| WS- 008111 | 11/14/2023 | 11/14/2024 | 1 | Food Prep Sink | In kitchen north wall Right | WF-11142023-008111 | 10/14/2024 | FT-FY25-10032024-008111-A | <2 | FT-FY25-10032024-008111-B | <2 |
| WS- 008113 | 11/14/2023 | 11/14/2024 | 1 | Food Prep Sink | In kitchen east wall Left | WF-11142023-008113 | 10/14/2024 | FT-FY25-10032024-008113-A | <2 | FT-FY25-10032024-008113-B | <2 |
| WS- 008117 | 11/14/2023 | 11/14/2024 | 1 | Food Prep Sink | In kitchen on island | WF-11142023-008117 | 10/14/2024 | FT-FY25-10032024-008117-A | <2 | FT-FY25-10032024-008117-B | <2 |

Due to changes in water sample analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.