



Deanwood RC Lead in Water Test Results

FY26 Filter Test

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 005334	2/16/2026	2/16/2027	1	Cooler	In hallway adjacent to room 1301	High Left	WF-02162026-005334	4/2/2026	FT-FY26-03202026-005334-A	<2	FT-FY26-03202026-005334-B	<2
WS- 005335	2/16/2026	2/16/2027	1	Cooler	In hallway adjacent to room 1301	Low Right	WF-02162026-005335	4/2/2026	FT-FY26-03202026-005335-A	<2	FT-FY26-03202026-005335-B	<2
WS- 005336	11/12/2025	11/12/2026	1	Food Prep Sink	In kitchen 1202		WF-11122025-005336	4/2/2026	FT-FY26-03202026-005336-A	<2	FT-FY26-03202026-005336-B	<2
WS- 005337	2/16/2026	2/16/2027	1	Cooler	In hallway adjacent to room 1105	High	WF-02162026-005337	4/2/2026	FT-FY26-03202026-005337-A	<2	FT-FY26-03202026-005337-B	<2
WS- 005338	2/16/2026	2/16/2027	1	Cooler	In hallway adjacent to room 1105	Low Right	WF-02162026-005338	4/2/2026	FT-FY26-03202026-005338-A	<2	FT-FY26-03202026-005338-B	<2
WS- 005340	2/16/2026	2/16/2027	1	Cooler	In hallway adjacent to room 1505	High Left	WF-02162026-005340	4/2/2026	FT-FY26-03202026-005340-A	<2	FT-FY26-03202026-005340-B	<2
WS- 005341	2/16/2026	2/16/2027	1	Cooler	In hallway adjacent to room 1505	Low Right	WF-02162026-005341	4/2/2026	FT-FY26-03202026-005341-A	<2	FT-FY26-03202026-005341-B	<2
WS- 005343	2/16/2026	2/16/2027	1	Fountain	In classroom 1410 in restroom area first clockwise around room from entry door	Left	WF-02162026-005343	4/2/2026	FT-FY26-03202026-005343-A	<2	FT-FY26-03202026-005343-B	<2
WS- 005345	2/16/2026	2/16/2027	1	Fountain	In classroom 1410 in restroom area second clockwise around room from entry door	Mid	WF-02162026-005345	4/2/2026	FT-FY26-03202026-005345-A	<2	FT-FY26-03202026-005345-B	<2
WS- 005347	2/16/2026	2/16/2027	1	Fountain	In classroom 1410 in restroom area third clockwise around room from entry door	Right	WF-02162026-005347	4/2/2026	FT-FY26-03202026-005347-A	<2	FT-FY26-03202026-005347-B	<2
WS- 005358	2/16/2026	2/16/2027	1	Fountain	In classroom 1414 in restroom area second clockwise around room from entry door		WF-02162026-005358	4/2/2026	FT-FY26-03202026-005358-A	<2	FT-FY26-03202026-005358-B	<2
WS- 005366	2/16/2026	2/16/2027	1	Break Room	In classroom 1415		WF-02162026-005366	4/2/2026	FT-FY26-03202026-005366-A	<2	FT-FY26-03202026-005366-B	<2
WS- 005367	11/12/2025	11/12/2026	1	Food Prep Sink	In kitchen 1417		WF-11122025-005367	4/2/2026	FT-FY26-03202026-005367-A	<2	FT-FY26-03202026-005367-B	<2

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.