



Deanwood RC Lead in Water Test Results



FY20 Filter Test

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 005334	4/2/2019	4/2/2020	1	Fountain	In hallway adjacent to room 1301	High Left	WF-04022019-005334	3/11/2020	FT-FY20-012020-005334-A	<1	FT-FY20-012020-005334-B	<1
WS- 005335	4/2/2019	4/2/2020	1	Fountain	In hallway adjacent to room 1301	Low Right	WF-04022019-005335	3/11/2020	FT-FY20-012020-005335-A	<1	FT-FY20-012020-005335-B	<1
WS- 005336	4/2/2019	4/2/2020	1	Food Prep Sink	In kitchen 1202		WF-04022019-005336	3/11/2020	FT-FY20-012020-005336-A	<1	FT-FY20-012020-005336-B	<1
WS- 005340	4/2/2019	4/2/2020	1	Cooler	In hallway adjacent to room 1505	High Left	WF-04022019-005340	3/11/2020	FT-FY20-012020-005340-A	<1	FT-FY20-012020-005340-B	<1
WS- 005341	4/2/2019	4/2/2020	1	Cooler	In hallway adjacent to room 1505	Low Right	WF-04022019-005341	3/11/2020	FT-FY20-012020-005341-A	<1	FT-FY20-012020-005341-B	<1
WS- 005343	4/2/2019	4/2/2020	1	Fountain	In classroom 1410 in restroom area first clockwise around room from entry door	Left	WF-04022019-005343	3/11/2020	FT-FY20-012020-005343-A	<1	FT-FY20-012020-005343-B	<1
WS- 005345	4/2/2019	4/2/2020	1	Fountain	In classroom 1410 in restroom area second clockwise around room from entry door	Mid	WF-04022019-005345	3/11/2020	FT-FY20-012020-005345-A	<1	FT-FY20-012020-005345-B	<1
WS- 005347	4/2/2019	4/2/2020	1	Fountain	In classroom 1410 in restroom area third clockwise around room from entry door	Right	WF-04022019-005347	3/11/2020	FT-FY20-012020-005347-A	<1	FT-FY20-012020-005347-B	<1
WS- 005367	4/2/2019	4/2/2020	1	Food Prep Sink	In kitchen 1417		WF-04022019-005367	3/11/2020	FT-FY20-012020-005367-A	<1	FT-FY20-012020-005367-B	<1