



EATON LEAD WATER TEST RESULTS



Initial Filter Test After Installation

Less than 1 ppb - Device Returned to Service											
	Building Location: Building Name	Water Source ID	Date Analyzed	Floor	Device Type	Device Location		1st Draw - Sample ID	Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	Final Result - 2nd Draw (ppb)
1	EATON ELEMENTARY	WS- 008666	12/11/2016	1	Classroom Faucet	In classroom 119	Right	FT-122016-008666-A	< 1	FT-122016-008666-B	< 1
2	EATON ELEMENTARY	WS- 008667	12/11/2016	1	Classroom Faucet	In classroom 119	Left	FT-122016-008667-A	< 1	FT-122016-008667-B	< 1
3	EATON ELEMENTARY	WS- 008668	12/11/2016	1	Classroom Faucet	In classroom 119B in room 119		FT-122016-008668-A	< 1	FT-122016-008668-B	< 1
4	EATON ELEMENTARY	WS- 008669	12/11/2016	1	Classroom Faucet	In classroom 120	Left	FT-122016-008669-A	< 1	FT-122016-008669-B	< 1
5	EATON ELEMENTARY	WS- 008670	12/11/2016	1	Classroom Faucet	In classroom 120	Right	FT-122016-008670-A	< 1	FT-122016-008670-B	< 1
6	EATON ELEMENTARY	WS- 008671	12/11/2016	1	Classroom Faucet	In classroom 111	Left	FT-122016-008671-A	< 1	FT-122016-008671-B	< 1
7	EATON ELEMENTARY	WS- 008672	12/11/2016	1	Classroom Faucet	In classroom 111	Mid	FT-122016-008672-A	< 1	FT-122016-008672-B	< 1
8	EATON ELEMENTARY	WS- 008681	12/11/2016	1	Classroom Faucet	In classroom 104		FT-122016-008681-A	< 1	FT-122016-008681-B	< 1
9	EATON ELEMENTARY	WS- 008682	12/11/2016	1	Classroom Faucet	In classroom 104 in room 104B		FT-122016-008682-A	< 1	FT-122016-008682-B	< 1
10	EATON ELEMENTARY	WS- 008691	12/11/2016	2	Break Room	In library office		FT-102016-008691-A	< 1	FT-102016-008691-B	< 1

Greater than 1 ppb - Devices Shut Off and Corrective Action Taken											
1	EATON ELEMENTARY	WS- 008673	12/11/2016	1	Classroom Faucet	In classroom 111	Right	FT-122016-008673-A	1.3	FT-122016-008673-B	< 1
2	EATON ELEMENTARY	WS- 008674	12/11/2016	1	Classroom Faucet	In classroom 113		FT-122016-008674-A	1.2	FT-122016-008674-B	< 1

First Filter Re-Test (After Filter and Plumbing Check with Aerator Replacement)

Greater than 1 ppb - Devices Remain Shut off, Continued Remediation											
1	EATON ELEMENTARY	WS- 008673	1/25/2017	1	Classroom Faucet	In classroom 111	Right	FT-122016-008673-A	2.6	FT-122016-008673-B	< 1
2	EATON ELEMENTARY	WS- 008674	1/25/2017	1	Classroom Faucet	In classroom 113		FT-122016-008674-A	3.5	FT-122016-008674-B	< 1

Second Filter Re-Test (After Device Replacement)

Less than 1 ppb - Device Returned to Service											
1	EATON ELEMENTARY	WS- 008673	4/7/2017	1	Classroom Faucet	In classroom 111	Right	FT-122016-008673-A	< 1	FT-122016-008673-B	< 1

Greater than 1 ppb - Devices Remain Shut off, Continued Remediation											
2	EATON ELEMENTARY	WS- 008674	4/7/2017	1	Classroom Faucet	In classroom 113		FT-122016-008674-A	1.1	FT-122016-008674-B	< 1

Filter Re-Test (Post Consultation; After Dual Supply Faucet Installation)

Less than 5 ppb - Device Returned to Service											
1	EATON ELEMENTARY	WS- 008674	8/11/2017	1	Classroom Faucet	In classroom 113		FT-122016-008674-A	< 1	FT-122016-008674-B	< 1