# **Questions & Answers**

# Solicitation No. DCAM-23-NC-RFP-0007

# Property Management Services at John A. Wilson Building

NO.	SECTION NO./PAGE NO	QUESTIONS	
01	C.4.2.2	Historically, how many occupants were in the building on a daily basis in the year 2019?	1800, on average
02	C.5.3	What is the historical service call information for the year 2019?	Historical service call information in 2019 is
03	C.5.20.1.1	What is the number of repairs over the \$1500 threshold in the year 2019?	17
04	C.5.20.1.1	What is the number of repairs under the \$1500 threshold in the year 2019?	Number of repairs under the \$1500 thresh
05	C.4.2.2	Historically, how many occupants were in the building on a daily basis in the year 2022?	1100
06	C.5.3	What is the historical service call information for the year 2022?	1260
07	C.5.20.1.1	What is the number of repairs over the \$1500 threshold in the year 2022?	18
08	C.5.20.1.1	What is the number of repairs under the \$1500 threshold in the year 2022?	Number of repairs under the \$1500 thresh
09	C.5.2.1.5.1.1 (e)	What is the estimated number of HVAC units and subsequent counts of filters which require monthly filter changes?	17 HVAC units with 272 filters
10	C.5.9	No fire protection system equipment is provided on the equipment lists. Please provide the equipment list for the Fire Protection Systems. This is imperative to obtaining competitive quotes for this service area.	Simplex 4100 addressable fire alarm syster site visit. Offerors can request to see bluep Varre at jean-francis.varre@dc.gov.
11	C.5.3.1.5	Please confirm the government is responsible for the cost and upgrades of the Salesforce WOMS.	Correct. There is no Salesforce cost to the
12	C.5.8.2.1	On page 90 of 229 states the requirement for a contractor provided WOMS supplement system. Is there an existing contractor provided WOMS supplement system currently in place? If so, will the awarded contractor have access to the data within this system during the transition period?	No, there is no supplemental Work Order I provide their own PC in order to interface
13	C.5.8.2	Please provide a list of DGS approved-for-use WOMS.	Work Order Management System ("WOMs used by DGS. The District will provide the a
14	H.11.5	Will the government provide training on the SalesForce Work Order Management System?	Yes
15	C.5.16	Is the Wilson building exempt from BEPS compliance? If yes, is the current contractor responsible for BEPS compliance?	No, the Wilson Building is not exempt from clarification, the contractor is responsible f
16	C.5.16.1	At what level is the building LEED Certified?	Wilson Building is not a LEED certified build
17	C.5.2.1.9.7	Please confirm that vandalism repairs and associated labor are excluded from FFP, and are to be included in the time and material portion of the contract.	Vandalism repairs above the \$1500 threshound of the \$1500 threshound of the \$1500 threshold shall be perform
18	C.5.8.1.2	Please confirm that the government is responsible for all IT Maintenance items listed in this section.	No, this section is referring to contractor's (laptop, phones, etc.) should have all the re shall be the contractor's responsibility to b not responsible.
19	C.5.10.1.3	Please provide the count and last inspection date of the roof anchors at the facility.	There are no roof anchors at the Wilson Bu

## DGS RESPONSE

) is not available.

shold in 2019 is not available.

shold in 2022 is not available.

em with a 750gpm fire pump. Equipment was shown during scheduled eprint drawings at the Facility by contacting the COTR, Jean-Francis

e vendor.

r Management systems (WOMs) besides Salesforce. Contractor must e with Salesforce where all the records are contained.

As") is Salesforce. For clarification, Salesforce is the only WOM system awarded contractor access to Salesforce.

om Building Energy Performance Standards ("BEPS") compliance. For e for BEPS compliance.

ilding

shold are under the time and material supplemental services; repairs prmed under basic services.

's equipment being used on district property. Contractor's equipment required anti-virus software, spyware protection program, etc., and buy/maintain these programs on their own equipment. The District is

Building.

<u>NO.</u>	SECTION NO./PAGE NO	QUESTIONS	
20	C.5.10.1.3	Please provide specifications on the use of the roof anchor system.	There are no roof anchors at the Wilson Bu
21	C.5.2.2.7	Please provide the dates and results of the last semi-annual roof inspection.	The entire roof was replaced within the las
22	C.5.4.1.2	Is the replacement of UPS Batteries the responsibility of the government or the contractor? If this is a contractor's responsibility is it a part of the time and material portion of the contract?	No, the Contractor is not responsible for U
23	C.5.4.1.2	If the replacement of UPS Batteries is the responsibility of the contractor, please provide the frequency of replacement and last time the batteries were replaced.	Not applicable. The Contractor is not respo
24		<ul> <li>and services. Please specify if any of the items listed below are <u>not</u> required in the Firm-Fixed-Price:</li> <li>a. C.5.2.2.5.1 Chiller Eddy Current Testing</li> <li>b. C.5.2.2.5.1 Chiller Tube Punching (condenser and evaporator)</li> <li>c. C.5.2.2.5.1 Chiller Oil Analysis</li> <li>d. C.5.2.2.5.1 Chiller Vibration Analysis</li> <li>e. C.5.6.3.1 Pressure Vessel Inspections (water heaters)</li> <li>f. C.5.13.15.14.k Legionella testing on Cooling Tower</li> <li>g. C.5.13.15.14.k Legionella testing on domestic water system</li> <li>h. C.5.4.1.1.2 IR Scanning</li> <li>i. C.5.4 Panel and Main Switchgear Tightening</li> <li>j. C.5.4.2.3.2 Fuel tank cleaning</li> </ul>	Frequencies are established by industry sta are part of the preventative maintenance s B. Annually C. Annually D. No vibration analysis E. None F. Annually G. None H. Inf Red 2019 I. 2013 J. 2013 K. No underground tank L. Annual
25	C.5.6.3.1	Do the water heaters have cathodic protection? And if so, how often is it inspected?	No, the water heaters do not have cathodi
26	C.5.2.2.8.a	Please provide the building's count of Fire Extinguishers and their frequency of inspection.	182; inspected annually
27	C.5.16.3.10.2	Is the government responsible for the purchasing of R-22 for chiller operations? If it is the contractor's responsibility please confirm that any refrigerant costs in excess of the repair threshold (\$1,500.00) are reimbursable to the awarded contractor.	They are the contractor's responsibility and
28	(551)	Boilers are mentioned throughout the RFP but are not on the mechanical equipment list, nor were they seen on the site visit. Please provide equipment information for boilers if they are present.	There are no boilers at the Wilson Building
29	C.5.13.15	Icarried in the associated Landscaning CLIN (0001AM) or it that should be carried under the OM&R CLIN	That was an error that has been fixed. Wat Services section and inserted in the Plumbi
30	C.5.13.10		Offerors can request to see blueprint draw jean-francis.varre@dc.gov.
31	C.5.8	A contractor mentioned on the site visit that there was also a Johnson Controls Building Automation System present at this facility – in addition to the Siemens Apogee System. This is not accounted for on the equipment list. If it is present, please provide system specifications including version and points, as well as the equipment that is tied into the system.	There is no Johnson control system. The er
32	C.4	Does DGS have a current capital improvement plan for the Wilson Building? Is this an expectation of the new contractor?	There is a long term plan and it is not the r

Building.

ast eight (8) years. No additional information is available at this time.

UPS batteries. UPS batteries is tenant property and responsibility.

ponsible for UPS batteries.

standards. All of these services are included as Basic Services, as they e services. A. 2011

dic protection.

and part of the basic services; and this cost is not reimbursable.

ng.

Vater Treatment section has been removed from the Landscaping hbing Services section. Please see revised RFP (16-Feb-2023).

awings at the Facility by contacting the COTR, Jean-Francis Varre at

entire EMS is Siemens.

e responsibility of the contractor.

<u>NO.</u>	SECTION NO./PAGE NO	QUESTIONS	
33	B3.1.1 – CLIN 0028AF	Does the requested 0027AF standby hourly rate relate to labor only or labor and equipment? For example, the standby rate for the "Laborer" is much cheaper than the standby rate for "Bobcat with Operator".	Both, Labor and equipment.
34	B3.1.1 CLIN 0015	Is the hourly rate for fire alarm maintenance also to include fire suppression systems (Sprinkler)?	Yes
35	C.5.2.2.9.5	Are asset tags currently in place on all existing equipment? Does this requirement only related to new equipment installations?	No, asset tags are not currently in place for equipment installations.
36	C.5.2.2.10.3	Is CAD software provided by the government or is the contractor to supply?	The contractor is to supply.
37	C.5.4.1.2	Page 66 States "some UPS are maintained by tenant occupants" – Are the UPS systems listed in Attachment J.4 the responsibility of the contractor or tenant?	All UPS at the Wilson Building are tenant e
38	C.5.13.1.4	Please specify quantity and size of plant life to be applied during March 1st and March 15th?	An average of 200 pansy plants per year.
39	C.5.13.9	The RFP mentions a green roof at the facility, but it was not seen on the site visit. Please provide number of square feet of the green roof.	There is no green roof at the Wilson Buildin
40	C.5.13.15.8	Do coupon racks currently exist on-site? If so, how many racks are being monitored?	Yes, there are 2 coupon racks: One for clos
41	C.5.14.1.2.2.1	The RFP references Residential Units - are there any living quarters within the building? If so, please provide information on such areas.	No, there are no residential units at the W
42	C.5.8.1.1.2	Page 88 states that repairs on the BAS are to be included as a basic service and are not eligible T&M services. Please confirm that any repair costs in excess of the repair threshold (\$1,500.00) are reimbursable to the awarded contractor.	Correct.
43	C.5.10.1.1.3.d	Page 94 references completely painting common areas and restrooms, please confirm the acceptable hours for this task to be performed.	After hours in designated common areas o
44	C.5.10.1.1.3.d	Page 94 references completely painting common areas and restrooms, please confirm the estimated square footage required to be painted for this task.	Offerors can request to see blueprint drav jean-francis.varre@dc.gov.
45	C.5.11.2.2	Page 96 mentions the use of a subcontractor pending COTR approval for removing snow during heavy accumulation, please confirm that all related costs will be reimbursable to the awarded contractor.	Snow in excess of 6 inches is reimbursable.
46	C.5.11.3.1	Page 97 mentions an excess snow removal plan, please confirm that all related costs related to any need to execute this plan will be reimbursable to the awarded contractor.	Snow in excess of 6 inches is reimbursable.
47	C.5.12.4.5	Please confirm both indoor and outdoor window washing is to be completed two (2) times per year.	Confirmed
48	C.5.12.1.4 (p)	Please clarify if the scope of work is to include the cleaning of the interior petition glass or just the interior windows on the perimeter.	Only accessible panes on the interior or ex
49	C.5.19.1	Please clarify if this contract requires only U.S. citizens to be on-site or if valid work authorization and permanent residence will suffice?	Valid work authorization and permaner
50	C.5.12.1.4.g.9.ii	What are the sizes of the dumpsters currently on site? Who is the incumbent refuse and recycling service provider?	12 totes/95 gallons ea. The vendor is pr
51	C.5.19.1.6.1	Security Clearance: Who issues and controls the access keys?	Protective Services Division (PSD)
52	C.5.2.1.8.14.3.2	Cooling Towers: Please provide any make-up water consumption data for the cooling tower system.	Make up water consumption is not metere

DGS RESPONSE
for all existing equipment. Yes, this requirement relates only to new
equipment and responsibility.
ding.
osed loop and one for the cooling towers
Wilson Building.
s only
awings at the Facility by contacting the COTR, Jean-Francis Varre at
le.
le.
exterior are to be cleaned.
ent residence is sufficient.
proprietary information to the current prime.
ered.

<u>NO.</u>	SECTION NO./PAGE NO	QUESTIONS	
53	C.5.2.2.2	Inspection & Testing: When was the last time the fire & smoke dampers were tested?	The last fire and smoke dampers were test
54	C.5.2.2.2	Inspection & Testing: When was the last time the Fire Extinguishers had a hydrostatic test?	The last time the fire extinguishers had a h
55	C.5.13	What is the water treatment equipment onsite for the towers and closed systems?	Water is treated by Pulsation pumps.
56	L.20	Is parking provided by the Client for Contractor personnel? If so, how many spaces?	The District provides 2 parking spaces for t
57		Does the building have an anchor system?	No
58		How many times will the cleaning be provided (once or twice a year)?	Twice a year.
59		Does the scope of work include the cleaning of the interior petition glass or just the interior windows on the perimeter?	Only accessible panes on the interior or ex
60		Does this job require only citizens to clean or are we able to use workers with work authorization and permanent residence?	Valid work authorization and permaner
61		Where are we supposed to place our pricing? There are no spots for roofing specifically and we are only	Offerors question is confusing. This RFP is s management services for the Wilson Buildi provide pricing on all CLINs on the price scl
62		Do you have any plans regarding the square footage of the roof in question?	No
63		How do we gain access to the roof? Whom do we contact?	Access is provided by engineering.
64		Is there an opportunity to visit the location?	Site visit was scheduled on January 19, 202 contract the COTR, Jean-Francis Varre at je Facility.
65		From paragraph C.5.14.1. 3, do we respond and begin the necessary work within two hours after receipt for service call?	Yes. The Contractor is expected to respond
66		Can you provide an estimate on the number of service calls received monthly?	Average 106 service calls a month
67		For bed bugs removal, paragraph C.5.14.1.2.2.1, will this be a separate price based on a requested service? Also, how many Bed Bug removal requests were received in the previous year?	Price based on assessment. The rough aver
68		About the cooling tower water treatment on the mechanical equipment list (3) Pulsation Chemical Feed pumps are listed and (1) Lakewood Microprocessor, are there any other water treatment equipment?	No
69		Are chemical feed tanks on site?	Yes
70		Are chemical shot feeders on site for close loop system?	Yes
71		How are all 3-5 floor windows approached for cleaning and repairs.	Contractors repel from roof.

DCC	RESPO	NICE
	RESPU	NSE
200		

sted on December of 2022.

hydrostatic test was on October of 2022.

the contractor.

exterior are to be cleaned.

ent residence is sufficient.

s seeking one (1) Contractor to provide comprehensive property Iding, which includes all services described in Section C. Offerors must schedule; otherwise, offerors will be deemed non-responsive.

2022 at 1:00 p.m. Another site visit is not available; however, please : jean-francis.varre@dc.gov, to view any blueprint drawings at the

nd immediately to all calls at the Wilson Building.

verage has been 2 a year in the last 5 years.

<u>NO.</u>	SECTION NO./PAGE NO	QUESTIONS	
72		Will the bird netting be removed to allow access to the 3-5th floor windows?	No, there will be no special removal just to
73		When was the last time those windows were cleaned or serviced?	November 2022.
74		Does the building have roof anchors? If so, can you send the most recent anchor inspection/load test?	No
75		Please send a detailed scope of work for the window washing.	Offerors are expected to review the requir
76		What is the residential space? (beds, sofas, etc., especially as related to bed bugs.)	There are no residential spaces. Living roor
77		Preventing pest entry, see Section C.5.14.1.1 f – "maintaining structures and grounds sealing cracks and eliminating moisture intrusion and accumulation, and add physical barriers to prevent pest entry and movement." Can you please explain more specifically?	All cracks and perforations are sealed acco materials (cement/brick/drywall/etc.)
78	C.5.18.2 .1	We will comply with all licensing requirements, however, with regard to Facility operations, maintenance and repair of systems and equipment. Can please explain more specifically?	This is a comprehensive contract for which required.
79	C.5.4.1 Electrical Distribution Systems	When was the last Switchgear Maintenance Performed?	2013
80	C.5.4.1 Electrical Distribution Systems	When was the last Thermographic Scanning of Electrical Equipment (IR Scan) performed?	2019
81	C.5.4.1.2 Uninterruptible Power System (UPS)	Is the contractor responsible for the UPS?	No, UPS is tenant equipment.
82	C.5.5 Mechanical Services	C.5.5.2.4 Pump Alignment- When was the last pump alignment performed?	The last pump alignment was performed ir
83	C.5.5 Mechanical Services	C.5.5.3.3 Maintenance and Cleaning of Terminal Boxes-What are the size and type of filters are used for the VAV boxes?	There are a total of 176 filters sized 10x24
84	C.5.5 Mechanical Services	Chillers-When was the last Eddy Current test performed on the chillers?	2011
85	C.5.13.10 Irrigation Systems	Is the irrigation system in full operation?	Yes
86	C.5.9 Fire Protection Systems, (a) Fire Life Safety Equipment	Who is the Fire Alarm and sprinkler system mfg.?	Simplex 4100 addressable fire alarm syster
87	C.5.9 Fire Protection Systems, (a) Fire Life Safety Equipment	What are the fire alarm device counts, including the number of control panels, booster panels, enunciators, ceiling smoke detectors, above ceiling smoke detectors, below-floor smoke detectors, manual pull stations, heat detectors, duct detectors, flow switches, pressure switches, fire and smoke dampers, tamper switches, horn-strobes, manual pull stations, bells, and strobes?	Offerors can request to see blueprint draw jean-francis.varre@dc.gov.
88	C.5.9 Fire Protection Systems, (a) Fire Life Safety Equipment	I (an you provide a fire sprinkler riser diagram?	Offerors can request to see blueprint draw jean-francis.varre@dc.gov.
89	C.5.9 Fire Protection Systems, (a) Fire Life Safety Equipment	Is the building fully sprinklered? If not, what % are sprinklered?	Yes
90	C.5.9 Fire Protection Systems, (a) Fire Life Safety Equipment	What is the make, model, and size (gpm's)of the Fire Pump?	ITT a-c Centrifugal Fire pump 750 gpm slit

DGS RESPONSE
to clean.
uirements under Section C.5.
bom furniture such as couches are located at every reception.
cording to industry standards and architectural design of wall/partition
ch all base building equipment operation, maintenance and repair is
ch an base building equipment operation, maintenance and repair is
l in 2012
24x1.
em with a 750gpm fire pump. This was shown during the site visit.
awings at the Facility by contacting the COTR, Jean-Francis Varre at
awings at the Facility by contacting the COTR, Jean-Francis Varre at

<u>NO.</u>	SECTION NO./PAGE NO	QUESTIONS	
91	C.5.9 Fire Protection Systems, (a) Fire Life Safety Equipment	Is there a dry pipe sprinkler systems or pre-action sprinkler systems? If so, how many of each? If pre-action, how many devices are associated with each system, such as the number of ceiling smoke detectors, below-floor smoke detectors, manual pull stations, horn-strobes, bells, and strobes?	1 pre-action in the OCTO suite. Offerors car COTR, Jean-Francis Varre at jean-francis.var
92	C.5.9 Fire Protection Systems, (a) Fire Life Safety Equipment	What areas have detectors that are above 12' that would require a lift or a ladder to reach? How many detectors above 12' are there in each building?	All the ceilings are above 20Feet and requir
93	C.5.9 Fire Protection Systems, (a) Fire Life Safety Equipment	How many fire extinguishers in the building, please list the total quantity, size and type?	33- 5lbs ABC ,35-10lbs ABC,37-20lbs ABC, 3
94	C.5.9 Fire Protection Systems, (a) Fire Life Safety Equipment	How many elevators in the building have recall which would require testing?	7 with the addition of an ADA lift.
95	C.5.9 Fire Protection Systems, (a) Fire Life Safety Equipment	Are there any kitchen fire systems to inspect? If so, what is the make, model, and size of each system (for example Ansul R102- 3 gallon)?	There are no kitchens at the Wilson Buildin
96	C.5.9 Fire Protection Systems, (a) Fire Life Safety Equipment	What type of scheduling coordination will be required to test the fire alarm, sprinkler, suppression systems or portable fire extinguishers?	Annual testing shall be coordinated throug
97	C.5.12 Cleaning Services - C.5.12.1.4g Collect and remove facility trash and recyclables Trash and Recyclables Collection Process.	Has the district provided employee desktop trash and recycling containers as well as Multi-port Centralized Containers located within office suites?	They have, but are not commonly used.
98	C.5.12 Cleaning Services - C.5.12.1.4g Collect and remove facility trash and recyclables Trash and Recyclables Collection Process.	Since there is not a dumpster, and on the walk-through, it was states that the site uses totes. How many, and what size containers are used for trash removal?	There are 12 totes/95 gallons each.
99	C.5.12 Cleaning Services - C.5.12.1.4g Collect and remove facility trash and recyclables Trash and Recyclables Collection Process.	What size and how many, and containers are used for Recycling?	3 - 95 gallon totes
100	C.5.12 Cleaning Services - C.5.12.1.4g Collect and remove facility trash and recyclables Trash and Recyclables Collection Process.	What is the trash pick up schedule?	Five (5) days a week; Monday through Frid
101	C.5.12 Cleaning Services - C.5.12.1.4g Collect and remove facility trash and recyclables Trash and Recyclables Collection Process.	What is the recycle pick up schedule?	Five (5) days a week; Monday through Frid
102	C.5.8. Energy Management Control System Services- C.5.8.1.5 requires software updates	Is the contractor responsible for software updates?	Yes, for Facilities office and base building IT
103	C.5.8. Energy Management Control System Services- C.5.8.1.5 requires software updates	When was the last software update?	2018
104	C.5.12. Window Cleaning	Are there any issues that the contractor should be aware of with the ability to perform window cleaning on the 3rd and 4th floor, façade due to the bird netting?	Facades with bird netting are not cleaned u

	CC.	DF	CD	$\mathbf{n}$	NSE
		кг	SР	UI	NSF.
-	99		<u> </u>	<u> </u>	

can request to see blueprint drawings at the Facility by contacting the	
varre@dc.gov.	

uire extension poles.

, 38-5lbs co2, 39-10lbs c02

ling.

ugh COTR.

iday.

iday.

g IT.

d until further notice.

Implete and model is a addet to the proceed of whow dealing?         Implete and model is a addet to the proceed of whow dealing?           106         Are there any union contracts associated with this contract? If so, please provide a copy of the CBA.         Ye, there is a CBA for costoolial and just be able to able the inscription of the formation o	<u>NO.</u>	SECTION NO./PAGE NO	QUESTIONS	
100         and there any union contracts associated with the contract / 150, piece provide a copy of the CAL.         Take been inserted in the RP document           107         What is the current onsite stalling (later categories and count for each)         Offerors can submit a Freedom of Inf.           108         is there an admin assistant on site?         Yes           109         is there offee space, if so what is the site?         There are 2 spaces for employees to p           110         is there offee space, if so what is the site?         Yes           111         What is the current period of performance for the incumbent contractor?         Offerors can submit a Freedom of Inf.           112         What is the current total contract pice for this contract?         Offerors can submit a Freedom of Inf.           113         What is the current total contract pice for this contract?         Offerors can submit a Freedom of Inf.           114         C.S.2.1.8; Page 40         There is no Section C.S.2.1.3. Please clarify if there is missing information or if sections are minimumberd. If the is no section C.S.2.1.7 between C.S.2.1.6 and C.S.2.1.8. Please clarify if there is missing information or if sections or file clarify a more is no section are minimumberd. If the is no section C.S.3.1.1 please clarify if there is missing information or if sections are minimumbered. If the is no section C.S.3.1.2 between C.S.3.1.1 please clarify if there is missing information or if sections are minimumbered. If the is no section C.S.3.1.2 between C.S.3.1.1 please clarify if there is missing information or if section are mi	105	C.5.12. Window Cleaning		Repelling from roof. No, cannot be remove
Image: Constraint of the second sec	106		Are there any union contracts associated with this contract? If so, please provide a copy of the CBA.	Yes, there is a CBA for custodial and janiton has been inserted in the RFP document.
Image: 109         Image: 109 <thimage: 109<="" th="">         Image: 109         Image: 1</thimage:>	107		What is the current onsite staffing (labor categories and count for each)	Offerors can submit a Freedom of Informa
Image: constraint of the second of	108		Is there an admin assistant on site?	Yes
110       In the end office space, if so what is the safe?       drawings at the facility by contacting:         111       What is the current period of performance for the incumbent contractor?       Offerors can submit a Freedom of Infe         112       What is the current total contract price for this contract?       Offerors can submit a Freedom of Infe         113       What is the current contract number for incumbent contract?       Offerors can submit a Freedom of Infe         114       C.5.2.1.8; Page 40       There is no Section C.5.2.1.8.1. Please darify if there is missing information or if sections are misnumbered. If the is derical error was fixed on revised inter, should we reference corrected numbers or use the existing?       This derical error was fixed on revised sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?         116       C.5.2.1.8; Page 41       There is no Section C.5.2.1.7 between C.5.3.1.3 Please darify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?       This derical error was fixed on revised section are misnumbered. If the latter, should we reference corrected numbers or use the existing?       This derical error was fixed on revised fatter, should we reference corrected numbers or use the existing?         117       C.5.4.1.3.2; Page 67       There is no Section C.5.4.1.3.1. Please darify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?       This derical error was fixed on revised fatter, should we referenc	109		Is there free parking for employees on site?	There are 2 spaces for employees to park o
112What is the current total contract price for this contract?Offerors can submit a Freedom of Info113What is the current contract number for incumbent contract?Offerors can submit a Freedom of Info114C.S.2.1.8, Page 40There is no Section C.S.2.1.8.1. Please darify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised115C.S.2.1.8.2; Page 41There is no Section C.S.2.1.7 between C.S.2.1.6 and C.S.2.1.8. Please clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised116C.S.3.1.3; Page 59There is no Section C.S.3.1.2 between C.S.3.1.1. Please clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised117C.S.4.1.3.2; Page 67There is no Section C.S.4.3.1. Please clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised118C.S.4.2.3.2; Page 69There is no Section C.S.4.3 and C.S.4.2 and C.S.4.4 Hease clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised118C.S.4.2.3.2; Page 69There is no Section C.S.4.2 and C.S.4.4 Hease clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected nu	110		Is there office space, if so what is the size?	Yes. Offerors can refer to blueprint drawin drawings at the Facility by contacting the C
Image: Contract of the second seco	111		What is the current period of performance for the incumbent contractor?	Offerors can submit a Freedom of Informa
Image: Constraint of the section C.S.2.1.8.1. Please clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised115C.S.2.1.8.2; Page 41There is no Section C.S.2.1.7 between C.S.2.1.6 and C.S.2.1.8. Please clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised116C.S.3.1.3; Page 59There is no Section C.S.3.1.2 between C.S.3.1.1 and C.S.3.1.3. Please clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?Section C.S.3.1.2 is included in the RF117C.S.4.1.3.2; Page 67There is no Section C.S.4.1.3.1. Please clarify if there is missing information or if sections are misnumbered. If the 	112		What is the current total contract price for this contract?	Offerors can submit a Freedom of Informa
114C.S.P.1.8; Page 40latter, should we reference corrected numbers or use the existing?Inits clerical error was fixed on revised115C.S.2.1.8.2; Page 41There is no Section C.S.2.1.7 between C.S.2.1.6 and C.S.2.1.8. Please clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised116C.S.3.1.3; Page 59There is no Section C.S.3.1.2 between C.S.3.1.1 and C.S.3.1.3. Please clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised117C.S.4.1.3.2; Page 67There is no Section C.S.4.1.3.1. Please clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised118C.S.4.2.3.2; Page 69There is no Section C.S.4.2.3.1. Please clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised118C.S.4.4; Page 72There is no Section C.S.4.2 and C.S.4.4. Please clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised120C.S.5.1.2.3; Page 73There is no Section C.S.6.1 and C.S.6.3. Please clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised1	113		What is the current contract number for incumbent contract?	Offerors can submit a Freedom of Informa
115C.S.2.1.8.2; Page 41sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised116C.S.3.1.3; Page 59There is no Section C.S.3.1.2 between C.S.3.1.1 and C.S.3.1.3. Please clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?Section C.S.3.1.2 is included in the RF117C.S.4.1.3.2; Page 67There is no Section C.S.4.1.3.1. Please clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised118C.S.4.2.3.2; Page 69There is no Section C.S.4.2.3.1. Please clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised119C.S.4.4; Page 72There is no Section C.S.4.2 and C.S.4.2 and C.S.4.4. Please clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised120C.S.5.1.2.3; Page 73There is no Section C.S.6.1 and C.S.6.3. Please clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised121C.S.6.3; Page 80There is no Section C.S.6.1 and C.S.6.3. Please clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised <td>114</td> <td>C.5.2.1.8; Page 40</td> <td></td> <td>This clerical error was fixed on revised RFP</td>	114	C.5.2.1.8; Page 40		This clerical error was fixed on revised RFP
116C.S.3.1.3; Page 59sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?Section C.S.3.1.2 is included in the RF117C.S.4.1.3.2; Page 67There is no Section C.S.4.1.3.1. Please clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised118C.S.4.2.3.2; Page 69There is no Section C.S.4.2.3.1. Please clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised119C.S.4.4; Page 72There is no Section C.S.4.2 and C.S.4.2 and C.S.4.4. Please clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised120C.S.5.1.2.3; Page 73There is no Section C.S.6.1 and C.S.6.3. Please clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised121C.S.6.3; Page 80There is no Section C.S.6.1 and C.S.6.3. Please clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised121C.S.6.3; Page 80There is no Section C.S.6.2 between C.S.6.1 and C.S.6.3. Please clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised	115	C.5.2.1.8.2; Page 41	· -	This clerical error was fixed on revised RFP
117C.S.4.1.3.2; Page 67latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised118C.S.4.2.3.2; Page 69There is no Section C.S.4.2.3.1. Please clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised119C.S.4.4; Page 72There is no Section C.S.4.2 and C.S.4.4. Please clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised120C.S.5.1.2.3; Page 73There is no Section C.S.5.1.2.2. Please clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised121C.S.6.3; Page 80There is no Section C.S.6.1 and C.S.6.3. Please clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised121C.S.6.3; Page 80There is no Section C.S.6.1 and C.S.6.3. Please clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised122C.S.6.3.1.2; Page 81There is no Section S.6.3.1.1. Please clarify if there is missing information or if sections are misnumbered. If the sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised123C.S.6.3.1.2; Page 8	116	C.5.3.1.3; Page 59		Section C.5.3.1.2 is included in the RFP.
118C.5.4.2.3.2; Page 69latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised119C.5.4.4; Page 72There is no Section C.5.4.3 between C.5.4.2 and C.5.4.4. Please clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised120C.5.5.1.2.3; Page 73There is no Section C.5.5.1.2.2. Please clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised121C.5.6.3; Page 80There is no Section C.5.6.2 between C.5.6.1 and C.5.6.3. Please clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised121C.5.6.3; Page 80There is no Section 5.6.3.1.1. Please clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised122C.5.6.3.1.2: Page 81There is no Section 5.6.3.1.1. Please clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised	117	C.5.4.1.3.2; Page 67		This clerical error was fixed on revised RFP
119C.S.4.4; Page 72sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised120C.S.5.1.2.3; Page 73There is no Section C.S.5.1.2.2. Please clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised121C.S.6.3; Page 80There is no Section C.S.6.2 between C.S.6.1 and C.S.6.3. Please clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised122C.S.6.3; Page 81There is no Section S.6.3.1.1. Please clarify if there is missing information or if sections are misnumbered. If the are sections are misnumbered. If the revised on revisedThis clerical error was fixed on revised	118	C.5.4.2.3.2; Page 69		This clerical error was fixed on revised RFP
120C.5.5.1.2.3; Page 73latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised121C.5.6.3; Page 80There is no Section C.5.6.2 between C.5.6.1 and C.5.6.3. Please clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?This clerical error was fixed on revised122C.5.6.3; Page 81There is no Section 5.6.3.1.1. Please clarify if there is missing information or if sections are misnumbered. If the are misnumbered. If there is missing information or if sections are misnumbered. If the there is no Section 5.6.3.1.1. Please clarify if there is missing information or if sections are misnumbered. If the This clerical error was fixed on revised	119	C.5.4.4; Page 72		This clerical error was fixed on revised RFP
121       C.5.6.3; Page 80       sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?       This clerical error was fixed on revised         122       C.5.6.3.1.2; Page 81       There is no Section 5.6.3.1.1. Please clarify if there is missing information or if sections are misnumbered. If the       This clerical error was fixed on revised	120	C.5.5.1.2.3; Page 73	· · ·	This clerical error was fixed on revised RFP
L 177 L C 5 6 3 1 7 Page 81 L L L L L L L L L L L L L L L L L L	121	C.5.6.3; Page 80		This clerical error was fixed on revised RFP
	122	C.5.6.3.1.2; Page 81		This clerical error was fixed on revised RFP

### DGS RESPONSE

ved or replaced at this time.

torial services. See Addendum No. 02, Item No. 1. In addition, the CBA

nation Act (FOIA) request by submitting an email to foia.dgs@dc.gov.

c on-site.

ings located at the Facility. Offerors can request to see blueprint COTR, Jean-Francis Varre at jean-francis.varre@dc.gov.

nation Act (FOIA) request by submitting an email to foia.dgs@dc.gov.

nation Act (FOIA) request by submitting an email to foia.dgs@dc.gov.

nation Act (FOIA) request by submitting an email to foia.dgs@dc.gov.

P (16-Feb-2023); Section C.5.2.1.8.1 is marked as RESERVED.

P (16-Feb-2023); Section C.5.2.1.7 is marked as RESERVED.

P (16-Feb-2023); Section C.5.4.1.3.1 is marked as RESERVED.

P (16-Feb-2023); Section C.5.4.2.3.1 is marked as RESERVED.

FP (16-Feb-2023); Section C.5.4.3 is marked as RESERVED.

P (16-Feb-2023); Section C.5.5.1.2.2 is marked as RESERVED.

P (16-Feb-2023); Section C.5.6.2 is Water Treatment Program.

P (16-Feb-2023).

NO.	SECTION NO./PAGE NO	QUESTIONS	
123	C.5.6.3.5.1; Page 81	The section number does not align with the previous number, which is C.5.6.5. Please clarify if Section 5.6.3.5.1 belongs in Section C.5.6.3 or if it belongs here and is misnumbered. If the latter, should we reference corrected numbers or use the existing?	This clerical error was fixed on revised RFP
124	C.5.7.1.2.3; Page 84 and 85	There are two sections numbered C.5.7.1.2.3. Please clarify if the second instance should be C.5.7.1.2.4 and subsequent sections renumbered accordingly. How should the contractor address in the proposal to distinguish between the two sections?	This clerical error was fixed on revised RFP
125	C.5.7.1.5.2; Page 87	There is no Section C.5.7.1.5.1. Please clarify if there is missing information or if sections are misnumbered. If the latter, should we reference corrected numbers or use the existing?	This clerical error was fixed on revised RFP
126	L.2.5.1; Page 215	Will the Government allow font size to be reduced in tables and figures (for example 10 point font)?	No, please use the font size indicated in the
127	M.3.1.1c; Page 224	Please clarify if the Past Performance Evaluation (PPE) Forms should be sent directly to DGS by the client or should the PPE Forms be included as part of the Offeror proposal submission.	The Past Performance Evaluation (PPE) form in the Offeror's proposal. Please do not have they do, it will not be accepted.
128	Н.9.1.3	If a company is DSLBD certified, do the subcontracting goals still apply?	This RFP is for CBE's certified by DC DSLBD. however, should the company choose to su the subcontracting effort with CBEs.
129		What is the annual contract value?	Offerors can submit a Freedom of Informat
130		Who is the incumbent?	Offerors can submit a Freedom of Informat
131		Can a company subcontract more than 35% of the entire contract?	That is the decision of the company; howev
132		How many subcontractors would be recommended to execute this RFP as a prime subcontractor?	This is a not a question the District can answ
133		Please provide a list of all current subcontractors.	Offerors can submit a Freedom of Informat
134		The current contactor at the time of last award had only one past performance and his subcontractor had the remainder (2), and things seems to have operated fairly smoothly. In the interest of supporting CBEs, would you consider revising the requirement so that the past performance of the subcontractor is acceptable in order to allow more capable and competent Prime contractors an opportunity to submit an acceptable proposal?	No. Offerors cannot substitute past perforr offeror provides three (3) previous or curre include the past performance evaluation (P
135		Can the experience of a company executive/s be used?	Yes
136		Due to the nature of this building what are the mandatory required hours of operation?	Monday through Friday, from 6:00 a.m. to
137		Is there a CBA associated with any portion of this contract?	Yes, custodial and janitorial services. See A
138		Can you provide a history of service call as well as reimbursable repairs?	Varies from year to year. There were 1260 threshold in 2022.
139		What proprietary systems should be considered in the performance of this contract?	BAS, York chillers and elevators.

### DGS RESPONSE

P (16-Feb-2023).

P (16-Feb-2023).

P (16-Feb-2023).

the RFP.

orms, completed and signed by the offeror's clients, shall be included nave clients send the PPE forms directly to the Contract Specialist; if

D. If a company is a CBE, the company is not required to subcontract; subcontract, then the company must subcontract at minimum 35% of

nation Act (FOIA) request by submitting an email to foia.dgs@dc.gov.

nation Act (FOIA) request by submitting an email to foia.dgs@dc.gov.

vever, please refer to subcontracting requirements in Section H.

nswer.

nation Act (FOIA) request by submitting an email to foia.dgs@dc.gov.

ormance of Prime Contractor to subcontractors. For example, if the rrent contracts as part of their past performance, they are also to (PPE) forms for each of those contracts.

to 6:00 p.m.

Addendum No. 02, Item No. 1.

io service calls in 2022; 18 numbers of repairs over the \$1500

<u>NO.</u>	SECTION NO./PAGE NO	QUESTIONS	
140		What coordination effort is required when performing emergency work during regular work hours?	Contractor shall coordinate with the COTR
141		I an you provide the list for the current statting?	No, DGS cannot provide a list for the currer a Freedom of Information Act (FOIA) reque

TR prior to performing emergency work during regular hours.

rent staffing employed by the current contractor. Offerors can submit uest by submitting an email to foia.dgs@dc.gov.