

Fire Extinguisher Inspection

National Fire Protection, LLC

207A Perry Parkway
Gaithersburg, MD 20877

Tel: 301-340-6500 Fax: 301-309-1294
24 Hour Emergency Service: 800-741-5137
www.natlfire.com



Inspector :

Paul Olson

Date:

12/14/2023

Inspection at Location

Cardozo High School

1300 Clifton Road NW

Washington, DC 20009

For Customer:

Cardozo High School

1300 Clifton Road NW

Washington, DC 20009

Work performed in accordance with
NFPA 10, 2010 Edition

Fire Extinguisher Inspection

Service Codes:	R = Repairs H = 12 Year Hydro	RC = Recharge I = 6 Year Internal	C = Compliance M = Maintenance	NC = Non Compliance X = Condemned
----------------	----------------------------------	--------------------------------------	-----------------------------------	--------------------------------------

	Size/Type	MFRS. Date	Serial #	Code	Location	Pass/Fail Next Service Date
1	5/ABC	2017	C84042248	C	Inside C101	Pass
2	10/ABC	2017	L89994617	C	Inside C101E (EMR)	Pass
3	5/ABC	2017	C92515807	C	Inside 3406	Pass
4	5/ABC	2017	C84042267	C	Inside 3501	Pass
5	10/CO2	2019	F65983061	C	Inside 3511 (Electric Room)	Pass
6	10/ABC	2017	C93841444	C	Inside 3502	Pass
7	5/ABC	2015	A37736414	I	Inside 3504	Replaced
8	10/CO2	2019	F56496399	C	Inside 3211 (Electric Room)	Pass
9	5/ABC	2017	C84042246	C	Inside 2204	Pass
10	10/CO2	2019	F56496420	C	Inside 2211 (Electric Room)	Pass
11	10/ABC	2019	F76151883	C	Inside 2501	Pass
12	10/CO2	2019	F65983045	C	Inside 2611 (Electric Room)	Pass
13	5/ABC	2017	C84042240	C	Inside 2602	Pass
14	5/ABC	2017	C92515256	C	Inside 2604	Pass
15	5/ABC	2017	C84042256	C	Inside 2104	Pass
16	10/ABC	2018	A40323189	C	Inside 1611	Pass
17	5/ABC	2017	C84042238	RC	Inside 1603	Pass
18	10/CO2	2019	F65983059	C	Inside 1603 (Electric Room)	Pass
19	5/ABC	2017	C84042237	C	Inside 1503	Pass
20	5/ABC	2017	C84042241	C	Inside 1501	Pass
21	5/ABC	2017	C92516866	C	Inside 1401	Pass
22	10/ABC	2019	F76151884	C	Inside 1304	Pass
23	5/ABC	2017	C84042236	C	Inside 1301	Pass
24	10/CO2	2019	F65983048	C	Inside 1211 (Electric Room)	Pass
25	5/ABC	2017	C84042268	C	Inside C205	Pass
26	10/CO2	2019	F65983048	C	Inside C207 (Electric Room)	Pass
27	5/ABC	2017	C84042256	C	Inside C302	Pass
28	6/K	2019	F65996168	C	Inside C118 (Kitchen)	Pass
29	10/CO2	2019	F56496404	C	Inside C502 (Electric Room)	Pass
30	5/ABC	2017	C84042249	RC	Inside C504	Replaced
31	10/CO2	2019	F56496406	C	Inside C613 (Electric Room)	Pass
32	5/ABC	2017	C84042239	C	Inside LT33 (EMR)	Pass
33	5/ABC	2017	C84042258	C	Inside T302	Pass
34	5/ABC	2017	C84042247	C	Inside T301	Pass
35	10/ABC	2017	B80239075	C	Inside T209	Pass
36	10/ABC	2017	C89237294	C	Inside T201	Pass
37	5/ABC	2017	C84042269	RC	Spare	Replaced
38	6/Water	2019	F75724398	C	Inside Filtration Room	Pass
39	10/CO2	2019	F56496422		Spare	Pass
40	10/CO2	2019	F56496421		Spare	Pass

Fire Extinguisher Inspection

Service Codes:	R = Repairs	RC = Recharge	C = Compliance	NC = Non Compliance
	H = 12 Year Hydro	I = 6 Year Internal	M = Maintenance	X = Condemned

	Size/Type	MFRS. Date	Serial #	Code	Location	Pass/Fail Next Service Date
41	10/ABC	2019	F76151885		Spare	Pass
42	10/ABC	2019	F76151919		Spare	Pass
43	10/ABC	2019	F76151886		Spare	Pass
44	10/ABC	2019	F78151884	C	Inside Staff Workroom 1304	Pass
45	5/ABC	2017	C84042249	RC	Inside Transtem Coord C504	Replaced
46	5/ABC	2017	C84042243	C	Inside Room C609	Pass
47	5/ABC	2017	C92515089	C	Inside Room C304	Pass
48	10/ABC	2017	C89292389	C	Inside Room T204	Pass
49	5/ABC	2017	C84042257	RC	Inside T105	Replaced
50	10/ABC	2019	F76151920	C	Inside Staff Workroom T108	Pass
51	10/ABC	2017	C84042270	C	Inside Daycare	Pass
52	10/CO2	2019	F65983062	C	Inside Mechanical Room LT02	Pass
53						
54						
55						
56						
57						
58						
59						
60						
61						
62						
63						
64						
65						
66						
67						
68						
69						
70						
71						
72						
73						
74						
75						
76						
77						
78						
79						
80						

Fire Extinguisher Inspection

Notes

Extinguishers need to be mounted insdie C502, C205, 1603. Recharged in room 3504, T105, 1603.
Extinguishers should be mounted by door.

Owner and/or representative acknowledges NFP inspected fire extinguished visually and did not manually operate the extinguishers. The inspection is limited to the moment the NFP technisian inspected the extinguisher. NFP is not responsible for any changes to the extinguisher after the inspection.

12/14/23

Paul Olson

12/14/23

Customer - Print: _____

Technician: _____

Paul Olson