



Guy Mason RC Lead in Water Test Results

FY25 Filter Test

Less than 5ppb - Devices requiring no remediation

| Record ID | Filter Installed Date | Filter Expiration Date | Floor | Device Type | Device Location | Water Filter's Name | Date Analyzed | 1st Draw - Sample ID | FT Final Result - 1st Draw (ppb) | 2nd Draw - Sample ID | FT Final Result - 2nd Draw (ppb) |
|------------|-----------------------|------------------------|----------|----------------|--|---------------------|---------------|---------------------------|----------------------------------|---------------------------|----------------------------------|
| WS- 012541 | 3/12/2024 | 3/12/2025 | Basement | Cooler | In hallway across from boiler room High Left | WF-03122024-012541 | 2/19/2025 | FT-FY25-01082025-012541-A | <2 | FT-FY25-01082025-012541-B | <2 |
| WS- 012542 | 3/12/2024 | 3/12/2025 | Basement | Cooler | In hallway across from boiler room Low Right | WF-03122024-012542 | 2/19/2025 | FT-FY25-01082025-012542-A | <2 | FT-FY25-01082025-012542-B | <2 |
| WS- 012548 | 11/20/2024 | 11/20/2025 | 2 | Food Prep Sink | In activity room 2A | WF-11202024-012548 | 2/19/2025 | FT-FY25-01082025-012548-A | <2 | FT-FY25-01082025-012548-B | <2 |
| WS- 012549 | 3/12/2024 | 3/12/2025 | 2 | Cooler | In hallway across from room 2A High Left | WF-03122024-012549 | 2/19/2025 | FT-FY25-01082025-012549-A | <2 | FT-FY25-01082025-012549-B | <2 |
| WS- 012550 | 3/12/2024 | 3/12/2025 | 2 | Cooler | In hallway across from room 2A Low Right | WF-03122024-012550 | 2/19/2025 | FT-FY25-01082025-012550-A | <2 | FT-FY25-01082025-012550-B | <2 |

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.