



HAMILTON REC LEAD WATER TEST RESULTS

May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1 HAMILTON RECREATION CENTER	5/25/2016	WS- 006388	Fountain	Ground Floor	On east said of the building	High	WT-042916-6405- A	< 1	WT-042916-6405- B	< 1			
2 HAMILTON RECREATION CENTER	5/25/2016	WS- 006389	Fountain	Ground Floor	On east said of the building	Low	WT-042916-6406- A	< 1	WT-042916-6406- B	< 1			
3 HAMILTON RECREATION CENTER	5/25/2016	WS- 006390	Fountain	Ground Floor	On west side of building	Low	WT-042916-6407- A	< 1	WT-042916-6407- B	< 1			
4 HAMILTON RECREATION CENTER	5/25/2016	WS- 006391	Fountain	Ground Floor	On west side of the building	Right High	WT-042916-6408- A	< 1	WT-042916-6408- B	< 1			
5 HAMILTON RECREATION CENTER	5/25/2016	WS- 006392	Fountain	Ground Floor	In building on south wall adjacent to men's	Left High	WT-042916-6409- A	< 1	WT-042916-6409- B	< 1			
6 HAMILTON RECREATION CENTER	5/25/2016	WS- 006393	Fountain	Ground Floor	In building on south wall adjacent to men's	Right Low	WT-042916-6410- A	< 1	WT-042916-6410- B	< 1			
7 HAMILTON RECREATION CENTER	5/25/2016	WS- 006394	Utility	Ground Floor	In janitor closet on west wall (water source)		WT-042916-6411- A	39.3	WT-042916-6411- B	1.8	Non-drinking water source - Not accessible to children		

Footnotes:

- A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.
- B - Second draw sample is collected after a 60 second flush at that device after the first draw.