



Hearst RC Lead in Water Test Results

FY25 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 004850	2/28/2024	2/28/2025	1	Break Room	In lifeguard room 101	WF-02282024-004850	2/17/2025	FT-FY25-01082025-004850-A	<2	FT-FY25-01082025-004850-B	<2
WS- 011580	2/28/2024	2/28/2025	1	Cooler	In hallway adjacent to stairwell	WF-02282024-011580	2/17/2025	FT-FY25-01082025-011580-A	<2	FT-FY25-01082025-011580-B	<2

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.