



# Hillcrest RC Lead in Water Test Results

## FY26 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 005628	2/26/2026	2/26/2027	1	Bottle Filler	In hallway adjacent to multimedia 105	WF-02262026-005628	4/7/2026	FT-FY26-03262026-005628-A	<2	FT-FY26-03262026-005628-B	<2
WS- 005629	2/26/2026	2/26/2027	1	Cooler	In hallway adjacent to multimedia 105 High Left	WF-02262026-005629	4/7/2026	FT-FY26-03262026-005629-A	<2	FT-FY26-03262026-005629-B	<2
WS- 005639	2/26/2026	2/26/2027	1	Cooler	In hallway adjacent to multimedia 105 Low Right	WF-02262026-005639	4/7/2026	FT-FY26-03262026-005639-A	<2	FT-FY26-03262026-005639-B	<2
WS- 005640	2/26/2026	2/26/2027	1	Cooler	In hallway across from gym 100	WF-02262026-005640	4/7/2026	FT-FY26-03262026-005640-A	<2	FT-FY26-03262026-005640-B	<2
WS- 005641	11/25/2025	11/25/2026	1	Food Prep Sink	In pantry room 102 in kitchen	WF-11252025-005641	4/7/2026	FT-FY26-03262026-005641-A	<2	FT-FY26-03262026-005641-B	<2

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.