



Kelly Miller MS Lead in Water Test Results

FY26 Filter Test

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS- 009702	2/14/2025	2/14/2026	1	Cooler	In cafeteria	WF-02142025-009702	1/16/2026	FT-FY26-01122026-009702-A	<2	FT-FY26-01122026-009702-B	<2	
WS- 009708	2/14/2025	2/14/2026	1	Bottle Filler	In cafeteria	WF-02142025-009708	1/16/2026	FT-FY26-01122026-009708-A	<2	FT-FY26-01122026-009708-B	<2	
WS- 009711	2/14/2025	2/14/2026	1	Cooler	In hallway adjacent to room A118	High Left	WF-02142025-009711	1/16/2026	FT-FY26-01122026-009711-A	<2	FT-FY26-01122026-009711-B	<2
WS- 009712	2/14/2025	2/14/2026	1	Cooler	In hallway adjacent to room A118	Low Right	WF-02142025-009712	1/16/2026	FT-FY26-01122026-009712-A	<2	FT-FY26-01122026-009712-B	<2
WS- 009734	2/14/2025	2/14/2026	1	Cooler	In hallway across from room C123	High Right	WF-02142025-009734	1/16/2026	FT-FY26-01122026-009734-A	<2	FT-FY26-01122026-009734-B	<2
WS- 009735	2/14/2025	2/14/2026	2	Cooler	In hallway adjacent to room A218	High Left	WF-02142025-009735	1/16/2026	FT-FY26-01122026-009735-A	<2	FT-FY26-01122026-009735-B	<2
WS- 009736	2/14/2025	2/14/2026	2	Cooler	In hallway adjacent to room A218	Low Right	WF-02142025-009736	1/16/2026	FT-FY26-01122026-009736-A	<2	FT-FY26-01122026-009736-B	<2
WS- 009737	2/14/2025	2/14/2026	2	Cooler	In hallway adjacent to elevator	High Left	WF-02142025-009737	1/16/2026	FT-FY26-01122026-009737-A	<2	FT-FY26-01122026-009737-B	<2
WS- 009738	2/14/2025	2/14/2026	2	Cooler	In hallway adjacent to elevator	Low Right	WF-02142025-009738	1/16/2026	FT-FY26-01122026-009738-A	<2	FT-FY26-01122026-009738-B	<2
WS- 009739	2/14/2025	2/14/2026	2	Break Room	In staff lounge kitchen		WF-02142025-009739	1/16/2026	FT-FY26-01122026-009739-A	<2	FT-FY26-01122026-009739-B	<2
WS- 009758	2/14/2025	2/14/2026	3	Cooler	In hallway adjacent to boys' restroom	High Right	WF-02142025-009758	1/16/2026	FT-FY26-01122026-009758-A	<2	FT-FY26-01122026-009758-B	<2
WS- 009759	2/14/2025	2/14/2026	3	Cooler	In hallway adjacent to boys' restroom	Low Left	WF-02142025-009759	1/16/2026	FT-FY26-01122026-009759-A	<2	FT-FY26-01122026-009759-B	<2
WS- 009779	2/14/2025	2/14/2026	3	Break Room	In workroom A325		WF-02142025-009779	1/16/2026	FT-FY26-01122026-009779-A	<2	FT-FY26-01122026-009779-B	<2
WS- 009780	2/14/2025	2/14/2026	2	Break Room	In workroom A227		WF-02142025-009780	1/16/2026	FT-FY26-01122026-009780-A	<2	FT-FY26-01122026-009780-B	<2
WS- 009781	2/14/2025	2/14/2026	3	Break Room	In workroom A327		WF-02142025-009781	1/16/2026	FT-FY26-01122026-009781-A	<2	FT-FY26-01122026-009781-B	<2
WS- 009782	2/14/2025	2/14/2026	2	Break Room	In workroom A226		WF-02142025-009782	1/16/2026	FT-FY26-01122026-009782-A	<2	FT-FY26-01122026-009782-B	<2
WS- 009786	2/14/2025	2/14/2026	1	Health Suite	In health suite B112		WF-02142025-009786	1/16/2026	FT-FY26-01122026-009786-A	<2	FT-FY26-01122026-009786-B	<2
WS- 009787	2/14/2025	2/14/2026	1	Break Room	In workroom B116		WF-02142025-009787	1/16/2026	FT-FY26-01122026-009787-A	<2	FT-FY26-01122026-009787-B	<2
WS- 009807	2/14/2025	2/14/2026	1	Combo Fountain	In Room 135		WF-02142025-009807	1/16/2026	FT-FY26-01122026-009807-A	<2	FT-FY26-01122026-009807-B	<2

Food Prep Sink

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 009706	12/9/2025	12/9/2026	1	Food Prep Sink	In kitchen across from room D114	WF-12092025-009706	1/16/2026	FT-FY26-01122026-009706-A	<2	FT-FY26-01122026-009706-B	<2

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.