



Kenilworth Swing Space Lead in Water Test Results

FY25 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS- 000416	5/7/2024	5/7/2025	1	Cooler	In hallway adjacent to 113 main office	WF-05072024-000416	2/13/2025	FT-FY25-12262024-000416-A	<2	FT-FY25-12262024-000416-B	<2	
WS- 000418	5/7/2024	5/7/2025	1	Cooler	In 102 library	WF-05072024-000418	2/13/2025	FT-FY25-12262024-000418-A	<2	FT-FY25-12262024-000418-B	<2	
WS- 000419	5/7/2024	5/7/2025	1	Cooler	In hallway adjacent to 101	WF-05072024-000419	2/13/2025	FT-FY25-12262024-000419-A	<2	FT-FY25-12262024-000419-B	<2	
WS- 000420	5/7/2024	5/7/2025	1	Cooler	In hallway adjacent to 109	WF-05072024-000420	2/13/2025	FT-FY25-12262024-000420-A	<2	FT-FY25-12262024-000420-B	<2	
WS- 000421	5/7/2024	5/7/2025	2	Cooler	In hallway adjacent to 213	WF-05072024-000421	2/13/2025	FT-FY25-12262024-000421-A	<2	FT-FY25-12262024-000421-B	<2	
WS- 000422	5/7/2024	5/7/2025	2	Cooler	In hallway adjacent to 201	WF-05072024-000422	2/13/2025	FT-FY25-12262024-000422-A	<2	FT-FY25-12262024-000422-B	<2	
WS- 000423	5/7/2024	5/7/2025	2	Cooler	In hallway adjacent to girls' restroom	WF-05072024-000423	2/13/2025	FT-FY25-12262024-000423-A	<2	FT-FY25-12262024-000423-B	<2	
WS- 000424	5/7/2024	5/7/2025	2	Cooler	In hallway adjacent to 231	Low Right	WF-05072024-000424	2/13/2025	FT-FY25-12262024-000424-A	<2	FT-FY25-12262024-000424-B	<2
WS- 000425	5/7/2024	5/7/2025	3	Break Room	In 304 staff lounge	WF-05072024-000425	2/13/2025	FT-FY25-12262024-000425-A	<2	FT-FY25-12262024-000425-B	<2	
WS- 000426	5/7/2024	5/7/2025	3	Cooler	In hallway adjacent to 313	WF-05072024-000426	2/13/2025	FT-FY25-12262024-000426-A	<2	FT-FY25-12262024-000426-B	<2	
WS- 000428	5/7/2024	5/7/2025	Ground Floor	Cooler	In cafeteria bubble	High Left	WF-05072024-000428	2/13/2025	FT-FY25-12262024-000428-A	<2	FT-FY25-12262024-000428-B	<2
WS- 000429	5/7/2024	5/7/2025	Ground Floor	Cooler	In cafeteria bubble	Low Right	WF-05072024-000429	2/13/2025	FT-FY25-12262024-000429-A	<2	FT-FY25-12262024-000429-B	<2
WS- 000716	5/7/2024	5/7/2025	1	Bottle Filler	In hallway adjacent to 113 main office	WF-05072024-000716	2/13/2025	FT-FY25-12262024-000716-A	<2	FT-FY25-12262024-000716-B	<2	
WS- 000718	5/7/2024	5/7/2025	1	Bottle Filler	In hallway adjacent to 109	WF-05072024-000718	2/13/2025	FT-FY25-12262024-000718-A	<2	FT-FY25-12262024-000718-B	<2	
WS- 000719	5/7/2024	5/7/2025	1	Bottle Filler	In hallway adjacent to 101	WF-05072024-000719	2/13/2025	FT-FY25-12262024-000719-A	<2	FT-FY25-12262024-000719-B	<2	
WS- 000779	5/7/2024	5/7/2025	2	Bottle Filler	In hallway adjacent to 201	WF-05072024-000779	2/13/2025	FT-FY25-12262024-000779-A	<2	FT-FY25-12262024-000779-B	<2	
WS- 000781	5/7/2024	5/7/2025	2	Bottle Filler	In hallway adjacent to 213	WF-05072024-000781	2/13/2025	FT-FY25-12262024-000781-A	<2	FT-FY25-12262024-000781-B	<2	
WS- 000782	5/7/2024	5/7/2025	2	Bottle Filler	In hallway adjacent to 231	WF-05072024-000782	2/13/2025	FT-FY25-12262024-000782-A	<2	FT-FY25-12262024-000782-B	<2	
WS- 000790	5/7/2024	5/7/2025	2	Cooler	In hallway adjacent to 231	High Left	WF-05072024-000790	2/13/2025	FT-FY25-12262024-000790-A	<2	FT-FY25-12262024-000790-B	<2
WS- 000791	5/7/2024	5/7/2025	2	Bottle Filler	In hallway adjacent to girls' restroom	WF-05072024-000791	2/13/2025	FT-FY25-12262024-000791-A	<2	FT-FY25-12262024-000791-B	<2	
WS- 000803	5/7/2024	5/7/2025	3	Bottle Filler	In hallway adjacent to 313	WF-05072024-000803	2/13/2025	FT-FY25-12262024-000803-A	<2	FT-FY25-12262024-000803-B	<2	

Food Prep Sink

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 000432	11/18/2024	11/18/2025	Ground Floor	Food Prep Sink	In kitchen trailer 1st clockwise from outdoor entry	WF-11182024-000432	2/13/2025	FT-FY25-12262024-000432-A	<2	FT-FY25-12262024-000432-B	<2

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.