



Kenilworth-Parkside RC Lead in Water Test Results

FY25 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 007000	4/9/2024	4/9/2025	1	Bottle Filler	In hallway adjacent to fitness room 106	WF-04092024-007000	3/7/2025	FT-FY25-01082025-007000-A	<2	FT-FY25-01082025-007000-B	<2
WS- 007001	4/9/2024	4/9/2025	1	Cooler	In hallway adjacent to fitness room 106	WF-04092024-007001	3/7/2025	FT-FY25-01082025-007001-A	<2	FT-FY25-01082025-007001-B	<2
WS- 007005	12/4/2024	12/4/2025	1	Food Prep Sink	In 114 kitchen second clockwise from entrance	WF-12042024-007005	3/7/2025	FT-FY25-01082025-007005-A	<2	FT-FY25-01082025-007005-B	<2

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.