



# KING ES LEAD WATER TEST RESULTS



## Initial Filter Test After Installation

Less than 1 ppb - Device Returned to Service										
	Building Location: Building Name	Water Source ID	Date Analyzed	Floor	Device Type	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	Final Result - 2nd Draw (ppb)
1	MARTIN LUTHER KING JR ELEMENTARY SCHOOL	WS- 008513	1/11/2017	1	Classroom Faucet	In classroom 113	FT-112016-008513-A	< 1	FT-112016-008513-B	< 1
2	MARTIN LUTHER KING JR ELEMENTARY SCHOOL	WS- 008507	1/11/2017	1	Classroom Faucet	In classroom 118	FT-112016-008507-A	< 1	FT-112016-008507-B	< 1

Greater than 1 ppb - Devices Shut Off and Corrective Action Taken										
1	MARTIN LUTHER KING JR ELEMENTARY SCHOOL	WS- 008516	1/11/2017	1	Classroom Faucet	In classroom 115	FT-112016-008516-A	1.7	FT-112016-008516-B	< 1
2	MARTIN LUTHER KING JR ELEMENTARY SCHOOL	WS- 008506	1/11/2017	1	Classroom Faucet	In classroom 109	FT-112016-008506-A	1.6	FT-112016-008506-B	< 1
3	MARTIN LUTHER KING JR ELEMENTARY SCHOOL	WS- 008515	1/11/2017	1	Classroom Faucet	In classroom 116	FT-112016-008515-A	1.5	FT-112016-008515-B	< 1
4	MARTIN LUTHER KING JR ELEMENTARY SCHOOL	WS- 008514	1/11/2017	1	Classroom Faucet	In classroom 114	FT-112016-008514-A	1.5	FT-112016-008514-B	< 1
5	MARTIN LUTHER KING JR ELEMENTARY SCHOOL	WS- 008512	1/11/2017	1	Classroom Faucet	In classroom 117	FT-112016-008512-A	1.4	FT-112016-008512-B	< 1

## First Filter Re-Test (After Filter and Plumbing Check with Aerator Replacement)

Less than 1 ppb - Device Returned to Service										
1	MARTIN LUTHER KING JR ELEMENTARY SCHOOL	WS- 008514	2/8/2017	1	Classroom Faucet	In classroom 114	FT-112016-008514-A	< 1	FT-112016-008514-B	< 1

Greater than 1 ppb - Devices Remain Shut off, Continued Remediation										
1	MARTIN LUTHER KING JR ELEMENTARY SCHOOL	WS- 008516	2/8/2017	1	Classroom Faucet	In classroom 115	FT-112016-008516-A	2.2	FT-112016-008516-B	< 1
2	MARTIN LUTHER KING JR ELEMENTARY SCHOOL	WS- 008506	2/8/2017	1	Classroom Faucet	In classroom 109	FT-112016-008506-A	21	FT-112016-008506-B	< 1
3	MARTIN LUTHER KING JR ELEMENTARY SCHOOL	WS- 008515	2/8/2017	1	Classroom Faucet	In classroom 116	FT-112016-008515-A	7.8	FT-112016-008515-B	< 1
4	MARTIN LUTHER KING JR ELEMENTARY SCHOOL	WS- 008512	2/8/2017	1	Classroom Faucet	In classroom 117	FT-112016-008512-A	1.6	FT-112016-008512-B	< 1

## Second Filter Re-Test (After Device Replacement)

Greater than 1 ppb - Devices Remain Shut off, Continued Remediation										
1	MARTIN LUTHER KING JR ELEMENTARY SCHOOL	WS- 008516	3/14/2017	1	Classroom Faucet	In classroom 115	FT-112016-008516-A	3	FT-112016-008516-B	< 1
2	MARTIN LUTHER KING JR ELEMENTARY SCHOOL	WS- 008506	3/14/2017	1	Classroom Faucet	In classroom 109	FT-112016-008506-A	4.2	FT-112016-008506-B	< 1
3	MARTIN LUTHER KING JR ELEMENTARY SCHOOL	WS- 008515	3/14/2017	1	Classroom Faucet	In classroom 116	FT-112016-008515-A	3.5	FT-112016-008515-B	< 1
4	MARTIN LUTHER KING JR ELEMENTARY SCHOOL	WS- 008512	3/14/2017	1	Classroom Faucet	In classroom 117	FT-112016-008512-A	5.6	FT-112016-008512-B	< 1

Note :

Filter re-tests are only performed to devices that have sampling results greater than 1 ppb