



Kramer MS Lead in Water Test Results

FY26 Filter Test

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 004414	2/18/2025	2/18/2026	Basement	Cooler	In hallway adjacent to room 003	High Left	WF-02182025-004414	12/17/2025	FT-FY26-12012025-004414-A	<2	FT-FY26-12012025-004414-B	<2
WS- 004426	2/18/2025	2/18/2026	1	Cooler	In hallway adjacent to room 104	High Left	WF-02182025-004426	12/17/2025	FT-FY26-12012025-004426-A	<2	FT-FY26-12012025-004426-B	<2
WS- 004427	2/18/2025	2/18/2026	1	Cooler	In hallway adjacent to room 104	Low Right	WF-02182025-004427	12/17/2025	FT-FY26-12012025-004427-A	<2	FT-FY26-12012025-004427-B	<2
WS- 004428	2/18/2025	2/18/2026	1	Health Suite	In health suite in treatment room 110A		WF-02182025-004428	12/17/2025	FT-FY26-12012025-004428-A	<2	FT-FY26-12012025-004428-B	<2
WS- 004429	2/18/2025	2/18/2026	1	Cooler	In hallway across from room 117	High Left	WF-02182025-004429	12/17/2025	FT-FY26-12012025-004429-A	<2	FT-FY26-12012025-004429-B	<2
WS- 004430	2/18/2025	2/18/2026	1	Cooler	In hallway across from room 117	Low Right	WF-02182025-004430	12/17/2025	FT-FY26-12012025-004430-A	<2	FT-FY26-12012025-004430-B	<2
WS- 004431	2/18/2025	2/18/2026	1	Cooler	In hallway adjacent to room 128	High Left	WF-02182025-004431	12/17/2025	FT-FY26-12012025-004431-A	<2	FT-FY26-12012025-004431-B	<2
WS- 004432	2/18/2025	2/18/2026	1	Cooler	In hallway adjacent to room 128	Low Right	WF-02182025-004432	12/17/2025	FT-FY26-12012025-004432-A	<2	FT-FY26-12012025-004432-B	<2
WS- 004433	2/18/2025	2/18/2026	2	Cooler	In hallway adjacent to room 200	High Left	WF-02182025-004433	12/17/2025	FT-FY26-12012025-004433-A	<2	FT-FY26-12012025-004433-B	<2
WS- 004434	2/18/2025	2/18/2026	2	Cooler	In hallway adjacent to room 200	Low Right	WF-02182025-004434	12/17/2025	FT-FY26-12012025-004434-A	<2	FT-FY26-12012025-004434-B	<2
WS- 004436	2/18/2025	2/18/2026	2	Cooler	In hallway adjacent to room 204	High Left	WF-02182025-004436	12/17/2025	FT-FY26-12012025-004436-A	<2	FT-FY26-12012025-004436-B	<2
WS- 004437	2/18/2025	2/18/2026	2	Cooler	In hallway adjacent to room 204	Low Right	WF-02182025-004437	12/17/2025	FT-FY26-12012025-004437-A	<2	FT-FY26-12012025-004437-B	<2
WS- 004439	2/18/2025	2/18/2026	2	Cooler	In hallway adjacent to room 211	High Left	WF-02182025-004439	12/17/2025	FT-FY26-12012025-004439-A	<2	FT-FY26-12012025-004439-B	<2
WS- 004440	2/18/2025	2/18/2026	2	Cooler	In hallway adjacent to room 211	Low Right	WF-02182025-004440	12/17/2025	FT-FY26-12012025-004440-A	<2	FT-FY26-12012025-004440-B	<2
WS- 008987	2/18/2025	2/18/2026	2	Break Room	In staff lounge 218		WF-02182025-008987	12/17/2025	FT-FY26-12012025-008987-A	<2	FT-FY26-12012025-008987-B	<2
WS- 008988	2/18/2025	2/18/2026	3	Cooler	In hallway adjacent to room 300	High Left	WF-02182025-008988	12/17/2025	FT-FY26-12012025-008988-A	<2	FT-FY26-12012025-008988-B	<2
WS- 008989	2/18/2025	2/18/2026	3	Cooler	In hallway adjacent to room 300	Low Right	WF-02182025-008989	12/17/2025	FT-FY26-12012025-008989-A	<2	FT-FY26-12012025-008989-B	<2
WS- 008990	2/18/2025	2/18/2026	3	Cooler	In hallway adjacent to room 306	High Left	WF-02182025-008990	12/17/2025	FT-FY26-12012025-008990-A	<2	FT-FY26-12012025-008990-B	<2
WS- 008991	2/18/2025	2/18/2026	3	Cooler	In hallway adjacent to room 306	Low Right	WF-02182025-008991	12/17/2025	FT-FY26-12012025-008991-A	<2	FT-FY26-12012025-008991-B	<2
WS- 008999	2/18/2025	2/18/2026	3	Cooler	In hallway across from room 311	High Left	WF-02182025-008999	12/17/2025	FT-FY26-12012025-008999-A	<2	FT-FY26-12012025-008999-B	<2

Food Prep Sink

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 004418	11/25/2025	11/25/2026	Basement	Food Prep Sink	In kitchen first clockwise from entry door		WF-11252025-004418	12/17/2025	FT-FY26-12012025-004418-A	<2	FT-FY26-12012025-004418-B	<2
WS- 004419	11/25/2025	11/25/2026	Basement	Food Prep Sink	In kitchen second clockwise from entry door		WF-11252025-004419	12/17/2025	FT-FY26-12012025-004419-A	<2	FT-FY26-12012025-004419-B	<2
WS- 004420	11/25/2025	11/25/2026	Basement	Food Prep Sink	In kitchen third clockwise from entry door		WF-11252025-004420	12/17/2025	FT-FY26-12012025-004420-A	<2	FT-FY26-12012025-004420-B	<2

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.