



Langdon Park RC Lead in Water Test Results

FY25 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 005790	3/13/2024	3/13/2025	1	Cooler	In hallway adjacent to reception	WF-03132024-005790	2/19/2025	FT-FY25-01082025-005790-A	<2	FT-FY25-01082025-005790-B	<2
WS- 005792	11/25/2024	11/25/2025	1	Food Prep Sink	In kitchen 212	WF-11252024-005792	2/19/2025	FT-FY25-01082025-005792-A	<2	FT-FY25-01082025-005792-B	<2
WS- 005793	3/13/2024	3/13/2025	Basement	Cooler	In hallway adjacent to gym 115	WF-03132024-005793	2/19/2025	FT-FY25-01082025-005793-A	<2	FT-FY25-01082025-005793-B	<2

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.