



Malcolm X ES @ Davis Swing Space Lead in Water Test Results

FY26 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 007499	4/1/2025	4/1/2026	1	Combo Fountain	In classroom c109	WF-04012025-007499	1/9/2026	FT-FY26-12302025-007499-A	<2	FT-FY26-12302025-007499-B	<2
WS- 007500	4/1/2025	4/1/2026	2	Cooler	In hallway adjacent to janitors closet b201c	WF-04012025-007500	1/9/2026	FT-FY26-12302025-007500-A	<2	FT-FY26-12302025-007500-B	<2
WS- 007501	4/1/2025	4/1/2026	2	Cooler	In hallway adjacent to classroom 204	WF-04012025-007501	1/9/2026	FT-FY26-12302025-007501-A	<2	FT-FY26-12302025-007501-B	<2
WS- 007505	4/1/2025	4/1/2026	1	Cooler	In hallway adjacent to janitors closet c108	WF-04012025-007505	1/9/2026	FT-FY26-12302025-007505-A	<2	FT-FY26-12302025-007505-B	<2
WS- 007508	4/1/2025	4/1/2026	1	Cooler	In hallway adjacent to b101c janitor closet	WF-04012025-007508	1/9/2026	FT-FY26-12302025-007508-A	<2	FT-FY26-12302025-007508-B	<2
WS- 007509	4/1/2025	4/1/2026	1	Health Suite	In health suite room a103	WF-04012025-007509	1/9/2026	FT-FY26-12302025-007509-A	<2	FT-FY26-12302025-007509-B	<2
WS- 007510	4/1/2025	4/1/2026	1	Cooler	In hallway adjacent to classroom a102	WF-04012025-007510	1/9/2026	FT-FY26-12302025-007510-A	<2	FT-FY26-12302025-007510-B	<2
WS- 007518	4/1/2025	4/1/2026	1	Combo Fountain	In classroom c104	WF-04012025-007518	1/9/2026	FT-FY26-12302025-007518-A	<2	FT-FY26-12302025-007518-B	<2
WS- 007519	4/1/2025	4/1/2026	1	Combo Fountain	In classroom c102	WF-04012025-007519	1/9/2026	FT-FY26-12302025-007519-A	<2	FT-FY26-12302025-007519-B	<2
WS- 007520	4/1/2025	4/1/2026	1	Combo Fountain	In classroom c103	WF-04012025-007520	1/9/2026	FT-FY26-12302025-007520-A	<2	FT-FY26-12302025-007520-B	<2
WS- 007524	4/1/2025	4/1/2026	2	Bottle Filler	In hallway adjacent to janitors closet b201c	WF-04012025-007524	1/9/2026	FT-FY26-12302025-007524-A	<2	FT-FY26-12302025-007524-B	<2
WS- 007526	4/1/2025	4/1/2026	1	Bottle Filler	In hallway adjacent to janitors closet c108	WF-04012025-007526	1/9/2026	FT-FY26-12302025-007526-A	<2	FT-FY26-12302025-007526-B	<2
WS- 007527	4/1/2025	4/1/2026	1	Bottle Filler	In hallway adjacent to b101c janitor closet	WF-04012025-007527	1/9/2026	FT-FY26-12302025-007527-A	<2	FT-FY26-12302025-007527-B	<2
WS- 007528	4/1/2025	4/1/2026	1	Bottle Filler	In hallway adjacent to classroom a102	WF-04012025-007528	1/9/2026	FT-FY26-12302025-007528-A	<2	FT-FY26-12302025-007528-B	<2

Food Prep Sink

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 007515	12/3/2025	12/3/2026	Basement	Food Prep Sink	In kitchen third from left Right	WF-12032025-007515	1/9/2026	FT-FY26-12302025-007515-A	<2	FT-FY26-12302025-007515-B	<2

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.