



McKinley MS Lead in Water Test Results

FY26 Filter Test

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 010468	3/26/2025	3/26/2026	1	Cooler	In hallway across from room 115F	Low Left	WF-03262025-010468	12/15/2025	FT-FY26-12082025-010468-A	<2	FT-FY26-12082025-010468-B	<2
WS- 010469	3/26/2025	3/26/2026	1	Cooler	In hallway across from room 115F	High Right	WF-03262025-010469	12/15/2025	FT-FY26-12082025-010469-A	<2	FT-FY26-12082025-010469-B	<2
WS- 010470	3/26/2025	3/26/2026	1	Cooler	In gym adjacent to room 114	High Left	WF-03262025-010470	12/15/2025	FT-FY26-12082025-010470-A	<2	FT-FY26-12082025-010470-B	<2
WS- 010471	3/26/2025	3/26/2026	1	Cooler	In gym adjacent to room 114	Low Right	WF-03262025-010471	12/15/2025	FT-FY26-12082025-010471-A	<2	FT-FY26-12082025-010471-B	<2
WS- 010472	3/26/2025	3/26/2026	1	Cooler	In gym adjacent to room 114F	Low Left	WF-03262025-010472	12/15/2025	FT-FY26-12082025-010472-A	<2	FT-FY26-12082025-010472-B	<2
WS- 010473	3/26/2025	3/26/2026	1	Cooler	In gym adjacent to room 114F	High Right	WF-03262025-010473	12/15/2025	FT-FY26-12082025-010473-A	<2	FT-FY26-12082025-010473-B	<2
WS- 010474	3/26/2025	3/26/2026	1	Health Suite	In health suite in treatment room 117D		WF-03262025-010474	12/15/2025	FT-FY26-12082025-010474-A	<2	FT-FY26-12082025-010474-B	<2
WS- 010475	3/26/2025	3/26/2026	1	Combo Fountain	In treatment room 117D in health suite		WF-03262025-010475	12/15/2025	FT-FY26-12082025-010475-A	<2	FT-FY26-12082025-010475-B	<2
WS- 010476	3/26/2025	3/26/2026	2	Cooler	In hallway adjacent to room 202	Low Left	WF-03262025-010476	12/15/2025	FT-FY26-12082025-010476-A	<2	FT-FY26-12082025-010476-B	<2
WS- 010477	3/26/2025	3/26/2026	2	Cooler	In hallway adjacent to room 202	High Right	WF-03262025-010477	12/15/2025	FT-FY26-12082025-010477-A	<2	FT-FY26-12082025-010477-B	<2
WS- 010486	3/26/2025	3/26/2026	2	Break Room	In staff lounge		WF-03262025-010486	12/15/2025	FT-FY26-12082025-010486-A	<2	FT-FY26-12082025-010486-B	<2
WS- 010488	3/26/2025	3/26/2026	3	Cooler	In hallway adjacent to room 302	Low Left	WF-03262025-010488	12/15/2025	FT-FY26-12082025-010488-A	<2	FT-FY26-12082025-010488-B	<2
WS- 010489	3/26/2025	3/26/2026	3	Cooler	In hallway adjacent to room 302	High Right	WF-03262025-010489	12/15/2025	FT-FY26-12082025-010489-A	<2	FT-FY26-12082025-010489-B	<2
WS- 010548	3/26/2025	3/26/2026	1	Bottle Filler	In hallway across from room 115F		WF-03262025-010548	12/15/2025	FT-FY26-12082025-010548-A	<2	FT-FY26-12082025-010548-B	<2

Food Prep Sink

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 011820	11/24/2025	11/24/2026	Basement	Food Prep Sink	In kitchen east wall	Left	WF-11242025-011820	12/15/2025	FT-FY26-12082025-011820-A	<2	FT-FY26-12082025-011820-B	<2

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.