



# Northwest One/RH Terrell RC Lead in Water Test Results

## FY26 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 006160	4/9/2025	4/9/2026	1	Cooler	In lobby across from elevator High Left	WF-04092025-006160	3/4/2026	FT-FY26-01282026-006160-A	<2	FT-FY26-01282026-006160-B	<2
WS- 006161	4/9/2025	4/9/2026	1	Cooler	In lobby across from elevator Low Right	WF-04092025-006161	3/4/2026	FT-FY26-01282026-006161-A	<2	FT-FY26-01282026-006161-B	<2

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.