



School Without Walls HS Lead in Water Test Results

FY26 Filter Test

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 012081	8/27/2025	8/27/2026	3	Cooler	In hallway adjacent to elevator	High Left	WF-08272025-012081	11/6/2025	FT-FY26-10172025-012081-A	<2	FT-FY26-10172025-012081-B	<2
WS- 012082	8/27/2025	8/27/2026	3	Cooler	In hallway adjacent to elevator	Low Right	WF-08272025-012082	11/6/2025	FT-FY26-10172025-012082-A	<2	FT-FY26-10172025-012082-B	<2
WS- 012084	4/8/2025	4/8/2026	3	Break Room	In break room		WF-04082025-012084	11/6/2025	FT-FY26-10172025-012084-A	<2	FT-FY26-10172025-012084-B	<2
WS- 012086	8/27/2025	8/27/2026	2	Cooler	In hallway adjacent to elevator	High Left	WF-08272025-012086	11/6/2025	FT-FY26-10172025-012086-A	<2	FT-FY26-10172025-012086-B	<2
WS- 012087	8/27/2025	8/27/2026	2	Cooler	In hallway adjacent to elevator	Low Right	WF-08272025-012087	11/6/2025	FT-FY26-10172025-012087-A	<2	FT-FY26-10172025-012087-B	<2
WS- 012088	8/27/2025	8/27/2026	1	Cooler	In hallway adjacent to elevator	High Left	WF-08272025-012088	11/6/2025	FT-FY26-10172025-012088-A	<2	FT-FY26-10172025-012088-B	<2
WS- 012089	8/27/2025	8/27/2026	1	Cooler	In hallway adjacent to elevator	Low Right	WF-08272025-012089	11/6/2025	FT-FY26-10172025-012089-A	<2	FT-FY26-10172025-012089-B	<2
WS- 012091	4/8/2025	4/8/2026	1	Health Suite	In health suite		WF-04082025-012091	11/6/2025	FT-FY26-10172025-012091-A	<2	FT-FY26-10172025-012091-B	<2
WS- 012136	8/27/2025	8/27/2026	Basement	Cooler	In hallway adjacent to elevator	High Left	WF-08272025-012136	11/6/2025	FT-FY26-10172025-012136-A	<2	FT-FY26-10172025-012136-B	<2
WS- 012137	8/27/2025	8/27/2026	Basement	Cooler	In hallway adjacent to elevator	Low Right	WF-08272025-012137	11/6/2025	FT-FY26-10172025-012137-A	<2	FT-FY26-10172025-012137-B	<2
WS- 012141	8/27/2025	8/27/2026	3	Bottle Filler	In hallway adjacent to elevator		WF-08272025-012141	11/6/2025	FT-FY26-10172025-012141-A	<2	FT-FY26-10172025-012141-B	<2
WS- 012142	8/27/2025	8/27/2026	2	Bottle Filler	In hallway adjacent to elevator		WF-08272025-012142	11/6/2025	FT-FY26-10172025-012142-A	<2	FT-FY26-10172025-012142-B	<2
WS- 012143	8/27/2025	8/27/2026	1	Bottle Filler	In hallway adjacent to elevator		WF-08272025-012143	11/6/2025	FT-FY26-10172025-012143-A	<2	FT-FY26-10172025-012143-B	<2

Food Prep Sink

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 012090	11/26/2024	11/26/2025	1	Food Prep Sink	In kitchen		WF-11262024-012090	11/6/2025	FT-FY26-10172025-012090-A	<2	FT-FY26-10172025-012090-B	<2

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.