



# Sousa MS Lead in Water Test Results

## FY26 Filter Test

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 009642	4/15/2025	4/15/2026	1	Cooler	In hallway adjacent to room A102	Low Left	WF-04152025-009642	10/15/2025	FT-FY26-09302025-009642-A	<2	FT-FY26-09302025-009642-B	<2
WS- 009643	4/15/2025	4/15/2026	1	Cooler	In hallway adjacent to room A102	High Right	WF-04152025-009643	10/15/2025	FT-FY26-09302025-009643-A	<2	FT-FY26-09302025-009643-B	<2
WS- 009645	4/15/2025	4/15/2026	1	Cooler	In hallway adjacent to room B122	Low Left	WF-04152025-009645	10/15/2025	FT-FY26-09302025-009645-A	<2	FT-FY26-09302025-009645-B	<2
WS- 009646	4/15/2025	4/15/2026	1	Health Suite	In health suite B122		WF-04152025-009646	10/15/2025	FT-FY26-09302025-009646-A	<2	FT-FY26-09302025-009646-B	<2
WS- 010987	4/15/2025	4/15/2026	1	Break Room	In mailroom B130		WF-04152025-010987	10/15/2025	FT-FY26-09302025-010987-A	<2	FT-FY26-09302025-010987-B	<2
WS- 010988	4/15/2025	4/15/2026	1	Health Suite	In health suite B122 in restroom		WF-04152025-010988	10/15/2025	FT-FY26-09302025-010988-A	<2	FT-FY26-09302025-010988-B	<2
WS- 011017	4/15/2025	4/15/2026	1	Cooler	In hallway adjacent to gym D111	Low Left	WF-04152025-011017	10/15/2025	FT-FY26-09302025-011017-A	<2	FT-FY26-09302025-011017-B	<2
WS- 011018	4/15/2025	4/15/2026	1	Cooler	In hallway adjacent to gym D111	High Right	WF-04152025-011018	10/15/2025	FT-FY26-09302025-011018-A	<2	FT-FY26-09302025-011018-B	<2
WS- 011019	4/15/2025	4/15/2026	1	Cooler	In hallway across from backstage D101	Low Left	WF-04152025-011019	10/15/2025	FT-FY26-09302025-011019-A	<2	FT-FY26-09302025-011019-B	<2
WS- 011020	4/15/2025	4/15/2026	1	Cooler	In hallway across from backstage D101	High Right	WF-04152025-011020	10/15/2025	FT-FY26-09302025-011020-A	<2	FT-FY26-09302025-011020-B	<2
WS- 011025	4/15/2025	4/15/2026	Basement	Ice Maker	In kitchen (ice maker)		WF-04152025-011025	10/15/2025	FT-FY26-09302025-011025-A	<2	FT-FY26-09302025-011025-B	<2
WS- 011031	4/15/2025	4/15/2026	2	Cooler	In hallway adjacent to room C201	High Left	WF-04152025-011031	10/15/2025	FT-FY26-09302025-011031-A	<2	FT-FY26-09302025-011031-B	<2
WS- 011032	4/15/2025	4/15/2026	2	Cooler	In hallway adjacent to room C201	High Right	WF-04152025-011032	10/15/2025	FT-FY26-09302025-011032-A	<2	FT-FY26-09302025-011032-B	<2
WS- 011062	4/15/2025	4/15/2026	2	Cooler	In hallway adjacent to room A202	High Right	WF-04152025-011062	10/15/2025	FT-FY26-09302025-011062-A	<2	FT-FY26-09302025-011062-B	<2
WS- 011063	4/15/2025	4/15/2026	2	Cooler	In hallway adjacent to room A202	Low Left	WF-04152025-011063	10/15/2025	FT-FY26-09302025-011063-A	<2	FT-FY26-09302025-011063-B	<2
WS- 011068	4/15/2025	4/15/2026	3	Break Room	In staff lounge B314		WF-04152025-011068	10/15/2025	FT-FY26-09302025-011068-A	<2	FT-FY26-09302025-011068-B	<2
WS- 011069	4/15/2025	4/15/2026	3	Cooler	In hallway adjacent to room A302	Low Left	WF-04152025-011069	10/15/2025	FT-FY26-09302025-011069-A	<2	FT-FY26-09302025-011069-B	<2
WS- 011070	4/15/2025	4/15/2026	3	Cooler	In hallway adjacent to room A302	High Right	WF-04152025-011070	10/15/2025	FT-FY26-09302025-011070-A	<2	FT-FY26-09302025-011070-B	<2
WS- 011085	4/15/2025	4/15/2026	3	Cooler	In hallway adjacent to room C301		WF-04152025-011085	10/15/2025	FT-FY26-09302025-011085-A	<2	FT-FY26-09302025-011085-B	<2

## Food Prep Sink

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 011027	11/13/2024	11/13/2025	Basement	Food Prep Sink	In kitchen on north wall	Left	WF-11132024-011027	10/15/2025	FT-FY26-09302025-011027-A	<2	FT-FY26-09302025-011027-B	<2

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.