



Sousa Middle School Lead in Water Test Results

FY25 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 009645	4/23/2024	4/23/2025	1	Cooler	In hallway adjacent to room B122 Low Left	WF-04232024-009645	2/7/2025	FT-FY25-12262024-009645-A	<2	FT-FY25-12262024-009645-B	<2
WS- 010987	4/23/2024	4/23/2025	1	Break Room	In mailroom B130	WF-04232024-010987	2/7/2025	FT-FY25-12262024-010987-A	<2	FT-FY25-12262024-010987-B	<2
WS- 010988	4/23/2024	4/23/2025	1	Health Suite	In health suite B122 in restroom	WF-04232024-010988	2/7/2025	FT-FY25-12262024-010988-A	<2	FT-FY25-12262024-010988-B	<2
WS- 011016	4/23/2024	4/23/2025	1	Cooler	In hallway adjacent to room C101 High Right	WF-04232024-011016	2/7/2025	FT-FY25-12262024-011016-A	<2	FT-FY25-12262024-011016-B	<2
WS- 011019	4/23/2024	4/23/2025	1	Cooler	In hallway across from backstage D101 Low Left	WF-04232024-011019	2/7/2025	FT-FY25-12262024-011019-A	<2	FT-FY25-12262024-011019-B	<2
WS- 011020	4/23/2024	4/23/2025	1	Cooler	In hallway across from backstage D101 High Right	WF-04232024-011020	2/7/2025	FT-FY25-12262024-011020-A	<2	FT-FY25-12262024-011020-B	<2
WS- 011025	4/23/2024	4/23/2025	Basement	Ice Maker	In kitchen (ice maker)	WF-04232024-011025	2/7/2025	FT-FY25-12262024-011025-A	<2	FT-FY25-12262024-011025-B	<2
WS- 011031	4/23/2024	4/23/2025	2	Cooler	In hallway adjacent to room C201 High Left	WF-04232024-011031	2/7/2025	FT-FY25-12262024-011031-A	<2	FT-FY25-12262024-011031-B	<2
WS- 011032	4/23/2024	4/23/2025	2	Cooler	In hallway adjacent to room C201 High Right	WF-04232024-011032	2/7/2025	FT-FY25-12262024-011032-A	<2	FT-FY25-12262024-011032-B	<2
WS- 011062	4/23/2024	4/23/2025	2	Cooler	In hallway adjacent to room A202 High Right	WF-04232024-011062	2/7/2025	FT-FY25-12262024-011062-A	<2	FT-FY25-12262024-011062-B	<2
WS- 011063	4/23/2024	4/23/2025	2	Cooler	In hallway adjacent to room A202 Low Left	WF-04232024-011063	2/7/2025	FT-FY25-12262024-011063-A	<2	FT-FY25-12262024-011063-B	<2
WS- 011068	4/23/2024	4/23/2025	3	Break Room	In staff lounge B314	WF-04232024-011068	2/7/2025	FT-FY25-12262024-011068-A	<2	FT-FY25-12262024-011068-B	<2
WS- 011085	4/23/2024	4/23/2025	3	Cooler	In hallway adjacent to room C301	WF-04232024-011085	2/7/2025	FT-FY25-12262024-011085-A	<2	FT-FY25-12262024-011085-B	<2

Food Prep Sink

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 011027	11/13/2024	11/13/2025	Basement	Food Prep Sink	In kitchen on north wall Left	WF-11132024-011027	2/7/2025	FT-FY25-12262024-011027-A	<2	FT-FY25-12262024-011027-B	<2

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.