



# STODDERT ES LEAD WATER TEST RESULTS



## Initial Filter Test After Installation

Less than 1 ppb - Device Returned to Service										
	Building Location: Building Name	Water Source ID	Date Analyzed	Floor	Device Type	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	Final Result - 2nd Draw (ppb)
1	STODDERT ELEMENTARY SCHOOL	WS- 003615	12/24/2016	1	Combo Faucet	In classroom 132	FT-122016-003615-A	< 1	FT-122016-003615-B	< 1
2	STODDERT ELEMENTARY SCHOOL	WS- 003619	12/24/2016	1	Combo Faucet	In classroom 134	FT-122016-003619-A	< 1	FT-122016-003619-B	< 1
3	STODDERT ELEMENTARY SCHOOL	WS- 003649	12/24/2016	2	Break Room	In break room 230	FT-112016-003649-A	< 1	FT-112016-003649-B	< 1

Greater than 1 ppb - Devices Shut Off and Corrective Action Taken										
1	STODDERT ELEMENTARY SCHOOL	WS- 003617	12/24/2016	1	Combo Faucet	In classroom 133	FT-122016-003617-A	1.2	FT-122016-003617-B	< 1

## First Filter Re-Test (After Filter and Plumbing Check with Aerator Replacement)

Greater than 1 ppb - Devices Remain Shut off, Continued Remediation										
1	STODDERT ELEMENTARY SCHOOL	WS- 003617	1/25/2017	1	Combo Faucet	In classroom 133	FT-122016-003617-A	2.1	FT-122016-003617-B	< 1

## Second Filter Re-Test (After Device Replacement)

Greater than 1 ppb - Devices Remain Shut off, Continued Remediation										
1	STODDERT ELEMENTARY SCHOOL	WS- 003617	4/7/2017	1	Combo Faucet	In classroom 133	FT-122016-003617-A	1	FT-122016-003617-B	< 1

## Filter Re-Test (Post Consultation; After Dual Supply Faucet Installation)

Less than 5 ppb - Device Returned to Service										
1	STODDERT ELEMENTARY SCHOOL	WS- 003617	8/11/2017	1	Combo Faucet	In classroom 133	FT-122016-003617-A	< 1	FT-122016-003617-B	< 1