



THOMSON ES LEAD WATER TEST RESULTS



Initial Filter Test After Installation

Less than 1 ppb - Device Returned to Service											
	Building Location: Building Name	Water Source ID	Date Analyzed	Floor	Device Type	Device Location		1st Draw - Sample ID	Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	Final Result - 2nd Draw (ppb)
1	THOMSON ELEMENTARY SCHOOL	WS- 000491	12/17/2016	1	Combo Faucet	In classroom 123	Left	FT-122016-000491-A	< 1	FT-122016-000491-B	< 1
2	THOMSON ELEMENTARY SCHOOL	WS- 000493	12/17/2016	1	Combo Faucet	In classroom 124	Left	FT-122016-000493-A	< 1	FT-122016-000493-B	< 1
3	THOMSON ELEMENTARY SCHOOL	WS- 000495	12/17/2016	1	Combo Faucet	In classroom 126	Left	FT-122016-000495-A	< 1	FT-122016-000495-B	< 1
4	THOMSON ELEMENTARY SCHOOL	WS- 000498	12/17/2016	1	Combo Faucet	In classroom 127	Left	FT-122016-000498-A	< 1	FT-122016-000498-B	< 1
5	THOMSON ELEMENTARY SCHOOL	WS- 000504	12/17/2016	1	Combo Faucet	In classroom 115	Left	FT-122016-000504-A	< 1	FT-122016-000504-B	< 1
6	THOMSON ELEMENTARY SCHOOL	WS- 000506	12/17/2016	1	Combo Faucet	In classroom 114	Left	FT-122016-000506-A	< 1	FT-122016-000506-B	< 1
7	THOMSON ELEMENTARY SCHOOL	WS- 000513	12/17/2016	2	Combo Faucet	In classroom 209	Left	FT-122016-000513-A	< 1	FT-122016-000513-B	< 1
8	THOMSON ELEMENTARY SCHOOL	WS- 000517	12/17/2016	2	Combo Faucet	In classroom 208	Left	FT-122016-000517-A	< 1	FT-122016-000517-B	< 1
9	THOMSON ELEMENTARY SCHOOL	WS- 000521	12/17/2016	2	Combo Faucet	In classroom 223	Left	FT-122016-000521-A	< 1	FT-122016-000521-B	< 1
10	THOMSON ELEMENTARY SCHOOL	WS- 000523	12/17/2016	2	Combo Faucet	In classroom 221	Left	FT-122016-000523-A	< 1	FT-122016-000523-B	< 1
11	THOMSON ELEMENTARY SCHOOL	WS- 000546	12/17/2016	2	Break Room	In staff lounge 218		FT-112016-000546-A	< 1	FT-112016-000546-B	< 1

Greater than 1 ppb - Devices Shut Off and Corrective Action Taken											
1	THOMSON ELEMENTARY SCHOOL	WS- 000535	12/17/2016	3	Combo Faucet	In classroom 307	Left	FT-122016-000535-A	1.1	FT-122016-000535-B	< 1
2	THOMSON ELEMENTARY SCHOOL	WS- 000531	12/17/2016	3	Combo Faucet	In classroom 310	Left	FT-122016-000531-A	1.4	FT-122016-000531-B	< 1
3	THOMSON ELEMENTARY SCHOOL	WS- 000512	12/17/2016	2	Combo Faucet	In classroom 210	Left	FT-122016-000512-A	1.5	FT-122016-000512-B	< 1
4	THOMSON ELEMENTARY SCHOOL	WS- 000515	12/17/2016	2	Combo Faucet	In classroom 211	Left	FT-122016-000515-A	1.5	FT-122016-000515-B	< 1
5	THOMSON ELEMENTARY SCHOOL	WS- 000503	12/17/2016	1	Combo Faucet	In classroom 112	Left	FT-122016-000503-A	2.3	FT-122016-000503-B	< 1
6	THOMSON ELEMENTARY SCHOOL	WS- 000529	12/17/2016	3	Combo Faucet	In classroom 309	Left	FT-122016-000529-A	2.5	FT-122016-000529-B	< 1
7	THOMSON ELEMENTARY SCHOOL	WS- 000525	12/17/2016	2	Combo Faucet	In classroom 220	Left	FT-122016-000525-A	2.9	FT-122016-000525-B	< 1
8	THOMSON ELEMENTARY SCHOOL	WS- 000508	12/17/2016	1	Combo Faucet	In classroom 113	Left	FT-122016-000508-A	3.2	FT-122016-000508-B	< 1
9	THOMSON ELEMENTARY SCHOOL	WS- 000527	12/17/2016	2	Combo Faucet	In classroom 219	Left	FT-122016-000527-A	7.9	FT-122016-000527-B	< 1

First Filter Re-Test (After Filter and Plumbing Check with Aerator Replacement)

Less than 1 ppb - Device Returned to Service											
1	THOMSON ELEMENTARY SCHOOL	WS- 000508	1/25/2017	1	Combo Faucet	In classroom 113	Left	FT-122016-000508-A	< 1	FT-122016-000508-B	< 1
2	THOMSON ELEMENTARY SCHOOL	WS- 000527	1/25/2017	2	Combo Faucet	In classroom 219	Left	FT-122016-000527-A	< 1	FT-122016-000527-B	< 1

Greater than 1 ppb - Devices Remain Shut off, Continued Remediation											
1	THOMSON ELEMENTARY SCHOOL	WS- 000503	1/25/2017	1	Combo Faucet	In classroom 112	Left	FT-122016-000503-A	16	FT-122016-000503-B	< 1
2	THOMSON ELEMENTARY SCHOOL	WS- 000512	1/25/2017	2	Combo Faucet	In classroom 210	Left	FT-122016-000512-A	1.3	FT-122016-000512-B	< 1
3	THOMSON ELEMENTARY SCHOOL	WS- 000515	1/25/2017	2	Combo Faucet	In classroom 211	Left	FT-122016-000515-A	2.6	FT-122016-000515-B	< 1
4	THOMSON ELEMENTARY SCHOOL	WS- 000525	1/25/2017	2	Combo Faucet	In classroom 220	Left	FT-122016-000525-A	1.8	FT-122016-000525-B	1.7

Note :

Filter re-tests are only performed to devices that have sampling results greater than 1 ppb

DCPS ECE Sink and DCPS Requested Sink Filtration

5	THOMSON ELEMENTARY SCHOOL	WS- 000529	1/25/2017	3	Combo Faucet	In classroom 309	Left	FT-122016-000529-A	1.4	FT-122016-000529-B	< 1
6	THOMSON ELEMENTARY SCHOOL	WS- 000531	1/25/2017	3	Combo Faucet	In classroom 310	Left	FT-122016-000531-A	3.2	FT-122016-000531-B	< 1
7	THOMSON ELEMENTARY SCHOOL	WS- 000535	1/25/2017	3	Combo Faucet	In classroom 307	Left	FT-122016-000535-A	3.5	FT-122016-000535-B	< 1

Second Filter Re-Test (After Device Replacement)

Less than 1 ppb - Device Returned to Service											
1	THOMSON ELEMENTARY SCHOOL	WS- 000503	3/14/2017	1	Combo Faucet	In classroom 112	Left	FT-122016-000503-A	< 1	FT-122016-000503-B	< 1
2	THOMSON ELEMENTARY SCHOOL	WS- 000529	3/14/2017	3	Combo Faucet	In classroom 309	Left	FT-122016-000529-A	< 1	FT-122016-000529-B	< 1
3	THOMSON ELEMENTARY SCHOOL	WS- 000535	3/14/2017	3	Combo Faucet	In classroom 307	Left	FT-122016-000535-A	< 1	FT-122016-000535-B	< 1

Greater than 1 ppb - Devices Remain Shut off, Continued Remediation											
1	THOMSON ELEMENTARY SCHOOL	WS- 000512	3/14/2017	2	Combo Faucet	In classroom 210	Left	FT-122016-000512-A	1.1	FT-122016-000512-B	< 1
2	THOMSON ELEMENTARY SCHOOL	WS- 000515	3/14/2017	2	Combo Faucet	In classroom 211	Left	FT-122016-000515-A	1.6	FT-122016-000515-B	< 1
3	THOMSON ELEMENTARY SCHOOL	WS- 000525	3/14/2017	2	Combo Faucet	In classroom 220	Left	FT-122016-000525-A	2.5	FT-122016-000525-B	< 1
4	THOMSON ELEMENTARY SCHOOL	WS- 000531	3/14/2017	3	Combo Faucet	In classroom 310	Left	FT-122016-000531-A	2.4	FT-122016-000531-B	< 1

Note :

Filter re-tests are only performed to devices that have sampling results greater than 1 ppb